


Overhead door will be raised by 2 feet to facilitate fork lift traffic.



Doors & frame are severely rusted at the bottom



North Building