



1st Floor

31




23




door
needs
safety glass


28



24




29




64




21




65



22



66




67


~~Flashed~~
obsolete
Bathroom
Glass

39/40/73/74/72
all new addition
windows 70s


68



69



42




double layer




double layer


43



70




9




10


Photo



71




11




2nd Floor


63




6




30




36




7




26




37




8




27




38




~~9~~



17



5




57 →

is stowed


54-new
53, 55, 56
unseen

58/59/60-new


18



19




20




3rd Floor

Room 10

1



2




32
95-
Ath C-
unseen


35




3




34



4




33




46


3rd stairwell



52




45



47, 48, 49 - all new


3rd

44




Back stairs


50




16




51




15





62




14



61



13



12

