



Note several spots where existing roof is rusting