
1980'S (?) ERA ADDITON TO BE REMOVED - INCLUDES GARAGE AND MASTER SUITE TINY ENCLOSED PORCH TO BE REMOVED



TINY ENCLOSED PORCH INTERIIORS






TINY ENCLOSED PORCH & CHIMNEY TO BE REMOVED







1980'S (?) ERA ADDITON TO BE REMOVED - INCLUDES GARAGE AND MASTER SUITE





GARAGE INTERIOR





· Plan views assume walls have first layer of sheathing on each side (see typical sections) unless otherwise noted.

steps up form garage to house is challenging for everyday living



Version/Date: LAND USE PHOTOS 180316 04.09.18 Printed by: m.t. ADDITION / REMODEL WRIGHTS Page Size: <u>11 × 17</u>

Scale: as noted

Page/Drawing

2 of 9


MASTER SUITE INTERIOR

(electric baseboard heat, no AC, insufficient insulation to garage below, awkward and unsafe transition off staircase winder treads)





THE WAY IN WHICH THE 1980'S ERA ADDITON WAS ADDED TO THE HOUSE CREATED AN UNSAFE CONDITION AT THE EXISTING WINDER OF THE STAIRCASE







Version/Date: LAND USE PHOTOS 180316 04.09.18 Printed by: m.t. ADDITION / REMODEL SEWRIGHTS SSOCIATED Page <u>11 × 17</u> Size: Scale: as noted Page/Drawing of