

EXISTING CONDITIONS:

Street view looking west



Existing concrete walk and driveway



Looking north from street



Existing house and garage



South side of existing house (looking north)



EXISTING CONDITIONS:

North side of house (looking south)



Existing boathouse



Existing shore



Lakeshore
looking east



Lakeshore
looking west

Diseased Silver Maple Removed:



Accessory Building : To be converted to compliant ADU



South Elevation



East Elevation




West Elevation




North Elevation

EXISTING CONDITIONS: Interior of Existing House



Crawl space



Foundation crack

Accessory Building : To be converted to compliant ADU INTERIOR



Basement

1st Fl Utility

