






















# Cured-in-Place Pipe (CIPP) 2026 - Woodvale Dr/Ferris Ave/Marg St/Meredithe Ave/Timothy Ave/Fleetwood Ave/Woodvale Circle



-  Structure
  -  Property
  -  Site
  -  Failure
  -  Pressure Zone
- Valve**
-  Valve (Open)
  -  Valve (Closed)
  -  Valve in Manhole (Open)
  -  Valve in Manhole (Closed)
- FIRE HYDRANT**
-  4" HYDRANT
  -  5" HYDRANT
-  Service Lateral
  -  Water Main
  -  Water Main (Private)
  -  Water Main (Other Private)
  -  Madison City Boundary
-  Street Labels
  -  Primary Address (Text)
  -  Parcel (City of Madison)



Dane County Land Information Office (LIO), Fly Dane Partnership, Ayres Associates, Wisconsin Regional Orthoimagery Consortium (WROC)