



This is the front facing windows at 1014 Williamson Street.



2nd floor second from the left



2nd floor second from the right



3rd floor

It was extremely difficult to obtain close up photos of these windows. You can tell from this picture that there is wood rot below these windows.