

1014 Williamson Street Window Project

Unit 1:

Both windows in unit 1 are eastside facing windows. As you will see in the pictures that the bedroom window has 1 rope and the kitchen window has none. Both top sashes do not sit well. You can see in the pictures that the top sashes sit too low and do not line up with the bottom sashes. Therefore, neither window can be locked. Also, both bottom sashes sit a little crooked which in my opinion highlights the wear on the sides of the sashes. Unfortunately, the pictures could not show the tilt of the bottom sashes because of the top sashes not being seated properly either.