

LIMITED ASBESTOS AND LEAD SURVEY REPORT

CITY OF MADISON

**215 Martin Luther King, Jr. Blvd
Madison, WI**

A&A ENVIRONMENTAL NO. AA3743

**INSPECTION DATE: OCTOBER 12, 2014
REPORT DATE: NOVEMBER 8, 2014**

Submitted By:

**A&A Environmental, Inc.
N4381 US Hwy 51
Poynette, WI 53955
(608) 240-1511**

A & A Environmental, Inc.

N4381 US Hwy 51, Poynette, WI 53955

Phone: (608) 240-1511, Mobile Phone: (608) 576-4960, Fax: (608) 635-9717

Inspection

November 7, 2014

Bryan Cooper
City of Madison Engineering
210 MLK, Jr. Blvd., Room 115
Madison, WI 53703-3342
(608) 261-5533, Fax (608) 264-9275
bcooper@cintyofmadison.com

RE: 215 Martin Luther King, Jr. Blvd, Madison, WI

On October 12, 2014 through October 24, 2014 an asbestos inspection for renovation and XRF sampling for lead based paint was completed on Madison Municipal Building located at 215 Martin Luther King, Jr. Blvd in Madison, WI.

Asbestos Inspection

Bulk samples collected and analyzed for asbestos content by polarized light microscopy (PLM). The following building materials were reported > 1% asbestos or are assumed to contain RACM - Category I and Category II non-friable asbestos. These materials must be properly removed prior to renovation.

Lower Level

- Zoning
 - 388 fittings above the ceilings
- Public Exit
 - 158 fittings above the ceilings
- Planning Department Storage
 - 37 fittings above the ceilings
- Women's Restroom
 - 31 fittings above the ceilings
 - 40 fittings in the chase
- Men's Restroom
 - 58 fittings above the ceilings
 - 40 fittings in the chase
- Systems Furniture Storage
 - 39 fittings

Housekeeping
 38 fittings
 192 Sq Ft of 12 x 12 floor tile and mastic - Samples #128, 129

Housing Storage
 196 Sq Ft of 12 x 12 floor tile and mastic

B.I. Storage
 96 Sq Ft of 12 x 12 floor tile and mastic

Conference Room LL130
 22 fittings above the ceilings

Word Processing
 18 fittings above the ceilings
 396 Sq Ft of 12 x 12 floor tile and mastic under carpet - Samples #125,126

Maintenance Office and Break Room
 42 fittings above the ceilings
 192 Sq Ft of 12 x 12 floor tile and mastic - Samples #113, 114

Men's and Women's Restrooms Next to Elevator
 41 fittings in the walls

Water Meter Room
 21 fittings

Housekeeping Storage
 18 fittings

Maintenance Shop
 48 fittings
 Unknown amount in pipe chases - estimate 80 Lin Ft

Boiler Room
 197 fittings 6" OD or larger
 293 fittings less than 6" OD
 2 large tanks - 10 Ft x 30 Ft long, each
 2 expansion tanks - 2 Ft x 6 Ft long, each
 1 tank 4 Ft x 6 ft long
 Boiler insulation on 2 boilers - 394 Sq Ft each
 Refractory and gaskets (assumed), not quantified
 Boiler insulation on 1 boiler (assumed) - 270 Sq Ft
 Refractory and gaskets (assumed), not quantified
 Boiler breaching - 1,188 Sq Ft
 All electrical boxes (assumed), not quantified. Most have been replaced
 therefore most likely not going to contain asbestos when opened.

The heating plan shows heating lines running throughout the lower level. It appears the ACM has been removed from the heating lines and re-insulated with fiberglass and asbestos/non-asbestos insulating cement. A&A Environmental, Inc. was unable to verify all of the ACM was removed in the parameter walls. The quantities of pipe insulation and fittings on the lower level and first floor were quantified unless stated otherwise.

First Floor

Transportation

230 fittings above the ceilings

6,074 Sq Ft of yellow carpet mastic throughout the transportation area.

Sample # 104 was negative, sample #108 was reported to contain asbestos. Both types of mastic appear to be present throughout the transportation work space.

Wilson Street Corridor

198 Sq Ft of 12 x 12 floor tile and mastic - Samples #163, 164

32 Sq Ft above the entry door

Martin Luther King, Jr. Blvd Vestibule and Lobby

220 fittings above the ceilings

96 Sq Ft of transite above three entry doors

Traffic Engineering, Room 130

178 fittings above the ceilings

Doty Street Vestibule

32 Sq Ft of transite above the exterior door

37 fittings above the ceilings

Doty Street Stairs

6 fittings

Post Office Boxes and Corridor

60 Lin Ft of TSI

43 fittings above the ceilings

1,176 Sq Ft of 12 x 12 floor tile and mastic

Mailroom/Shipping and Receiving

196 fittings

2,670 Sq Ft of 12 x 12 floor tile and mastic

3 x 3 metal panel above the exterior door next to the dock

Mailroom Restrooms

49 fittings above ceilings and in the chases

US Post Office Lobby

97 fittings above the ceilings

Men's Restroom in Front of the Credit Union

43 fittings above the ceilings and in the chases

Women's Restroom in Front of the Credit Union

57 fittings above the ceilings and in the chases

Housing Unit

186 fittings above the ceilings

Black floor tile mastic appears to be only around columns and appears to be residue material under non-asbestos yellow mastic. Quantity is unknown - Samples #189,190

The heating plan shows heating lines running through the center of the first floor. It appears the ACM has been removed and replaced with fiberglass and asbestos/non-asbestos insulating cement. The ACM shown on the plan in the walls going to the second floor unit heaters in front of each window could not be verified. Estimate 840 Lin Ft and 420 fittings.

Second Floor

Room 202

456 Sq Ft of floor tile and mastic under carpet on wood
80 Lin Ft and 24 fittings of pipe insulation (assumed) in the walls
Window glazing and caulking on two metal framed windows -
Samples #13, 78

Room 203

600 Sq Ft of floor tile and mastic under carpet on wood
80 Lin Ft and 24 fittings of pipe insulation (assumed) in the walls
Window glazing and caulk on two metal framed windows

Room 205

462 Sq Ft of floor tile and mastic under carpet on wood
80 Lin Ft and 24 fittings of pipe insulation (assumed) in the walls
Window glazing and caulk on two metal framed windows

Room 206

220 Sq Ft of floor tile and mastic under carpet on wood
40 Lin Ft and 12 fittings of pipe insulation (assumed) in the walls
Window glazing and caulk on one metal framed window

Room 207

462 Sq Ft of floor tile and mastic under carpet on wood
80 Lin Ft and 24 fittings of pipe insulation (assumed) in the walls
Window glazing and caulk on two metal framed windows

Room 208

484 Sq Ft of floor tile and mastic under carpet on wood -
Samples #161, 162
80 Lin Ft and 24 fittings of pipe insulation (assumed) in the walls
Window glazing and caulk on two metal framed windows

Room 209

462 Sq Ft of floor tile and mastic under carpet on wood
80 Lin Ft and 24 fittings of pipe insulation (assumed) in the walls
Window glazing and caulk on two metal framed windows

Room 210

220 Sq Ft of floor tile and mastic under carpet on wood

Room 211

110 Sq Ft of floor tile and mastic under carpet on wood

Room 212

212 Sq Ft of floor tile and mastic under carpet on wood

Room 213

264 Sq Ft of floor tile and mastic under raised floor
40 Lin Ft and 12 fittings of pipe insulation (assumed) in the walls

Room 214

100 Sq Ft of floor tile and mastic under carpet on wood

Room 215

130 Sq Ft of floor tile and mastic under caret on wood
80 Lin Ft and 24 fittings of pipe insulation (assumed) in walls

Room 216

130 Sq Ft of floor tile and mastic under caret on wood

Room 218

40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls
Window glazing and caulk on one metal framed window

Room 220

40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls

Room 221

80 Lin Ft and 24 fittings of pipe insulation (assumed) in walls
589 Sq Ft of glue pods on ceiling - Sample #58
Window glazing and caulk on one metal framed window

Room 222

40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls

Room 223

80 Lin Ft and 24 fittings of pipe insulation (assumed) in walls
12 Lin Ft and 8 fittings of pipe insulation exposed
Window glazing and caulk on two metal framed windows

Room 224

40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls

Room 225

420 Sq Ft of floor tile and mastic under carpet on wood
80 Lin Ft and 24 fittings of pipe insulation (assumed) in walls

Room 226

80 Lin Ft and 24 fittings of pipe insulation (assumed) in walls
86 Lin Ft and 18 fittings of pipe insulation exposed

Room 230

140 Sq Ft of floor tile and mastic under carpet on wood

Room 232

165 Sq Ft of floor tile and mastic under carpet on wood
40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls

Room 233

209 Sq Ft of floor tile and mastic under carpet on wood
40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls
Window glazing and caulk on one metal framed window

Room 249

90 Lin Ft and 40 fittings on plumbing lines above the ceiling
40 Lin Ft on water lines in plumbing chase in the wall behind the door
40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls
Window glazing and caulk on one metal framed window

Room 260

Window glazing and caulk on ten metal framed windows

Room 270

90 Lin Ft and 31 fittings of pipe insulation above the ceiling
60 Lin Ft of insulation in plumbing chase
40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls
Window glazing and caulk on one metal framed window

Room 272

40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls
Window glazing and caulk on one metal framed window

Room 274B

40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls
Window glazing and caulk on one metal framed window

Room 278

18 Lin Ft of pipe insulation on heating lines

Room 279

40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls
Window glazing and caulk on two metal framed windows

Room 284

40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls
Window glazing and caulk on one metal framed window

Room 285

40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls
Window glazing and caulk on one metal framed window

Room 286

40 Lin Ft and 12 fittings of pipe insulation (assumed) in walls
Window glazing and caulk on one metal framed window

Third Floor

Room 300

1,512 Sq Ft of floor tile and mastic under carpet on wood
1,081 Sq Ft of ceiling glue pods
Window glazing and caulk on three metal framed windows

Room 301

464 Sq Ft of floor tile and mastic under carpet on wood
464 Sq Ft of ceiling glue pods
Window glazing and caulk on two metal framed windows

Room 302

256 Sq Ft of floor tile and mastic under carpet on wood
256 Sq Ft of ceiling glue pods

Room 302A

204 Sq Ft of floor tile and mastic under carpet on wood
204 Sq Ft of ceiling glue pods
Window glazing and caulk on one metal framed window

Room 302B

230 Sq Ft of floor tile and mastic under carpet on wood
230 Sq Ft of ceiling glue pods
Window glazing and caulk on one metal framed window

Room 302C

160 Sq Ft of floor tile and mastic under carpet on wood
160 Sq Ft of ceiling glue pods
Window glazing and caulk on one metal framed window

Room 303

418 Sq Ft of floor tile and mastic under carpet on wood
418 Sq Ft of ceiling glue pods

Room 304

273 Sq Ft of floor tile and mastic under carpet on wood
273 Sq Ft of ceiling glue pods
Window glazing and caulk on one metal framed window

Room 305

264 Sq Ft of floor tile and mastic under carpet on wood
264 Sq Ft of ceiling glue pods above drop in ceiling

Room 306

294 Sq Ft of floor tile and mastic under carpet on wood
294 Sq Ft of ceiling glue pods
Window glazing and caulk on one metal framed window

Room 307

Window glazing and caulk on one metal framed window

Room 308

256 Sq Ft of floor tile and mastic under carpet on wood
256 Sq Ft of ceiling glue pods
Window glazing and caulk on one metal framed window

Room 309

308 Sq Ft of floor tile and mastic under carpet on wood
308 Sq Ft of ceiling glue pods

Room 310

231 Sq Ft of floor tile and mastic under carpet on wood
231 Sq Ft of ceiling glue pods
Window glazing and caulk on one metal framed window

Room 312
399 Sq Ft of floor tile and mastic under carpet on wood
Window glazing and caulk on two metal framed windows

Room 314
210 Sq Ft of floor tile and mastic under carpet on wood
Window glazing and caulk on one metal framed window

Room 316
273 Sq Ft of floor tile and mastic under carpet on wood
Window glazing and caulk on one metal framed window

Room 317
60 Lin Ft of pipe insulation in pipe chase - unverified

Room 318
441 Sq Ft of floor tile and mastic under carpet on wood
Window glazing and caulk on two metal framed windows

Room 320
210 Sq Ft of floor tile and mastic under carpet on wood
Window glazing and caulk on one metal framed window

Room 322
210 Sq Ft of floor tile and mastic under carpet on wood
Window glazing and caulk on one metal framed window

Room 324
910 Sq Ft of floor tile and mastic under carpet on wood
Window glazing and caulk on two metal framed windows

Room 326
40 Sq Ft of pipe insulation in wall chase
Window glazing and caulk on one metal framed window

Room 328
Window glazing and caulk on one metal framed window

Room 330
Window glazing and caulk on one metal framed window

Room 332
414 Sq Ft of ceiling glue pods
Window glazing and caulk on one metal framed window

Room 334
638 Sq Ft of ceiling glue pods
Window glazing and caulk on two metal framed windows

Room 350
6 fittings on pipe insulation
Window glazing and caulk on two metal framed windows

Room 354
6 fittings on pipe insulation
Window glazing and caulk on one metal framed window

Elevator Doors

8 doors (assumed)

Penthouse

85 Lin Ft and 14 fittings of pipe insulation

Interstitial Space between Third Floor and Roof Access through Penthouse

280 Lin Ft and 35 fittings of pipe insulation

600 Sq Ft of clean up of broken pipe insulation

Fire Doors

Lower Level

Boiler Room - 4

Maintenance Office - 1

Stairway - 3

First Floor Stairway - 2

Second Floor Stairway - 2

Third Floor Stairway - 3

Penthouse - 1

All fire doors were assumed

Roof

506 Lin Ft of caulking on parapets, roof caps, and brick - Sample #04

Roofing material on the entire building

Ground Floor/Lower Level Exterior Caulking

414 Lin Ft of caulking on Wilson Street stairs and walls beside the stairs -

Sample #171

Exterior Door Frame Caulking

156 Lin Ft of door frame caulking on entrance doors, one on Wilson Street, three on Martin Luther King, Jr. Blvd, and one on Doty Street

20 Lin Ft on Post Office overhead door frame facing Pinckney Street

There is black material on the maintenance storage room wall of the lower level annex.

A&A Environmental, Inc. was unable to collect a bulk sample from this material.

There are several pipe chases noted on the drawings without access. Once the building is vacated more investigation needs to be completed. This also holds true for the supply lines going to the heating units in front of each window.

The following building materials tested <1% asbestos by PLM 400 point count:

None

The following building materials were bulk sampled and reported as no asbestos detected:

- White/gray roof insulation mastic
- Roof caulking
- Caulking on ductwork
- Exterior stucco - topcoat/basecoat
- Gray window caulking
- Ductwork vibration dampers
- Black caulking on metal window frames
- White wall paint
- Tan wall paint
- Topcoat plaster
- Basecoat plaster
- Drywall
- Drywall compound
- Ceramic floor tile grout
- Yellow carpet mastic - except first floor traffic
- Floor leveler
- 12 x 12 ceiling tiles
- 2 x 2 ceiling tiles
- 2 x 4 ceiling tiles
- Black/dark brown vinyl flooring
- Yellow vinyl floor mastic
- Black vinyl flooring mastic
- Green carpet mastic
- Base cove
- Yellow/brown base cove mastic
- Ceramic wall tile grout
- Ceramic wall tile glue
- Ceramic wall tile thinset
- Ceramic floor tile thinset
- Sheet vinyl
- Gray sink mastic
- Gray duct sealer
- Clear carpet mastic
- Vapor barrier under floor tile on second floor
- Clay wall bricks
- Window glazing on internal windows
- Red fire stop material
- Tuff bond on stick clips on annex ceilings
- Black tar on wall in lower level annex
- Stair treads
- Stair tread mastic
- Brown exterior caulking in lower level, first, second, and third floors


XRF Sampling for Lead in Paint

As a result of the XRF sampling only the previously renovated areas of the building should be considered for renovation without using lead safe work practices. Once the newer construction materials are removed the original plaster will be exposed requiring lead safe work practices.

A&A Environmental Inc.'s inspectors are only able to inspect open, safe, and accessible areas inside and outside of the building. Inaccessible suspect material may be hidden throughout this building. Any additional suspect materials discovered during the course of abatement/demolition/remodeling must be assumed to be ACM until sampled by and EPA/State of Wisconsin certified asbestos inspector and proven negative.

If you have any questions concerning this report or the sampling performed please feel free to contact me.

Sincerely,

A handwritten signature in black ink, appearing to read "Kim Sopha", with a stylized flourish at the end.

Kim Sopha
President/Inspector #AII01851

Encl

KAS/bls

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: A & A ENVIRONMENTAL, INC. Job# / P.O. #: 3743
Address: N4381 US HWY 51 Date Received: 10/22/2014
POYNETTE WI 53955 Date Analyzed: 10/27/2014
Collected: 10/21/2014 Date Reported: 10/27/2014
Project Name: 215 MARTIN LUTHER KING JR. BLVD EPA Method: EPA 600/R-93/116
Address: Submitted By: KIM SOPHA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-001 1	ROOF	Roof Insulation Mastic, White	No	None Detected	Gypsum Quartz Binder/Filler 100%
0147811-002 2	ROOF	Roof Insulation Mastic, Gray/ Silver	No	None Detected	Gypsum Quartz Mica Binder/Filler 100%
0147811-003 3	ON TOP OF ROOF DUCTS	Roof Duct Caulk, White/ Gray	No	None Detected	Gypsum Carbonates Binder/Filler 100%
0147811-004 4	CHIMNEY & PARAPETS	Parapet Caulking, White/ Gray	Yes	Chrysotile 3%	Carbonates Quartz Binder/Filler 97%
0147811-005 5	PENTHOUSE	Ext. Stucco-Top Coat, Lt. Gray	No	None Detected	Synthetic Fiber <1% Carbonates Quartz Mica Binder/Filler 99%
0147811-006 6	PENTHOUSE	Ext. Stucco-Base Coat, Gray	No	None Detected	Cellulose Fiber 1% Carbonates Quartz Mica Binder/Filler 99%
0147811-007 7	PENTHOUSE	Window Caulk, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/22/2014
	POYNETTE WI 53955	Date Analyzed:	10/27/2014
Collected:	10/21/2014	Date Reported:	10/27/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-008 8	TOP OF PARAPETS	Parapet Caulking, Gray	No	None Detected	Carbonates Binder/Filler 100%
0147811-009 9	DOOR FRAME	Door Frame Caulk, White	No	None Detected	Silicone Binder/Filler 100%
0147811-010 10	PENTHOUSE	Duct Work Flex Joint, Tan	No	None Detected	Cellulose Fiber Carbonates 95% 5%
0147811-011 11	METAL FRAMED WINDOWS 3RD FL	LAYER 1 Window Frame Caulk, White	No	None Detected	Carbonates Quartz Binder/Filler 100%
		LAYER 2 Window Frame Caulk, Lt. Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
0147811-012 12	METAL FRAMED WINDOWS 3RD FL	Window Glazing, Black	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler 3% 97%
0147811-013 13	3RD FL (SOFT)	Window Caulking, Gray	Yes	Chrysotile 3%	Carbonates Quartz Binder/Filler 97%
0147811-014 14	3RD FL HALL	Wall Plaster-Top Coat, White/ Off White	No	None Detected	Carbonates Gypsum Quartz Mica Binder/Filler 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/22/2014
	POYNETTE WI 53955	Date Analyzed:	10/27/2014
Collected:	10/21/2014	Date Reported:	10/27/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-015 15	3RD FL HALL	Wall Plaster-Base Coat, Off White	No	None Detected	Cellulose Fiber <1% Gypsum Quartz Carbonates Mica Binder/Filler 99%
0147811-016 16	3RD FL HALL	Ceramic Floor Tile Grout, Black	No	None Detected	Cellulose Fiber 2% Carbonates Quartz Binder/Filler 98%
0147811-017 17	3RD FL HALL	Metal Window Frame Paint, Gray/ Green/ Red	No	None Detected	Carbonates Quartz Binder/Filler 100%
0147811-018 18	RM 302C	Carpet Mastic, Yellow	No	None Detected	Synthetic Fiber <1% Carbonates Quartz Binder/Filler 99%
0147811-019 19	RM 302C	Floor Leveler, Tan	Yes	Chrysotile 3%	Cellulose Fiber 1% Carbonates Mica Quartz Binder/Filler 96%
0147811-020 20	RM 302C	12"x12" Ceiling Tile, Beige	No	None Detected	Mineral Wool 50% Cellulose Fiber 45% Gypsum Binder/Filler 5%
0147811-021 21	RM 302C	Glue Pods, Brown	Yes	Chrysotile 5%	Carbonates Gypsum Quartz Binder/Filler 95%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/22/2014
	POYNETTE WI 53955	Date Analyzed:	10/27/2014
Collected:	10/21/2014	Date Reported:	10/27/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-022 22	POST OFFICE LOBBY	2x2 Ceiling Tile, Off White/ Lt. Gray	No	None Detected	Mineral Wool 85% Gypsum Carbonates Quartz Binder/Filler 15%
0147811-023 23	POST OFFICE LOBBY	12"x12" Floor Tile, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
0147811-024 24	POST OFFICE LOBBY	Floor Tile Mastic, Black	No	None Detected	Cellulose Fiber <1% Carbonates Quartz Binder/Filler 99%
0147811-025 25	POST OFFICE LOBBY	Carpet Mastic, Green	No	None Detected	Synthetic Fiber 2% Carbonates Quartz Binder/Filler 98%
0147811-026 26	POST OFFICE LOBBY	Floor Leveler, Gray/ Tan	No	None Detected	Carbonates Quartz Mica Binder/Filler 100%
0147811-027 27	POST OFFICE LOBBY	Drywall, White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 3% Gypsum Carbonates Mica 87%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: A & A ENVIRONMENTAL, INC. Job# / P.O. #: 3743
Address: N4381 US HWY 51 Date Received: 10/22/2014
POYNETTE WI 53955 Date Analyzed: 10/27/2014
Collected: 10/21/2014 Date Reported: 10/27/2014
Project Name: 215 MARTIN LUTHER KING JR. BLVD EPA Method: EPA 600/R-93/116
Address: Submitted By: KIM SOPHA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-028 28	POST OFFICE LOBBY	Drywall Compound, White	No	None Detected	Cellulose Fiber <1% Carbonates Perlite Mica Binder/Filler 99%
0147811-029 29	POST OFFICE LOBBY	Caulking, Yellow	No	None Detected	Carbonates Binder/Filler 100%
0147811-030 30	POST OFFICE PO BOXES	2x2 Ceiling Tile, White/ Gray/ Mauve	No	None Detected	Mineral Wool 60% Cellulose Fiber 20% Carbonates Perlite Binder/Filler 20%
0147811-031 31	PO BOX AREA	12"x12" Floor Tile, Off White	Yes	Chrysotile 3%	Carbonates Quartz Binder/Filler 97%
0147811-032 32	PO BOX AREA	Mastic, Black	Yes	Chrysotile 8%	Cellulose Fiber 2% Carbonates Binder/Filler 90%
0147811-033 33	PO BOX AREA	Basecove, Black	No	None Detected	Carbonates Quartz Binder/Filler 100%
0147811-034 34	PO BOX AREA	Basecove Mastic, Yellow	No	None Detected	Cellulose Fiber 1% Carbonates Quartz Binder/Filler 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: A & A ENVIRONMENTAL, INC. Job# / P.O. #: 3743
Address: N4381 US HWY 51 Date Received: 10/22/2014
POYNETTE WI 53955 Date Analyzed: 10/27/2014
Collected: 10/21/2014 Date Reported: 10/27/2014
Project Name: 215 MARTIN LUTHER KING JR. BLVD EPA Method: EPA 600/R-93/116
Address: Submitted By: KIM SOPHA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-035 35	PO BOX AREA	Drywall, White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 3% Gypsum Carbonates Mica 87%
0147811-036 36	PO BOX AREA	Drywall Compound, White	No	None Detected	Carbonates Perlite Mica Binder/Filler 100%
0147811-037 37	WOMEN'S BATHRM POST OFFICE MAIL RM	Ceramic Wall Tile Grout, White	No	None Detected	Carbonates Quartz Gypsum Binder/Filler 100%
0147811-038 38	WOMEN'S BATHRM POST OFFICE MAIL RM	Ceramic Wall Tile Glue, Yellow	No	None Detected	Cellulose Fiber <1% Gypsum Quartz Carbonates Binder/Filler 99%
0147811-039 39	WOMEN'S BATHRM POST OFFICE MAIL RM	Ceramic Floor Tile Grout/Thin Set, Black	No	None Detected	Cellulose Fiber 2% Carbonates Quartz Binder/Filler 98%
0147811-040 40	3RD FL HALL WAITING RM	12"x12" Floor Tile, White/ Black	No	None Detected	Carbonates Quartz Binder/Filler 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/22/2014
	POYNETTE WI 53955	Date Analyzed:	10/27/2014
Collected:	10/21/2014	Date Reported:	10/27/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-041 41	3RD FL HALL WAITING RM	Floor Tile Mastic, Black	No	None Detected	Cellulose Fiber 5% Carbonates Binder/Filler 95%
0147811-042 42	RM 317	Sheet Vinyl, Gray/ Yellow/ Black	No	None Detected	Carbonates Quartz Binder/Filler 100%
0147811-043 43	RM 317	Sheet Vinyl Mastic, Yellow	No	None Detected	Cellulose Fiber 5% Carbonates Quartz Binder/Filler 95%
0147811-044 44	RM 317	Basecove, Brown	No	None Detected	Carbonates Quartz Binder/Filler 100%
0147811-045 45	RM 317	Basecove Mastic, Yellow	No	None Detected	Cellulose Fiber 3% Carbonates Quartz Binder/Filler 97%
0147811-046 46	RM 317	Drywall, White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Carbonates Mica 88%
0147811-047 47	RM 317	Drywall Compound, White	No	None Detected	Cellulose Fiber <1% Carbonates Mica Quartz Binder/Filler 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/22/2014
	POYNETTE WI 53955	Date Analyzed:	10/27/2014
Collected:	10/21/2014	Date Reported:	10/27/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-048 48	RM 317	Wall Plaster-Top Coat, White	No	None Detected	Carbonates Gypsum Mica Binder/Filler 100%
0147811-049 49	RM 317	Wall Plaster-Base Coat, Off White Note: Very small amount of Base Coat	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates Binder/Filler 99%
0147811-050 50	RM 321-BRAKE RM	Sink Mastic, Gray	No	None Detected	Cellulose Fiber Carbonates Mica Quartz Binder/Filler 88%
0147811-051 51	RM 321	Int./Ext. Window Caulking, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
0147811-052 52	RM 334	LAYER 1 Glue Pod, Brown	Yes	Chrysotile 4%	Cellulose Fiber Carbonates Quartz Binder/Filler 95%
		LAYER 2 Coating, Beige	No	None Detected	Carbonates Quartz Binder/Filler 100%
0147811-053 53	RM 334	Ceiling Tile 12"x12", Beige	No	None Detected	Cellulose Fiber Mineral Wool Carbonates Perlite Binder/Filler 45% 40% 15%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: A & A ENVIRONMENTAL, INC. Job# / P.O. #: 3743
Address: N4381 US HWY 51 Date Received: 10/22/2014
POYNETTE WI 53955 Date Analyzed: 10/27/2014
Collected: 10/21/2014 Date Reported: 10/27/2014
Project Name: 215 MARTIN LUTHER KING JR. BLVD EPA Method: EPA 600/R-93/116
Address: Submitted By: KIM SOPHA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-054 54	RM 334	Carpet Mastic, Tan	No	None Detected	Synthetic Fiber 1% Carbonates Quartz Binder/Filler 99%
0147811-055 55	RM 332	Window Glazing, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%
0147811-056 56	RM 308	2x4 Ceiling Tile, Brown	No	None Detected	Cellulose Fiber 90% Gypsum Binder/Filler 10%
0147811-057 57	RM 221	12"x12" Ceiling Tile, Beige	No	None Detected	Mineral Wool 50% Cellulose Fiber 30% Gypsum Carbonates Binder/Filler 20%
0147811-058 58	RM 221	Glue Pod, Brown	Yes	Chrysotile 3%	Carbonates Quartz Binder/Filler 97%
0147811-059 59	RM 221	Sheet Flooring, Lt. Brown/ White/ Black	No	None Detected	Carbonates Binder/Filler 100%
0147811-060 60	RM 221	Mastic, Yellow	No	None Detected	Cellulose Fiber <1% Carbonates Quartz Binder/Filler 99%
0147811-061 61	RM 219	Cove Base, Black	No	None Detected	Carbonates Quartz Binder/Filler 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/22/2014
	POYNETTE WI 53955	Date Analyzed:	10/27/2014
Collected:	10/21/2014	Date Reported:	10/27/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-062 62	RM 219	Cove Base Mastic, Tan	No	None Detected	Cellulose Fiber <1% Carbonates Quartz Binder/Filler 99%
0147811-063 63	RM 222	Wall Plaster-Top Coat, White	No	None Detected	Carbonates Gypsum Quartz Mica Binder/Filler 100%
0147811-064 64	RM 222	Wall Plaster-Base Coat, Lt. Gray/ Tan	No	None Detected	Cellulose Fiber <1% Gypsum Quartz Carbonates Mica Binder/Filler 99%
0147811-065 65	RM 210	2x2 Ceiling Tile, White	No	None Detected	Mineral Wool 50% Cellulose Fiber 30% Carbonates Perlite Binder/Filler 20%
0147811-066 66	RM 210	Drywall, White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Carbonates Mica 88%
0147811-067 67	RM 210	Drywall Compound, White	No	None Detected	Carbonates Mica Binder/Filler 100%
0147811-068 68	RM 210	Duct Sealer, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: A & A ENVIRONMENTAL, INC. Job# / P.O. #: 3743
Address: N4381 US HWY 51 Date Received: 10/22/2014
POYNETTE WI 53955 Date Analyzed: 10/27/2014
Collected: 10/21/2014 Date Reported: 10/27/2014
Project Name: 215 MARTIN LUTHER KING JR. BLVD EPA Method: EPA 600/R-93/116
Address: Submitted By: KIM SOPHA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-069 69	RM 213	Floor Leveler/Floor Tile, Gray/ Tan Note: Sample appears to be Floor Tile	Yes	Chrysotile 5%	Carbonates Quartz Binder/Filler 95%
0147811-070 70	RM 213	Tar Material, Black Note: Sample appears to be Vapor Barrier	No	None Detected	Cellulose Fiber 50% Synthetic Fiber 10% Gypsum Carbonates Binder/Filler 40%
0147811-071 71	RM 260	Carpet Mastic, Yellow/ Clear	No	None Detected	Mineral Wool 3% Carbonates Gypsum Quartz Binder/Filler 97%
0147811-072 72	RM 260	Clay Wall Brick, Orange	No	None Detected	Gypsum Quartz Binder/Filler 100%
0147811-073 73	RM 226	2x4 Ceiling Tile, Tan	No	None Detected	Cellulose Fiber 40% Mineral Wool 40% Gypsum Perlite Binder/Filler 20%
0147811-074 74	RM 288	Wall Plaster-Top Coat, White	No	None Detected	Cellulose Fiber <1% Gypsum Mica Quartz Carbonates Binder/Filler 99%
0147811-075 75	RM 288	Wall Plaster-Base Coat, Lt. Gray/ Tan	No	None Detected	Cellulose Fiber <1% Gypsum Quartz Carbonates Mica 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/22/2014
	POYNETTE WI 53955	Date Analyzed:	10/27/2014
Collected:	10/21/2014	Date Reported:	10/27/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-076 76	RM 286	Wall Drywall, White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 3% Gypsum Mica Carbonates Quartz 87%
0147811-077 77	RM 286	Wall Drywall Compound, White	No	None Detected	Gypsum Carbonates Mica Perlite Binder/Filler 100%
0147811-078 78	RM 272	Window Glazing, Beige/ White	Yes	Chrysotile 5%	Carbonates Quartz Binder/Filler 95%
0147811-079 79	RM 272	Window Frame Caulk, Black	No	None Detected	Gypsum Quartz Carbonates Binder/Filler 100%
0147811-080 80	OFFICE & MEETING RM CU	2x2 Ceiling Tile, White/ Beige	No	None Detected	Cellulose Fiber 50% Mineral Wool 30% Gypsum Perlite Binder/Filler 20%
0147811-081 81	OFFICE & MEETING RM CU	Wall Drywall, White/ Brown	No	None Detected	Cellulose Fiber 10% Fibrous Glass 2% Gypsum Carbonates Mica Quartz 88%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/22/2014
	POYNETTE WI 53955	Date Analyzed:	10/27/2014
Collected:	10/21/2014	Date Reported:	10/27/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-082 82	CU	Wall Drywall Compound, White	No	None Detected	Carbonates Mica Quartz Binder/Filler 100%
0147811-083 83	CU	Carpet Mastic, Yellow	No	None Detected	Synthetic Fiber Gypsum Carbonates Binder/Filler 99%
0147811-084 84	CU	Cove Base Mastic, Brown	No	None Detected	Cellulose Fiber Gypsum Quartz Binder/Filler 99%
0147811-085 85	CU	Cove Base, Black	No	None Detected	Carbonates Gypsum Binder/Filler 100%
0147811-086 86	CU	Internal Window Glazing, Black	No	None Detected	Wollastonite Cellulose Fiber Carbonates Gypsum Binder/Filler 3% 2% 95%
0147811-087 87	LOBBY RM 125 CU	Vinyl Flooring, Black	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
0147811-088 88	LOBBY RM 125 CU	Vinyl Glue, Yellow/ Clear	No	None Detected	Talc Gypsum Quartz Carbonates Binder/Filler 5% 95%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: A & A ENVIRONMENTAL, INC. Job# / P.O. #: 3743
Address: N4381 US HWY 51 Date Received: 10/22/2014
POYNETTE WI 53955 Date Analyzed: 10/27/2014
Collected: 10/21/2014 Date Reported: 10/27/2014
Project Name: 215 MARTIN LUTHER KING JR. BLVD EPA Method: EPA 600/R-93/116
Address: Submitted By: KIM SOPHA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-089	LOBBY RM 125 CU	Floor Leveler, Off White	No	None Detected	Gypsum Quartz Binder/Filler 100%
0147811-090	RM 135	2x2 Ceiling Tile, White/ Beige	No	None Detected	Mineral Wool 45% Cellulose Fiber 40% Perlite Gypsum Binder/Filler 15%
0147811-091	RM 135	Wall Drywall, White/ Brown	No	None Detected	Cellulose Fiber 10% Gypsum Carbonates Mica Quartz 90%
0147811-092	RM 135	Wall Drywall Compound, White	No	None Detected	Cellulose Fiber <1% Gypsum Quartz Carbonates Binder/Filler 99%
0147811-093	RM 135	Carpet Mastic, Yellow	No	None Detected	Fibrous Glass 2% Gypsum Carbonates Quartz Binder/Filler 98%
0147811-094	MAIN LOBBY OFF MLK	Ceiling Drywall, White/ Brown	No	None Detected	Cellulose Fiber 10% Gypsum Carbonates Quartz 90%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report

0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/22/2014
	POYNETTE WI 53955	Date Analyzed:	10/27/2014
Collected:	10/21/2014	Date Reported:	10/27/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-095 95	MAIN LOBBY OFF MLK	Ceiling Drywall Compound, White	No	None Detected	Cellulose Fiber <1% Gypsum Quartz Carbonates Binder/Filler 99%
0147811-096 96	RM 136	Sink Mastic, Black	No	None Detected	Cellulose Fiber <1% Gypsum Quartz Binder/Filler 99%
0147811-097 97	RM 130	Ceramic Tile Grout/ Thin Set, Beige	No	None Detected	Carbonates Quartz Gypsum Binder/Filler 100%
0147811-098 98	RM 130	2x4 Ceiling Tile, White/ Beige	No	None Detected	Mineral Wool 50% Cellulose Fiber 35% Carbonates Perlite Quartz Binder/Filler 15%
0147811-099 99	RM 100	2x4 Ceiling Tile, White/ Beige	No	None Detected	Cellulose Fiber 50% Mineral Wool 30% Carbonates Perlite Binder/Filler 20%
0147811-100 104		Carpet Mastic, Yellow/ Black	No	None Detected	Synthetic Fiber 1% Cellulose Fiber <1% Gypsum Quartz Carbonates Binder/Filler 98%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/22/2014
	POYNETTE WI 53955	Date Analyzed:	10/27/2014
Collected:	10/21/2014	Date Reported:	10/27/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-101 105		Wall Drywall, White/ Brown	No	None Detected	Cellulose Fiber 10% Gypsum Carbonates Quartz 90%
0147811-102 106	RM 100	Wall Plaster-Top Coat, White	No	None Detected	Gypsum Quartz Carbonates Binder/Filler 100%
0147811-103 107	RM 100	Wall Plaster-Base Coat, Lt. Gray/ Tan	No	None Detected	Cellulose Fiber <1% Gypsum Quartz Carbonates Binder/Filler 99%
0147811-104 108		Carpet Mastic, Yellow/ Black	Yes	Chrysotile 3%	Synthetic Fiber 1% Gypsum Carbonates Quartz Binder/Filler 96%
0147811-105 109		Wall Drywall, White/ Brown	No	None Detected	Cellulose Fiber 10% Gypsum Carbonates Mica Quartz Binder/Filler 90%
0147811-106 110		Wall Plaster-Top Coat, White	No	None Detected	Gypsum Quartz Carbonates Binder/Filler 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report

0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: A & A ENVIRONMENTAL, INC. Job# / P.O. #: 3743
Address: N4381 US HWY 51 Date Received: 10/22/2014
POYNETTE WI 53955 Date Analyzed: 10/27/2014
Collected: 10/21/2014 Date Reported: 10/27/2014
Project Name: 215 MARTIN LUTHER KING JR. BLVD EPA Method: EPA 600/R-93/116
Address: Submitted By: KIM SOPHA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-107 111		Wall Plaster-Base Coat, Lt. Gray/ Tan	No	None Detected	Cellulose Fiber <1% Gypsum Quartz Carbonates Mica 99%
0147811-108 112	RM 100	TSI Filling, Gray	No	None Detected	Mineral Wool 50% Gypsum Quartz Carbonates 50%
0147811-109 113	MAINTENACE OFFICE LL	12"x12" Floor Tile, Beige/ Brown	Yes	Chrysotile 3%	Carbonates Quartz Binder/Filler 97%
0147811-110 114	MAINTENACE OFFICE LL	Floor Tile Mastic, Black	Yes	Chrysotile 4%	Cellulose Fiber 3% Carbonates Gypsum Quartz Binder/Filler 93%
0147811-111 115	MAINTENACE OFFICE LL	2x2 Ceiling Tile, White/ Beige	No	None Detected	Mineral Wool 60% Cellulose Fiber 20% Carbonates Perlite Quartz Binder/Filler 20%
0147811-112 116	MAINTENACE OFFICE LL	Wall Drywall, White/ Brown	No	None Detected	Cellulose Fiber 10% Gypsum Carbonates Quartz 90%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report

0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: A & A ENVIRONMENTAL, INC. Job# / P.O. #: 3743
Address: N4381 US HWY 51 Date Received: 10/22/2014
POYNETTE WI 53955 Date Analyzed: 10/27/2014
Collected: 10/21/2014 Date Reported: 10/27/2014
Project Name: 215 MARTIN LUTHER KING JR. BLVD EPA Method: EPA 600/R-93/116
Address: Submitted By: KIM SOPHA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-113 117	MAINTENACE OFFICE LL	Wall Plaster, Gray	No	None Detected	Cellulose Fiber <1% Gypsum Quartz Carbonates Binder/Filler 99%
0147811-114 118	MAINTENACE OFFICE LL	TSI Filling, Off White	Yes	Chrysotile 10%	Mineral Wool 40% Gypsum Diatoms Quartz 50%
0147811-115 119	LL	Stair Tread, Black	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
0147811-116 120	LL	Mastic, Tan	No	None Detected	Gypsum Quartz Binder/Filler 100%
0147811-117 121	LL	Boiler Insulation, Lt. Gray	Yes	Chrysotile 20%	Mineral Wool 5% Gypsum Diatoms Quartz 75%
0147811-118 122	WORD PROCESSING LL	12"x12" Ceiling Tile, Tan	No	None Detected	Mineral Wool 50% Cellulose Fiber 35% Carbonates Gypsum Binder/Filler 15%
0147811-119 123	WORD PROCESSING LL	Glue Pods, Brown	Yes	Chrysotile 3%	Mineral Wool 1% Gypsum Quartz Binder/Filler 96%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/22/2014
	POYNETTE WI 53955	Date Analyzed:	10/27/2014
Collected:	10/21/2014	Date Reported:	10/27/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147811-120 124	WORD PROCESSING LL	Carpet Mastic, Clear	No	None Detected	Synthetic Fiber <1% Carbonates Quartz Binder/Filler 99%
0147811-121 125	WORD PROCESSING LL	12"x12" Floor Tile, Off White	Yes	Chrysotile 3%	 Carbonates Quartz Gypsum Binder/Filler 97%
0147811-122 126	WORD PROCESSING LL	Floor Tile Mastic, Black	Yes	Chrysotile 5%	Cellulose Fiber 1% Carbonates Gypsum Quartz Binder/Filler 94%
0147811-123 127	ZONING LL	Carpet Mastic, Yellow	No	None Detected	Synthetic Fiber 1% Carbonates Gypsum Quartz Binder/Filler 99%
0147811-124 128	HOUSING STORAGE LL	12"x12" Floor Tile, White/ Beige	Yes	Chrysotile 3%	 Carbonates Quartz Gypsum Binder/Filler 97%
0147811-125 129	HOUSING STORAGE LL	Floor Tile Mastic, Black	Yes	Chrysotile 5%	 Carbonates Gypsum Binder/Filler 95%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147811

Bulk Asbestos Analysis by Polarized Light Microscopy


NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/22/2014
	POYNETTE WI 53955	Date Analyzed:	10/27/2014
Collected:	10/21/2014	Date Reported:	10/27/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID	Sample	Layer Name /	Asbestos	Asbestos Type	Non-Asbestos
Client ID	Location	Sample Description	Detected	(%)	Constituents



Analyst - Kurt Kettler



Signatory - Lab Manager - Ken Scheske

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicated or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY

EMC Labs, Inc.

9830 S. 51st., Ste B-109

Phoenix, AZ 85044

(800) 362-3373 Fax (480) 893-1726

LAB#: 147811

TAT: 3 day

Rec'd: OCT 22 P.M.

COMPANY NAME: A & A ENVIRONMENTAL INC.

BILL TO: (If Different Location)

N4381 US Hwy 51

Poynette, WI 53955

CONTACT: Kim Sopha **Scan & Email COC**

Phone/Fax: (608) 576-4960 / (608) 635-9717

Email: blsopha@aol.com, aaenvinc@aol.com, rsopha@aaenv.com

Now Accepting: VISA – MASTERCARD

Price Quoted: \$ / Sample \$ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. TURNAROUND TIME: [Same Day RUSH] [1-Day] [2-Day] (3-4-5-Day) [6-10 Day]

****Prior confirmation of turnaround time is required

****Additional charges for rush analysis (please call marketing department for pricing details)

****Laboratory analysis may be subject to delay if credit terms are not met.

2. TYPE OF ANALYSIS: ☒ [Bulk-PLM] ☐ [Air-PCM] ☐ [Lead] ☐ [Point Count] ☐ [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. DISPOSAL INSTRUCTIONS: [Dispose of samples at EMC] / [Return samples to me at my expense]

(If you do not indicate preference, EMC will dispose of samples 30 days from analysis.)

4. Project Name: 215 Martin Luther King Jr Blvd

P.O. Number: _____ Project Number: 3742

[illegible]

SPECIAL INSTRUCTIONS: Point Count if <1% or trace unless otherwise specified on COC

Sample Collector: (Print) _____ (Signature) _____

Relinquished by: _____ Date/Time: _____ Received by: Diana Fedeyko Date/Time: 10/22/14

Relinquished by: Diana Federico Date/Time: 10/22/14 Received by: [Signature] Date/Time: 10/24/14

Relinquished by: _____ Date/Time: _____ Received by: 104 EV Date/Time: 1/1

**** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.**

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report

0147874

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/23/2014
	POYNETTE WI 53955	Date Analyzed:	10/28/2014
Collected:	10/22/2014	Date Reported:	10/28/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147874-001 136	STAFF BREAK RM- LL	Base Cove, Black	No	None Detected	Gypsum Quartz Binder/Filler 100%
0147874-002 137	STAFF BREAK RM- LL	Base Cove Mastic, Lt. Brown	No	None Detected	Cellulose Fiber <1% Gypsum Quartz Binder/Filler 99%
0147874-003 138	MEN'S BATHRM EAST-LL	Plaster-Base Coat, Lt. Gray	No	None Detected	Cellulose Fiber <1% Gypsum Quartz Carbonates Mica 99%
0147874-004 139	MEN'S BATHRM EAST-LL	Plaster-Top Coat, White/ Lt. Gray	No	None Detected	Gypsum Carbonates Quartz Binder/Filler 100%
0147874-005 140	MEN'S BATHRM EAST-LL	TSI Fitting Insulation, Lt. Gray	No	None Detected	Mineral Wool 35% Gypsum Diatoms Quartz 65%
0147874-006 141	MEN'S BATHRM EAST-LL	Ceramic Wall Tile Grout, White	No	None Detected	Carbonates Quartz Binder/Filler 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147874

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: A & A ENVIRONMENTAL, INC. Job# / P.O. #: 3743
Address: N4381 US HWY 51 Date Received: 10/23/2014
POYNETTE WI 53955 Date Analyzed: 10/28/2014
Collected: 10/22/2014 Date Reported: 10/28/2014
Project Name: 215 MARTIN LUTHER KING JR. BLVD EPA Method: EPA 600/R-93/116
Address: Submitted By: KIM SOPHA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147874-007 142	MEN'S BATHRM EAST-LL	Ceramic Wall Tile Mastic, Tan	No	None Detected	Gypsum Carbonates Quartz Binder/Filler 100%
0147874-008 143	CEILING OF CORRIDOR PUBLIC EXIT-LL	Tuf Bond Mastic, Gray	No	None Detected	Synthetic Fiber 5% Gypsum Binder/Filler 95%
0147874-009 144	FIRE STOP MATERIAL CORRIDOR PUBLIC EXIT-LL	Fire Stop Material, Red/ Brown	No	None Detected	Fibrous Glass 20% Gypsum Binder/Filler 80%
0147874-010 145	EOC WAITING RM- LL	Drywall, White/ Brown	No	None Detected	Cellulose Fiber 12% Gypsum Mica Carbonates 88%
0147874-011 146	EOC WAITING RM- LL	Drywall Compound, White/ Off White	No	None Detected	Carbonates Mica Quartz Binder/Filler 100%
0147874-012 147	CONFERENCE RM LL 110	Duct Sealer, Gray	No	None Detected	Fibrous Glass 15% Carbonates Gypsum Quartz Binder/Filler 85%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report

0147874

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/23/2014
	POYNETTE WI 53955	Date Analyzed:	10/28/2014
Collected:	10/22/2014	Date Reported:	10/28/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147874-013 148	ON WALL MAINT STORAGE-LL	Tar Material, Black	No	None Detected	Gypsum Binder/Filler 100%
0147874-014 149	ON CEILING MAINT STORAGE-LL	Tar Material, Black	No	None Detected	Gypsum Binder/Filler 100%
0147874-015 150	CORRIDOR PUBLIC EXIT-LL	Vinyl Flooring, Black	No	None Detected	Cellulose Fiber 5% Gypsum Quartz Binder/Filler 95%
0147874-016 151	CORRIDOR PUBLIC EXIT-LL	Mastic, Yellow	No	None Detected	Wollastonite 5% Carbonates Gypsum Binder/Filler 95%
0147874-017 152	LL	Floor Leveling Material, White	No	None Detected	Gypsum Quartz Binder/Filler 100%
0147874-018 153	RM 301	12"x12" Floor Tile, Tan	Yes	Chrysotile 3%	Carbonates Gypsum Quartz Binder/Filler 97%
0147874-019 154	RM 301	Carpet Mastic, Yellow	No	None Detected	Synthetic Fiber <1% Gypsum Carbonates Quartz Binder/Filler 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147874

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: A & A ENVIRONMENTAL, INC. Job# / P.O. #: 3743
Address: N4381 US HWY 51 Date Received: 10/23/2014
POYNETTE WI 53955 Date Analyzed: 10/28/2014
Collected: 10/22/2014 Date Reported: 10/28/2014
Project Name: 215 MARTIN LUTHER KING JR. BLVD EPA Method: EPA 600/R-93/116
Address: Submitted By: KIM SOPHA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147874-020 155	RM 301	Floor Tile Mastic, Black	No	None Detected	Cellulose Fiber 5% Carbonates Gypsum Quartz Binder/Filler 95%
0147874-021 156	RM 301	Tar Paper, Black	No	None Detected	Cellulose Fiber 60% Synthetic Fiber 6% Gypsum Binder/Filler 34%
0147874-022 157	RM 301	2x4 Ceiling Tile, White/ Beige	No	None Detected	Cellulose Fiber 40% Mineral Wool 40% Carbonates Perlite Binder/Filler 20%
0147874-023 158	PH RM 3RD FL	12"x12" Floor Tile, White	No	None Detected	Carbonates Quartz Binder/Filler 100%
0147874-024 159	PH RM 3RD FL	Floor Tile Mastic, Black	No	None Detected	Cellulose Fiber 10% Gypsum Carbonates Binder/Filler 90%
0147874-025 160	RM 328	Carpet Mastic, Black/ Brown Note: Very small amount of black mastic	No	None Detected	Cellulose Fiber 10% Synthetic Fiber 2% Carbonates Gypsum Binder/Filler 88%
0147874-026 161	RM 208	9"x9" Floor Tile, Tan	Yes	Chrysotile 10%	Carbonates Gypsum Quartz Binder/Filler 90%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report

0147874

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/23/2014
	POYNETTE WI 53955	Date Analyzed:	10/28/2014
Collected:	10/22/2014	Date Reported:	10/28/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147874-027 162	RM 208	Floor Tile Mastic, Black	Yes	Chrysotile 5%	Cellulose Fiber 3% Carbonates Gypsum Quartz Binder/Filler 92%
0147874-028 163	EAST STAIRWAY 1ST FL	12"x12" Floor Tile, Beige	Yes	Chrysotile 3%	Carbonates Gypsum Quartz Binder/Filler 97%
0147874-029 164	EAST STAIRWAY 1ST FL	Floor Tile Mastic, Black	Yes	Chrysotile 5%	Cellulose Fiber 3% Carbonates Gypsum Quartz Binder/Filler 92%
0147874-030 165	WATER METER RM- LL	TSI-Water Heater, White	Yes	Chrysotile 25%	Gypsum Carbonates Binder/Filler 75%
0147874-031 166	BOILER RM TANK- LL	TSI-Tank, White	Yes	Chrysotile 25%	Gypsum Carbonates Binder/Filler 75%
0147874-032 167	BOILER RM-LL	TSI-Filling In, White	Yes	Chrysotile 25%	Gypsum Carbonates Binder/Filler 75%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report

0147874

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: A & A ENVIRONMENTAL, INC. Job# / P.O. #: 3743
Address: N4381 US HWY 51 Date Received: 10/23/2014
POYNETTE WI 53955 Date Analyzed: 10/28/2014
Collected: 10/22/2014 Date Reported: 10/28/2014
Project Name: 215 MARTIN LUTHER KING JR. BLVD EPA Method: EPA 600/R-93/116
Address: Submitted By: KIM SOPHA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147874-033 168	ALU WINDOW FRAMES EXTERIOR DOCK-	Caulking, Brown	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
0147874-034 169	EAST WALL DOCK- LL	Expansion Joint Caulking, Brown	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
0147874-035 170	UNDER STAIRWAY TO WILSON ST.-LL	Window Frame Caulk, Gray	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
0147874-036 171	WALL NEXT TO WILSON ST.-LL	Caulking, Gray	Yes	Chrysotile 5%	Gypsum Carbonates Binder/Filler 95%
0147874-037 172	DECORATIVE STONE NEXT TO WILSON ST.-LL	Caulking, Gray	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
0147874-038 173	MLK GRAY-1ST	Side Walk Caulking, Gray	No	None Detected	Carbonates Quartz Binder/Filler 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147874

Bulk Asbestos Analysis by Polarized Light Microscopy


NVLAP#101926-0

Client: A & A ENVIRONMENTAL, INC. Job# / P.O. #: 3743
Address: N4381 US HWY 51 Date Received: 10/23/2014
POYNETTE WI 53955 Date Analyzed: 10/28/2014
Collected: 10/22/2014 Date Reported: 10/28/2014
Project Name: 215 MARTIN LUTHER KING JR. BLVD EPA Method: EPA 600/R-93/116
Address: Submitted By: KIM SOPHA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147874-039 174	MLK ENTRANCE (3DD)-1ST	Door Frame Caulk, Gray	Yes	Chrysotile 5%	Carbonates Quartz Binder/Filler 95%
0147874-040 175	PO LARGE OH DOOR-1ST	Door Frame Caulk, Gray	Yes	Chrysotile 5%	Gypsum Carbonates Quartz Binder/Filler 95%



Analyst - Kurt Kettler



Signatory - Lab Manager - Ken Scheske

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicated or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY

EMC Labs, Inc.
9830 S. 51st, Ste B-109
Phoenix, AZ 85044
(800) 362-3373 Fax (480) 893-1726

LAB#: 147874
TAT: 3day
Rec'd OCT 23 P.M.

COMPANY NAME: **A & A ENVIRONMENTAL INC.**
N4381 US Hwy 51
Poynette, WI 53955
CONTACT: Kim Sopha **Scan & Email COC**
Phone/Fax: (608) 576-4960 / (608) 635-9717
Email: blsopha@aol.com, aaenvinc@aol.com, rsopha@aaenv.com

BILL TO: (If Different Location)

Now Accepting: **VISA - MASTERCARD**

Price Quoted: \$ ____ / Sample \$ ____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)**1. TURNAROUND TIME:** [Same Day RUSH] [1-Day] [2-Day] (3-4-5-Day) [6-10 Day]

****Prior confirmation of turnaround time is required

****Additional charges for rush analysis (please call marketing department for pricing details)

****Laboratory analysis may be subject to delay if credit terms are not met

2. TYPE OF ANALYSIS: [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]**3. DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]

(If you do not indicate preference, EMC will dispose of samples 30 days from analysis.)

4. Project Name: 215 Martin Luther King Jr Blvd

P.O. Number:

Project Number:

3743

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No	AIR SAMPLE INFO / COMMENTS		
					ON	OFF	FLOW RATE
6	136	10/22		Y N			
				Y N			
				Y N			
				Y N			
				Y N			
40	175			Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			

SPECIAL INSTRUCTIONS: Point Count if <1% or trace unless otherwise specified on COC

Sample Collector: (Print) (Signature)

Relinquished by: Date/Time: Received by: Diana Federico Date/Time: 10/23/14

Relinquished by: Diana Federico Date/Time: 10/23/14 Received by: [Signature] Date/Time: 10/23/14

Relinquished by: Date/Time: Received by: Date/Time:

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix, Arizona and prevailing party will be entitled to attorney's fees and court costs.

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0147958

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/27/2014
	POYNETTE WI 53955	Date Analyzed:	10/28/2014
Collected:	10/24/2014	Date Reported:	10/28/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147958-001 181	HOUSING 1ST FL	Drywall Backing, Blue	No	None Detected	Cellulose Fiber 95% Carbonates Binder/Filler 5%
0147958-002 182	HOUSING 1ST FL	Plaster-Top Coat, White	No	None Detected	Quartz Carbonates Mica Binder/Filler 100%
0147958-003 183	HOUSING 1ST FL	Plaster - Base Coat/ Paint, White	No	None Detected	Carbonates Quartz Gypsum Mica Binder/Filler 100%
0147958-004 184	HOUSING 1ST FL	2x2 Ceiling Tile, White/ Gray	No	None Detected	Mineral Wool 40% Cellulose Fiber 35% Carbonates Gypsum Perlite Quartz Binder/Filler 25%
0147958-005 185	HOUSING 1ST FL	TSI Fitting, Gray	No	None Detected	Mineral Wool 30% Carbonates Gypsum Diatoms Mica Binder/Filler 70%
0147958-006 186	HOUSING 1ST FL	Duct Mastic, Gray	No	None Detected	Carbonates Gypsum Binder/Filler 100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report

0147958

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/27/2014
	POYNETTE WI 53955	Date Analyzed:	10/28/2014
Collected:	10/24/2014	Date Reported:	10/28/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents
0147958-007 187	HOUSING 1ST FL	Duct Mastic, Gray	No	None Detected	Carbonates Gypsum Quartz Binder/Filler 100%
0147958-008 188	HOUSING 1ST FL	Wall Texture, White/ Off White	No	None Detected	Carbonates Mica Quartz Binder/Filler 100%
0147958-009 189	HOUSING 1ST FL	Carpet Mastic, Black	Yes	Chrysotile 4%	Cellulose Fiber 2% Carbonates Quartz Binder/Filler 94%
0147958-010 190	HOUSING 1ST FL	Carpet Mastic, Yellow/ Black	No	None Detected	Cellulose Fiber 3% Carbonates Quartz Binder/Filler 97%
0147958-011 191	HOUSING 1ST FL	Cove Base, Black	No	None Detected	Carbonates Quartz Binder/Filler 100%
0147958-012 192	HOUSING 1ST FL	Cove Base Mastic, Brown	No	None Detected	Cellulose Fiber <1% Carbonates Gypsum Quartz Binder/Filler 99%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726


Laboratory Report
0147958

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	A & A ENVIRONMENTAL, INC.	Job# / P.O. #:	3743
Address:	N4381 US HWY 51	Date Received:	10/27/2014
	POYNETTE WI 53955	Date Analyzed:	10/28/2014
Collected:	10/24/2014	Date Reported:	10/28/2014
Project Name:	215 MARTIN LUTHER KING JR. BLVD	EPA Method:	EPA 600/R-93/116
Address:		Submitted By:	KIM SOPHA
		Collected By:	

Lab ID	Sample	Layer Name /	Asbestos	Asbestos Type	Non-Asbestos
Client ID	Location	Sample Description	Detected	(%)	Constituents



Analyst - Kenneth Scheske



Signatory - Lab Director - Kurt Kettler

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicated or representative of the qualities of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

CHAIN OF CUSTODY

EMC Labs, Inc.
9830 S. 51st, Ste B-109
Phoenix, AZ 85044
(800) 362-3373 Fax (480) 893-1726

LAB#: 147958
TAT: 1 day
Rec'd: OCT 27 AM.

COMPANY NAME: **A & A ENVIRONMENTAL INC.**
N4381 US Hwy 51
Poynette, WI 53955
CONTACT: Kim Sopha **Scan & Email COC**
Phone/Fax: (608) 576-4960 / (608) 635-9717
Email: blsopha@aol.com, aaenvinc@aol.com, rsopha@aaenv.com

BILL TO: (If Different Location)

Now Accepting: VISA – MASTERCARD

Price Quoted: \$____ / Sample \$____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)1. **TURNAROUND TIME:** [Same Day RUSH] [1-Day] [2-Day] [3-4-5-Day] [6-10 Day]****Prior confirmation of turnaround time is required

****Additional charges for rush analysis (please call marketing department for pricing details)

****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
(If you do not indicate preference, EMC will dispose of samples 30 days from analysis.)4. **Project Name:** 215 Martin Luther King Jr. BlvdP.O. Number: _____ Project Number: 3743

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No	AIR SAMPLE INFO / COMMENTS		
					ON	OFF	FLOW RATE
1	181	10/24	Bulk	Y N			
5	5	5	5	Y N			
				Y N			
				Y N			
12	192			Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			
				Y N			

SPECIAL INSTRUCTIONS: Point Count if <1% or trace unless otherwise specified on COC

Sample Collector: (Print) _____ (Signature) _____

Relinquished by: _____ Date/Time: _____ Received by: Diana Federico Date/Time: 10/27/14Relinquished by: Diana Federico Date/Time: 10/27/14 Received by: B-S Date/Time: 10/27/14

Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____

** In the event of any dispute between the above parties for these services or otherwise, parties agree that jurisdiction and venue will be in Phoenix Arizona and prevailing party will be entitled to attorney's fees and court costs.

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955

Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377

Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

Index	Component	Substrate	Side	Color	Floor	Room	Results	PbC
1								2.68
2			CAL		PH		Positive	1
3			CAL		PH		Positive	1
4			CAL		PH		Positive	1.2
5	WALL	CONCRETE	A	WHITE	PH	ELEVATOR RM	Negative	0.2
6	WALL	CONCRETE	A	WHITE	PH	ELEVATOR RM	Negative	0.05
7	WALL	CONCRETE	B	WHITE	PH	ELEVATOR RM	Negative	0.26
8	WALL	CONCRETE	C	WHITE	PH	ELEVATOR RM	Negative	0.3
9	WALL	CONCRETE	D	WHITE	PH	ELEVATOR RM	Negative	0.11
10	WALL	CONCRETE	D	WHITE	PH	ELEVATOR RM	Negative	0.22
11	CEILING	CONCRETE		WHITE	PH	ELEVATOR RM	Negative	0.19
12	FLOOR	CONCRETE		GREY	PH	ELEVATOR RM	Negative	0.6
13	DOOR	CONCRETE		BROWN	PH	ELEVATOR RM	Negative	0.01
14	WALL	CONCRETE	C	WHITE	PH	ELEVATOR RM EXT	Negative	0
15	WALL	CONCRETE	C	WHITE	PH	ELEVATOR RM EXT	Negative	0
16	WALL	CONCRETE	D	WHITE	PH	ELEVATOR RM EXT	Negative	0
17	WALL	CONCRETE	A	WHITE	PH	ELEVATOR RM EXT	Negative	0
18	WALL	CONCRETE	B	WHITE	PH	ELEVATOR RM EXT	Negative	0
19	WINDOW	METAL	B	WHITE	PH	3RD FLOOR HALL	Positive	33.6
20	WINDOW	METAL	B	WHITE	PH	3RD FLOOR HALL	Positive	30.2
21	WALL	PLASTER	B	WHITE	PH	3RD FLOOR HALL	Positive	14
22	WALL	PLASTER	A	WHITE	PH	3RD FLOOR HALL	Positive	14
23	WALL	DRYWALL	C	WHITE	PH	3RD FLOOR HALL	Negative	0.06
24	WALL	PLASTER	D	WHITE	PH	3RD FLOOR HALL	Positive	12.1
25	WALL	PLASTER	A	WHITE	THIRD	3RD FL MENS RR	Positive	11.3
26	WALL	PLASTER	B	WHITE	THIRD	3RD FL MENS RR	Positive	10.7
27	WALL	PLASTER	C	WHITE	THIRD	3RD FL MENS RR	Positive	11.3
28	WALL	PLASTER	D	WHITE	THIRD	3RD FL MENS RR	Positive	11.3
29	WINDOW	METAL	B	WHITE	THIRD	3RD FL MENS RR	Positive	25.2
30	DOOR	WOOD	D	WHITE	THIRD	3RD FL MENS RR	Positive	6.7
31	WALL	WOOD	B	WHITE	THIRD	301	Positive	6.5

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955

Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377

Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

32	WALL	WOOD	C	WHITE	THIRD	301	Positive	5.9
33	WALL	WOOD	D	WHITE	THIRD	301	Positive	6.8
34	WALL	WOOD	A	WHITE	THIRD	301	Positive	7.3
35	WINDOW	METAL	B	WHITE	THIRD	301	Positive	17.6
36	WALL	PLASTER	A	WHITE	THIRD	301	Positive	10.4
37	WALL	PLASTER	A	WHITE	THIRD	303	Positive	7.1
38	WALL	PLASTER	B	WHITE	THIRD	303	Positive	7.1
39	WALL	PLASTER	C	WHITE	THIRD	303	Positive	8.1
40	WALL	PLASTER	D	WHITE	THIRD	303	Positive	7.7
41	WINDOW	METAL	C	WHITE	THIRD	303	Positive	5.9
42	WALL	METAL	D	WHITE	THIRD	302	Negative	0
43	WALL	METAL	A	WHITE	THIRD	302	Positive	14.6
44	WALL	METAL	B	WHITE	THIRD	302	Positive	11.2
45	WALL	METAL	C	WHITE	THIRD	302	Positive	9.1
46	WALL	PLASTER	A	WHITE	THIRD	305	Positive	9.2
47	WALL	PLASTER	B	WHITE	THIRD	305	Positive	9.6
48	WALL	PLASTER	C	WHITE	THIRD	305	Positive	10.3
49	WALL	PLASTER	D	WHITE	THIRD	305	Positive	9.7
50	WALL	PLASTER	C	WHITE	THIRD	304	Positive	9.5
51	WALL	PLASTER	D	WHITE	THIRD	304	Negative	0
52	WALL	PLASTER	A	WHITE	THIRD	304	Positive	10.2
53	WALL	PLASTER	B	WHITE	THIRD	304	Negative	0.01
54	WALL	PLASTER	B	WHITE	THIRD	306	Negative	0
55	WALL	PLASTER	C	WHITE	THIRD	306	Positive	10.7
56	WALL	PLASTER	D	WHITE	THIRD	306	Negative	0.04
57	WALL	PLASTER	A	WHITE	THIRD	306	Positive	11.5
58	WALL	WOOD	C	WHITE	THIRD	308	Positive	5.4
59	WALL	WOOD	D	WHITE	THIRD	308	Positive	6.1
60	WALL	WOOD	B	WHITE	THIRD	308	Negative	0.03
61	WALL	WOOD	A	WHITE	THIRD	308	Positive	6.8
62	WALL	DRYWALL	A	WHITE	FIRST	POST OFFICE LOBBY	Negative	0
63	WALL	DRYWALL	C	WHITE	FIRST	POST OFFICE LOBBY	Negative	0

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955

Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377

Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

64	WALL	DRYWALL	D	WHITE	FIRST	POST OFFICE LOBBY	Negative	0
65	WALL	DRYWALL	B	WHITE	FIRST	POST OFFICE LOBBY	Negative	0
66	WALL	DRYWALL	A	WHITE	FIRST	POST OFFICE MAIL RM	Negative	0.01
67	WALL	DRYWALL	B	WHITE	FIRST	POST OFFICE MAIL RM	Negative	0
68	WALL	DRYWALL	C	WHITE	FIRST	POST OFFICE MAIL RM	Negative	0
69	WALL	DRYWALL	D	WHITE	FIRST	POST OFFICE MAIL RM	Negative	0
70	CEILING	PLASTER		WHITE	FIRST	POST OFFICE MAIL RM	Positive	3.8
71	WALL	PLASTER	B	WHITE	THIRD	312	Positive	9.4
72	WALL	PLASTER	C	WHITE	THIRD	312	Positive	10.5
73	WALL	DRYWALL	D	WHITE	THIRD	312	Negative	0
74	WALL	PLASTER	A	WHITE	THIRD	312	Positive	9.9
75	WALL	DRYWALL	B	WHITE	THIRD	314	Negative	0
76	WALL	PLASTER	C	WHITE	THIRD	314	Negative	0.01
77	WALL	DRYWALL	D	WHITE	THIRD	314	Negative	0
78	WALL	PLASTER	C	WHITE	THIRD	314	Positive	10.3
79	WALL	PLASTER	A	WHITE	THIRD	314	Positive	8.2
80	WALL	PLASTER	A	WHITE	THIRD	316	Positive	8.9
81	WALL	DRYWALL	B	WHITE	THIRD	316	Negative	0
82	WALL	PLASTER	C	WHITE	THIRD	316	Positive	12.8
83	WALL	DRYWALL	D	WHITE	THIRD	316	Negative	0
84	WALL	DRYWALL	B	WHITE	THIRD	316	Negative	0
85	WALL	PLASTER	C	WHITE	THIRD	316	Positive	8.1
86	WALL	PLASTER	D	WHITE	THIRD	316	Negative	0
87	WALL	PLASTER	A	WHITE	THIRD	316	Positive	7.8
88	RADIATOR	METAL	A	WHITE	THIRD	316	Negative	0
89	WALL	PLASTER	B	WHITE	THIRD	320	Negative	0.01
90	WALL	PLASTER	C	WHITE	THIRD	320	Positive	8.8
91	WALL	DRYWALL	D	WHITE	THIRD	320	Negative	0
92	WALL	PLASTER	A	WHITE	THIRD	320	Positive	8.7
93	WALL	PLASTER	A	WHITE	THIRD	322	Positive	8.5
94	WALL	DRYWALL	B	WHITE	THIRD	322	Negative	0
95	WALL	PLASTER	C	WHITE	THIRD	322	Positive	10.5

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955
 Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377
 Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

96	WALL	PLASTER	D	WHITE	THIRD	322	Negative	0.01
97	WALL	PLASTER	A	WHITE	THIRD	324	Positive	9.9
98	WALL	PLASTER	B	WHITE	THIRD	324	Negative	0.02
99	WALL	PLASTER	C	WHITE	THIRD	324	Positive	10.3
100	WALL	PLASTER	D	WHITE	THIRD	324	Positive	9.8
101	WALL	PLASTER	A	WHITE	THIRD	326	Positive	11.8
102	WALL	PLASTER	B	WHITE	THIRD	326	Positive	12.9
103	WALL	PLASTER	C	WHITE	THIRD	326	Positive	10.9
104	WALL	PLASTER	D	WHITE	THIRD	326	Positive	10.9
105	WALL	PLASTER	A	WHITE	THIRD	328	Negative	0
106	WALL	PLASTER	B	WHITE	THIRD	328	Positive	9.8
107	WALL	PLASTER	C	WHITE	THIRD	328	Negative	0
108	WALL	DRYWALL	C	WHITE	THIRD	328	Negative	0
109	WALL	DRYWALL	C	WHITE	THIRD	328	Negative	0
110	WALL	PLASTER	D	WHITE	THIRD	328	Positive	1.7
111	WALL	PLASTER	D	WHITE	THIRD	328	Positive	12.3
112	WALL	DRYWALL	A	WHITE	THIRD	330	Negative	0.01
113	WALL	PLASTER	B	WHITE	THIRD	330	Positive	10
114	WALL	PLASTER	C	WHITE	THIRD	330	Positive	10.2
115	WALL	PLASTER	D	WHITE	THIRD	330	Positive	8.6
116	WALL	PLASTER	A	WHITE	THIRD	330	Positive	8.7
117	WALL	PLASTER	A	WHITE	THIRD	332	Positive	9.6
118	WALL	PLASTER	D	WHITE	THIRD	332	Positive	11.2
119	WALL	PLASTER	C	WHITE	THIRD	332	Positive	9.5
120	WALL	PLASTER	B	WHITE	THIRD	332	Positive	10.1
121	WALL	PLASTER	A	WHITE	THIRD	334	Positive	10.6
122	WALL	PLASTER	D	WHITE	THIRD	334	Positive	11.5
123	WALL	PLASTER	C	WHITE	THIRD	334	Positive	11.1
124	WALL	PLASTER	B	WHITE	THIRD	334	Positive	10.4
125	WINDOW	PLASTER	B	WHITE	THIRD	334	Negative	0
126	WINDOW	METAL	C	WHITE	THIRD	334	Positive	15.3
127	WINDOW	METAL	B	WHITE	THIRD	353	Negative	0

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955

Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377

Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

128	WINDOW	DRYWALL	A	WHITE	THIRD	321	Negative	0
129	WINDOW	PLASTER	D	WHITE	THIRD	321	Positive	5.1
130	WINDOW	PLASTER	C	WHITE	THIRD	321	Positive	5.9
131	WINDOW	DRYWALL	B	WHITE	THIRD	321	Negative	0
132	WALL	DRYWALL	A	WHITE	THIRD	319	Negative	0
133	WALL	PLASTER	D	WHITE	THIRD	319	Positive	6
134	WALL	DRYWALL	C	WHITE	THIRD	319	Negative	0
135	WALL	DRYWALL	B	WHITE	THIRD	319	Negative	0
136	WALL	PLASTER	A	WHITE	THIRD	317	Positive	6.3
137	WALL	DRYWALL	B	WHITE	THIRD	317	Negative	0
138	WALL	DRYWALL	C	WHITE	THIRD	317	Negative	0
139	WALL	PLASTER	D	WHITE	THIRD	317	Positive	6.1
140	WALL	PLASTER	A	WHITE	THIRD	351	Positive	12.7
141	WALL	PLASTER	D	WHITE	THIRD	351	Negative	0.01
142	WALL	PLASTER	C	WHITE	THIRD	351	Positive	12.7
143	WALL	PLASTER	B	WHITE	THIRD	351	Negative	0
144	WALL	PLASTER	A	WHITE	THIRD	304	Positive	8.3
145	WALL	DRYWALL	B	WHITE	THIRD	304	Negative	0.09
146	WALL	DRYWALL	C	WHITE	THIRD	304	Negative	0.14
147	WALL	PLASTER	C	WHITE	THIRD	304	Positive	7.8
148	WALL	PLASTER	D	WHITE	THIRD	304	Positive	6.2
149	WALL	DRYWALL	A	WHITE	THIRD	311	Negative	0
150	WALL	PLASTER	B	WHITE	THIRD	311	Positive	7.2
151	WALL	PLASTER	C	WHITE	THIRD	311	Positive	8.8
152	WALL	PLASTER	D	WHITE	THIRD	311	Positive	6.6
153	WALL	DRYWALL	A	WHITE	SECOND	220	Negative	0
154	WALL	PLASTER	B	WHITE	SECOND	220	Positive	8
155	WALL	PLASTER	D	WHITE	SECOND	220	Positive	7.9
156	WALL	PLASTER	A	WHITE	SECOND	222	Positive	8.6
157	WALL	PLASTER	B	WHITE	SECOND	222	Positive	7.3
158	WALL	PLASTER	C	WHITE	SECOND	222	Positive	8.6
159	WALL	PLASTER	D	WHITE	SECOND	222	Positive	8.1

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955

Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377

Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

160	WALL	PLASTER	A	WHITE	SECOND	223	Positive	6.7
161	WALL	PLASTER	B	WHITE	SECOND	223	Positive	8.7
162	WALL	PLASTER	C	WHITE	SECOND	223	Positive	8.3
163	WALL	PLASTER	D	WHITE	SECOND	223	Positive	7
164	WALL	DRYWALL	A	WHITE	SECOND	224	Negative	0.05
165	WALL	PLASTER	B	WHITE	SECOND	224	Positive	8.7
166	WALL	PLASTER	C	WHITE	SECOND	224	Positive	7.3
167	WALL	DRYWALL	D	WHITE	SECOND	224	Negative	0
168	WALL	PLASTER	A	WHITE	SECOND	219	Positive	8
169	WALL	PLASTER	D	WHITE	SECOND	219	Positive	5.5
170	WALL	PLASTER	C	WHITE	SECOND	219	Positive	8.3
171	WALL	WOOD	D	WHITE	SECOND	219	Negative	0
172	WALL	DRYWALL	A	WHITE	SECOND	216	Negative	0
173	WALL	PLASTER	B	WHITE	SECOND	216	Negative	0
174	WALL	PLASTER	C	WHITE	SECOND	216	Positive	6
175	WALL	DRYWALL	D	WHITE	SECOND	216	Negative	0
176	DOOR	METAL	D	WHITE	SECOND	216	Negative	0.03
177	DOOR	METAL	D	WHITE	SECOND	216	Negative	0
178	DOOR	METAL	A	WHITE	SECOND	215	Negative	0
179	WALL	DRYWALL	A	WHITE	SECOND	215	Negative	0.01
180	WALL	DRYWALL	B	WHITE	SECOND	215	Negative	0
181	WALL	PLASTER	C	WHITE	SECOND	215	Positive	2.2
182	WALL	DRYWALL	D	WHITE	SECOND	215	Negative	0
183	WALL	DRYWALL	A	WHITE	SECOND	214	Negative	0
184	WALL	DRYWALL	B	WHITE	SECOND	214	Negative	0
185	WALL	DRYWALL	C	WHITE	SECOND	214	Negative	0
186	WALL	DRYWALL	D	WHITE	SECOND	214	Negative	0
187	WALL	PLASTER	A	WHITE	SECOND	210	Positive	2.7
188	WALL	DRYWALL	B	WHITE	SECOND	210	Negative	0
189	WALL	DRYWALL	C	WHITE	SECOND	210	Negative	0
190	WALL	DRYWALL	D	WHITE	SECOND	210	Negative	0
191	WALL	PLASTER	A	WHITE	SECOND	203	Positive	5.4

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955

Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377

Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

192	WALL	PLASTER	B	WHITE	SECOND	203	Positive	7.4
193	WALL	PLASTER	C	WHITE	SECOND	203	Positive	6.2
194	WALL	PLASTER	D	WHITE	SECOND	203	Positive	7.6
195	WALL	PLASTER	C	WHITE	SECOND	205	Positive	9.9
196	WALL	DRYWALL	D	WHITE	SECOND	205	Negative	0
197	WALL	PLASTER	A	WHITE	SECOND	205	Positive	6
198	WALL	PLASTER	B	WHITE	SECOND	205	Positive	5.9
199	WALL	DRYWALL	B	WHITE	SECOND	206	Negative	0.01
200	WALL	DRYWALL	C	WHITE	SECOND	206	Positive	8.7
201	WALL	PLASTER	C	WHITE	SECOND	206	Positive	7.9
202	WALL	DRYWALL	B	WHITE	SECOND	206	Negative	0
203	WALL	PLASTER	A	WHITE	SECOND	206	Positive	7.7
204	WALL	PLASTER	A	WHITE	SECOND	202	Positive	8
205	WALL	PLASTER	B	WHITE	SECOND	202	Positive	8.7
206	WALL	PLASTER	C	WHITE	SECOND	202	Positive	7.6
207	WALL	PLASTER	D	WHITE	SECOND	202	Positive	7.5
208	WALL	PLASTER	A	WHITE	SECOND	208	Positive	9.9
209	WALL	PLASTER	D	WHITE	SECOND	208	Positive	9.6
210	WALL	PLASTER	C	WHITE	SECOND	208	Positive	8.2
211	WALL	PLASTER	B	WHITE	SECOND	208	Positive	8
212	WALL	PLASTER	B	WHITE	SECOND	209	Positive	7
213	WALL	PLASTER	A	WHITE	SECOND	209	Positive	8.3
214	WALL	PLASTER	C	WHITE	SECOND	209	Positive	8.3
215	WALL	PLASTER	D	WHITE	SECOND	209	Positive	7.3
216	WALL	PLASTER	C	WHITE	SECOND	225	Positive	6.4
217	WALL	PLASTER	D	WHITE	SECOND	225	Positive	8.1
218	WALL	PLASTER	A	WHITE	SECOND	225	Positive	8.4
219	WALL	PLASTER	B	WHITE	SECOND	225	Positive	9
220	WALL	PLASTER	A	GREY	SECOND	231	Positive	3.9
221	WALL	PLASTER	B	GREY	SECOND	231	Positive	3.1
222	WALL	PLASTER	C	GREY	SECOND	231	Positive	3
223	WALL	PLASTER	D	GREY	SECOND	231	Positive	3.4

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955

Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377

Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

224	CEILING	CONCRETE	D	GREY	SECOND	231	Positive	2.8
225	CEILING	CONCRETE	A	WHITE	SECOND	230	Positive	7.7
226	CEILING	CONCRETE	B	WHITE	SECOND	230	Positive	7.9
227	CEILING	CONCRETE	A	WHITE	SECOND	230	Positive	8.4
228	CEILING	CONCRETE	B	WHITE	SECOND	230	Positive	9.4
229	CEILING	CONCRETE	C	WHITE	SECOND	230	Positive	6
230	CEILING	CONCRETE	D	WHITE	SECOND	230	Positive	9.2
231	CEILING	CONCRETE	A	WHITE	SECOND	232	Positive	9.7
232	CEILING	DRYWALL	D	WHITE	SECOND	232	Negative	0
233	CEILING	DRYWALL	C	WHITE	SECOND	232	Negative	0
234	CEILING	DRYWALL	B	WHITE	SECOND	232	Positive	6.7
235	CEILING	PLASTER	B	WHITE	SECOND	232	Positive	7.6
236	WALL	DRYWALL	B	WHITE	SECOND	232	Negative	0
237	WALL	PLASTER	A	WHITE	SECOND	232	Positive	6.7
238	WALL	PLASTER	D	WHITE	SECOND	232	Positive	8.1
239	WALL	PLASTER	C	WHITE	SECOND	232	Positive	7.3
240	WALL	DRYWALL	A	WHITE	SECOND	272	Negative	0.01
241	WALL	PLASTER	B	WHITE	SECOND	272	Positive	9.6
242	WALL	PLASTER	C	WHITE	SECOND	272	Positive	11.1
243	WALL	PLASTER	D	WHITE	SECOND	272	Positive	10.2
244	WALL	DRYWALL	A	WHITE	SECOND	274a	Negative	0
245	WALL	DRYWALL	B	WHITE	SECOND	274a	Negative	0.1
246	WALL	PLASTER	C	WHITE	SECOND	274a	Negative	0.04
247	WALL	PLASTER	D	WHITE	SECOND	274b	Positive	8.3
248	WALL	PLASTER	A	WHITE	SECOND	284	Positive	6.7
249	WALL	PLASTER	D	WHITE	SECOND	284	Positive	9
250	WALL	PLASTER	C	WHITE	SECOND	284	Positive	6.1
251	WALL	DRYWALL	B	WHITE	SECOND	284	Negative	0.01
252	WALL	DRYWALL	B	WHITE	SECOND	285	Negative	0
253	WALL	PLASTER	A	WHITE	SECOND	285	Positive	6.2
254	WALL	PLASTER	D	WHITE	SECOND	285	Positive	6.7
255	WALL	PLASTER	C	WHITE	SECOND	285	Positive	8.2

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955
 Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377
 Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

256	WALL	DRYWALL	A	WHITE	SECOND	286	Negative	0
257	WALL	DRYWALL	D	WHITE	SECOND	286	Negative	0
258	WALL	PLASTER	C	WHITE	SECOND	286	Positive	6.8
259	WALL	PLASTER	B	WHITE	SECOND	286	Positive	6.6
260	WALL	PLASTER	A	WHITE	SECOND	286	Positive	6.3
261	WALL	PLASTER	A	WHITE	SECOND	282	Positive	6.7
262	WALL	PLASTER	B	WHITE	SECOND	282	Positive	7.3
263	WALL	PLASTER	C	WHITE	SECOND	282	Positive	7.1
264	WALL	DRYWALL	D	WHITE	SECOND	282	Negative	0
265	WALL	DRYWALL	A	WHITE	SECOND	226	Negative	0
266	WALL	DRYWALL	D	WHITE	SECOND	226	Negative	0.01
267	WALL	PLASTER	C	WHITE	SECOND	226	Positive	7.3
268	WALL	PLASTER	B	WHITE	SECOND	226	Positive	9
269	WALL	PLASTER	A	WHITE	SECOND	229	Positive	5.4
270	WALL	PLASTER	B	WHITE	SECOND	229	Negative	0.01
271	WALL	PLASTER	B	WHITE	SECOND	229	Positive	3.7
272	WALL	DRYWALL	C	WHITE	SECOND	229	Negative	0
273	WALL	PLASTER	D	WHITE	SECOND	229	Negative	0.02
274	WALL	PLASTER	D	WHITE	SECOND	218	Positive	6.7
275	WALL	DRYWALL	C	WHITE	SECOND	218	Negative	0.11
276	WALL	PLASTER	A	WHITE	SECOND	218	Positive	7.2
277	WALL	DRYWALL	C	WHITE	SECOND	218	Negative	0.11
278	WALL	DRYWALL	CAL	WHITE	FIRST	CORRIDOR	Positive	1
279	WALL	DRYWALL	CAL	WHITE	FIRST	CORRIDOR	Positive	0.9
280	WALL	DRYWALL	CAL	WHITE	FIRST	CORRIDOR	Positive	1.1
281			CAL				Positive	3.22
282			CAL				Positive	1
283			CAL				Positive	1.1
284			CAL				Positive	1.1
285	WALL	DRYWALL	C	WHITE	FIRST	CU MEETING	Negative	0
286	WALL	DRYWALL	D	WHITE	FIRST	CU MEETING	Negative	0
287	WALL	DRYWALL	A	WHITE	FIRST	CU MEETING	Negative	0

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955
 Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377
 Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

288	WALL	DRYWALL	B	WHITE	FIRST	CU MEETING	Negative	0
289	WALL	DRYWALL	B	WHITE	FIRST	CU WORK	Negative	0
290	WALL	DRYWALL	C	BLUE	FIRST	CU WORK	Negative	0.01
291	WALL	DRYWALL	D	WHITE	FIRST	CU WORK	Negative	0
292	WALL	DRYWALL	A	WHITE	FIRST	CU WORK	Negative	0
293	WALL	DRYWALL	A	WHITE	FIRST	MAIN LOBBY	Negative	0
294	WALL	DRYWALL	B	WHITE	FIRST	MAIN LOBBY	Negative	0
295	WALL	DRYWALL	C	WHITE	FIRST	MAIN LOBBY	Negative	0
296	WALL	DRYWALL	D	WHITE	FIRST	MAIN LOBBY	Negative	0
297	WALL	DRYWALL	B	WHITE	FIRST	TRANSPORTATION	Negative	0
298	WALL	DRYWALL	A	WHITE	FIRST	TRANSPORTATION	Negative	0
299	WALL	DRYWALL	D	WHITE	FIRST	TRANSPORTATION	Negative	0
300	WALL	DRYWALL	D	WHITE	FIRST	TRANSPORTATION	Negative	0
301	WALL	DRYWALL	C	WHITE	FIRST	TRANSPORTATION	Negative	0
302	WALL	METAL	C	WHITE	FIRST	TRANSPORTATION	Negative	0.02
303	WALL	METAL	C	BLUE	FIRST	TRANSPORTATION	Negative	0
304	WALL	DRYWALL	A	WHITE	FIRST	135	Negative	0
305	WALL	METAL	B	WHITE	FIRST	135	Negative	0
306	WALL	METAL	C	WHITE	FIRST	135	Negative	0
307	WALL	DRYWALL	D	WHITE	FIRST	135	Negative	0
308	WALL	DRYWALL	A	WHITE	FIRST	130	Negative	0
309	WALL	DRYWALL	B	WHITE	FIRST	130	Negative	0
310	WALL	DRYWALL	C	WHITE	FIRST	130	Negative	0
311	WALL	DRYWALL	D	WHITE	FIRST	130	Negative	0
312	WALL	DRYWALL	D	WHITE	FIRST	130	Negative	0
313	WALL	DRYWALL	A	WHITE	BASEMENT	HOUSEKEEPING	Negative	0
314	WALL	DRYWALL	A	grey	BASEMENT	HOUSEKEEPING	Negative	0
315	WALL	DRYWALL	B	grey	BASEMENT	HOUSEKEEPING	Negative	0.01
316	WALL	DRYWALL	C	grey	BASEMENT	HOUSEKEEPING	Negative	0
317	WALL	DRYWALL	D	WHITE	BASEMENT	HOUSEKEEPING	Negative	0
318	WALL	DRYWALL	A	TAN	BASEMENT	MAINT SHOP	Positive	3
319	WALL	PLASTER	A	TAN	BASEMENT	MAINT SHOP	Positive	3.2

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955
 Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377
 Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

320	WALL	PLASTER	B	TAN	BASEMENT	MAINT SHOP	Positive	5.5
321	WALL	PLASTER	C	TAN	BASEMENT	MAINT SHOP	Negative	0
322	WALL	CONCRETE	D	TAN	BASEMENT	MAINT SHOP	Negative	0
323	WALL	DRYWALL	A	WHITE	BASEMENT	II-140	Negative	0
324	WALL	DRYWALL	B	WHITE	BASEMENT	II-140	Negative	0
325	WALL	DRYWALL	C	WHITE	BASEMENT	II-140	Negative	0
326	WALL	DRYWALL	D	WHITE	BASEMENT	II-140	Negative	0
327	WALL	DRYWALL	A	WHITE	BASEMENT	II-130	Negative	0
328	WALL	DRYWALL	B	WHITE	BASEMENT	II-130	Negative	0
329	WALL	DRYWALL	C	WHITE	BASEMENT	II-130	Negative	0
330	WALL	DRYWALL	D	WHITE	BASEMENT	II-130	Negative	0
331	WALL	DRYWALL	A	WHITE	BASEMENT	MAINT OFFICE	Negative	0
332	WALL	DRYWALL	B	WHITE	BASEMENT	MAINT OFFICE	Negative	0
333	WALL	DRYWALL	C	WHITE	BASEMENT	MAINT OFFICE	Negative	0
334	WALL	DRYWALL	D	WHITE	BASEMENT	MAINT OFFICE	Negative	0
335	WALL	DRYWALL	A	WHITE	BASEMENT	BREAK ROOM	Negative	0
336	WALL	DRYWALL	B	WHITE	BASEMENT	BREAK ROOM	Negative	0
337	WALL	DRYWALL	C	WHITE	BASEMENT	BREAK ROOM	Positive	3.4
338	WALL	DRYWALL	D	WHITE	BASEMENT	BREAK ROOM	Positive	3.2
339	WALL	CONCRETE	A	TAN	BASEMENT	SWITCH GEAR RM	Negative	0.4
340	WALL	CONCRETE	A	TAN	BASEMENT	SWITCH GEAR RM	Positive	0.9
341	WALL	CONCRETE	D	TAN	BASEMENT	SWITCH GEAR RM	Negative	0.1
342	WALL	CONCRETE	D	TAN	BASEMENT	SWITCH GEAR RM	Negative	0.14
343	WALL	CONCRETE	C	TAN	BASEMENT	SWITCH GEAR RM	Negative	0.09
344	WALL	CONCRETE	B	TAN	BASEMENT	SWITCH GEAR RM	Negative	0.11
345	WALL	CONCRETE	A	TAN	BASEMENT	MECHANICAL RM	Negative	0
346	WALL	CONCRETE	B	TAN	BASEMENT	MECHANICAL RM	Positive	1.3
347	WALL	CONCRETE	C	TAN	BASEMENT	MECHANICAL RM	Positive	2
348	WALL	CONCRETE	D	TAN	BASEMENT	MECHANICAL RM	Positive	1.3
349	WALL	DRYWALL	A	WHITE	BASEMENT	HOUSING STORAGE	Negative	0.01
350	WALL	DRYWALL	D	WHITE	BASEMENT	HOUSING STORAGE	Negative	0
351	WALL	DRYWALL	C	WHITE	BASEMENT	HOUSING STORAGE	Negative	0.03

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955
 Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377
 Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

352	WALL	DRYWALL	D	WHITE	BASEMENT	HOUSING STORAGE	Negative	0
353	WALL	DRYWALL	A	WHITE	BASEMENT	BI STORAGE	Negative	0
354	WALL	DRYWALL	B	WHITE	BASEMENT	BI STORAGE	Negative	0
355	WALL	DRYWALL	D	WHITE	BASEMENT	BI STORAGE	Negative	0
356	WALL	DRYWALL	C	WHITE	BASEMENT	BI STORAGE	Negative	0
357	WALL	CONCRETE	A	WHITE	BASEMENT	VAULT STORAGE	Negative	0
358	WALL	CONCRETE	B	WHITE	BASEMENT	VAULT STORAGE	Negative	0.03
359	WALL	CONCRETE	B	WHITE	BASEMENT	VAULT STORAGE	Positive	4.5
360	WALL	CONCRETE	C	WHITE	BASEMENT	VAULT STORAGE	Positive	4.3
361	WALL	CONCRETE	D	WHITE	BASEMENT	VAULT STORAGE	Negative	0.01
362	DOOR	METAL	D	grey	BASEMENT	VAULT STORAGE	Positive	5
363	WALL	DRYWALL	A	WHITE	BASEMENT	HSKEEPING STORAGE	Negative	0
364	WALL	CONCRETE	B	WHITE	BASEMENT	HSKEEPING STORAGE	Negative	0
365	WALL	DRYWALL	D	WHITE	BASEMENT	HSKEEPING STORAGE	Negative	0
366	WALL	DRYWALL	D	WHITE	BASEMENT	HSKEEPING STORAGE	Negative	0.06
367	WALL	DRYWALL	A	TAN	BASEMENT	HSKEEPING STORAGE	Negative	0
368	WALL	DRYWALL	B	TAN	BASEMENT	HSKEEPING STORAGE	Negative	0
369			CAL				Positive	3.22
370	WALL	DRYWALL	A	TAN	BASEMENT	HSKEEPING STORAGE	Negative	0
371	WALL	DRYWALL	B	TAN	BASEMENT	HSKEEPING STORAGE	Negative	0
372	WALL	DRYWALL	C	TAN	BASEMENT	HSKEEPING STORAGE	Negative	0
373	WALL	DRYWALL	D	TAN	BASEMENT	HSKEEPING STORAGE	Negative	0
374	WALL	DRYWALL	A	TAN	BASEMENT	T&E	Negative	0.01
375	WALL	DRYWALL	B	TAN	BASEMENT	T&E	Negative	0
376	WALL	DRYWALL	C	TAN	BASEMENT	T&E	Negative	0
377	WALL	DRYWALL	D	TAN	BASEMENT	T&E	Negative	0
378	WALL	DRYWALL	A	WHITE	BASEMENT	T&E	Negative	0
379	WALL	DRYWALL	B	WHITE	BASEMENT	T&E	Negative	0
380	WALL	DRYWALL	C	WHITE	BASEMENT	T&E	Negative	0
381	WALL	DRYWALL	D	WHITE	BASEMENT	T&E	Negative	0
382	WALL	DRYWALL	B	WHITE	BASEMENT	BREAK ROOM	Negative	0.01
383	WALL	DRYWALL	C	WHITE	BASEMENT	BREAK ROOM	Negative	0.01

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955

Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377

Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

384	WALL	DRYWALL	C	WHITE	BASEMENT	BREAK ROOM	Negative	0.01
385	WALL	DRYWALL	D	WHITE	BASEMENT	BREAK ROOM	Negative	0
386	WALL	DRYWALL	A	WHITE	BASEMENT	BREAK ROOM	Negative	0
387	WALL	DRYWALL	A	WHITE	BASEMENT	II-110	Negative	0
388	WALL	DRYWALL	B	WHITE	BASEMENT	II-110	Negative	0
389	WALL	DRYWALL	C	WHITE	BASEMENT	II-110	Negative	0
390	WALL	DRYWALL	D	WHITE	BASEMENT	II-110	Negative	0.01
391	WALL	DRYWALL	A	WHITE	BASEMENT	II-120	Negative	0
392	WALL	DRYWALL	B	WHITE	BASEMENT	II-120	Negative	0.04
393	WALL	DRYWALL	C	WHITE	BASEMENT	II-120	Negative	0
394	WALL	DRYWALL	D	WHITE	BASEMENT	II-120	Negative	0
395	WALL	DRYWALL	A	TAN	BASEMENT	PLANNING STORAGE	Negative	0
396	WALL	DRYWALL	B	TAN	BASEMENT	PLANNING STORAGE	Negative	0
397	WALL	DRYWALL	C	TAN	BASEMENT	PLANNING STORAGE	Negative	0
398	WALL	DRYWALL	D	TAN	BASEMENT	PLANNING STORAGE	Negative	0
399	WALL	DRYWALL	A	WHITE	BASEMENT	PLANNING DESK	Negative	0
400	WALL	DRYWALL	B	WHITE	BASEMENT	PLANNING DESK	Negative	0
401	WALL	DRYWALL	C	WHITE	BASEMENT	PLANNING DESK	Negative	0
402	WALL	DRYWALL	D	WHITE	BASEMENT	PLANNING DESK	Negative	0
403	WALL	METAL	A	WHITE	BASEMENT	PLANNING STUDIO	Negative	0.01
404	WALL	METAL	B	WHITE	BASEMENT	PLANNING STUDIO	Negative	0
405	WALL	PLASTER	C	WHITE	BASEMENT	PLANNING STUDIO	Negative	0
406	WALL	DRYWALL	D	WHITE	BASEMENT	PLANNING STUDIO	Negative	0
407	WALL	DRYWALL	D	WHITE	BASEMENT	PLANNING STUDIO	Negative	0
408	WALL	DRYWALL	A	WHITE	BASEMENT	PLANNING STUDIO	Negative	0
409	WALL	DRYWALL	A	WHITE	BASEMENT	ZONING	Negative	0
410	WALL	DRYWALL	B	WHITE	BASEMENT	ZONING	Negative	0.01
411	WALL	DRYWALL	B	WHITE	BASEMENT	ZONING	Negative	0
412	CEILING	PLASTER		TAN	BASEMENT	ZONING	Positive	6.1
413			CAL				Positive	1.1
414			CAL				Positive	1.3
415			CAL				Positive	1

A & A Environmental, Inc.

N4381 US Hwy 51 • Poynette, WI 53955

Phone: (608) 240-1511 • Mobile Phone: (608) 576-4960 • Pager: (608) 275-5377

Fax: (608) 635-9717

CLIENT:	City Of Madison	AA ENV #:	AA3743
LOCATION:	215 Martin Luther King Jr Blvd	SITE DATE	10/21/14
SAMPLE TYPE:	Paint	INSPECTOR	Kim Sopha

416	CAL	Positive	2.84
417	CAL	Positive	1.1
418	CAL	Positive	1
419	CAL	Positive	0.9
420	WALL DRYWALL B WHITE Housing	Negative	0
421	WALL DRYWALL C WHITE Housing	Negative	0
422	WALL PLASTER D WHITE Housing	Negative	0
423	WALL METAL A WHITE Housing	Negative	0
424	WALL DRYWALL A WHITE Housing	Negative	0
425	WALL DRYWALL A WHITE Housing	Negative	0
426	CAL	Positive	1.1
427	CAL	Positive	1.1
428	CAL	Positive	1