

1014 Williamson Street Window Project

Unit 3 – 3rd floor

Photos 1-6 are for the right window facing the street on the third floor. Pictures 1 and 2 show different brackets holding the bottom sash together. Pictures 3-6 show the deterioration of the wood. This window has new glass, no ropes and will not lock.

Photos 7-15 are for the middle window facing the street on the third floor. Pictures 7 and 8 show the broken and deteriorating bottom rail on the top sash close up. Pictures 9 and 10 are the same areas from a little distance. This window would not open and has new glass and no ropes. Pictures 11-15 show the deterioration of the sides and sill area.

Photos 16-24 are for the left window facing the street on the third floor. I believe this window is the only one with old glass. This window has no ropes. Pictures 18-20 show the extensive decay of this window along with the added weather stripping and duct tape. Pictures 21-23 show other damage on this window. Picture 24 shows the extensive deterioration of the sill area.

Photos 25-36 are for the kitchen window on the west side of the building. This window does have ropes, new glass and no lock. All of these pictures show extensive deterioration.

Photos 37-46 are for the bedroom window facing the rear of the building. This window has no ropes, new glass and doesn't lock. All of these pictures show the extensive deterioration of the window.

Photos 47-54 are for the hallway window facing the rear of the building. This window has 1 rope, new glass and can't lock. All of these photos show the deterioration of this window.

Photos 55-60 are for the bathroom window on the east side of the building. All of these pictures show the extreme deterioration of this window. This window has no ropes, no lock and new glass.

Photos 61-72 are for the closet window on the east side of the building. This window has new glass, no ropes and cannot lock. All of these pictures show the extensive deterioration of this window.

Photos 73-81 are for the 2 dining room windows on the east side of the building. Each window has only 1 rope, new glass and cannot lock. All of these pictures show the extensive deterioration of these 2 windows. They also show where weather stripping has been added as well as duct tape to cover the gaps.