

Photos



Figure 1. North east corner of the building.



Figure 2. North elevation of 923 Clymer. Original materials have been replaced or covered with vinyl siding and windows infilled. The porch has been rebuilt.



Figure 3. Historic image of 923 Clymer from AHI website.



Figure 4. Basement Utility Room.



Figure 5. Basement access stairs.



Figure 6. North entrance door.



Figure 7. Primary stair to second floor.



Figure 8. First floor living room.



Figure 9. Second floor living room and kitchen.



Figure 10. Second floor bathroom.