

Presentation addressing UDC Comments:


- 1. Public Parking information
- 2. Thru-block pedestrian pathway
- 3. Building set back of 15'+
- 4. Revised Lighting Plans
- 5. Landscape planting changes
- 6. Building top refinement




E. WASHINGTON A

Public Parking:

- 1. 150 new stalls
- 2. Total Stalls 540
- 3. Public Stalls: 91 to 145
- 4. 2 entry points
- 5. PARCS system
- 6. Open 24/7
- 7. Signage added













Parking Summary

Use	Stalls
WHEDA Building	225
Hotel Indigo	55 to 70
Hilton Hotel	100 to 150
Public Use Stalls	96 to 161 (17% to 27%)
Total Stalls	541




Through-block pedestrian path:

- 1. Landscaping
- 2. Lighting
- 3. Mural
- 4. Covered drop off








E. MAIN ST.



















GABION SEAT WALLS - 2'x2' & 4'x2'




















Building Set Back: 15'-9" from property line to furthest protruding building element.

Building Top: Current version Previous version














Sustainability

- Internal block structured parking
- Green roofs, outdoor roof-top public spaces
- 15th floor roof is 65% vegetative cover
- Heat pump system with efficient centralized chiller and boilers
- LED lighting throughout with occupancy sensors and dimming
- Through-block pedestrian connection
- Mix of uses on the block with shared & public parking
- Less than 40% total glazing
- Increased density on an existing urban site
- Brownfield site cleanup
- Long-life durable exterior materials brick, precast concrete
- Window muntins increase bird friendly glazing
- Working with Focus on Energy to identify additional energy efficiencies
- Historic Adaptive Reuse on the block
- Boilers are 95% efficient
- Water heaters have a 94% thermal efficiency rating
- Fluid coolers have high efficiency motors with added VFDs for increased efficiency










Appendix
929 East Washington Avenue
Dual Brand Hotel: Hilton Tempo and Homewood Suites

















6TH FLOOR NORTH ROOF TERRACE PLAN

0 10' 20'

NORTH

















































- 1 BRICK VENEER
- 2 PAINTED METAL PANEL, MATTE BLACK
- 3 PRECAST CONCRETE BAND, BLACK
- 4 CONCEALED FASTENER FORMED METAL PANEL, MATTE BLACK
- 5 STEEL CHANNEL, PAINTED MATTE BLACK
- 6 ALUMINUM OR FIBERGLASS COMPOSITE WINDOW SYSTEM, BLACK
- 7 ALUMINUM OR STEEL TRELLIS
- 8 ALUMINUM STOREFRONT SYSTEM, BLACK
- 9 CAST CONCRETE WITH BOARD FORMED LINER
- 10 ALUMINUM HANDRAIL, BLACK
- 11 STEEL TURNBUCKLE AND CROSS-BRACING
- 12 METAL CORNICE, MATTE BLACK
- 13 PAINTED STEEL CHANNEL COLUMN, BLACK
- 14 EXISTING PARKING STRUCTURE
- 15 METAL PANELS SALVAGED FROM PARKING STRUCTURE
- 16 STONE OR CAST STONE BASE COURSE, BLACK
- 17 GLASS AT GARAGE LEVELS TO BE TRANSLUCENT
- 18 METAL LOUVERED PANELS, BLACK





- 1 BRICK VENEER
- 2 PAINTED METAL PANEL, MATTE BLACK
- 3 PRECAST CONCRETE BAND, BLACK
- 4 CONCEALED FASTENER FORMED METAL PANEL, MATTE BLACK
- 5 STEEL CHANNEL, PAINTED MATTE BLACK
- 6 ALUMINUM OR FIBERGLASS
 COMPOSITE WINDOW SYSTEM,
 BLACK
- 7 ALUMINUM OR STEEL TRELLIS
- 8 ALUMINUM STOREFRONT SYSTEM, BLACK
- 9 CAST CONCRETE WITH BOARD FORMED LINER
- 10 ALUMINUM HANDRAIL, BLACK
- 11 STEEL TURNBUCKLE AND CROSS-BRACING
- 12 METAL CORNICE, MATTE BLACK
- PAINTED STEEL CHANNEL COLUMN, BLACK
- 14 EXISTING PARKING STRUCTURE
- 15 METAL PANELS SALVAGED FROM PARKING STRUCTURE
- 16 STONE OR CAST STONE BASE COURSE, BLACK
- 17 GLASS AT GARAGE LEVELS TO BE TRANSLUCENT
- 18 METAL LOUVERED PANELS, BLACK






- 1 BRICK VENEER
- 2 PAINTED METAL PANEL, MATTE BLACK
- 3 PRECAST CONCRETE BAND, BLACK
- 4 CONCEALED FASTENER FORMED METAL PANEL, MATTE BLACK
- 5 STEEL CHANNEL, PAINTED MATTE BLACK
- 6 ALUMINUM OR FIBERGLASS COMPOSITE WINDOW SYSTEM, BLACK
- 7 ALUMINUM OR STEEL TRELLIS
- 8 ALUMINUM STOREFRONT SYSTEM, BLACK
- 9 CAST CONCRETE WITH BOARD FORMED LINER
- 10 ALUMINUM HANDRAIL, BLACK
- 11 STEEL TURNBUCKLE AND CROSS-BRACING
- 12 METAL CORNICE, MATTE BLACK
- 13 PAINTED STEEL CHANNEL COLUMN, BLACK
- 14 EXISTING PARKING STRUCTURE
- 15 METAL PANELS SALVAGED FROM PARKING STRUCTURE
- 16 STONE OR CAST STONE BASE COURSE, BLACK
- 17 GLASS AT GARAGE LEVELS
 TO BE TRANSLUCENT
- 18 METAL LOUVERED PANELS, BLACK









3 PRECAST CONCRETE BAND,

4 CONCEALED FASTENER FORMED

METAL PANEL, MATTE BLACK

5 STEEL CHANNEL, PAINTED

7 ALUMINUM OR STEEL TRELLIS

10 ALUMINUM HANDRAIL, BLACK

12 METAL CORNICE, MATTE BLACK

11 STEEL TURNBUCKLE AND CROSS-BRACING

13 PAINTED STEEL CHANNEL COLUMN, BLACK
14 EXISTING PARKING STRUCTURE

15 METAL PANELS SALVAGED FROM PARKING STRUCTURE

16 STONE OR CAST STONE

BASE COURSE, BLACK

17 GLASS AT GARAGE LEVELS

TO BE TRANSLUCENT

18 METAL LOUVERED

PANELS, BLACK

9 CAST CONCRETE WITH BOARD FORMED LINER

8 ALUMINUM STOREFRONT SYSTEM,

BRICK VENEER
 PAINTED METAL PANEL,
 MATTE BLACK

BLACK

BLACK

BLACK

MATTE BLACK

6 ALUMINUM OR FIBERGLASS
COMPOSITE WINDOW SYSTEM.





- Black Precast Panels
 Black Granite Stone Base
 Brick Old Chicago
 Brick Black
 Aluminum Window Frames Black Anodized
 Painted Metal Panels and Louvers Matte Black
 Steel Painted Black
 Translucent Glass Parking Floors







929 East Washington Avenue Hotel - 2016.36.02.4 01/10/24

Translucent glass lit up from behind at night.













Exterior Material Inspiration



Project site along E. Washington Ave. (Phase 1 Parking Ramp is visible in background)



Madison Credit Union at E. Washington Ave. and S. Brearly St.



Hotel Indigo at E. Washington Ave. and S. Paterson St.

E. WASHINGTON AVE.

