_ANDMARKSCOMMISSION APPLICATION

Complete all sections of this application, making sure to note the requirements on the accompanying checklist (reverse).

If you need an interpreter, translator, materials in alternate formats or other accommodations to access these forms, please call (608) 266-4635

907 10,45

Grocer

City of Madison Planning Division 215 Martin Luther King Jr Blvd POBox 2985 Madison, WI 53701-2985 (608) 266-4635



١	LO	CA	T	1	AC	Į

Project Address: 807	JENIFER STREET			_AldermanicDistrict:(٥
2. PROJECT					
Project Title/ Description:	REROOFING & EXTE	RIOR REPAIRS, E	EE A	TTACHMENTS	
This is an application for: (d	neck all that apply)			Legistar#:	
or Designated Landmar		strict			
☐ Mansion Hill		☐ First Settlement		DATESTAMP	
☐ University Heights	☐ Marquette Bungalows	□ Landmark			
□ Land Division/ Combina or to Designated Landn□ Mansion Hill	tion in a Local Historic District nark Site (specify)**: □ Third Lake Ridge	☐ First Settlement	DPCED USE ONLY		
☐ University Heights	☐ Marquette Bungalows	□ Landmark	Bus		
☐ Demolition			DPCE		
☐ Alteration/ Addition to	a building adjacent to a Designa	ated Landmark			
☐ Variance from the Histo	oric Preservation Ordinance (Ch	apter 41)			
☐ Landmark Nomination/ (Please contact the His ☐ Other (specify):		Preliminary Zoning Review Zoning Staff Initial:	W		
3. <u>APPLICANT</u>				Date: / /	
Applicant's Name: <u>GAR</u>	TIPLER	Company:			10
	JEWIFER STREET		N	WI 5370	3
	Street		Oty		žρ
	352 4695	Email: GARYTIP	8778@	26MAIL, COM	
Property Owner (if not applied	cant):				
Address:	Street .		Oty	State Z	
Property Owner's Signature	$\alpha \lambda : I$		Date		Ž ip
residential development of over assistance), then you likely are s	ORDINANCE If you are seeking approval of r 10 dwelling units, or if you are seeking assi subject to Madison's lobbying ordinance (Se information. Failure to comply with the lobb	stance from the City with a value of \$10 c. 2.40, MGO). You are required to regist	,000 (includi	ng grants, loans, TIF or similar	296

4. APPLICATION SUBMISSION REQUIREMENTS (see checklist on reverse)

All applications must be filed by 12:00 pm on the submission date with the Preservation Planner, the Department of Planning & Community & Economic Development, Planning Division, located at 215 Martin Luther King Jr Blvd. Applications submitted after the submission date or incomplete applications will be postponed to the next scheduled filing time. Submission deadlines can be viewed here: https://www.cityofmadison.com/dpced/planning/documents/2019LCMeetingScheduleDates.pdf

Building Permit Items for 807 Jenifer Street

Gary Tipler, Owner 608-852-4695, garytip8778@gmail.com

Members of the Landmarks Commission,

This application for a Certificate of Appropriateness is to include re-roofing my house at 807 Jenifer Street, to install an original rear porch door as a window, and to attend to minor exterior repairs, primarily to porches.

I will provide an actual product of the roofing selection and the assembly of the leaf guard and gutter for the commission meeting.

Below is the list of repairs.

Thank you for your consideration.

Gary Tipler

EXTERIOR REPAIRS for 807 JENIFER STREET

ROOF

A complete tear off the pitched roofing is required. The wood sheathing is to be repaired or replaced as needed. The new pitched roof sheathing is to be Owens Corning Duration Series 30-year architectural shingles, drip edge, gutters, leaf guard and downspouts per specifications. The gutter is to be a 6-inch an aluminum K-Style gutter. There will be none installed on the round turret. There were no gutters or downspouts on the house when I bought it in 1997.

The front and side porch pitched roofs are in good condition and to remain. The front porch has a K-Style gutter and I'd like to add one to the Spaight-side porch. The flat roof of the rear porch is in good condition and is to remain. See Gallardo Roofing, LLC contract specifications.

REPAIRS, FRONT PORCH

Replace deteriorated wood, treads and risers of front porch stoop to match existing. Add cast concrete top piece to match existing one.

REPAIRS, REAR PORCH

Replace deteriorated rail and post sheathing to match existing. Replace steps to rear porch and add a simple handrail hung by brackets attached to the adjoining wall.

Reinstall horizontal 1x10 sheathing to cover porch floor framing. Add moldings to match other porches.

Replace 1x sheathing and moldings of porch roof as needed.

SIDING & DOOR, REAR PORCH

Reinstall original door as a window to the half bath adjoining the rear porch. Trims to match the dimensions but not the detail of original casing around the door will be installed along with missing lapped siding to match existing. A simple wood storm door is to be installed outside to give the fully original appearance. The door had been removed by the previous owner and a shower was built through the exterior wall onto the porch.

WINDOW CASING and TRIM REPAIRS

Deteriorated original window casing on a Spaight-side window and a kitchen window will be replaced with original remnant casing that is a match. A section of the deteriorated watertable sill moldings and lapped siding above it adjoining the Spaight-side porch will be replaced with sill moldings and lapped siding to match originals. The pine sill molding was installed at part of the exterior renovations I undertook in 1999 or so. It was detailed to match a shadow of the original which had been removed to cover the house in aluminum siding in the 1970s.

OVERHANGING WOOD EVES

The wood fascia and the beaded board wood soffits are to be repaired and replaced where damaged and missing with wood to match. Sistering rafters may be required.

ATTIC DORMER SHINGLES & TRIMS

The original sawn cedar shingles sheathing the attic dormer on the Spaight side have some warped and curled shingles and some of the small ones along the edge are missing. The curled pieces will be removed and replaced with sawn cedar shingles to match. Missing cedar shingles will be replaced, as well. Any original areas that remain intact may be left in place, such as on the sides. There were small bracket details on the dormer front that were removed at the time when all protruding trims on the house were removed to re-side it with aluminum siding in the 1970s by the previous owner. Only the outlines remain where they were located below the window. Simple flat pieces will be installed to the same dimensions as the missing brackets.

MASONRY REPAIRS

The northeast corner of the house was damaged by the severe vibrations of the Jenifer Street reconstruction a couple years ago. Corners are particularly vulnerable to that intensity of vibrations. It only became evident over time. This will be rebuilt and tuck pointing to repair select other areas where needed. Original loose stones will be reset. The mortar is to be largely composed of sand and lime so to match the content, color and physical characteristics of existing mortar.

807 JENIFER STREET - AREAS OF PROPOSED REPAIRS



View East fr Jenifer



N fr Spaight





Front Porch Stoop



Rear Porch lkg S along Jenifer





Rear Porch Ikg NW





Rear porch door/window reinstall



Spaight-side dormer sheathing repairs



Proposed K-Style gutter and leaf guard



Satellite view, 807 Jenifer. The house faces neither Jenifer, nor Spaight.