

Certificate of Appropriateness Review for 1450 Monroe St.

April 8, 2019



Proposed Work

Field House

- Improve appearance of building with façade cleaning.
- Fix masonry by filling cracks/voids and replacing broken stones as budget allows.
- Improve the thermal performance of the building.
- Addition of lighting to match existing.
- Terra Cotta replacement as budget allows.

Plaza

- Improve condition and function of existing parking lot.
- Install piers and fencing to match Breese Terrace/North stadium plaza area.
- Enlarge plaza area with terraced seating, special paving, and landscaping.
- Implement a new retaining wall with fence along Little Street/Monroe Street. Encroachment request.
- Rebuild historic stairs and stone wing walls to Field House per Wisconsin Historical Society.



Proposed Work

Window Scope

- Removal of the existing windows and replacing with an aluminum replica (SRW windows by Diamond Windows)
- The windows on the North Elevation will remain and have the black paint removed from the existing glass.
- The existing wood window frames above the doors will be repaired and repainted. The black paint will be removed.

Door Scope

- Remove and replace all doors on the South elevation of the Field House as well as Gate B and Gate C doors
- Existing wood frames are to be stripped of all paint
- Existing wood door frames are to be repaired and repainted with exterior grade paint
- New solid wood doors are to be furnished and installed with nine true divided lites per door



History of Property

- Constructed in 1929
- Renaissance Revival style
- 1998: Listed in the NR
- 2009: City of Madison Landmark
















CONDITION ASSESSMENT SUMMARY - SOUTH ELEVATION - BAY S2

- AD1 NON-ORIGINAL HOLLOW-METAL DOORS ARE IN GOOD CONDITION
- ADS SEALANT AT DOOR PERIMETER IN POOR CONDITION
- AD4 NON-ORIGINAL PLASTER DOOR SURROUND IN FAIR CONDITION


AE2 LIGHT FIXTURE MISSING - ORIGINAL FIXTURE MOUNTING HARDWARE REMAINS

- MASONRY
- AM1 EVIDENCE OF PREVIOUS TUCKPOINTING EFFORT WITH NON-MATCHING MORTAR
- AMS EVIDENCE OF TERRA COTTA SPALLING
- AM4 FRACTURED TERRA COTTA UNIT(S) AM5 DIAGONAL STEP CRACKING PRESENT
- AMB BRICK AT THE PERIMETER OF THE WINDOW APPEARS TO BE IN GOOD CONDITION
- AM7 MASONRY STAINING PRESENT AM10 FLASHING AND SEALANT IN POOR CONDITION
- AM11 CRACK OBSERVED IN "W" CARTOUCHE


WINDOWS

- AWI DETERIORATED FINISH AT METAL WINDOW
- AWZ GLAZING UNITS HAVE BEEN PAINTED ON THE INTERIOR FACE
- AW3 SEALANT AT WINDOW PERIMETER IN POOR CONDITION

UW-MADISON FIELD HOUSE HISTORIC STRUCTURE REPORT





















Applicable Standards

- As a designated Landmark, SOI Standards
- As a State Property, does not require a COA
- As a PD, LC can provide recommendations to the Director



Staff Recommendation

Staff recommends that the Landmarks Commission provide the advisory opinion to the Director that the design meets the intent and conditions for alterations to a City Landmark with the following condition:

 Replacement windows should feature low-E glass in order to better replicate the historic character of the original windows.

