


NORTH SIDEWALK AND CANOPY

WEST BAY TO BE DEMOLISHED



VIEW UNDER CANOPY TOWARD PARKING LOT



NORTHWEST CORNER

WEST BAY TO BE DEMOLISHED.



WEST FACADE, VIEW FROM N CHARTER STREET



**VIEW OF WEST FACADE** 

BRICK BUILDING AT THE CORNER OF REGENT AND N CHARTER

STRUCTURAL INSTABILITY RESULTING FROM POOR SOIL CONDITIONS -PORTION OF THE BUILDING (WEST BAY) TO BE DEMOLISHED.

PROJ. #:	20001-01
© SKETCHWORKS	


**Project Status** 

**ARCHITECTURE 2021** 

**EXISTING CONDITIONS -EXTERIOR** 

**EXISTING CONDITIONS -INTERIOR** 






**INTERIOR PARTITIONS** 




**EXISTING GABLE TRUSSES** 



**EXISTING STRUCTURE TO REMAIN** 



**GABLE STRUCTURE AND WEST BAY** 



TRUSSES TO REMAIN

FRONT FOUR BAYS OF ROOF DECK TO REMAIN

**EXISTING ROOF DECK AND STRUCTURE**