Bailey, Heather

From: Bailey, Heather
Sent: Thursday, March 9, 2023 2:36 PM
To: Moskowitz, Jacob
Cc: Bannon, Katherine J
Subject: RE: Fire Report

The house at 311 E Dean was constructed in 1955. There is no WHS site file and no City preservation file for this property. Staff recommendation to the Landmarks Commission would be that this property has no known historic value. I will provide that recommendation to the Landmarks Commission at their April 3 meeting and will let them now that the demolition of this fire damaged building was approved administratively due to health & safety reasons.

Heather L. Bailey, Ph.D. *(she/her)*
Preservation Planner
Neighborhood Planning, Preservation + Design Section

Department of Planning + Community + Economic Development
Planning Division
215 Martin Luther King, Jr. Blvd.; Suite 017
PO Box 2985
Madison WI 53701-2985
Email: hbailey@cityofmadison.com *Phone: 608.266.6552*

From: Moskowitz, Jacob <JMoskowitz@cityofmadison.com>
Sent: Wednesday, March 8, 2023 3:47 PM
To: Bailey, Heather <HBailey@cityofmadison.com>
Cc: Bannon, Katherine J <KBannon@cityofmadison.com>
Subject: FW: Fire Report

Jacob Moskowitz (He/Him)
Assistant Zoning Administrator
608-266-4560
jmoskowitz@cityofmadison.com

Department of Planning & Community & Economic Development
Building Inspection Unit
215 Martin Luther King, Jr. Blvd.
P. O. Box 2984
Madison, WI 53701

From: Ben Mueller <ben@muellerbuilderswi.com>
Sent: Wednesday, March 1, 2023 8:39 AM
To: Moskowitz, Jacob <JMoskowitz@cityofmadison.com>
Subject: Fire Report

Caution: This email was sent from an external source. Avoid unknown links and attachments.

Jacob,

Attached is the Fire report for 311 E. Dean Ave.

Thanks,
Ben

--

Benjamin Mueller
General Contractor

ADDRESS · 729 Prospect Ave, Portage, WI 53901
PHONE · 608-617-5616
WEB · muellerbuilderswi.com



City of Madison Fire Department

Fire/Arson Investigation Unit

314 W. Dayton St., Madison, WI 53703-2506

Phone: 608-266-4484 • Fax: 608-267-1100 • E-mail: *fire@cityofmadison.com*

June 6, 2022

Andrew Marcellino
311 E Dean Ave
Madison, WI 53716

SUBJECT: **MFD INVESTIGATIVE REPORT # 22-155544, 311 E Dean Ave - 4/27/2022**
Claim No.: n/a

We have received your request for a copy of the report(s) associated with the matter identified above. I have reviewed the report(s) and authorized release of an edited copy. Information in the report was redacted for the reason(s) specified below:

☒ I have redacted information in this report due to the fact that it contains confidential juvenile material. Wis. Stats. 48.396 and 938.396 relating to peace officer's records of juveniles prohibit the release of such records except in certain circumstances.

☒ I have redacted information in this report as release of this information would reveal highly personal and private medical and/or mental health information. Disclosure of the information would violate multiple state and federal laws and the disclosure of such personal and sensitive information would not further the intent of the Wisconsin Public Records Laws: that of keeping the public informed of the operations of its government.

☒ In compliance with various state and federal statutes, I have redacted Personally Identifiable Information (PII) from the enclosed records in order to prevent identity theft crimes. This PII is composed of specific addresses, dates of birth, and driver's license numbers, social security numbers, and private phone numbers. These statutes include but are not limited to the Federal Drivers' Privacy Protection Act, the Privacy Act and Wis. Stats. §§ 15.04, 16.61, 19.65, 19.67, 19.68, 19.69, 19.77, 19.80, 45.81, 46.283, 46.284. 46.2895, 66.0903(10), 77.61, 85.61, 100.54, 103.49, 115.297, 118.125, 134.405, 196.23, 441.50, 450.145, 604.04(8), 610(6), 756.04, 949.04, and 949.36.

☐ I have redacted information under authority of Wisconsin Statute 19.36(8) Identities of Law Enforcement Informants. I have redacted that information in this report which is necessary to safeguard the identity of the informant.

After consultation with the City Attorney's office, I have reached the above conclusions as dictated by statutes, case law and after weighing the reasons for non-disclosure against the public interest in disclosure. For the reasons set forth above, I have concluded that the records may only be released after having redacted the above described information. Pursuant to Sec. 19.35(4)(b) Wis. Stats., I advise you that this determination not to disclose a portion of the requested record is subject to review by mandamus under Sec. 19.37(1) Wis. Stats., or upon application to the Wisconsin Attorney General or the Dane County District Attorney.

Sincerely,

Jerome Buechner, Division Chief
Fire / Arson Investigation Division

JDB/hld
cc: Mayor's Office, City Attorney's Office

NFIRS-1 Basic

A

FDID	State	Month	Day	Year	Station	Number	Exposure
13010	WI	04	27	2022	Station #5 (05)	22-155544	0

B **Location Type**

Census tract:

- [x] Street Address
- [ ] Intersection
- [ ] In Front Of
- [ ] Rear Of
- [ ] Adjacent To
- [ ] Directions
- [ ] US National Grid

Number	Prefix	Street or Highway	Street Type	Suffix
311	E-East	DEAN	AVE-Avenue	

Apt./Suite/Room	City	State	Zip Code
	Madison	WI	53716

Cross Street: Lance Ln/Seth Cir

C **Incident Type**

111-Building fire

D **Aid Given Or Received**

Their FDID | Their State

Their Incident Number

- [ ] 1 Mutual Aid Received
- [ ] 2 Auto. Aid Received
- [ ] 3 Mutual Aid Given
- [ ] 4 Auto. Aid Given
- [ ] 5 Other Aid Given
- [x] None

E1 **Dates and Times**

Alarm	04	27	2022	11:37
Arrival	04	27	2022	11:42
Controlled				
Last Unit Cleared	04	27	2022	14:11

E2 **Shifts and Alarms**

Shift or Platoon	Alarms	District
C		5

E3 **Special Studies**

ID# | Value

F **Actions Taken**

11-Extinguishment by fire service personnel

Primary Action Taken

G1 **Resources**

☑ Apparatus or Personnel Module is used.

	Apparatus	Personnel
Suppression	7	25
EMS	2	4
Other	2	2

☐ Resource counts include aid received resources.

G2

Estimated Dollar Losses and Values

Losses: Required for all fires if known. Optional for all non-fires. None

Property: $ ☑

Contents: $ ☑

Pre-Incident Values: Optional None

Property: $ ☑

Contents: $ ☑

Completed Modules

☐ 2 - Fire
☐ 3 - Structure Fire
☐ 4 - Civilian Fire Cas.
☐ 5 - Fire Service Cas.
☐ 6 - EMS
☐ 7 - HazMat
☐ 8 - Wildland Fire
☐ 9 - Apparatus
☐ 10 - Personnel
☐ 11 - Arson

H1 **Casualties** ☐ None

	Deaths	
Fire Service	0	
Civilian	0	

H2 **Detector**

Required for Confined Fires

☐ 1 - Detector Alerted Occupants
☐ 2 - Detector Did Not Alert Them
☐ 3 - Unknown

H3

Hazardous Materials Release

☐ 1 - Natural Gas
☐ 2 - Propane Gas
☐ 3 - Gasoline
☐ 4 - Kerosene
☐ 5 - Diesel Fuel / Fuel Oil
☐ 6 - Household Solvents
☐ 7 - Motor Oil
☐ 8 - Paint
☐ 0 - Other
☑ None

I **Mixed Use Property**

☐ Not Mixed
☐ 10 - Assembly Use
☐ 20 - Education Use
☐ 33 - Medical Use
☐ 40 - Residential Use
☐ 51 - Row Of Stores
☐ 53 - Enclosed Mall
☐ 58 - Business and Residential
☐ 59 - Office Use
☐ 60 - Industrial Use
☐ 63 - Military Use
☐ 65 - Farm Use
☐ 00 - Other Mixed Use

J **Property Use** ☐ None

Structures

131 ☐ Church, Place of Worship
161 ☐ Restaurant or Cafeteria
162 ☐ Bar/Tavern or Nightclub
213 ☐ Elementary School, Kindegarten
215 ☐ High School, Junior High
241 ☐ College, Adult Education
311 ☐ Nursing Home
331 ☐ Hospital
341 ☐ Clinic, Clinic-Type Infirmary
342 ☐ Doctor/Dentist Office
361 ☐ Prison or Jail, Not Juvenile
419 ☑ 1- or 2-Family Dwelling
429 ☐ MultiFamily Dwelling
439 ☐ Rooming/Boarding House
449 ☐ Commerical Hotel or Motel
459 ☐ Residential, Board and Care
464 ☐ Dormitory/Barracks
519 ☐ Food and Beverage Sales
539 ☐ Household Goods, Sales, Repairs
571 ☐ Gas or Service Station
579 ☐ Motor Vehicle/Boat Sales/Repairs
599 ☐ Business Office
615 ☐ Electric-Generating Plant
629 ☐ Laboratory/Science Laboratory
700 ☐ Manufacturing Plant
819 ☐ Livestock/Poultry Storage (Barn)
882 ☐ Non-Residential Parking Garage
891 ☐ Warehouse

Outside

124 ☐ Playground or Park
655 ☐ Crops or Orchard
669 ☐ Forest (Timberland)
807 ☐ Outdoor Storage Area
919 ☐ Dump or Sanitary Landfill
931 ☐ Open Land or Field
936 ☐ Vacant Lot
938 ☐ Graded/Cared for Plot of Land
946 ☐ Lake, River, Stream
951 ☐ Railroad Right-of-Way
960 ☐ Other Street
961 ☐ Highway/Divided Highway
962 ☐ Residential Street/Driveway
981 ☐ Construction Site
984 ☐ Industrial Plant Yard

Property Use:

Description

Look up and enter a Property Use code and description only if you have NOT checked a Property Use box.

K2

Owner

Local Option | Person/Entity Type | Business Name (if applicable) | Phone Number

Mr., Ms., Mrs. | First Name | MI | Last Name | Suffix

Number | Prefix | Street or Highway | Street Type | Suffix

Post Office Box | Apt./Suite/Room | City

State | Zip Code

L **Remarks:**

E5 on scene to dispatched address. One story wood frame construction. Dark grey smoke visible from approach B, C and D divisions. E5 command called for an additional engine and ambulance.

Assigned E14 water supply. 360 completed and fire attack initiated "A" division 200' 1 3/4". C division four seasoned porch noted. Assigned first in ladder ventilation. Assigned M5 backup line off of E5 300' 1 3/4".

Neighbor stated that home is thought to be unoccupied. Same neighbor handed me a slip of paper with the back door code to gain access to home. Code was not used and forcible entry to front door storm door and main door accomplished with irons.

On entry dark smoke banked to the floor. Left hand hose advancement first floor. No fire located on stretch to the basement. Fire located in basement behind stairs B C corner. Horizontal ventilation assigned and accomplished. Fire under control and knocked down.

Overhaul operations performed and additional hot spots extinguished. Scene ventilated and monitored. Scene left to FIT. E5 returned.

[redacted] approximately 12 steps to the back of preceding firefighter during hose advancement for fire attack. [redacted]. A [redacted] completed 04/27/22. -Crossen

M **Authorization**

fddmc	Crossen, David	Lieutenant	E5	04/27/2022
Officer In Charge ID	Signature	Position or Rank	Assignment	Date
fddmc	Crossen, David	Lieutenant	E5	04/27/2022
Member Making Report ID	Signature	Position or Rank	Assignment	Date

NFIRS-2 Fire

A

FDID	State	Month	Day	Year	Station	Number	Exposure
13010	WI	04	27	2022	Station #5 (05)	22-155544	0

B

Property Details

B1 1 ☐ Not Residential

Estimated number of residential living units in the building of origin whether or not all units became involved

B2 1 ☐ Buildings Not Involved

Number of buildings involved

B3 ☐ ☑ None ☐ Less than 1 acre

Acres burned (outside fires)

C

On-Site Materials Or Products

On-Site Materials Storage Use

D

Ignition

D1 43-Storage: supplies or tools; dead storage

Area of Fire Origin

D2

Heat Source

D3

Item First Ignited

D4

Type of Material First Ignited

E1

Cause of Ignition

☐ 1 - Intentional
☑ 2 - Unintentional
☐ 3 - Failure of Equipment or Heat Source
☐ 4 - Act of Nature
☐ 5 - Cause Under Investigation
☐ U - Cause Undetermined After Investigation

E2

Factors Contributing to Ignition

Undetermined

Factor Contributing to Ignition

E3

Human Factors Contributing to Ignition

Check all applicable boxes

☑ None
☐ 1 - Asleep
☐ 2 - Possibly impaired by alcohol or drugs
☐ 3 - Unattended person
☐ 4 - Possibly Mentally Disabled
☐ 5 - Physically Disabled
☐ 6 - Multiple Persons Involved
☐ 7 - Age Was A Factor

Estimated Age of Person Involved

☐ Male ☐ Female

F1

Equipment Involved In Ignition

☑

Equipment Involved

Brand
Model
Serial #
Year

F2

Equipment Power Source

Equipment Power Source

F3

Equipment Portability

☐ 1 - Portable
☐ 2 - Stationary

Portable equipment normally can be moved by one or two persons.

G

Fire Suppression Factors

H1

Mobile Property Involved

- ☐ 1 - Not involved in ignition, but burned
- ☐ 2 - Involved in ignition, but did not burn
- ☐ 3 - Involved in ignition and burned
- ☑ None

H2

Mobile Property Type and Make

Mobile Property Type

Mobile Property Make

Mobile Property Model

Year

State

License Plate Number

VIN

Local Use

- ☐ Pre-Fire Plan Available
- ☐ Arson Report Attached
- ☐ Police Report Attached
- ☐ Coroner Report Attached
- ☐ Other Reports Attached

NFIRS-3 Structure Fire

I1 Structure Type

- [x] 1 - Enclosed Building
- [ ] 2 - Portable/Mobile Structure
- [ ] 3 - Open Structure
- [ ] 4 - Air-Supported Structure
- [ ] 5 - Tent
- [ ] 6 - Open Platform
- [ ] 7 - Underground Structure
- [ ] 8 - Connective Structure
- [ ] 0 - Other

I2 Building Status

- [ ] 1 - Under Construction
- [x] 2 - In Normal Use
- [ ] 3 - Idle, Not Routinely Used
- [ ] 4 - Under Major Renovation
- [ ] 5 - Vacant and Secured
- [ ] 6 - Vacant and Unsecured
- [ ] 7 - Being Demolished
- [ ] 0 - Other
- [ ] U - Undetermined

I3 Building Height

1 — Number of Stories At/Above Grade

1 — Number of Stories Below Grade

I4 Main Floor Size

1000 — Total Square Feet

OR

____ BY ____ — Length (ft) X Width (ft)

J1 Fire Origin

0 — [ ] Below Grade

Story of Fire Origin

J2 Fire Spread

- [ ] Confined to Object of Origin
- [x] 2 - Confined to Room of Origin
- [ ] 3 - Confined to Floor of Origin
- [ ] 4 - Confined to Building of Origin
- [ ] 5 - Beyond Building of Origin

J3 Number of Stories Damaged By Flame

____ Number of Stories w/Minor Damage (1-24%)

____ Number of Stories w/Significant Damage (25-49%)

____ Number of Stories w/Heavy Damage (50-74%)

____ Number of Stories w/Extreme Damage (75-100%)

*Count the roof as part of the highest story

K Type of Material Contributing Most to Flame Spread

K1 [ ] Item Contributing Most to Flame Spread

K2 [ ] Type of Material Contributing Most To Flame Spread

L1 Presence of Detectors

- [ ] N - None Present
- [x] 1 - Present
- [ ] U - Undetermined

L2 Detector Type

- [x] 1 - Smoke
- [ ] 2 - Heat
- [ ] 3 - Combination of Smoke and Heat
- [ ] 4 - Sprinkler, Water Flow Detection
- [ ] 5 - More Than One Type Present
- [ ] 0 - Other
- [ ] U - Undetermined

L3 Detector Power Supply

- [ ] 1 - Battery Only
- [ ] 2 - Hardwire Only
- [ ] 3 - Plug-In
- [ ] 4 - Hardwire With Battery
- [ ] 5 - Plug-In With Battery
- [ ] 6 - Mechanical
- [ ] 7 - Multiple Detectors & Power Supplies
- [ ] 0 - Other
- [x] U - Undetermined

L4 Detector Operation

- [ ] 1 - Fire Too Small To Activate
- [x] 2 - Operated
- [ ] 3 - Failed To Operate
- [ ] U - Undetermined

L5 Detector Effectiveness

- [ ] 1 - Alerted Occupants, Occupants Responded
- [ ] 2 - Alerted Occupants, Occupants Failed to Respond
- [x] 3 - There Were No Occupants
- [ ] 4 - Failed to Alert Occupants
- [ ] U - Undetermined

L6 Detector Failure Reason

- [ ] 1 - Power Failure, Shutoff, or Disconnect
- [ ] 2 - Improper Installation or Placement
- [ ] 3 - Defective
- [ ] 4 - Lack of Maintenance, Dirty
- [ ] 5 - Battery Missing or Disconnected
- [ ] 6 - Battery Discharged or Dead
- [ ] 0 - Other
- [ ] U - Undetermined

M1

Presence of Automatic Extinguishing System

- [x] N - None Present
- [ ] 1 - Present
- [ ] 2 - Partial System Present
- [ ] U - Undetermined

M2

Type of Automatic Extinguishing System

- [ ] 1 - Wet-Pipe Sprinkler
- [ ] 2 - Dry-Pipe Sprinkler
- [ ] 3 - Other Sprinkler System
- [ ] 4 - Dry Chemical System
- [ ] 5 - Foam System
- [ ] 6 - Halogen-Type System
- [ ] 7 - Carbon Dioxide System
- [ ] 0 - Other
- [ ] U - Undetermined

Required if fire was within designed range of AES

M3

Operation of Automatic Extinguishing System

- [ ] 1 - Operated/Effective
- [ ] 2 - Operated/Not Effective
- [ ] 3 - Fire Too Small To Activate
- [ ] 4 - Failed To Operate
- [ ] 0 - Other
- [ ] U - Undetermined

Required if fire was within designed range

M4

Number of Sprinkler Heads Operating

[ ]

Required if system operated

M5

Reason for Automatic Extinguishing System Failure

- [ ] 1 - System Shut Off
- [ ] 2 - Not Enough Agent Discharged
- [ ] 3 - Agent Discharged But Did Not Reach Fire
- [ ] 4 - Wrong Type of System
- [ ] 5 - Fire Not In Area Protected
- [ ] 6 - System Components Damaged
- [ ] 7 - Lack of Maintenance
- [ ] 8 - Manual Intervention
- [ ] 0 - Other
- [ ] U - Undetermined

Required if system failed or not effective

NFIRS-9 Apparatus or Resources

A

FDID	State	Month	Day	Year	Station	Number	Exposure
13010	WI	04	27	2022	Station #5 (05)	22-155544	0

B **Apparatus/Resource**	Dates/Times	Sent	Number of People	Apparatus Use	Actions Taken
ID: C31 Type: 92-Chief officer car	Dispatch: 04/27/2022 11:37 Arrival: 04/27/2022 11:48 Clear: 04/27/2022 12:26	☑ Sent	2	☐ Suppression ☐ EMS ☑ Other	81-Incident command
ID: E11 Type: 11-Engine	Dispatch: 04/27/2022 11:56 Arrival: 04/27/2022 12:46 Clear: 04/27/2022 14:11	☑ Sent	5	☑ Suppression ☐ EMS ☐ Other	87-Investigate fire out on arrival
ID: E14 Type: 11-Engine	Dispatch: 04/27/2022 11:37 Arrival: 04/27/2022 11:44 Clear: 04/27/2022 12:48	☑ Sent	4	☑ Suppression ☐ EMS ☐ Other	81-Incident command 92-Standby
ID: E3 Type: 11-Engine	Dispatch: 04/27/2022 11:43 Arrival: 04/27/2022 11:51 Clear: 04/27/2022 12:04	☑ Sent	0	☑ Suppression ☐ EMS ☐ Other	92-Standby
ID: E5 Type: 11-Engine	Dispatch: 04/27/2022 11:37 Arrival: 04/27/2022 11:42 Clear: 04/27/2022 12:57	☑ Sent	4	☑ Suppression ☐ EMS ☐ Other	81-Incident command 11-Extinguishment by fire service personnel
ID: E8 Type: 11-Engine	Dispatch: 04/27/2022 11:37 Arrival: 04/27/2022 11:45 Clear: 04/27/2022 12:07	☑ Sent	4	☑ Suppression ☐ EMS ☐ Other	51-Ventilate
ID: F71 Type: 92-Chief officer car	Dispatch: 04/27/2022 12:18 Arrival: 04/27/2022 12:18 Clear: 04/27/2022 12:50	☐ Sent	0	☐ Suppression ☐ EMS ☑ Other	86-Investigate
ID: L6 Type: 12-Truck or aerial	Dispatch: 04/27/2022 11:37 Arrival: 04/27/2022 11:46 Clear: 04/27/2022 12:33	☑ Sent	4	☑ Suppression ☐ EMS ☐ Other	21-Search
ID: L8 Type: 12-Truck or aerial	Dispatch: 04/27/2022 11:37 Arrival: 04/27/2022 11:46 Clear: 04/27/2022 12:41	☑ Sent	4	☑ Suppression ☐ EMS ☐ Other	51-Ventilate
ID: M14 Type: 76-ALS unit	Dispatch: 04/27/2022 11:43 Arrival: 04/27/2022 11:55 Clear: 04/27/2022 12:24	☑ Sent	2	☐ Suppression ☑ EMS ☐ Other	72-Assist animal 92-Standby
ID: M5 Type: 76-ALS unit	Dispatch: 04/27/2022 11:37 Arrival: 04/27/2022 11:42 Clear: 04/27/2022 12:11	☑ Sent	2	☐ Suppression ☑ EMS ☐ Other	11-Extinguishment by fire service personnel

NFIRS-10 Personnel

A

FDID	State	Month	Day	Year	Station	Number	Exposure
13010	WI	04	27	2022	Station #5 (05)	22-155544	0

B

Apparatus/Resource

ID: C31
Type: 92-Chief officer car

Dates/Times
Dispatch: 04/27/2022 11:37
Arrival: 04/27/2022 11:48
Clear: 04/27/2022 12:26

Sent: ☑ Sent
Number of People: 2
Apparatus Use: ☐ Suppression ☐ EMS ☑ Other
Actions Taken: 81-Incident command

Personnel ID	Name	Rank	Role	Attend	Actions Taken
FDCAS	Stedman, Che	Division Chief		☐	☐
FDBMV	Vogen, Bradley	Apparatus Engineer		☐	☐

ID: E11
Type: 11-Engine

Dates/Times
Dispatch: 04/27/2022 11:56
Arrival: 04/27/2022 12:46
Clear: 04/27/2022 14:11

Sent: ☑ Sent
Number of People: 5
Apparatus Use: ☑ Suppression ☐ EMS ☐ Other
Actions Taken: 87-Investigate fire out on arrival

Personnel ID	Name	Rank	Role	Attend	Actions Taken
FDGDJ	Johnson, Jr., Guy	Firefighter		☐	☐
FDDAS	Santana, David	Apparatus Engineer		☐	☐
FDSMS	Smith, Shannon	Firefighter Paramedic		☐	☐
FDJAV	Vogen, Jeffrey	Lieutenant		☐	☐
fdkem	McDonald, Kevin	Lieutenant		☐	☐

ID: E14
Type: 11-Engine

Dates/Times
Dispatch: 04/27/2022 11:37
Arrival: 04/27/2022 11:44
Clear: 04/27/2022 12:48

Sent: ☑ Sent
Number of People: 4
Apparatus Use: ☑ Suppression ☐ EMS ☐ Other
Actions Taken: 81-Incident command, 92-Standby

Personnel ID	Name	Rank	Role	Attend	Actions Taken
FDPGB	Burns, Patrick	Apparatus Engineer		☐	☐
FDWWE	Ecker, Wesley	Lieutenant		☐	☐
FDJJS	Suttle, Jason	Firefighter		☐	☐
FDPAS	Schecklman, Paul	Firefighter Paramedic 2		☐	☐

ID: E3
Type: 11-Engine

Dates/Times
Dispatch: 04/27/2022 11:43
Arrival: 04/27/2022 11:51
Clear: 04/27/2022 12:04

Sent: ☑ Sent
Number of People: 0
Apparatus Use: ☑ Suppression ☐ EMS ☐ Other
Actions Taken: 92-Standby

Personnel ID	Name	Rank	Role	Attend	Actions Taken

ID: E5 Dispatch: 04/27/2022 11:37 ☑ Sent 4 ☑ Suppression 81-Incident command

Type: 11-Engine | Arrival: 04/27/2022 11:42 | Clear: 04/27/2022 12:57 | ☐ EMS ☐ Other | 11-Extinguishment by fire service personnel

Personnel ID	Name	Rank	Role	Attend	Actions Taken
FDDMC	Crossen, David	Lieutenant		☐	☐
FDJAS2	Schutz, Joseph			☐	☐
FDBRS	Suter, Brian	Firefighter		☐	☐
FDBLS	Schultz, Brittany	Firefighter		☐	☐

ID: E8 | Type: 11-Engine | Dispatch: 04/27/2022 11:37 | Arrival: 04/27/2022 11:45 | Clear: 04/27/2022 12:07 | ☑ Sent | 4 | ☑ Suppression ☐ EMS ☐ Other | 51-Ventilate

Personnel ID	Name	Rank	Role	Attend	Actions Taken
FDJDA	Ahn, James	Lieutenant		☐	☐
FDDJB2	Belovarac, Daniel	Apparatus Engineer		☐	☐
FDTMD	Donkle, Troy	Firefighter		☐	☐
FDRS	Scott, Richard	Firefighter		☐	☐

ID: F71 | Type: 92-Chief officer car | Dispatch: 04/27/2022 12:18 | Arrival: 04/27/2022 12:18 | Clear: 04/27/2022 12:50 | ☐ Sent | 0 | ☐ Suppression ☐ EMS ☑ Other | 86-Investigate

Personnel ID	Name	Rank	Role	Attend	Actions Taken

ID: L6 | Type: 12-Truck or aerial | Dispatch: 04/27/2022 11:37 | Arrival: 04/27/2022 11:46 | Clear: 04/27/2022 12:33 | ☑ Sent | 4 | ☑ Suppression ☐ EMS ☐ Other | 21-Search

Personnel ID	Name	Rank	Role	Attend	Actions Taken
FDCMC	Christenson, Cole	Firefighter		☐	☐
FDEJM	Mills, Eric	Lieutenant		☐	☐
FDWRB	Boone, William	Firefighter		☐	☐
FDLDM	Moen, Larry	FireFighter		☐	☐

ID: L8 | Type: 12-Truck or aerial | Dispatch: 04/27/2022 11:37 | Arrival: 04/27/2022 11:46 | Clear: 04/27/2022 12:41 | ☑ Sent | 4 | ☑ Suppression ☐ EMS ☐ Other | 51-Ventilate

Personnel ID	Name	Rank	Role	Attend	Actions Taken
FDETF	Fredrickson, Eric	Apparatus Engineer		☐	☐
FDCJH	Hesseling, Cory	Firefighter		☐	☐
FDMRO	O'Connell, Michael	Firefighter		☐	☐
FDRKS	Stebnitz, Ryan	Lieutenant		☐	☐

ID: M14 | Dispatch: 04/27/2022 11:43 | ☑ Sent | 2 | ☐ Suppression | 72-Assist animal

						☑ EMS ☐ Other	92-Standby
Type: 76-ALS unit		Arrival: 04/27/2022	11:55				
		Clear: 04/27/2022	12:24				

Personnel ID	Name	Rank	Role	Attend	Actions Taken
FDLLB2	Buggs, Leon JR	Firefighter		☐	☐
FDMVS	Schabert, Matthew	Firefighter paramedic		☐	☐

ID: M5		Dispatch: 04/27/2022	11:37	☑ Sent	2	☐ Suppression ☑ EMS ☐ Other	11-Extinguishment by fire service personnel
Type: 76-ALS unit		Arrival: 04/27/2022	11:42				
		Clear: 04/27/2022	12:11				

Personnel ID	Name	Rank	Role	Attend	Actions Taken
FDBCP	Powell, Bryce	FireFighter Paramedic		☐	☐
FDAMF	Feys, Alexandra	Firefighter Paramedic		☐	☐

NFIRS-1S Supplemental

A

FDID	State	Month	Day	Year	Station	Number	Exposure
13010	WI	04	27	2022	Station #5 (05)	22-155544	0

Primary Narrative:

E5 on scene to dispatched address. One story wood frame construction. Dark grey smoke visible from approach B, C and D divisions. E5 command called for an additional engine and ambulance.

Assigned E14 water supply. 360 completed and fire attack initiated "A" division 200' 1 3/4". C division four seasoned porch noted. Assigned first in ladder ventilation. Assigned M5 backup line off of E5 300' 1 3/4".

Neighbor stated that home is thought to be unoccupied. Same neighbor handed me a slip of paper with the back door code to gain access to home. Code was not used and forcible entry to front door storm door and main door accomplished with irons.

On entry dark smoke banked to the floor. Left hand hose advancement first floor. No fire located on stretch to the basement. Fire located in basement behind stairs B C corner. Horizontal ventilation assigned and accomplished. Fire under control and knocked down.

Overhaul operations performed and additional hot spots extinguished. Scene ventilated and monitored. Scene left to FIT. E5 returned.

[redacted] approximately 12 steps to the back of preceding firefighter during hose advancement for fire attack. [redacted]. A [redacted] completed 04/27/22. -Crossen

Additional Narrative (#1 of 5):

E14 - ECKER

E5 arrived assumed command, self-assigned to interior fire attack. E14 arrived on scene. Assigned by IC to water supply. Laid LDH into E5. E5 assigned 1st in ladder (Ladder 8) to ventilation.

E14 assumed Incident Command. As Command assigned remainder of E14 crew to backup line and to assist with attack line deployment.

E8 arrived ,requested staging location. Assigned to hydrant W of incident location.

Ladder 6 arrived. Assigned L6 to S&R.

L8 requested permission to initiate vertical ventilation.
Request denied pending location of fire.

E5 advised fire appeared to be in basement via radio.

C31 arrived on location and assumed incident command.

E14 reformed at front door on backup line.

Performed 360. Noted smoke stained cracked basement window on B-division in BC corner. Advised command and E5 of findings via radio.

Post extinguishment, E14 assisted with breakdown of hose.

E14 returned.

Additional Narrative (#2 of 5):

L6 dispatched to the incident address for report of a structure fire.

Upon arrival, L6 was assigned to search by Command.

Primary search of the 1st and 2nd floor were completed, locating only 1 feline who had perished and was removed from the structure and given to its owners.

Once the primary search of the structure had been completed with an all clear and Command notified, L6 assisted E5 in the overhaul and extinguishment of the fire area in the B/C Division corner of the basement level.

Once overhaul was completed, L6 made contact with command who cleared L6 from the incident.

L6 returned.

Lt Mills

Additional Narrative (#3 of 5):

Lt McDonald was added to this report due to [redacted]. E11 was FIT during this fire. Lt Vogen was Lt of E11 at the time. Lt McDonald came in for the second half of the shift. [redacted]. Lt McDonald was added to call in order to complete associated [redacted] Lt McDonald was not active on this call during incident. See ePCR. Other paperwork was completed and filed.

Per FF, during fire investigation at Dean Ave FF Smith was climbing through a lot of debris and garbage bags in the basement. [redacted].

Lt McDonald

Additional Narrative (#4 of 5):

Incident # 22-155544
04/27/2022 Alarm Time 11:36 AM
311 E Dean Ave
Madison, WI 53703

INCIDENT SYNOPSIS:

On April 27, 2022 MFD units responded to a structure fire at the above address. Engine 5 arrived on scene and reported smoke showing on arrival. Engine 5 went to fire attack. Ladder companies 6 and 8 performed search and rescue and ventilation operations. Fire was found in the basement and extinguished. Crews performed overhaul and damage was contained to the basement.
A total of 4 Engines, 2 Ladder Trucks, 2 Medic Units, and 1 Command Car, responded for the Suppression of this fire totaling 30 Madison Fire Department personnel under the command of Division Chief Stedman Che. Additionally, the Fire Investigation Team (FIT) responded with Fire investigators utilizing E11 and Car 80 and 2 Occupation Services Unit (OSU) members Responded to assist displaced residents.

MFD FIT (C-Shift) responded to the scene per the request of Incident Commander, Division Chief Stedman Che to conduct an origin and cause fire investigation.

During the course of this investigation, one interviews was performed by FF Doug Johnson along with a fire scene exam performed by AE Santana & FF Smith Shannon to include 63 photographs which were added to the electronic case file. No evidentiary items were collected as a result of this fire.

Damages as a result of this fire are estimated at $50,000.

After the initial investigation was complete, control and authority of the property was turned over to owner OLIVIA MARCELLINO and ANDREW MARCELLINO, on April 27, 2022 at approximately 1600 hours.

WITNESS STATEMENTS:

See FF Doug Johnson's report for statements

BUILDING CONSTRUCTION:

The fire involved structure is located at 311 E Dean Ave in Madison WI. The structure is a one story single family home approximately 1,152 sq. ft. Built in 1953 valued at $289,000. It is a 3 bedroom 1 full bathroom and half bathroom. The addressed side of the structure face Dean Ave with the original two car detached garage.
The structure involved is a wood frame construction house, zoned for residential use and built with lightweight wood framing on a concrete foundation. The roof was covered with asphalt shingles. The home had three points of entry through the front door and two on the C side. Sliding Deck door on the C side and one regular door. Engine 5 forced entry on storm door and main house front door. Because there was no one home. Engine 5 pulled the 200 pre-connect line for fire attack.

UTILITIES:

Electric Service – Electrical Service to the structure was located on the Charlie Division of the structure.

AE Santana visually examined and photographed the service panel and circuit breakers for 311 E Dean.
Gas Service – The gas meter was mounted on the Charlie Division of the structure.

MGE had been dispatched to the incident scene and secured all utilities for the structure.

EXTERIOR SCENE EXAM:

Investigators approach the one-story ranch structure addressed at 311 East Dean Avenue conducted a 360° walk around exterior. Investigators observed no exterior visual signs of heat or fire damage. There was damage to siding above the B-side basement rear window from smoke damage.

INTERIOR SCENE EXAM:

Entering 311 E. Dean Avenue, investigators walked in the front door into living room area there was no visible smoke, heat or fire damage. Walking past living room to dining room area led to kitchen area where there was some smoke damage. In the kitchen was a door that led to the basement stairs. There was smoke damage in the basement stairway. In the basement there was some smoke and heat damage to game room in basement. In the office room there was smoke, heat and fire damage and in the storage room there was heavy smoke, heat and fire damage. Some of the wall 2 x 4 and floor trusses had severe burn damage. In the laundry room there was smoke heat and fire damage to water heater, PVC drain pipes and PVC water lines from heat and fire. Several breakers were tripped which according to the labels correspond to the area of fire. See photo file for reference.

ROOM/AREA OF ORIGIN:

The storage room on the B and C side of the basement had the most damaged from the fire, heat and smoke. The window in that room had a crack. Possibly from heat. It was noticed from a firefighter doing a 360 around house before windows where broken for ventilation. According to one of the firefighters from engine 14. The floor Joist in the storage room where heavily damaged by the fire. The Wall between the office and the storage room was heavy damage. The top portion of the 2x4 was damaged by the fire. A lot of the plastic containers or plastic fixtures were melted by the heat and fire in the storage room. Some of the drywall was pulled down by the fire fighters to do overhaul. The Floor Joyce had little damage if any because they were protected by the insulation and the drywall when exposed.

See photo file for room/area origin documentation

FIRE CAUSE HYPOTHESIS

Hypothesis 1:
Investigators
Santana and Smith notice a fire pattern in the office basement room. The location is where
The baby chicks had been housed in a cardboard box. A heat lamp was used to keep them warm. The walls that touched the cardboard box showed a fire pattern on one side and on the other side showed fire damage from the floor to the ceiling. No other area in that room had that type of damage. The owners gave information about how they kept the chicks warm and the location. Owners said in there interview they used a heat lamp to keep chicks warn in a cardboard box.
Because of the location of the dead chickens. We determined that what they were telling us was consistent to what we found.

FIRE CAUSE CLASSIFICATION:

Based on the information and evidence available to investigators at this time, to include witness interviews and statements, collection of data, fire dynamics, fire behavior and the examination of the fire scene by MFD fire investigators, it is the opinion of investigators based on a reasonable degree of fire investigative certainty, that this fire resulted due to chicken heat lamp falling or touching something to start the fire. Investigators found evidence of charring to the 2 walls that touched the cardboard box that held the chicks. Furthermore, the fire patterns supported this area, as the area of origin.

.

Fire Investigator David Santana –FIT
Madison Fire Department
Fire Investigation Division

Additional Narrative (#5 of 5):

WITNESS INTERVIEWS

INCIDENT # 22155544
311 E DEAN AVE MADISON, WI 53716
INTERVIEWER: FIRE INV. GUY JOHNSON
WITNESSES: OLIVIA MARCELLINO, ANDREW MARCELLINO, AMBER JIRSCHELE, ADAM HANEK, JACOB WELLS

OLIVIA MARCELLINO (HOMEOWNER), ANDREW MARCELLINO (HOMEOWNER)
(OLIVIA MARCELLINO) [redacted], 311 E Dean Ave Madison, WI 53716
(ANDREW MARCELLINO) [redacted], 311 E Dean Ave Madison, WI 53716
Mrs. Marcellino stated that she, Mr. Marcellino, and thei [redacted] were at her place of work called Rehab Path. Mrs. Marcellino stated that her neighbor, Amber Jirschele, called her cell phone at 11:39am on the day of the incident to tell her that there was smoke coming from the exterior of their home. Mrs. Marcellino said that she and [redacted] were given a ride back home by a coworker at Rehab Path named Robb Schuler. Mr. Marcellino stated that he took his personal vehicle (RAV-4) and left just before his wife to head back to the home. Mr. Marcellino said that he arrived home at approximately 11:45am and saw grayish smoke coming from the front door and chimney. Mrs. Marcellino says that she arrived home at approximately 12:10pm and saw gray lazy smoke coming from the home. Mr. Marcellino then stated that he thought he know what started the fire. He stated they had six 3-week old baby chickens in the Bravo, Charlie (B, C) corner of the basement. He said they were being kept in a cardboard brooder with wood shavings in the bottom. He also stated that that a heat lamp, that was used to keep the chicks warm, was zip-tied to a level directly above the brooder and that it was always on.

In addition to the statements above regarding the incident, Mr. and Mrs. Marcellino answered general questions regarding the home: Mrs. Marcellino stated that she had not made contact with her insurance company at the time of our interview. She stated that she had a mortgage on the home through Fairway Independent Mortgage, with an escrow payment of approximately $1,400 and that she was current with the payments. She stated that they moved into the home in November of 2018, installed new flooring in December of 2021 and took down a wall in January of 2022. She stated the only electrical issues in the home were the kitchen appliances that would overload the outlet and trip the circuit breakers at times. She stated that they did not have candles or incense in the home. She also stated that no one in the home smoked or vaped. She stated that they owned a grill that is located on the back deck and it was not in use the time of the incident. She stated there were no oily rags in the house. She stated there was a dehumidifier in the basement but was not running or plugged in. Mr. Marcellino said there was a space heater in the basement, in the same area as the chicken brooder, that was purchased new 5 years ago that was plugged in but not running. Mr. Marcellino stated there were two power strips in the basement area near the chicken brooder. He said the heating lamp was plugged into one strip and the computer was plugged into a different strip.

AMBER JIRSCHELE (NEIGHBOR), [redacted], 309 E Dean Ave, Madison, WI 53716
Ms. Jirschele stated that she was in her bathroom when she heard loud knocking on her neighbor's doors. She came outside of her back door and saw gray smoke coming from a vent near the roof of Mr. and Mrs. Marcellino's home. Next, she noticed a woman on a phone inside a dark SUV in the street. She said that the woman pulled into her, Ms. Jirschele's, driveway. Ms. Jirschele described the woman as older, white, with dark hair. Ms. Jirschele then called Mrs. Marcellino at 11:39am. She then got her cat carrier because she knew the Marcellinos had a cat that may be rescued. She saw Andrew Marcellino arrive between 11:39am and 12:03pm. She then went back inside her home.

ADAM HANEK, [redacted] (WITNESS) [redacted] 612 ACKER PKWY, DEFOREST, WI 53532
Mr. Hanek is employed with the Madison Forestry Dept. and was working in the area at the time of the incident. He stated that he drove by the address where the fire occurred and saw smoke. He thought maybe someone was burning in the backyard. He then went up to the house to investigate further. He and his coworker Jacob Wells went around the house knocking on windows and doors. Adam then opened a window on the back side of the house and saw the first floor was full of smoke. They then told a woman in an SUV to call 911.

JACOB WELLS, [redacted] (WITNESS) [redacted], 510 WALKER ST, MAZOMANIE, WI 53560
Mr. Wells is employed the Madison Forestry Dept., and stated that a woman in a silver SUV, who appeared to be in her early 40's with dark hair, drove by them and reported smoke coming from a house. He and Mr. Hanek went to the address and started to bang on windows and doors to see if someone was home. They then went to the back of the house. They opened a back window and could hear a crackling sound in the basement. Mr. Wells then encountered the neighbor, Ms. Jirschele, and that's when he started to hear sirens coming.




Manville
gold fiber glass
building insulation
save energy
enjoy comfort
CAUTION









