



Existing Limestone Railroad Arch Summer 2017



Existing Limestone Railroad Arch Spring 2018



Erosion Downstream of Existing Inlet



Erosion at the upstream storm sewer caused by failure of the diversion wall