

WESTVIEW HILLS GREENWAY PHOTOS 06/15/21



Upstream Channel Erosion – Just Downstream of Culverts





Channel Erosion – Middle Section of Channel





Channel Erosion – Just Prior to Basin Area





Outflow Pipe From Detention Basin