

Sewer Lateral Repair Pavement Restoration Pilot Program Evaluation- 1 Year Update

3414 Hargrove- Property owner had service line warranty protection (lateral warranty) but the repair cost was \$31,500 and the insurance coverage provided for up to \$10,000 of protection. \$15,000 was for pavement. City covered the final pavement restoration. Property Owner paid for temporary concrete patch. (street pavement rating 7 out of 10)

718 Hintze Road- Property owner had service line warranty protection (lateral warranty) but the repair exceeded the warranty coverage. The property owner took out a permit to complete the repair but has not yet completed the work.(street pavement rating 8 out of 10)

8434 Prairie Hill Road- New Construction to subdivision served by well and septic system. The sewer lateral had a riser pipe when it should not have. The City provided target elevations at the property line. The City reimbursed property owner to replace lateral to City sewer main because it was more cost effective than using City crews to do the work. The City will pay for pavement restoration for this property and potential other properties after all are connected to City sewer. (street pavement rating 8 out of 10).