



The additional 4 feet of ceiling height will allow for more efficient storage with racking along the walls. This will allow for floor space to be opened up in the South Building.

Presently there is no ventilation for the motorized vehicles & lawn cutting equipment stored here. Code requires a minimum fresh air exchange. There will also be a purge cycle that will be turned on when vehicles are started.

North Building