



6675 C01

EXPANSION JOINT STYLE CHANGE

09/28/2011

6675 CO 2 Repair of Bearing Haunch
CAPITOL SQUARE NORTH GARAGE

Supported
Slab


← Bearing
Haunch


09/28/2011

6675 C02

Repair of bearing haunch


09/28/2011





09/28/2011

CAPITOL SQUARE NORTH COVERED
GARAGE: ADDL WORK CONTACT
WILLIAMS CONTRACT



6675 CO 3 STATE ST. CAPITOL GARAGE
ADDITIONAL DEPTH FOR CONCRETE REPAIR



6675

CO 3 STATE ST CAPITAL GARAGE

CONCRETE REPAIR

State St
Capital St