•		ing 2009	7	Otrainer Andre Ma		
ı	Midvale, Tokay, and Waite circle Resurfacing 2009		Change Order No. Contract No. Project No. Change Order Project No.		CO 2 6370 53W0834 53W0834	
Change Or	der Description		,			
Ţ	30" rcp was all change to 27" rcp. An unknown shallow structure found at the intersection of Cherokee and Midvale had rotted CMP which was changed to 10" C-900. 8" pvc was place at a low pt on Yuma with in the terrace.			for this Change Order: ESTM-58279-810358-00-53W0834		
	place at a low pt of Tunta with in the teria					
•	SPEEDWAY SAND & GRAVEL INC 8500 GREENWAY BLVD #202 MIDDLETON, WI 53562		· · · · · · · · · · · · · · · · · · ·			
•						
	thorized and directed to make the following			hi wa i	1 43470	I =
Item No.	Description	Est. Qty	Unit	Unit Price	*N/B	Total .
1	27" RCP	642.00	lf .	65.25	N	41,890,50
2	10" C-900	44,00	(f	56,55	N	2,488.20
3	8" PVC	54.00	İf	49.00	N	2,646.00
		-				Ö.00
				,		0.00
-		<u> </u>				0.00
<u>-</u>						0.00
Net Change Order The Original Contract Total Sum of previous Change Orders The new Contract Sum including this Change Order will be				1		47,024.70 1,922,172.05 28,087.00 1,997,283.75
This Contra	act is a:		Calendar Days	l⁻ Working Days		Completion Date
Original Contract Time/Completion Date						October 31, 2009
	e in Contract Time by previous change or				2	
Contract Time/Completion Date prior to this change order						November 2, 2009
Additional day(s) as a result of this Change Order						1
Contract tin	me/completion date as a result of this chan		Marchan the minimum of the Alberta States		November 3, 2009	
By Title Date City's Appr Construct	r's Acceptance Color Color Color roval (see reverse side for instructions) lion Inspector lion Supervisor	o If Nach	[4-: > 4.	* Mark if negotiate	od (N) or	bid (B) unit price

0/10