

1014 Williamson Street Window Project

Outside photos of the street facing windows.

It was very difficult obtaining these photos. As you can see in the 2 photos of the second floor windows, you can't see any damage because of the screens. We were not able to obtain a closer photo of the 3rd floor windows. You can see the wood rot below the windows.