## STREET PLANT VALUE

SIDEWALKS

## 3201 Latham Drive 8545/12917

## SIDEWALK

Description	Limits	Limits	Quantity	Unit	Unit Cost		tal Cost
Latham Drive sidewalk	STA 57+15	STA 62+22	507	LF	\$ 19.72		10,000.00
concrete sidewalk, 5' wide			Enginee	ring @ 12%		\$ \$	1,200.00
MS LINK NO 1173	<u> </u>			Total Cost		\$	11,200.00
			Enginee	ring @ 12% Total Cost			
	!			Total Cost	<u> </u>		
			Enginee	ring @ 12% Total Cost			
	<del> </del>			Total Cost			
			Enginoo	ring @ 12%			
	+	+	Enginee	Total Cost			
		·		70147 0051			
			Enginee	ring @ 12%			
			Liiginee	ring @ 12% Total Cost			
	;	·		T	l — — — —		
			Enainee	ring @ 12% Total Cost			
				Total Cost			
	:	·					
			Enginee	ring @ 12%			
				Total Cost			
			Enginee	ring @ 12%			
				Total Cost			
			Enginee	ring @ 12%			
	!			Total Cost			
			<b>F</b>	: 0 100/			
			Enginee	ring @ 12%			
	<del> </del>	·		Total Cost	<u> </u>		
	+	+	Enginoo	ring @ 120/			
		1	Enginee	ring @ 12% Total Cost			
<b></b>	<del> </del>	<b>├</b>					
		<u> </u>	Enginee	ring @ 12%			
			g00	Total Cost			
GRAND TOTAL COST				• — — — —		\$	11,200.00

Prepared By:	pkt			
Date:	3/28/2023			