## Official Project Name

## Sherman Ave and Brearly St Assessment District-2011



Project Engineer

LeAnne Hannan

266-4057

**Project Limits** 

Brearly St to Thornton Ave

E Gorham St to the lake

Existing	Proposed
1967-1990	Resurfacing
1962	Reconst-Brearly from Sherman to lake
	Resurfacing
	Reconst-Brearly from Sherman to lake
-	
	Resurfacing
_	Reconst-Brearly from Sherman to lake
32-36'	Resurfacing
26	Reconst-Brearly from Sherman to lake
Asphaltic	Asphaltic
	Same
oree Balawin memen	Same
Existing	Proposed
	Replace As Necessary
Existing	Proposed
	replacement, additional inlets
12' 15" on cul-de-sac	12-21"
	RCP
· · · · · · · · · · · · · · · · · · ·	11.01
1911, 1901 off cul-de-sac	
Existing	Proposed
<b>.</b>	Complete Replacement
6" 8"	8"
	PVC
1909-1911	
Existing	Proposed
	Complete Replacement on Brearly
	and Sherman from Brearly to Marston
011 011	
	8" DI
1897 & 1909, 1935 for 8"	
Eviation	Drawagad
	Proposed
one side	Same
Existing	Proposed
	Same
55d=5d po.ss	proposal for ped scale lighting was
	not supported by the neighborhood
	by a voite of 32 to 24
11/11/2010	Lapham School
<b>\$2.00</b> 7.700	
\$244,000	
\$1,981,500	
	1967-1990 1962 5 4 8-May 3 32-36' 26 Asphaltic 5100- Baldwin -Thornton  Existing  12' 15" on cul-de-sac VP, RPC on cul-de-sac 1911, 1961 on cul-de-sac 1911, 1961 on cul-de-sac Existing  6" 8" VP 1909-1911  Existing  6" 8" SACI-UL 1897 & 1909, 1935 for 8"  Existing  one side  Existing  On MG&E wood poles

## **Assessment Policy**

Owner 50% / City 50% Street Concrete Items Sanitary Sewer Lateral Replacements Owner 25% / City 75%

Assessments payable in one lump sum or over a period of 8 years, with 5% interest charged on unpaid balance All remaining contract items to be paid for by the City of Madison

## **Schedule**

Start Date April, 2011 Length of Project 3-4 months

Traffic Calming Not Included- possibly in future

Traffic Detours none

Real Estate Requirements Not Required

Tree Information trimming prior to construction

Correspondence

Caroline Alexander-1154 Sherman

confusion over why the assm't included 2 laterals, Staff explained that our records show 2, but if only 1 is in use, only one will be replaced and she'll only be assessed for the work that is done. Also, since her SW is new, she won't be assessed for replacement.

Cyril Hetsko, 1114 Sherman Ave

same problem/concern as 1154 Sherman

Madelynn Mueller,

questions regarding drive apron material and ped lighting.