Oil Equipment Co.

4701 Lien Road Madison, WI 53704

EQUIPMENT ESTIMATE

JOB DESCRIPTION: Repair inground lifts

Item #'s	Qty	Description	Unit Price	Extended Price
R10ML	2	Rear Replacment w/multi locks	\$15,750.00	\$31,500.00
Steel Surcharge	2	Steel Surcharge	\$427.38	\$1,282.14
ş				
Balast	1	Balast for the replacement cyclinders		\$900.00
MISC	1	Chase pipe/ Hydraulic hose		\$250.00
LABOR	1	110 Labor Hrs to Install replacement likfts		\$8,500.00
AW32-5	1	30 Gallons of Hydraulic Fluid		\$330.00
Travel	1	7 Round Trips		\$374.40
Labor	will be ch	arged on a time and material basis at a rate of \$85.00/hour per mar		\$43,136.54

NOTES: Excavation, Concrete, and Electrical to be completed by others.

THIS ESTIMATE IS FOR COMPLETING THE JOB AS DESCRIBED ABOVE. IT IS BASED ON OUR EVALUATION AND DOES NOT INCLUDE MATERIAL PRICE INCREASES OR ADDITIONAL LABOR AND MATERIALS WHICH MAY BE REQUIRED SHOULD UNFORESEEN PROBLEMS OR ADVERSE WEATHER CONDITIONS ARISE AFTER THE WORK HAS STARTED, OR APPLICABLE SALES/USE TAXES. OEC REQUIRES PAYMENT OF 50% OF THE ESTIMATED JOB COST BEFORE PROJECT START DATE. THE REMAINING ACTUAL JOB COST WILL BE INVOICED UPON JOB COMPLETION AND MUST BE PAID IN ACCORDANCE WITH OEC'S STANDARD PAYMENT TERMS AND CREDIT POLICY AS OUTLINED ON THE APPLICATION FOR CREDIT. SIGN AND RETURN THIS AGREEMENT ALONG WITH PAYMENT IN ORDER TO ACCEPT THIS ESTIMATE.

ESTIMATED
JOB COST:

\$43,136.54



Oil Equipment Companying

Accepted:

Date: