Change Order Report for BPW

Entered Date From:

12/1/2018

To:

12/31/2018

Contract: 7450 Darbo Drive to Webb Avenue New Street Connection Assessment District - 2018 (Richard Dayis Contract Amount: \$974,989 Change Order Work necessary to modify the 8'x4' concrete storm box in conflict with existing 8" pvc sa 1/9/2019 **Issue Date:** \$16,550.00 1.6975% Amount Percent: Project(s): 53W1867 Darbo Drive to Webb Avenue New Street Connection Assessment District - 2018 (I Reason(s): Design did not adequately anticipate field conditions. Change Type(s): Sewer-Storm **CO** Description: Work necessary to modify the 8'x4' concrete storm box in conflict with existing 8" pvc sanitary sewer in Webb Avenue. This work also includes placing a 12" steel casing pipe around the existing 8" sanitary sewer. 2-days added. Notes: **Previous Percent: Total Previous:** 0.0000% **Current Percent: Total Current:** 0.0000% #Error Revised Percent **Revised Contract Amount:** \$974,989.32 0.0000% Contract: 8000 E. Gilman St and N. Pinckney St Resurfacing **Contract Amount:** \$1,462,067 Change Order Additional area to grind, adjust storm numbers, increase erosion control measures. Pipe p 12/12/2018 \$14,932.00 **Issue Date:** 1.0213% Amount Percent: 11649 E. Gilman St, N. Pinckney St and N. Bultler St Resurfacing w/Utilities Project(s): Reason(s): Actual vs. Estimated Quantities differ. Missing Bid Item or Additional Bid Item needed. Change Type(s): Street Sewer-Sanitary Sewer-Storm CO Description: Additional area to grind, adjust storm numbers, increase erosion control measures. Pipe plugs. Notes: **Total Previous:** \$1,600.00 **Previous Percent:** 0.1094% Total Current: Current Percent: \$14,932.00 1.0213% **Revised Percent Revised Contract Amount:** 1.1307% \$1,462,066.58 Contract: 8116 Gilson Street Reconstruction \$1,038,377 **Contract Amount:** 1 Change Order Contractor performed work on items we have set prices for instead of bid items. Using 7

\$4,955.00 0.4772% 12/7/2018 Percent: **Issue Date:** Amount 11180 Gilson Street Reconstruction Project(s): Field Decision (Expanded Scope). Reason(s): Change Type(s): Contractor performed work on items we have set prices for instead of bid items. Using 70053 CO Description: item to bring contract value under 100%. Notes: 2 We increased storm quantites to upgrade some clay pipe and eliminate some possible dra Change Order 0.6785% 12/12/2018 \$7,045.00 Percent: **Issue Date:** Amount 10901 Pine Street Reconstruction Project(s): Actual vs. Estimated Quantities differ. Reason(s): Change Type(s): Sewer-Storm We increased storm quantites to upgrade some clay pipe and eliminate some possible drainage CO Description: issues @ Pine & Beld. Notes: **Previous Percent:** 0.0000% **Total Previous: Current Percent:** 1.1556% Total Current: \$12,000.00 Revised Percent 1.1556% **Revised Contract Amount:** \$1,038,377.22 Local Road Traffic Calming & Arterial Ped Enhancements 2018 Contract: 8126 **Contract Amount:** \$236,475 Overruns in bid quantities causing the respective account to exceed 100% and no bid ite Change Order 2 \$5,846.56 2.4724% 12/17/2018 Percent: **Issue Date:** Amount Local Road Traffic Calming & Arterial Ped Enhancements 2018 11587 Project(s): Reason(s): Actual vs. Estimated Quantities differ. Missing Bid Item or Additional Bid Item needed. Change Type(s): Street Overruns in bid quantities causing the respective account to exceed 100% and no bid item for CO Description: account 11587-402-200 (Tokay). Notes: **Total Previous: Previous Percent:** 0.5286% \$1,250.00

Contract: 8184

Westview Hills Sewer and Water Assessment District 2018

Contract Amount: \$1,095,704

Total Current:

Revised Contract Amount:

Change Order 3 New pavement taper (shoulder) was too short where new pavement tied into existing pav

\$5,846.56

\$236,475.00

Current Percent:

Revised Percent

2.4724%

3.0010%

Issue Date: 12/3/2018 Amount \$9,113.00 Percent: 0.8317% 11767 WESTVIEW HILLS SEWER & WATER A.D. Project(s): Missing Bid Item or Additional Bid Item needed. Reason(s): Other Change Type(s): Street Sewer-Sanitary **CO** Description: New pavement taper (shoulder) was too short where new pavement tied into existing pavement causing a traffic concern. There was no bid item for EMBs. Notes: **Total Previous:** \$6,974.00 **Previous Percent:** 0.6365% **Total Current:** \$9,113.00 **Current Percent:** 0.8317% **Revised Contract Amount:** \$1,095,704.13 **Revised Percent** 1.4682% Contract: 8240 Demolition - Unit Well 3, 212 N First St Contract Amount: \$88,866 Change Order 1 Adjust final quantities from Project Manager design estimated to actual quantities used. **Issue Date:** 12/5/2018 \$252.00 Amount Percent: 0.2836% 10287 Project(s): Demolition - Unit Well 3, 212 N First St Reason(s): Actual vs. Estimated Quantities differ. Change Type(s): **Facilities** CO Description: Adjust final quantities from Project Manager design estimated to actual quantities used. Notes: **Total Previous: Previous Percent:** 0.0000%**Total Current: Current Percent:** \$252.00 0.2836% **Revised Contract Amount:** \$88,865.50 **Revised Percent** 0.2836% Contract: 8250 Sycamore Sanitary Sewer Interceptor Maintenance Access - Phase 1 Contract Amount: \$148,318 Change Order 1 12/26/2018 **Issue Date:** \$2,350.00 Amount Percent: 1.5844% 10426 Project(s): Sycamore Sanitary Sewer Interceptor Maintenance Access - Phase 1 Missing Bid Item or Additional Bid Item needed. Reason(s): Change Type(s): Sewer-Storm **CO** Description: Notes: **Total Previous: Previous Percent:** 0.0000% **Total Current: Current Percent:** \$2,350.00 1.5844%

\$148,318.00

Revised Contract Amount:

1.5844%

Revised Percent

		÷		