## LANDMARKS COMMISSION APPLICATION

Complete all sections of this application, making sure to note the requirements on the accompanying checklist (reverse).

If you need an interpreter, translator, materials in alternate formats or other accommodations to access these forms, please call (608) 266-4635

City of Madison Planning Division 215 Martin Luther King Jr Blvd, Ste 017 PO Box 2985 Madison, WI 53701-2985 (608) 266-4635



	(608) 266-4635	SCONSI
1. LOCATION		**
Project Address: 41 North Roby Road, Ma	adison, Wi53726	Aldermanic District:5
Project Title/Description: Front R Porch R	oof Repair	· · · · · · · · · · · · · · · · · · ·
This is an application for: (check all that apply)	V	Legistar#:
☑ New Construction/Alteration/Addition in a Local Hist District or Designated Landmark (specify)**: ☐ Mansion Hill ☐ Third Lake Ridge	oric  ☐ First Settlement	DATE STAMP
☑ University Heights ☐ Marquette Bungalows	☐ Landmark	
<ul> <li>□ Land Division/Combination in a Local Historic District or to Designated Landmark Site (specify)**:</li> <li>□ Mansion Hill</li> <li>□ Third Lake Ridge</li> <li>□ University Heights</li> <li>□ Marquette Bungalows</li> <li>□ Demolition</li> <li>□ Alteration/Addition to a building adjacent to a Design</li> </ul>	☐ First Settlement ☐ Landmark	12/21/20 11:33 am
☐ Variance from the Historic Preservation Ordinance (C	hapter 41)	
<ul> <li>□ Landmark Nomination/Rescission of Historic District In (Please contact the Historic Preservation Planner for spe</li> <li>□ Other (specify):</li> <li>3. APPLICANT</li> </ul>		Preliminary Zoning Review  Zoning Staff Initial:  Date: / /
Applicant's Name: James Stange	Company	
Address: 41 North Roby 12 and Street Telephone: 608-332-3093	Madisan City	State Zip
Property Owner (if not applicant):	Email. 314/190100	31110110111
Address:		
Street	/) City	State 7in

NOTICE REGARDING LOBBYING ORDINANCE: If you are seeking approval of a development that has over 40,000 square feet of non-residential space, or a residential development of over 10 dwelling units, or if you are seeking assistance from the City with a value of \$10,000 (including grants, loans, TIF or similar assistance), then you likely are subject to Madison's lobbying ordinance (Sec. 2.40, MGO). You are required to register and report your lobbying. Please consult the City Clerk's Office for more information. Failure to comply with the lobbying ordinance may result in fines.

Date:

## 4. APPLICATION SUBMISSION REQUIREMENTS (see checklist on reverse)

**Property Owner's Signature:** 

All applications must be filed by 12:00 pm on the submission date with the Preservation Planner. Applications submitted after the submission date *or* incomplete applications will be postponed to the next scheduled filing time. Submission deadlines can be viewed here: <a href="https://www.cityofmadison.com/dpced/planning/documents/LC">https://www.cityofmadison.com/dpced/planning/documents/LC</a> Meeting Schedule Dates.pdf

Porch Project 12-21-20 41 North Roby Road Madison Wi 53726 Historical District University Heights

The Porch roof is failing at our home at 41 North Roby Road. In investigating the porch roof, it appears to us that the original roof was extended at some time by about 12-16 inches. This can be seen on the picture of the porch which is attached to the proposed porch building plan application. It appears this was done so that the water would fall beyond the porch wall instead of dripping directly onto the porch landing. This additional weight may have caused the roof to start pulling away from the top of the porch roof and the wall of the main house.

We have contacted numerous contractors over the past year to review the roof and have had the company Mid Towne Construction respond. The idea of extending the roof and placing 2 pillars resting on the porch wall was proposed and drawn by Bill Montebano the architect working with Mid Towne Construction. The proposed plan would extend the roof slightly beyond the existing porch wall. The planned design will prevent water from spilling onto the porch landing or the wall and reduce ice on the existing porch landing. The extension of the roof and the pillars are planned to match the existing construction of the roof. This will provide better support of the roof since it would be extended.

We have attached the proposed plan from Mid Towne Construction to this application for review.

Jim Stangel Homeowner <u>Jstangel85@gmail.com</u> 608-332-3093

## Bill Montelbano Architect AIA

ARCHITECTURE INTERIORS PLANNING ENGINEERING

November 17th, 2020


Jim Stangel 41 N. Roby Road Madison, WI. 53726


Jim.

It seems that the cause of the sagging of your existing cantilevered porch roof was likely inadequate design and/or construction especially because of the hollow structural clay tile exterior walls plastered on the interior and stuccoed on the exterior. It's difficult to know if the wall contains any reinforcing when constructed in 1915 and the wall and second floor would need to be opened up to determine what type of connection exists between the wall and canopy and if some type of reinforcing can be added within the wall without damaging the stucco. This type of cantilever if built today would be more common with concrete or reinforced concrete block walls and steel tension rods in the canopy roof.


Sincerely,

Bill Montelbano





PORCH-FRONT ELEVATION SCALE: 3/8'= 1'-0' EXISTING



PORCH- FRONT ELEVATION
SCALE: 3/8'= 1'-0' PRUPUSED



