STORMWATER IMPROVEMENTS GLENWOOD CHILDREN'S PARK

BOARD OF PARK COMMISSIONERS JULY 2018


LOCATION



EXISTING LIMESTONE RAILROAD ARCH SUMMER 2017



EXISTING LIMESTONE RAILROAD ARCH SPRING 2018





EROSION DOWNSTREAM OF EXISTING INLET





APRIL 2018

JULY 2018






EROSION AT THE UPSTREAM STORM SEWER CAUSED BY FAILURE OF THE DIVERSION WALL





PROPOSED IMPROVEMENTS





DESIGN EXAMPLES



STEPPED OVERFLOW



TYPICAL PIPE WITH NO SURFACE TREATMENTS

STONE VENEER



