



2121 Jefferson St

Front Elevation


No original siding nor windows remain, replaced with vinyl. It is important to note that the simple act of replaced siding was considered an "unsympathetic alteration" and excluded a property from being listed as "contributing" to the National Historic District.



2121 Jefferson St

Side Elevation

No original siding nor windows remain, replaced with vinyl. It is important to note that the simple act of replaced siding was considered an "unsympathetic alteration" and excluded a property from being listed as "contributing" to the National Historic District.



Closeup of non-original vinyl siding and windows.

It is important to note that the simple act of replaced siding was considered an "unsympathetic alteration" and excluded a property from being listed as "contributing" to the National Historic District.


2121 Jefferson St



2121 Jefferson St

Side Elevation

No original siding nor windows remain, replaced with vinyl. It is important to note that the simple act of replaced siding was considered an "unsympathetic alteration" and excluded a property from being listed as "contributing" to the National Historic District.



Closeup of non-original vinyl siding and windows.

It is important to note that the simple act of replaced siding was considered an "unsympathetic alteration" and excluded a property from being listed as "contributing" to the National Historic District.

2121 Jefferson St



2121 Jefferson St

Interior view
No original kitchen cabinetry or details.

2121 Jefferson St

Interior view

No built-ins remain.

2121 Jefferson St


Interior view of hallway leading to small bedrooms.





2121 Jefferson St

Interior view of a small, virtually unusable bedroom.



2121 Jefferson St

Interior view
Wet basement



1007 Edgewood Ave

Front Elevation


No original siding nor windows remain, replaced with vinyl. It is important to note that the simple act of replaced siding was considered an "unsympathetic alteration" and excluded a property from being listed as "contributing" to the National Historic District.



1007 Edgewood Ave

Side Elevation

No original siding nor windows remain, replaced with vinyl. It is important to note that the simple act of replaced siding was considered an "unsympathetic alteration" and excluded a property from being listed as "contributing" to the National Historic District. Also, note the lack of formal window placement. It is our opinion this house is not exemplary of the Foursquare style.



1007 Edgewood Ave

Side Elevation


No original siding nor windows remain, replaced with vinyl. It is important to note that the simple act of replaced siding was considered an "unsympathetic alteration" and excluded a property from being listed as "contributing" to the National Historic District. Also, note the lack of formal window placement. It is our opinion this house is not exemplary of the Foursquare style.



Closeup of non-original vinyl siding and windows.

It is important to note that the simple act of replaced siding was considered an "unsympathetic alteration" and excluded a property from being listed as "contributing" to the National Historic District.

1007 Edgewood Ave



1007 Edgewood Ave

Rear Elevation

No original siding nor windows remain, replaced with vinyl. It is important to note that the simple act of replaced siding was considered an "unsympathetic alteration" and excluded a property from being listed as "contributing" to the National Historic District. Also, note the lack of formal window placement. It is our opinion this house is not exemplary of the Foursquare style.

1007 Edgewood Ave

Interior view

No built-ins remain. Also, note the drop ceiling and "vinyl plank" flooring.




1007 Edgewood Ave

Interior view
No original kitchen elements remain.

1007 Edgewood Ave


Interior view of a small bedroom.





1007 Edgewood Ave

Interior view of a small bedroom



1007 Edgewood Ave

Interior view
Wet basement