

Date: July 7, 2015  
To: Landmarks Commission  
Subject: 423 N Carroll  
From: Franny Ingebritson

**Building Inspection Information for 423 N. Carroll Street.**

- June 10, 1974: Remove side porch. Replace door and window. Not required exit. \$500.
- Aug. 13, 1986: Reroof. Change shingles from green to black. (Rankin OK) \$2485.
- July 19, 1987: Replaced exchange softener with automatic unit.
- Nov. 2, 1988: Reroof garage and rebuild overhang on garage. No change in appearance.  
\$1200.
- May 11, 1990: Repair overhang and gutters. \$1600.
- May 7, 1991: Repair of fascia and crown molding on west and north sides. No change in appearance.
- May 19, 1992: Rankin memo OKs rebuilding rear chimney. Chimney will have decorative Victorian brickwork which will be matched exactly in appearance.
- Dec. 14, 1995: Steve Brown becomes owner of 423 N. Carroll Street.