



City of Madison Planning Division
215 Martin Luther King Jr. Blvd. | Room LL.100 | P.O. Box 2985 | Madison, WI 53701-2985

Madison Landmarks Commission
APPLICATION
37901

1. LOCATION

Project Address: 848 SPAIGHT ST, MADISON 53703 Aldermanic District: 6

2. PROJECT

Date Submitted: 3-1-2015

Project Title / Description: Second Floor Window Replacements + Roof Project

This is an application for: (check all that apply)

- Alteration / Addition to a Designated Madison Landmark
- Alteration / Addition to a building adjacent to a Designated Madison Landmark
- Alteration / Addition to a building in a Local Historic District (specify):
 - Mansion Hill
 - University Heights
 - Third Lake Ridge
 - Marquette Bungalows
 - First Settlement
- New Construction in a Local Historic District (specify):
 - Mansion Hill
 - University Heights
 - Third Lake Ridge
 - Marquette Bungalows
 - First Settlement
- Demolition
- Variance from the Landmarks Ordinance
- Referral from Common Council, Plan Commission, or other referral

CITY OF MADISON
MAR 27 2015
Planning & Community & Economic Development

Other (specify): Replace 7 windows + replace roof, shingles, gutters + downspouts. (one window, 1st floor rear bldg)

3. APPLICANT

Applicant's Name: Thomas A. Goodwyn + Craig C. Kowalke Company: ---
 Address: 848 Spaight St., Apt B City/State: Madison, WI Zip: 53703
 Telephone: 608-251-9117 / 608-556-1326 E-mail: GIOVERVE2@G-MAIL.COM
 Property Owner (if not applicant): N/A
 Address: --- City/State: --- Zip: ---

Property Owner's Signature: Thomas A. Goodwyn / Craig C. Kowalke Date: 3-1-2015

GENERAL SUBMITTAL REQUIREMENTS

Twelve (12) collated paper copies and electronic (.pdf) files of the following: (Note the filing deadline is 4:30 PM on the filing day)

- Application
- Brief narrative description of the project
- Scaled plan set reduced to 11" x 17" or smaller pages. Please include:
 - Site plan showing all property lines and structures
 - Building elevations, plans and other drawings as needed to illustrate the project
 - Photos of existing house/building
 - Contextual information (such as photos) of surrounding properties
- Any other information that may be helpful in communicating the details of the project and how it complies with the Landmarks Ordinance, including the impacts on existing structures on the site or on nearby properties.

Questions? Please contact the Historic Preservation Planner:
Amy Scanlon
Phone: 608.266.6552
Email: ascanlon@cityofmadison.com

NOTICE REGARDING LOBBYING ORDINANCE: If you are seeking approval of a development that has over 40,000 square feet of non-residential space, or a residential development of over 10 dwelling units, or if you are seeking assistance from the City with a value of \$10,000 (including grants, loans, TIF or similar assistance), then you likely are subject to Madison's lobbying ordinance (Sec. 2.40, MGO). You are required to register and report your lobbying. Please consult the City Clerk's Office for more information. Failure to comply with the lobbying ordinance may result in fines.

March 27, 2015

Madison Landmarks Commission
City of Madison Planning Division
215 Martin Luther King Jr. Blvd, Room LL 100
PO Box 2985
Madison WI 53701-2985

RE: Application for Exterior Projects dated March 1, 2015: Window Replacements and Roof Project Certificate of Appropriateness

To the Members of the Madison Landmarks Commission:

This letter provides a narrative description of the projects proposed at 848 Spaight Street (see PDF of Application) in Madison's Historic Third Lake Ridge District as well as our intent to comply with the Madison Landmarks Ordinance (see photo 1 for a front view of the house and the neighboring houses).

The first of the two projects comprises replacements of six windows on the second floor and one on the first floor of the building. Below is a summary of their locations when facing the front of the house:

- One window, front of house, second floor (see photo 2)
- One window, right side of house, second floor (see photo 3)
- Three windows, back of house, one on first floor, two on second (see photo 4)
- Two windows, left side of house, second floor (one toward back of the house, see photo 5)

The windows in question are the original windows. They are not beyond the state of repair but are horribly inefficient which has prompted us to replace them. Because the house has been used as a rental property for nearly 60 years, many past tenants have been excessively harsh to the interior portions of the windows. We have tried to strip the paint from the interior of some of the windows. Whenever we have done this, we discover that the wood is so badly damaged that the frames of the windows no longer fit snugly. This causes the windows to rattle. In some cases we have had to use shims to hold the frames in place. We have also had to use excessive amounts of caulk and felt padding to cut down on the amount of air escaping through the cracks. We have to leave the weather stripping on some of the windows year around because there is so much air loss throughout the year.

In addition, due to a problematic section of the roof in the front center of the house, water is drawn to the face of the building and has caused excessive wear to the front window (see additional notes below on the proposed addition of an "eyebrow").

Our intent is to leave the existing trim and exterior casing intact in order to preserve architectural purity. In 2006 we had kitchen remodel work done which included replacing windows on the rear of the building. These windows were in bad repair. The replacements were Marvin Full Frame windows selected to match the historical aspects of the building. We have noticed positive effects on the internal temperature of the room in all seasons and believe this has increased energy efficiency.

Ganser's approach on this current window replacement would be similar to the kitchen windows described above. We have intentions to replace the existing double hung windows and install Marvin Insert Double Hung Windows. The exterior color would match up with the existing windows. The "cut"

specifications would be similar with narrow styles and rails to honor a clean and traditional frame look (see Appendix A).

The second of the two projects comprises replacement of the roof, rain gutters and downspouts and the addition of “eyebrow” features. The current roof has been in place for just over 20 years and has required repairs over the past three years. The rain gutters and downspouts were replaced several years ago but, even with annual maintenance, they have become worn and are not functioning properly. An example of the dysfunction is how ice accumulates excessively in sections of the driveway.


It is hoped that the additional eyebrow feature will address several problems with a section of the roof on the front center of the house. Currently, this section has very little slope and attracts nesting birds and bats that get in the attic through cracks (see photos 6 and 7). Due to the lack of slope, water is also drawn toward the face of the building. The eyebrow is intended to direct water away from the building, prevent birds from nesting, and prevent bats from entering through the cracks. Photos 8, 9 and 10 show examples of eyebrows on other structures.

The roof replacement and eyebrows will utilize GAF Timberline Lifetime Shingles in brown (color – Barkwood, with brown as the drip edge) to blend with the current trim of the house. The rain gutters and downspouts are Frey Construction’s Absolute Gutter System with leafproofs; the color is dark brown (see Appendix B for specs).

In summary, the proposed window replacements will increase energy efficiency, provide comfort, and along with the eyebrow feature, mitigate water damage. The roof, rain gutter, and downspout replacement is prudent maintenance, given the age of the existing features. The eyebrow addition to the front center roof section is intended to direct water away from the building, prevent birds from nesting, and prevent bats from entering through the cracks. All work and materials are intended to comply with the Madison Landmarks Ordinance. We request a Certificate of Appropriateness from the Madison Landmarks Commission.

We and our contractors will be glad to answer any questions you have on these projects.

Sincerely,



Thomas A. Goodwyn
Kraig C. Kowalke (owners)
848 Spaight St., Apt. B
Madison, WI 53703-3585

(608) 556-1326 – cell
(608) 251-9117 – home

Marc Ganser (window project contractor)
(608) 212-2165
marcg@gansercompany.com

Scott Frey (roof, rain gutter, downspout, and eyebrow contractor)
(608) 643-7914
(608) 644-0821
www.FreyConstruction.com



Photo 1 – 848 Spaight Street and houses on either side



Photo 2 – 848 Spaight Street – 2nd floor center window & center roof feature



Photo 3 – 848 Spaight Street – 2nd floor window replacement (right)



Photo 4 – 848 Spaight Street – window replacements (rear)



Photo 5 – 848 Spaight Street – 2nd floor window replacement (left)



Photo 6 – 848 Spaight Street – area of proposed eyebrow (left)




Photo 7 – 848 Spaight Street – area of proposed eyebrow (right)



Photo 8 – Example of roof with eyebrow feature



Photo 9 – Example of roof with eyebrow feature



Photo 10 – Example of roof with eyebrow feature

Appendix A

Global Specs

The following product and option choices were designated as part of this project's Global Spec. Global Specs can be overridden on a line item basis. Exceptions to the specification are outlined in Line Item Quotes. Please proof all units thoroughly to ensure accuracy.

Infinity Spec



Infinity Specification - Advanced Options	True
Exterior/Interior Colors/Finishes - Exterior Color	Bahama Brown
Exterior/Interior Colors/Finishes - Interior Finish	EverWood Pine
Window Glass Type - Glazing Configuration	Standard Glazing
Window Glass Type - Glass Types	LoE 366 - i89 w/Argon
Divided Lites - Divided Lite Type	None
Window Hardware - Window Handle/Lock Color	Satin Taupe
Window Hardware - Window Lift Color	Satin Taupe
Window Hardware - Window Control Device	False
Window Screens - Screen Type	Extruded Full Screen
Window Screens - Exterior Screen Surround Color	Bahama Brown
Window Screens - Mesh Type	Charcoal Hi-Transparency Fbrgls Mesh
Jambs - Jamb Depth	4 9/16"
Casing/Subsill - Top Casing Type	None
Casing/Subsill - Side Casing Type	None
Installation Method - Installation Options	Nailing Fin
Ship Loose Options - Screen/Combo Ship Loose	False

Sign offs

Tom Goodwyn and Kraig Kowalke Partial Home Windows

Quote #: XBDC6KQ

A Proposal for Window and Door Products prepared for:

Shipping Address:

GANSER COMPANY INC
2616 INDUSTRIAL DR
MADISON, WI 53713-2248



MARC GANSER
GANSER COMPANY INC
1906 W BELTLINE HWY
MADISON, WI 53713
Phone: (608) 222-1243
Fax: (608) 222-8199
Email: marcg@gansercompany.com

This report was generated on 2/19/2015 3:11:09 PM using the Marvin Order Management System, version 0002.00.00 (Current). Price in USD. Unit availability and price are subject to change. Dealer terms and conditions may apply.

Featuring products from:

INFINITY
REPLACEMENT WINDOWS
MARVIN
REPLACEMENT WINDOWS
Built for life

UNIT SUMMARY

The following is a schedule of the windows and doors for this project. For additional unit details, please see Line Item Quotes.

Additional charges, tax or Terms and Conditions may apply. Detail pricing is per unit.

⊗ Lines with Errors Exist on Project - Unit Pricing is not Valid

NUMBER OF LINES: 7	TOTAL UNIT QTY: 7
--------------------	-------------------


LINE	MARK UNIT	BRAND	ITEM	QTY
⊗1	Goodwin Office A	Infinity	Insert Double Hung IO 49" X 68" Entered as Inside Opening 49" X 68"	1
2	Goodwyn Office A	Infinity	Insert Double Hung IO 38" X 66" Entered as Inside Opening 38" X 66"	1
3	Goodwyn Closet A	Infinity	Insert Double Hung IO 32" X 42" Entered as Inside Opening 32" X 42"	1
4	Goodwyn Meditation A	Infinity	Insert Double Hung IO 33" X 68" Entered as Inside Opening 33" X 68"	1
5	Goodwyn Master Bath A	Infinity	Insert Double Hung IO 32" X 42" Entered as Inside Opening 32" X 42"	1
6	Goodwyn Panty A	Infinity	Insert Double Hung IO 33" X 62" Entered as Inside Opening 33" X 62"	1
7	Goodwyn Apt C	Infinity	Insert Double Hung IO 38" X 66" Entered as Inside Opening 38" X 66"	1

LINE ITEM QUOTES

The following is a schedule of the windows and doors for this project. For additional unit details, please see Line Item Quotes. Additional charges, tax or Terms and Conditions may apply. Detail pricing is per unit.

Line #1 Qty: 1	Mark Unit: Goodwin Office A			
-------------------	-----------------------------	--	--	--

INFINITY
by MARVIN
 REPLACEMENT WINDOWS
Built for life



As Viewed From The Exterior

Entered As: IO
 FS 48 5/8" X 67 3/4"
 IO 49" X 68"

Bahama Brown Exterior
 EverWood Pine Interior
 Infinity Insert Double Hung
 Inside Opening 49" X 68"
Error: 'Frame\Basic Shape\Height' = 67.75, cannot be greater than 60
 Cottage 2.0:5.0
Error: Top sash exceeds maximum square foot.
 Top Sash
 G.S. 44 1/2" X 24 29/32"
 IG - 1 Lite
 LoE 366 - i89 w/Argon
 Bottom Sash
 G.S. 44 1/2" X 37 11/32"
 IG - 1 Lite
 LoE 366 - i89 w/Argon
 2 Satin Taupe Sash Lock
 2 Satin Taupe Sash Lift
 Extruded Full Screen
 Bahama Brown Surround
 Charcoal Hi-Transparency Fbrgl's Mesh
 3 1/4" Jambs
 Existing Sill Angle 0
Hindrance: Is the existing Sill Angle of 0 degrees correct?
*****Note: Frame Size width exceeds 48". Unit may have limited travel and may not meet egress requirements.**
*****Error: Pricing is not Valid**


Initials required

Seller: _____

Buyer: _____

Line #2 Qty: 1	Mark Unit: Goodwyn Office A			
-------------------	-----------------------------	--	--	--

INFINITY
by MARVIN
 REPLACEMENT WINDOWS
Built for life



As Viewed From The Exterior

Entered As: IO
 FS 37 5/8" X 65 3/4"
 IO 38" X 66"

Bahama Brown Exterior
 Stone White Interior
 Infinity Insert Double Hung
 Inside Opening 38" X 66"
 Top Sash
 IG - 1 Lite
 LoE 366 - i89 w/Argon
 Bottom Sash
 IG - 1 Lite
 LoE 366 - i89 w/Argon
 White Sash Lock
 White Sash Lift
 Extruded Full Screen
 Bahama Brown Surround
 Charcoal Hi-Transparency Fbrgl's Mesh
 3 1/4" Jambs
 Existing Sill Angle 0
Hindrance: Is the existing Sill Angle of 0 degrees correct?


Initials required

Seller: _____

Buyer: _____

Line #3	Mark Unit: Goodwyn Closet A			
Qty: 1				

INFINITY
by MARVIN
 REPLACEMENT WINDOWS
Built for life



As Viewed From The Exterior

Entered As: IO
 FS 31 5/8" X 41 3/4"
 IO 32" X 42"

Bahama Brown Exterior
 Stone White Interior
 Infinity Insert Double Hung
 Inside Opening 32" X 42"
 Top Sash
 IG - 1 Lite
 LoE 366 - i89 w/Argon
 Bottom Sash
 IG - 1 Lite
 LoE 366 - i89 w/Argon
 White Sash Lock
 White Sash Lift
 Extruded Full Screen
 Bahama Brown Surround
 Charcoal Hi-Transparency Fbrgl's Mesh
 3 1/4" Jamb's
 Existing Sill Angle 0
Hindrance: Is the existing Sill Angle of 0 degrees correct?


Initials required

Seller: _____

Buyer: _____

Line #4	Mark Unit: Goodwyn Meditation A			
Qty: 1				

INFINITY
by MARVIN
 REPLACEMENT WINDOWS
Built for life



As Viewed From The Exterior


Entered As: IO
 FS 32 5/8" X 67 3/4"
 IO 33" X 68"


Bahama Brown Exterior
 Stone White Interior
 Infinity Insert Double Hung
 Inside Opening 33" X 68"
 Top Sash
 IG - 1 Lite
 LoE 366 - i89 w/Argon
 Bottom Sash
 IG - 1 Lite
 LoE 366 - i89 w/Argon
 White Sash Lock
 White Sash Lift
 Extruded Full Screen
 Bahama Brown Surround
 Charcoal Hi-Transparency Fbrgl's Mesh
 3 1/4" Jamb's
 Existing Sill Angle 0
Hindrance: Is the existing Sill Angle of 0 degrees correct?

Initials required


Seller: _____

Buyer: _____

Line #5 Qty: 1	Mark Unit: Goodwyn Master Bath A			
<p>INFINITY <small>REPLACEMENT WINDOWS</small> <i>Built for life</i></p>  <p>As Viewed From The Exterior</p> <p>Entered As: IO FS 31 5/8" X 41 3/4" IO 32" X 42"</p>	<p>Bahama Brown Exterior Stone White Interior Infinity Insert Double Hung Inside Opening 32" X 42"</p> <p>Top Sash IG - 1 Lite Tempered LoE 366 - i89 w/Argon</p> <p>Bottom Sash IG - 1 Lite Tempered LoE 366 - i89 w/Argon</p> <p>White Sash Lock White Sash Lift Extruded Full Screen Bahama Brown Surround Charcoal Hi-Transparency Fbrgls Mesh</p> <p>3 1/4" Jamb Existing Sill Angle 0 Hindrance: Is the existing Sill Angle of 0 degrees correct?</p>	<p>Initials required</p> <p>Seller: _____</p> <p>Buyer: _____</p>		

Line #6 Qty: 1	Mark Unit: Goodwyn Panty A			
<p>INFINITY <small>REPLACEMENT WINDOWS</small> <i>Built for life</i></p>  <p>As Viewed From The Exterior</p> <p>Entered As: IO FS 32 5/8" X 61 3/4" IO 33" X 62"</p>	<p>Bahama Brown Exterior Stone White Interior Infinity Insert Double Hung Inside Opening 33" X 62"</p> <p>Top Sash IG - 1 Lite LoE 366 - i89 w/Argon</p> <p>Bottom Sash IG - 1 Lite LoE 366 - i89 w/Argon</p> <p>White Sash Lock White Sash Lift Extruded Full Screen Bahama Brown Surround Charcoal Hi-Transparency Fbrgls Mesh</p> <p>3 1/4" Jamb Existing Sill Angle 0 Hindrance: Is the existing Sill Angle of 0 degrees correct?</p>	<p>Initials required</p> <p>Seller: _____</p> <p>Buyer: _____</p>		

Line #7 Qty: 1	Mark Unit: Goodwyn Apt C			
<p>INFINITY <small>REPLACEMENT WINDOWS</small> <i>Built for life</i></p>	<p>Bahama Brown Exterior Stone White Interior Infinity Insert Double Hung Inside Opening 38" X 66"</p> <p>Top Sash</p>			



Entered As: IO
FS 37 5/8" X 65 3/4"
IO 38" X 66"

IG - 1 Lite
LoE 366 - i89 w/Argon
Bottom Sash
IG - 1 Lite
LoE 366 - i89 w/Argon
White Sash Lock
White Sash Lift
Extruded Full Screen
Bahama Brown Surround
Charcoal Hi-Transparency Fbrgl's Mesh
3 1/4" Jambs
Existing Sill Angle 0
Hindrance: Is the existing Sill Angle of 0 degrees correct?


Initials required

Seller: _____


Buyer: _____

**INFINITY INSERT DOUBLE HUNG
SECTION DETAILS-OPERATOR**


SCALE 3" = 1' 0"




Head Jamb and Checkrail



Jamb



Head Jamb and Checkrail



Jamb

Appendix B



FREY CONSTRUCTION & HOME IMPROVEMENT, LLC

530 PARK AVE PRAIRIE DU SAC, WI 53578 | PHONE: (608) 643-7914 | FAX: (608) 644-0821
WWW.FREYCONSTRUCTION.COM | INFO@FREYCONSTRUCTION.COM

Proposal

Date: February 19, 2015

Job Number: 151008

Estimate Submitted To:

Tom Goodwyn & Kraig Kowalke
848 Spaight St.
Madison, WI 53703
Cell: 608-251-9117

For Work At:

Same
848 Spaight St.
Madison, WI 53703

Frey Construction & Home Improvement, LLC proposes to furnish all materials and perform all labor necessary to complete the following work:

<u>Description</u>	<u>Cost</u>
Total Replacement GAF Timberline Lifetime Shingle	\$20,579.87

Description**Cost**

Description: ****Exclusive Warranty Available Only From a GAF Master Elite Contractor****
 Weather Stopper Golden Pledge Warranty covers complete Roofing System, not just the shingles. Warranty provides 50 years of 100% coverage for material defects and labor to repair or replace materials, including tear-off and disposal. After installation, an exclusive 40-point factory inspection will be completed. Upon completion, Workmanship will be 100% covered by the warranty for 25 years. Wind coverage for winds up to 130 MPH is provided for 15 years. If the home is sold, the warranty may be transferred once during the first twenty years of the warranty.
 Tear off existing one layer of roof materials down to roof deck. Supply & install GAF Weather Watch Ice and Water Protection on all roof areas within 6' of eaves and 3' of valleys. Supply & install GAF Premium Breathable Deck Armor in all other areas. Supply & install GAF Snow Country ridge vent, 20" of valley tin in all valleys, and drip edge along all eaves & rakes. Install plywood in existing vent openings. Replace plumbing vent flashings, Broan vents and chimney flashings. Clean up, and recycle or dispose of waste. Supply & install GAF Timberline Lifetime Shingle. Rebuild street side eyebrows onto stucco with a steeper pitch. 5 or 6 pitch to increase better water flow away from the building and stucco to reduce the opportunity for water to penetrate the attic space. The installation will require grinding into the stucco and adding wood with raised eyebrows. Additional materials will include fascia, wood, drip edge, shingles and proper flashings.
 Shingle Color: ~~Black~~ *Barkwood*
 Drip Edge Color: ~~Black~~ *brown*

Custom Bend Vent. Drip Edge With 2x4 furring strips \$7,596.88

Description: Custom Bend Ventilating Drip Edge on the Eaves. With 2x4" Furring Strips to Create a 1.5" Air Chamber for Ventilation to connect overhang to attic space.. 7/16" OSB Roof Sheeting applied over furring strips. 7/16 osb over entire roof.

Absolute Gutter System \$3,719.96

Description: Tear Off Existing Gutters. Clean Up, Recycle, and Dispose of all Waste. Install Absolute Gutter: The Ultimate Water Dispensing system with 3x4 downspouts and Big Mouth Outlets.
 Gutter Color: ~~Black~~ *brown*
 Downspout Color: ~~Black~~ *brown*

Leafproof Gutter Protection \$3,456.06

Description: Supply and install Leafproof gutter protection on gutters.
 Color: ~~Black~~ *brown.*

Discount (\$500.00)

Description: Discount to Customer: February special \$500 off

Total Replacement Total \$34,852.77

All work is to be completed in a substantial and workman-like manner for the sum of **Thirty Four Thousand Eight Hundred Fifty Two Dollars and Seventy Seven Cents.**

Typical payment schedule is as follows: 33 1/3% Deposit Upon Signing, 33 1/3% on Start Date, 33 1/3% Upon Completion.

Full Balance Due upon Completion: \$34,852.77

Approximate Start Date: March 15th - April 15 2015

Approximate Completion Date: March 28th - April 28 2015

Rotten wood and unforeseen complications will be replaced as Time and Material at a Rate of \$63.50 per man hour plus 20% over Material, Labor, and Sub-Contractor costs. Any alterations or deviation from the above specifications involving extra costs will be executed only upon written orders and will become an extra charge over and above the estimate. Frey Construction & Home Improvement, LLC is not responsible for damage to the interior of the house caused by exterior work (including knick-knacks and pictures falling off walls, nail pops and cracked drywall). This contract does not include, unless expressly specified, any mold abatement, removal, or cleaning. If mold is found existing on the premises, any cost to abate, remove, or clean shall be paid by the homeowner as an extra. In addition, any warranty given to the homeowner under this contract does not include the cost to abate, remove, or clean mold that may be found on the premises in the future. Frey Construction & Home Improvement, LLC obtains all necessary permits and the cost will be added to your invoice. Any pictures taken of your property may be used for marketing purposes. Note: This proposal may be withdrawn by Frey Construction & Home Improvement, LLC if not accepted within 10 days.

This contract does not include, unless expressly specified, any mold abatement, removal, or cleaning. If mold is found existing on the premises, any cost to abate, remove, or clean shall be paid by the homeowner as an extra. In addition, any warranty given to the homeowner under this contract does not include the cost to abate, remove, or clean mold that may be found on the premises in the future.

_____ I would not like to receive communications from Frey Construction about home maintenance, future specials and discounts or promotions.

I am presenting the above estimate along with the terms of payment for your consideration.

2-19-15
Date

[Signature]

Frey Construction & Home Improvement, LLC

ACCEPTANCE

You are hereby authorized to furnish all materials and labor required to complete the work described above, for which I agree to pay according to the terms described above.

Kraig C Kowalke
Tom Goodwyn & Kraig Kowalke

2-19-2015
Date

[Signature]

2-19-2015
Date