

CITY OF MADISON FIRE DEPARTMENT

Fire Prevention Division

325 W. Johnson St., Madison, WI 53703-2295 Phone: 608-266-4484 • FAX: 608-267-1153

_	-	-	_	
ì١	Λ	- 1	↓	•
	~		Ł	

July 7, 2008

TO:

Plan Commission

FROM:

Edwin J. Ruckriegel, Fire Marshal

SUBJECT:

515 S. Midvale Boulevard

The City of Madison Fire Department (MFD) has reviewed the subject development and has the following comments:

MAJOR OR NON-STANDARD REVIEW COMMENTS (Comments which are special to the project and/or may require additional work beyond a standard, more routine project.)

1						
1						
1						
1						
1		A 1				
1	7	NIANA				
1		None				
1						
1						
į.						
1						
1						
1						
1						
1						
1						
1						
l .						
}						
1						
1						
1						
1						
1						
1						
1						

GENERAL OR STANDARD REVIEW COMMENTS

In addition, we offer the following General or Standard Review Comments:

- 2. Provide fire apparatus access as required by Comm 62.0509 and MGO 34.19, as follows:
 - a. The site plans shall clearly identify the location of all fire lanes.
 - b. Provide an aerial apparatus access fire lane that is at least 26-feet wide, with the near edge of the fire lane within 30-feet of the structure, and parallel to one entire side of the structure, if any part of the building is over 30 feet in height.

Please contact Scott Strassburg, New Construction Inspector at 608-261-9843 if you have questions regarding the above items.

CC:

Bill Sullivan

circulate tretura to kevin firchow

Plan Commission, July 7, 2008

Two years ago, 1200 members of the neighborhoods surrounding Sequoya Commons signed a petition asking for, among other things, 1) traffic flow that utilizes Midvale and Tokay Blvds and minimizes spillover into the neighborhoods and 2) that significant setbacks be maintained to fit in with the scale and context of the neighborhood.

At that time, the UDC approved plans that included a Phase II driveway onto Midvale Blvd. Joe Krupp agreed to this condition unless he developed condos at this site. He has returned with 100 apartments and a garage on Caromar Drive. There is no necessity for this change.

This property was designated for this type of redevelopment because of its location at the intersection of Midvale and Tokay. Traffic engineering has stated that they can accept a driveway on either Midvale or Caromar and that Midvale is not overloaded for its design. If parking along Midvale presents a safety hazard, as Joe Krupp believes, then eliminate parking on Midvale south of the new driveway. This would involve approximately four parking spaces.

This driveway's increase of traffic onto Midvale will be negligible while this amount added to Caromar will be significant onto a residential street that is already facing traffic problems. In addition, this particular driveway will funnel traffic through the most pedestrian-friendly entryway into the Sequoya Commons at South Owen Drive. This is where the neighborhood pedestrians as well as others from farther away who drive to the Commons but can not park in the lot will enter the property on foot.

Mr. Krupp originally proposed a two story building with a stepback to four stories at this site. He now wants a three story building. Regardless of the height of the building but particularly if the building is going to be three stories high, the full standard 30 foot setback from the sidewalk should be maintained on the Caromar side of the building so that it fits within the context of the neighborhood. This is already a much less attractive façade for the neighborhood. Phase II sits across the street from small single story homes and next to a two story apartment building that sits at a low elevation. Placing the building closer to the sidewalk will make it appear to loom over the neighborhood. This is another self-imposed problem of this design.

In the words of the Comprehensive Plan, I ask that you "balance the preferences of residents with citywide and neighborhood planning objectives and priorities."

I ask for referral.

Dann Me Milli Lasta

July 7, 2008

Madison Planning Commission Madison, Wisconsin

Re: Sequoya Commons - Plan Change

Greetings:

We are writing in opposition to the latest set of changes proposed by Joe Krupp for his Sequoya Commons development project.

Specifically, we oppose the following:

1. Garage entrance on Caromar Drive. Our family has used the north exit onto Midvale Blvd. for years, as do many others. We've never had or seen any problems there. Do traffic records indicate a high number of accidents at this location? Why was this alternative acceptable in the past, but not now?

Joe Krupp indicated he was OK with this location if he built apartments. Why is he allowed to change his mind at the expense of our neighborhood?

2. <u>Setback</u>. Given that Mr. Krupp has changed the Caromar facade from two stories to three, it seems only fair that the standard 30' setback should apply in his case, as it does for most others in the neighborhood.

Mayro Hanso

Thank you for your consideration of these matters.

Sincerely,

anet and Wayne Hanson

Westmorland Neighborhood

received 7/7/08 circulate + Alturn to Kevin Firehow

Midvale Plaza - Sequoya Commons Phase II

We have several concerns about Phase II and feel that the problems are self-inflicted by Midvale Plaza Joint Venture (MPJV) LLP due to poor design choices.

Background: The original Sequoya Commons GDP was approved by the UDC with the understanding that the Phase II garage entrance would be on Midvale Blvd. Mr. Krupp stated at that time that he reserved the possibility of revisiting this if the building was condos. The Plan Commission left the issue open for discussion at the time of the Phase II SIP. When the Phase II apartments were submitted in early 2008 the garage entrance was on Caromar. The Alder and the neighborhood (through its representatives) told Mr. Krupp at that time that the Caromar garage entrance was not acceptable. The UDC has expressed similar sentiments about Phase II. Concerns have also been raised since February about the massing and setback along Caromar. The typical setback on residential streets in Westmorland and Midvale Heights is 30 feet or more.

Our concerns and responses to issues raised at the UDC:

- The original Midvale Plaza had 1 entrance/exit and 1 exit-only on Midvale, 2 entrance/exits on Tokay, and 1 entrance/exit on Caromar. The current plan calls for 3 entrance/exits on Caromar and 1 entrance/exit on Midvale. The increased traffic from Phase II is being diverted onto residential streets, primarily Caromar but also S. Owen Dr. Due to the Sequoya Library and local retail those streets experience a great deal of pedestrian traffic, especially children.
- For a residential area there is already a large amount of traffic at the Caromar and S. Owen intersection due to:
 - O Queen of Peace Elementary School: ~400 of its 450 students are driven to school because the families do not live in the neighborhood.
 - Midvale Elementary School: Parents drive their children to school if they live on the other side of Mineral Point Rd or the opposite side of Midvale, because of obvious safety concerns. Midvale is a paired school and some parents from the Lincoln school area drive their children to Midvale school.
- Per MPJV's Traffic Engineer John Lichtenheld Phase II will increase traffic on Caromar from the proposed garage exit to Tokay by >40 cars per peak hour in the PM. The percentage increase at peak traffic times (8am-10am and 3pm-5pm) is estimated from numbers in his report to be roughly 50%. The percentage increase of traffic on Midvale if the Phase II traffic were directed there is very small.
- The current existing Midvale Plaza has only a northbound exit onto Midvale, yet still sees very heavy traffic to the library and local businesses, specifically La Brioche and The Chocolate Shoppe. There is no data suggesting an increase in accidents at the Midvale and Ames intersection under these conditions.
- Nothing prevents removal of parking spots on Midvale to accommodate sight lines for a garage curb-cut from Phase II.
- The 12% grade of a Midvale driveway from Phase II represents a worst-case scenario and could quite easily be more shallow.
- At a meeting held with Alder Gruber, Mr. Krupp, residents, and others Dan McCormick of Traffic Engineering stated that they:
 - Can support a garage entrance on either Midvale or Caromar.
 - o Would not recommend stop signs on Caromar at the Caromar and S. Owen intersection.
 - o Would not recommend a 'table top' at that intersection due to cost (approx \$150,000).
 - O Would support sidewalk 'bump outs' to increase pedestrian safety.
 - o "Prefer" a Caromar garage entrance

We find it ironic that stop signs, the simplest and cheapest step, were outright rejected by traffic engineering.

- The failed vote for traffic calming on Caromar has frequently been cited as an obstacle to finding a compromise. The traffic calming proposal vote did not represent nor reflect the concerns about traffic south of the Caromar S-curve. The traffic calming did not seem necessary to the residents north of the S-curve on Caromar who represented the majority of residents polled.
- We are unaware of any discussion of alternatives to address the decrease or loss of the rain gardens on the North side of Phase II that would be necessary for a Midvale entrance/exit, but we are willing to work with Mr Krupp to find a place to infiltrate the run-off.
- We appreciate the setback being increased to 25 ft since Phase II was introduced but we prefer 30 ft, especially in light of the changes to the Caromar façade from a two to a three story structure.

Signed,		12 200
CLARENCE C. OLSON	537 Togstad Clenn 6	Carene al alson
Name	Address	Signature
Louise 6 Olson	337100stad 6/EUM	Signature Signature
Jerold W. Hans	522 Turstad Glan	Just w. ag
Name	Address	Signature
Ruth E. Apps	522 Togstad Clar /	Signature Company
DONALD W. SEVERSON	534 504TH MIDUALE BUD.	Signature Signature
Name	Address	Signature
KATHERINE M. LORONNA Name	530 SOUTH MIDIALE BLYD. Address	Natheren m. Coron Signature
Name	Address	Signature

- The failed vote for traffic calming on Caromar has frequently been cited as an obstacle to finding a compromise. The traffic calming proposal vote did not represent nor reflect the concerns about traffic south of the Caromar S-curve. The traffic calming did not seem necessary to the residents north of the S-curve on Caromar who represented the majority of residents polled.
- We are unaware of any discussion of alternatives to address the decrease or loss of the rain gardens on the North side of Phase II that would be necessary for a Midvale entrance/exit, but we are willing to work with Mr Krupp to find a place to infiltrate the run-off.
- We appreciate the setback being increased to 25 ft since Phase II was introduced but we prefer 30 ft, especially in light of the changes to the Caromar façade from a two to a three story structure.

Signed, Feffice MCT to sl		<i>⊗</i> .
Signed, Esther McIntosh Esther McIntosh	526 S. Miduale Blod.	Esther WM Intock
Name	Address	Signature
Randall J. Molle	4925 To Ray Blud.	tomacoll. While
Name	Address	Signature
Syl M. Molle	4925 Tokay Blvd.	JylM. Molla
Name C. Mat Ical	Address	Signature
Ginger McIntosh	3326 Gregory St.	Linge McInto
Name (Address	Signature
Name	Address	Signature
Name	Address	Signature
Name	Address	Signature

- The failed vote for traffic calming on Caromar has frequently been cited as an obstacle to finding a compromise. The traffic calming proposal vote did not represent nor reflect the concerns about traffic south of the Caromar S-curve. The traffic calming did not seem necessary to the residents north of the S-curve on Caromar who represented the majority of residents polled.
- We are unaware of any discussion of alternatives to address the decrease or loss of the rain gardens on the North side of Phase II that would be necessary for a Midvale entrance/exit, but we are willing to work with Mr Krupp to find a place to infiltrate the run-off.
- We appreciate the setback being increased to 25 ft since Phase II was introduced but we prefer 30 ft, especially in light of the changes to the Caromar façade from a two to a three story structure.

Midvale was not designed to be the arterial that it has become. The issues with safety and traffic on Midvale existed 10 years ago and will increase even if Sequoya Commons had instead been made into a prairie. Those issues must be addressed, but not at the cost of the quality-of-life of those surrounding Sequoya Commons. In our opinion as those who live near the site the cost of putting Phase II traffic onto Caromar outweighs the benefit to the issues surrounding Midvale Blvd. This situation could have been avoided with a more thoughtful design of this entire site.

Signed,
Bonnie McMollin-howsten, 555 Chotham Ter, Sommitted Mille dante
Tack Lawton, 559 Chatham Ter, Jank R South
Anna Strenslei 4317 S. Owen D. Attensli

Vicki Goodman
Vicki Goodman
Vicki Goodman

- The failed vote for traffic calming on Caromar has frequently been cited as an obstacle to finding a compromise. The traffic calming proposal vote did not represent nor reflect the concerns about traffic south of the Caromar S-curve. The traffic calming did not seem necessary to the residents north of the S-curve on Caromar who represented the majority of residents polled.
- We are unaware of any discussion of alternatives to address the decrease or loss of the rain gardens on the North side of Phase II that would be necessary for a Midvale entrance/exit, but we are willing to work with Mr Krupp to find a place to infiltrate the run-off.
- We appreciate the setback being increased to 25 ft since Phase II was introduced but we prefer 30 ft, especially in light of the changes to the Caromar façade from a two to a three story structure.

Signed,		
ANDREA E. LEWISON	639 S.OWEN Dr.	Chalea F. Lewisa
Name	Address	Signature
PANNA & ERIC CODNER	4022 BIRCH AVE	James & CC
Name	Address	Signature
Michelle Olsen	544 Cately Ten	Michelle Olsen
Name	Address	Signature
South Olsen	544 GATEUT TERR	SouthOber
Name	Address	Signature
SAVITAL TERING	548 Cotely Ter	Saidi Iseriz
Name	Address	Signature
Tsering Dhouday	548 hasely Ter	her yless
Name 1	Address	Signature
Kim Brilauski	42/8 St CLAIR =	tentroloo1
Name	Address	Signature /

- The failed vote for traffic calming on Caromar has frequently been cited as an obstacle to finding a compromise. The traffic calming proposal vote did not represent nor reflect the concerns about traffic south of the Caromar S-curve. The traffic calming did not seem necessary to the residents north of the S-curve on Caromar who represented the majority of residents polled.
- We are unaware of any discussion of alternatives to address the decrease or loss of the rain gardens on the North side of Phase II that would be necessary for a Midvale entrance/exit, but we are willing to work with Mr Krupp to find a place to infiltrate the run-off.
- We appreciate the setback being increased to 25 ft since Phase II was introduced but we prefer 30 ft, especially in light of the changes to the Caromar façade from a two to a three story structure.

Signed,		
Robert R. Kowal	537 Gately Ter.	Robert R. Kows
Name	Address	Signature
MARY CHECOVICH	533 CUPDEN	Mon Checomen
Name	Address	Signature /
John Kennerly	522 5. Owen Dr.	John Love May
Name	Address	/Signature
Jeanne Daniels.	549 Caromar Dr	Jeanne Daniels
Name	Address	Signature
PAUL CERUTTI	549 CAROMAR DR.	Harl Cutt
Name	Address	Signature
SOBY Way	545 CAROMAR DR	Duyway
Name /	Address	Signature
Kurt Kaczmatek	4308 5 Over Pr.	Hert fazzur
Name	Address	Signature /

Midvale Plaza – Sequoya Commons Phase II

Warren Krammarch	4308 5. Owen Drive	Nany Kaymare
Name		Muney Kaugmerer Signature
Denias Theles.	Address Clair Dr.	DINEAN THELEN Signature
May Can about	533 Rafele Tex	Mary Campbell
Name	Address 1710 yeland Place wine of 14313 & Owin Daire	Signature FAREN MATTOO
//2 /// week	Address 14313 & Owen Dive	Signature Signature
Name	Address	Digimuic
Name	Address	Signature

- The failed vote for traffic calming on Caromar has frequently been cited as an obstacle to finding a compromise. The traffic calming proposal vote did not represent nor reflect the concerns about traffic south of the Caromar S-curve. The traffic calming did not seem necessary to the residents north of the S-curve on Caromar who represented the majority of residents polled.
- We are unaware of any discussion of alternatives to address the decrease or loss of the rain gardens on the North side of Phase II that would be necessary for a Midvale entrance/exit, but we are willing to work with Mr Krupp to find a place to infiltrate the run-off.
- We appreciate the setback being increased to 25 ft since Phase II was introduced but we prefer 30 ft, especially in light of the changes to the Caromar façade from a two to a three story structure.

Signed,		
minamelleringe		Miriam Leviuse
Name /	Address	Signature
Syla W. Fruh		Kyle W. Friedon
Name	Address	Signature
gil M. Frin	532 S. Own Pr.	Jill M. Friedow
Name	Address	Signature
Greg Thain	543 Charbam Tar	4
Name	Address	Signature
Heather Mmsm	548 Chatham Ten	Heaster Monson
Name -	Address	Signature
"Kichelle Quenn	544 Chatham Fest	Michelle Quinn
Name	Address	Signature
Adles monito	4312 S. aug Dr.	Sam
Name	Address	-Signature

	Midvale Plaza – Sequoya Commons Phase II			
		4310 Tokay Blvd. Address	Signature Signature	
	Name OMA	4313 80 wm 6	a farin Tall Is	
	Name	Address	Signature	
	Mary ann Introll	4313 S. Ferren Vor.	Man & Mutan	
	Name of the state	4309 5 Owen Dr.	the farms	
	Name D 1	Address	Signature /	
	Name Name	4369 S. OWN DR. Address	Signature Signature	
	Katlan Oker	529 G. Owen Dr.	- 7	
	Name	Address	Signature	
	Name D	Address S, Owen Dr.	David Herrnam Signature	
	Name Major M	4364 S. Outpun. Address	Jeff Grahy Signature	
٠.	Roy Numerici.	450 Glenwey SY. Address	Rocer Nicolai Signature	
	Dolores C. Nicolai Name	450 Glenway St. Address	Dolores C. Nicolai Signature	
	Mary ann Lynch	4313 Takay Blul. Address	Marey Jun Lynch	
	Iom la lerico	4218 Tokay Address	Signature	
	Amy Talerico Name	4218 Tokay Address	Signature	
	Elner a. Reichel Name	4306 To Kay Address	Elnor A. Reichel Signature	
	EARL H. REICHE	L (()(Carl H. Orleichel	
	Donne M. TAFT	Address 430 Tokag Blvd. Address	Signature Signature	
	Name	Additss (/	oignature v	

- The failed vote for traffic calming on Caromar has frequently been cited as an obstacle to finding a compromise. The traffic calming proposal vote did not represent nor reflect the concerns about traffic south of the Caromar S-curve. The traffic calming did not seem necessary to the residents north of the S-curve on Caromar who represented the majority of residents polled.
- We are unaware of any discussion of alternatives to address the decrease or loss of the rain gardens on the North side of Phase II that would be necessary for a Midvale entrance/exit, but we are willing to work with Mr Krupp to find a place to infiltrate the run-off.
- We appreciate the setback being increased to 25 ft since Phase II was introduced but we prefer 30 ft, especially in light of the changes to the Caromar façade from a two to a three story structure.

Signed,		
Pat Keterman	552 (hatham Terrace	Las telleman
Name	Address	Signature
May Chance	559 Chathan Kenace	May Chang
Name 1	Address	Signature
Pet (Inc	559 Chathan Dorage	the
Name	Address	Signature
Wym Karis	537 Carona Dr	Dyn Davie
Name Longe Davies	Address	Signature
Force Navies	537 Caromar Dr.	Loree Navies
Name	Address	Signature
WALLA TROY HE	1529 Caronas VE	Thos
Name	Address	Signature
Hal Hasken	453 Tups Red Slem	DAK/KL)
Name	Address	Signature

Midvale Plaza - Sequoya Commons Phase II

PRINT		
Name A Oc. O	Address	Signature / // // /
Mas H Allala	5/0 (decomps //p	Alae the Hamba
Name Name	Address	Signature
1		TI CZ II. O
The State of the S	Address 501 CAROMEN DO	Signature Steinhout
Name		_ /
Jerry Henl	- 465 CARAMOR DR	JERRY HARBER
Name /	Address	Signature
3111 L	441 Coroner Dr	Borred Van Sichban
Name	Address	Signature Van Sichler
Ann Martinelli	445 Caroman DR	the Martineth
Mame Plantikelli	Address	Signature
- 00 10	elli 445 Carona-Dr.	To met Ils
Name Narting	elli 445 Caroma-Dr. Address	Signature Martinell
,		
mayorie M. Hr	Tober 43/8 Heating Address	Marpine M. Thobach
Name		Signature
Julie A. Hor		Chili la HI
Name	Address Sowen	Signature / //
D.C. CILIENTA	al 4557 = "	000000
Name	Address	Signature
Middle T. Moor	20 4321 Solven	Ille
Name	Address	Signature
2 A Dancon	4312 S. Owen	7
Name	Address	Signature
Λ	1 C C T T	ZONA BOELSING
	Sin 539 Chalhamber	Signature Signature
Name O		Signature A /
May Dello Sa	oner 539 Villente	My riffeth Lawson
Name //	Address	Signature//
Math Lewi son	539 In Owen In	M Vola house
Name /	Address	Signature
John Thurs	fo \$39 Seven Ol.	John Lew Food in
Name	Address	Signature

- The failed vote for traffic calming on Caromar has frequently been cited as an obstacle to finding a compromise. The traffic calming proposal vote did not represent nor reflect the concerns about traffic south of the Caromar S-curve. The traffic calming did not seem necessary to the residents north of the S-curve on Caromar who represented the majority of residents polled.
- We are unaware of any discussion of alternatives to address the decrease or loss of the rain gardens on the North side of Phase II that would be necessary for a Midvale entrance/exit, but we are willing to work with Mr Krupp to find a place to infiltrate the run-off.
- We appreciate the setback being increased to 25 ft since Phase II was introduced but we prefer 30 ft, especially in light of the changes to the Caromar façade from a two to a three story structure.

Signed,		
HAMAUN	545 CARCY TEASTE	
Name	Address	Signature
(Mat Matheto-	1710 YAHALA PL	PAUL MATTEON
Name	Address	Signature
Maryn	445 S. Own Dr.	Michael Ben
Name JAWET BEACH	Address	Signature
Land Beaule Hasm Hawson	4209 St Clair MAISM 53711	Sant Bearlanson
Name/	Address	Signature
Name	Address	Signature
Name	Address	Signature
Name	Address	Signature