

**From:** [Stelljes, Corey](#)  
**To:** [Fries, Gregory](#); [Hacker, Marsha](#)  
**Subject:** Adams/Randall CO documents for BPW  
**Date:** Wednesday, July 08, 2015 12:48:24 PM  
**Attachments:** [RANDALL LATERALS PLAN SHEETS.pdf](#)  
[RANDALL LATERALS.pdf](#)

---

Marsha- Please see attached documents for the board tonight

Greg- Thanks for taking this for me

Change Order description:

As part of the street reconstruction the City proposed replacing the original sanitary sewer main from 1914. During replacement it was discovered that at some point after the original City main was installed the laterals for the properties at 9-39 S Randall were re-laid over the MMSD interceptor (1964). Since the interceptor was installed higher than the City main the laterals between the interceptor and the properties were all back pitched towards the properties resulting in poor or non functioning sewer. This was discussed with MMSD and MMSD allowed the laterals to be tapped directly into the interceptor to solve this problem. One condition of the interceptor connections was that backflow preventers be installed for each lateral.