LANDMARKS COMMISSION APPLICATION

Complete all sections of this application, making sure to note the requirements on the accompanying checklist (reverse).

If you need an interpreter, translator, materials in alternate formats or other accommodations to access these forms, please call (608) 266-4635

City of Madison Planning Division 126 S Hamilton St PO Box 2985 Madison, WI 53701-2985 (608) 266-4635



4	10	C A	 0	AI
1		CA	 	N
	-		 \mathbf{v}	···

Project Address: 171	LANGDON STR	367		_Aldermanic District:
2. <u>PROJECT</u>	en en			
Project Title/Description:	EXTERIOR REPA	1R - 121 LANGOE	W.	
This is an application for: (cl	neck all that apply)			Legistar#:
☐ Alteration/Addition to or Designated Landman	a building in a Local Historic D rk (specify)**:	vistrict		53000
☐ Mansion Hill	☐ Third Lake Ridge	☐ First Settlement		DATE STAMP
☐ University Heights	☐ Marquette Bungalows	Landmark		CITY OF MADISON
☐ Land Division/Combina or to Designated Landr ☐ Mansion Hill ☐ University Heights	ation in a Local Historic District mark Site (specify)**: ☐ Third Lake Ridge ☐ Marquette Bungalows	☐ First Settlement	DPCED USE ONLY	SEP - 4 2018 [1:10 And
☐ Demolition		Can Alexand No. 1 years	PCED	& Economic Development
	a building adjacent to a Desig	nated Landmark	Δ	A Chizell
	oric Preservation Ordinance (C			Preliminary Zoning Review
	/Rescission of Historic District istoric Preservation Planner for spo			Zoning Staff Initial:
3. <u>APPLICANT</u>				Date: / /
Applicant's Name: DA Address: 270 4 6		Company: FER	CH A	RCHITECTURE State Zip
Telephone: <u>608 - 88</u>	36-3394	Email: davide f	evchē	orchiteuture, com
		J STREET GROUPE	? HAR	30LD LANGHAMMER
Address: 513 N. L	MICE STRUCT, MI	40150N, WI 5370	3	Partue
Property Owner's Signature	Street	ing hamme	City Dat	e: <u>2-4-18</u>
residential development of over	er 10 dwelling units, or if you are seeking a	of a development that has over 40,000 sq assistance from the City with a value of \$10 (Sec. 2.40, MGO). You are required to regis	,000 (includ	ing grants, loans, TIF or similar

assistance), then you likely are subject to Madison's lobbying ordinance (Sec. 2.40, MGO). You are required to register and report your lobbying. Please const the City Clerk's Office for more information. Failure to comply with the lobbying ordinance may result in fines.

4. APPLICATION SUBMISSION REQUIREMENTS (see checklist on reverse)

All applications must be filed by 12:00 pm on the submission date with the Preservation Planner, the Department of Planning & Community & Economic Development, Planning Division, located at 126 S Hamilton Street. Applications submitted after the submission date *or* incomplete applications will be postponed to the next scheduled filing time. Submission deadlines can be viewed here: www.cityofmadison.com/dpced/planning/documents/2018LCMeetingScheduleDates.pdf

FERCH ARCHITECTURE

2704 Gregory Street, Madison, WI 53711 (608) 238-6900

September 3, 2018 Project: 01815

Madison Landmarks Commission 126 S. Hamilton St. Madison, WI 53701

RE: Letter of Intent – 121 Langdon Street

Dear Madison Landmarks Commission Members:

The owner of the registered landmarks building (John Suhr Residence) at 121 Langdon was issued a notice for needed repair work on the building. Attached is that repair notice and drawings addressing the repairs.

The attached drawings are not quite finished, but I am requesting review at this time to receive input on the design and detail work on the front, south side and porches. The south side porch could be repaired to meet the design of the approved plans in 2008 (last 3 sheets of the drawings), but the owner is willing to make additional design improvements to that porch to be in more conforming to the original building design.

Thank you for your time in reviewing this proposal.

Respectfully Submitted,

David Ferch

From: Building Inspection Division
126 S. Hamilton St.
P.O. Box 2984
Madison, Wisconsin 53701-2984

City of Madison OFFICIAL NOTICE

Notice: An inspection discloses that certain sections of the City
Ordinances are being violated.

Property Located At:

121 LANGDON STREET

OWNER:

121 LANGDON STREET GROUP % SHAKESPEARE'S BOOKS 513 N LAKE ST MADISON WI 53703

Item No. Violating Section No.

CORRECTIONS REQUIRED

121 LANGDON STREET

REISSUE

FIELD OBSERVATION

Exterior of house

NOTE:

THIS IS A **REISSUE** OF THE PREVIOUSLY ISSUED NOTICE CB2016-040-01121 DUE TO ITEMS HAVING NOT BEEN PROPERLY IDENTIFIED AND INCLUDED ON THE ORIGINAL NOTICE THAT WAS ISSUED. YOU MAY DISREGUARD THE ORIGINAL NOTICE AND NOTE THAT THE DUE DATE FOR THIS CASE HAS BEEN EXTENDED TO JULY 16, 2017.

ALL HISTORIC DISTRICT AND LANDMARK REGULATIONS APPLY.

ALL DIRECTIONS ARE VIEWED LOOKING AT THE FRONT OF THE HOUSE FROM LANGDON ST.

1. 41.09(2) 41.16 41.21(2)

Obtain a Certificate of Appropriateness from the Landmarks Commission before proceeding with any exterior repairs or alterations to this property. Because this property is a designated Landmark, any exterior work must be reviewed and approved by the Landmarks Commission, or staff designee, and a Certificate of Appropriateness granted before a Building Permit may be issued and/or before any exterior work may begin. Contact Amy Scanlon, Preservation Planner, to discuss this project and to discuss the approval process. Please also note that failure to comply with any provision of the Landmarks Commission Ordinance, including failure to comply with any conditions of your approval, are subject to a minimum forfeiture of

From: Building Inspection Division 126 S. Hamilton St. P.O. Box 2984

Madison, Wisconsin 53701-2984

City of Madison OFFICIAL NOTICE

Notice: An inspection discloses that certain sections of the City Ordinances are being violated.

Property Located At:

121 LANGDON STREET

OWNER:

121 LANGDON STREET GROUP % SHAKESPEARE'S BOOKS 513 N LAKE ST MADISON WI 53703

Item No.	Violating Section No.	CORRECTIONS REQUIRED
		\$250 a day and a maximum forfeiture of \$500 a day for each separate violation. [See Madison General Ordinances Sec 41.14(3).]
		Compliance with any of the exterior-related items listed in this Official Notice shall be contingent upon these repairs being completed in such a manner that meets all of the criteria and expectations set forth by the Landmarks Commission, by Preservation Planner, Amy Scanlon, and by Madison Building Inspection.
		You may contact the Preservation Planner by phone at (608)266-6552 or by email at: ascanlon@cityofmadison.com
2.	29.05(1) 29.08(1) 27.05(2)i	Obtain the required building permit and inspections and renair or rebuild the front

27.05(2)i

Obtain the required building permit and inspections and repair or rebuild the front porch and roof assembly to a safe and substantial condition. This includes, but is not limited to:

- Repair or replace the damaged and out of plumb masonry piers supporting the front porch roof columns, tuck point the columns as needed, and replace any missing material. Ensure all piers are returned to plumb condition and can support all loads applied to them
- Repair or replace the porch columns the columns are deteriorating and out of plumb - ensure all columns are returned to plumb condition and can support all loads applied to them
- Repair or replace any deteriorated beams and framing in the front porch roof assembly and return them to a level condition.
- Replace any rotted, missing, or damaged fascia, soffit, trim, or decorative members on the front porch assembly

From: Building Inspection Division 126 S. Hamilton St. P.O. Box 2984

P.O. Box 2984 Madison, Wisconsin 53701-2984

with the term of the contract of the contract

City of Madison OFFICIAL NOTICE

Notice: An inspection discloses that certain sections of the City
Ordinances are being violated.

Property Located At:

121 LANGDON STREET

OWNER:

121 LANGDON STREET GROUP % SHAKESPEARE'S BOOKS 513 N LAKE ST MADISON WI 53703

Item No.	Violating Section No.	* CORRECTIONS REQUIRED
	type of the second	• Eliminate all holes, gaps, and cracks, and repair the crushed areas where the support columns meet the beams
		• Ensure that the roof system is weatherproof, rodent proof, and in proper repair
3.	29.05(1)	
	29.08(1)	
	27.05(2)(i)	Obtain the required building permit and inspections for the right side porch stairway
2	44 % %	that was installed without approvals or return the area to its original condition. An
		inspection found that a non-code complaint right side porch stairway was installed
) 1	and the second	without a building permit or approvals. Some items observed that do not comply with the building code are as follows:
	i i i a Éir ra i	• Use of a 2x4 as top of handrail
··.,		 Handrail does not extend to the bottom landing
		 Unknown construction of support post footings

Stair stringers not properly attached to the top beam
Existing box beam supporting roof system crushed/rotted
Beam connections not resting on top of support posts
Drywall screws used in post to footing connection
Foundation window not safety glass at base of stairs

ئ فقاۂ تاہ کا دائموں ہے۔

From Building Inspection Division 126 S. Hamilton St. P.O. Box 2984 Madison, Wisconsin 53701-2984

City of Madison **OFFICIAL NOTICE**

Notice: An inspection discloses that certain sections of the City Ordinances are being violated.

5× 与上外提出

Property Located At: 121 LANGDON STREET **OWNER:**

121 LANGDON STREET GROUP % SHAKESPEARE'S BOOKS 513 N LAKE ST MADISON WI 53703

Item	Violating	CORRECTIONS REQUIRED	
No.	Section No.	CORRECTIONS REQUIRED	
4.	29.05(1)		
	29.08(1)		
4		Obtain the required building permit and inspections for the wo rear porch assembly and return the rear porch assembly to a sat condition. An inspection found that incorrect rear porch repairs building permit or approvals. Some items observed that do building code are as follows:	e and code compliant were made without a
		Open stair risers	
	· Para	 Over span of deck support beams 	
	udjes, dibi	with "support of stUnknown construction and use of "cookie" support post	footings
:† .:	return f	 Missing beam/support post connections 	
yur in	natalja kazītei k	 Loose, rotted, and/or missing balusters 	

- Rotted wood in the roof support columns
- Rotted/animal damaged wood roof fascias/soffits/trim

केंद्री पार अन्यास्त्राची स्वत्रुत्वेतुर्वत्त्र ते त्यु वर्वेत्रप्तृत्वतः

5. 27.05(2)(g)2 Tuck point and repair the masonry throughout the building wherever the existing and thinks changed chan mortar and blocks or bricks are loose, damaged, cracked, or missing. Remove any spray foam that has been installed between bricks. Repairs shall be completed in a workmanlike manner using accepted masonry construction methods and materials. Ensure that the foundation is waterproof, rodent proof, and can support all loads applied to it. Areas to be repaired shall include, but are not limited to:

- The building block foundation walls
- The masonry brick walls, window, and door openings
- The rear chimney
- The right side chimney

From: Building Inspection Division 126 S. Hamilton St. P.O. Box 2984 Madison, Wisconsin 53701-2984

City of Madison OFFICIAL NOTICE

Notice: An inspection discloses that certain sections of the City
Ordinances are being violated.

Property Located At:

121 LANGDON STREET

2 - 11 - 12 - 12

e terminale stations.

OWNER:

121 LANGDON STREET GROUP % SHAKESPEARE'S BOOKS 513 N LAKE ST MADISON WI 53703

Item No.	Violating Section No	CORRECTIONS REQUIRED
	orman ser a gradens m	crape and repaint the building wherever paint is peeling, chipping, cracking, or issing. All newly painted areas shall closely match the surrounding areas in color dappearance. Areas to be painted include, but are not limited to:
	11.4.	• The first floor front stair risers
	fir m trop, man	• Exterior of the common front entry doors
		• Front porch ceiling
		All new wood installation or repairs
		Wherever the existing finish is missing or damaged
	<u> </u>	operly relocate the non-conforming metal duct through the front skirt.
	usi (1924). — viltska i sal an mentil (1944). Viltakinska <mark>an</mark>	eplace the missing, rotted, or deteriorated wood fascias, trim, gable end trim, siding, d metal sheeting throughout the building. Ensure that all repairs are weatherproof d rodent proof and painted to match the surrounding areas. Areas needing repair clude, but are not limited to:
onnelle file e e e lec ente		 The second floor front balconet The storm window assemblies in the first floor front bay window system below the balconet
	និស្ស គឺមាន ភាព នៃ នេះសម	• The framing in the two story bay window system on the right side of the house

The framing in the third floor mansard roof and rear roof systems

, 🍅 144 master (1917) (1

From Building Inspection Division

126 S. Hamilton St.

P.O. Box 2984

Madison, Wisconsin 53701-2984

City of Madison
OFFICIAL NOTICE

Notice: An inspection discloses that certain sections of the City
Ordinances are being violated.

Property Located At: 121 LANGDON STREET.

ers wrendi:

ALLOSUTIVE LETY.

점 문화되었습니다 그는 것 없는 것이

OWNER:

121 LANGDON STREET GROUP % SHAKESPEARE'S BOOKS 513 N LAKE ST MADISON WI 53703

Item No.	Violating Section No. 1992 P. 1998	CORRECTIONS REQUIRED
iiui na	27.05(2)(h) less said	Remove the plastic cover in the half-moon foundation window on the front of the house, and replace the missing window glass and rotted wood trim and framing, and repair any holes. Ensure that the window system is weatherproof and rodent proof.
	· 27.04(2)(g)·, · · · · · · · · · · · · · · · · · ·	Properly secure and install the loose orange communication wires and open/loose gray communication junction box on the front porch next to the gas meters.
11.	27.05(2)(d) :: 1. 11.11	Repair or rebuild the masonry retaining wall under the right side porch; the wall is leaning and out of plumb.
9.1 - 1.0 -	27.05(2)a 27.05(2)(g)2	Properly re-grade the ground around the perimeter of the foundation so that the rigid insulation is no longer exposed. If the insulation cannot be property covered via grading, ensure the rigid insulation is properly covered with an approved material and not exposed to ultraviolet light sources.
	: 27.05(2)(a) *** - 4-4-4-4	Remove the plastic down spout extension assemblies and replace them with a downspout system that conforms with the Landmark requirements for this property.
14.	27.05(2)(h)	Remove the cracked plastic from the foundation window opening toward the front and replace the rotted wood in the middle foundation window assembly next to it on the left side of the house.

From Building Inspection Division City of Madison 126 S. Hamilton St. P.O. Box 2984

OFFICIAL NOTICE Madison, Wisconsin 53701-2984

Notice: An inspection discloses that certain sections of the City

Ordinances are being violated.

Property Located At:

121 LANGDON STREET

ROMERN THE NEWS MOON British NARL SE

MALIEUM BETO.

OWNER:

121 LANGDON STREET GROUP % SHAKESPEARE'S BOOKS 513 N LAKE ST MADISON WI 53703

	Violating New York 1997	CORRECTIONS REQUIRED
No.	Section No. 1941 1941 1941 1941	CORRECTIONS REQUIRED

This notice does not start any legal action. However, if the violations are not and the latest and a latest at a corrected by the due date listed below, the Building Inspection Division may issue citation(s), and/or refer the situation to the City Attorney's Office.

The Building Inspection Division is willing to answer questions pertaining to this official notice in order to assist you in correcting the violations. If you have questions where a problem of the compression of problems, it is important to contact me before the due date at the number listed below. You should also contact me on or before the due date if you wish to attend the follow-up inspection.

THE MADISON GENERAL ORDINANCES REQUIRE THAT A FEE OF A TOWNS OF THE SECOND PROPERTY ATTEMPTED REINSPECTIONS (NO ENTRY) ARE BILLED AT \$35.00 EACH.


The inspector can be reached by phone at 608-266-4495 or by email at rales@cityofmadison.com Inspected by: Robert Ales On: 11-21-2016


July 16, 2017

Date Issued: 4-21-2017

The violations shall be corrected on or before:

Code Enforcement Officer:









2704 GREGORY STREET, MADISON, WI 53711 608-238-6900 david@fercharchitecture.com






9/3/18

FERCH ARCHITECTURE 2704 GREGORY STREET, MADISON, WI 53711 608-238-6900 david@fercharchitecture.com



121 LANGDON

EXTERIOR REPAIR




SHEET INDEX

- C1 SITE PLAN, COVER
- P1 EXTERIOR PHOTOS
- P2 FRONT PORCH PHOTO
- P3 SIDE PORCH PHOTO
- P4 REAR PHOTO
- P5 HISTORIC PHOTO
- P6 HISTORIC PHOTO
- D1 LOWER LEVEL DEMOLITION PLAN
- D2 FIRST FLOOR DEMOLITION PLAN
- A1 LOWER LEVEL PLAN
- A2 FIRST FLOOR PLAN
- A3 SIDE PORCH ELEVATION
- A4 REAR PORCH ELEVATION
- A5 FRONT PORCH SECTION
- A6 SIDE PORCH SECTION
- S1 FIRST FLOOR FRAMING PLAN
- S2 SECOND FLOOR FRAMING PLAN


SIDE PORCH SITE PLAN APPROVAL 9/19/2008 (3 PAGES)

121 LANGDON





121 LANGDON



REV. 8/23/18

121 LANGDON







121 LANGDON



FRONT PORCH PHOTO

REV. 8/23/18

121 LANGDON



SIDE PORCH PHOTO

REV. 8/23/18 121 LANGDON



121 LANGDON

8/23/18







Photo: Wisconsin Historical Society, WHS-3280



Photo: Wisconsin Historical Society, WHS-39049







RAL PROPERTIES CENT

Telephone: 608-255-1767 13 North Lake Street Madison, WI 53703

August 11, 2008

FROM: Harold Langhammer RE: 121 Langdon Street TO: Alderman Verveer

Hi Mike. Please sign the application for existing conditional use, and give a call to our office and we will pick it up.

years and we have it propped up with jacks because the steel beams holding the concrete with a simple entry stairs, as shown on the and porch. The garage hasn't been used in hazard as well as unsightly. The picture shows the existing garage, stairs deck are rusting through. We think it is a remove everything that is there and replace it attached drawing.

Kitty Rankin has approved the demolition and building the stairs.

Call me with any questions. Thanks...

Project detail



City of Madison Site Plan Verification

Pick up

Review

All Projects

User Info

Logout

Admin

PROJECT 1178: 121 Langdon St

remove existing carport and deck & replace with parking stalls and entry stairs Harold Langhammer: (608) 255-1767 Minor Alteration to CU Submitted by: Central Properties Project type: Contact:

Project has been completed.

completed on 9/19/2008

Description:

Status:

Agency	Status	Requirements	Remarks	Requirements Remarks Checkout Date	Contact	Reviewed
Zoning	approved		1	8/22/2008	ikirchgatter (266-4429)	8/22/2008
Traffic Engineering	approved			8/20/2008	<u>ileach</u> (267-8755)	8/20/2008
Fire	approved			8/20/2008	sstrassburg (608-261-9843)	8/20/2008
Engineering	approved		12	8/21/2008	ttroester (608-267-1995)	8/26/2008
Planning	approved			8/20/2008	bmurphy (608-266-4635)	8/20/2008
Landmarks Commission	approved		1	8/21/2008	bfruhlingLM (608-267-8736)	8/21/2008
Engineering Mapping	approved			8/26/2008	epederson ((608)266-4056)	8/28/2008

Engineering

Note: Supplementary Condition Completed (was Submit revised site plan that clearly identifies existing features vs. new or revised features. The plan submitted was originally submited in 1997 and it is unclear with the notation of what all exactly is currenly proposed as "new" and what was "new" in 1997.)

Note: Supplementary Condition Completed (was If after review of the revised site plan it is determined that 4,000 sf or more of area is being disturbed an Erosion Control & Storm Water Management Permit may be required.)

Top

Landmarks Commission

Note: Supplementary Condition Completed (was 1) Submit a revised site plan detail showing the exact location and dimensions of the parking spaces to be retained in conjunction with the location of the new stairs/deck—it appears that this new structure will make one of the parking spaces non functional.2) Provide a revised landscaping plan that provides some screening for the parking spaces that will now be exposed to the street—recommend removing pavement from the parking space mentioned in item one and landscaping that area.3) Kitty Rankin must approve the design of the new stairs/deck—especially concerned about the underside and the spindly appearance of the 4" x 4" posts that will rise 6+ feet from the ground.4) Provide information on the appearance and condition of the walls of the house once the porch and carport are removed.)


Top


Zoning

Note: Supplementary Condition Completed (was Provide zoning with a copy of the revised site and landscaping plans per Landmarks

Top

http://citypermits.cityofmadison.com/PL2/projects/1178,0






NEW-(で、五分) AND SCAPING SCAPULE (0, 25) <u>Ö</u> <u><u></u></u> APINE BLOCK BASSWOOD ARDR VIA ARREVITAE BASSWOOD 20 MAPLE 10" MAPLE 10 TEW SIZE MAPLE 12' OK 74 Ø¥ OK

Vincent

SPET NIMBER

DRAMN BY; Wasse



IXI LANGBON ST., MADISON, WI ZI LANGDON STREET GROUP APARTMENTS

