Bailey, Heather

From: Bailey, Heather

Sent: Thursday, March 9, 2023 2:36 PM

To: Moskowitz, Jacob
Cc: Bannon, Katherine J
Subject: RE: Fire Report

The house at 311 E Dean was constructed in 1955. There is no WHS site file and no City preservation file for this property. Staff recommendation to the Landmarks Commission would be that this property has no known historic value. I will provide that recommendation to the Landmarks Commission at their April 3 meeting and will let them now that the demolition of this fire damaged building was approved administratively due to health & safety reasons.



Heather L. Bailey, Ph.D. (she/her)

Preservation Planner

Neighborhood Planning, Preservation + Design Section

Department of Planning + Community + Economic Development Planning Division

215 Martin Luther King, Jr. Blvd.; Suite 017

PO Box 2985 Madison WI 53701-2985

Email: hbailey@cityofmadison.com

on.com Phone: 608.266.6552

From: Moskowitz, Jacob < JMoskowitz@cityofmadison.com>

Sent: Wednesday, March 8, 2023 3:47 PM

To: Bailey, Heather <HBailey@cityofmadison.com> **Cc:** Bannon, Katherine J <KBannon@cityofmadison.com>

Subject: FW: Fire Report

Jacob Moskowitz (He/Him)
Assistant Zoning Administrator
608-266-4560
jmoskowitz@cityofmadison.com

Department of Planning & Community & Economic Development Building Inspection Unit 215 Martin Luther King, Jr. Blvd. P. O. Box 2984 Madison, WI 53701

From: Ben Mueller < ben@muellerbuilderswi.com >

Sent: Wednesday, March 1, 2023 8:39 AM

To: Moskowitz, Jacob <JMoskowitz@cityofmadison.com>

Subject: Fire Report

Caution: This email was sent from an external source. Avoid unknown links and attachments.

Jacob,

Attached is the Fire report for 311 E. Dean Ave.

Thanks, Ben

Benjamin Mueller

General Contractor

ADDRESS · 729 Prospect Ave, Portage, WI 53901 PHONE · 608-617-5616
WEB · muellerbuilderswi.com





City of Madison Fire Department

Fire/Arson Investigation Unit

314 W. Dayton St., Madison, WI 53703-2506





June 6, 2022

Andrew Marcellino 311 E Dean Ave Madison, WI 53716

SUBJECT: MFD INVESTIGATIVE REPORT # 22-155544, 311 E Dean Ave - 4/27/2022

Claim No.: n/a

We have received your request for a copy of the report(s) associated with the matter identified above. I have reviewed the report(s) and authorized release of an edited copy. Information in the report was redacted for the reason(s) specified below:

- ☑ I have redacted information in this report due to the fact that it contains confidential juvenile material. Wis. Stats. 48.396 and 938.396 relating to peace officer's records of juveniles prohibit the release of such records except in certain circumstances.
- I have redacted information in this report as release of this information would reveal highly personal and private medical and/or mental health information. Disclosure of the information would violate multiple state and federal laws and the disclosure of such personal and sensitive information would not further the intent of the Wisconsin Public Records Laws: that of keeping the public informed of the operations of its government.
- ☑ In compliance with various state and federal statutes, I have redacted Personally Identifiable Information (PII) from the enclosed records in order to prevent identity theft crimes. This PII is composed of specific addresses, dates of birth, and driver's license numbers, social security numbers, and private phone numbers. These statutes include but are not limited to the Federal Drivers' Privacy Protection Act, the Privacy Act and Wis. Stats. §§ 15.04, 16.61, 19.65, 19.67, 19.68, 19.69, 19.77, 19.80, 45.81, 46.283, 46.284. 46.2895, 66.0903(10), 77.61, 85.61, 100.54, 103.49, 115.297, 118.125, 134.405, 196.23, 441.50, 450.145, 604.04(8), 610(6), 756.04, 949.04, and 949.36.

☐ I have redacted information under authority of Wisconsin Statute 19.36(8) Identities of Law Enforcement Informants. I have redacted that information in this report which is necessary to safeguard the identity of the informant.

After consultation with the City Attorney's office, I have reached the above conclusions as dictated by statutes, case law and after weighing the reasons for non-disclosure against the public interest in disclosure. For the reasons set forth above, I have concluded that the records may only be released after having redacted the above described information. Pursuant to Sec. 19.35(4)(b) Wis. Stats., I advise you that this determination not to disclose a portion of the requested record is subject to review by mandamus under Sec. 19.37(1) Wis. Stats., or upon application to the Wisconsin Attorney General or the Dane County District Attorney.

Sincerely,

Jerome Buechner, Division Chief Fire / Arson Investigation Division

Jerome D. Buerhun

JDB/hld

cc: Mayor's Office, City Attorney's Office



NFIRS-1 Basic

Α							
13010	w	04	27	2022	Station #5 (05)	22-155544	0
FDID	State	Month	Day	Year	Station	Number	Exposure
				i	P A		
B Location Type		y - i-y				100000	Census tract:
Street Address Intersection In Front Of Rear Of	311	E-East	DEAN				VE-Avenue
☐ Adjacent To ☐ Directions ☐ US National Grid	Number	Prefix	Street o	or Highway		Str	eet Type Suffix
the section of the			Madison			w	53716
	Apt./Suite/I	Room	City			State	Zip Code
,							
1415 F 517 A	Lance Ln/Se	eth Cir					4
1 1990 PM	Cross Stree	et	25			1 7 7 3	
С				E1 Dakes			E2 Shifts and Alasms
Incident Type		,		Alarm	nd Times 04 27 2022	11:37	Shifts and Alarms
111-Building fire				Arrival	04 27 2022		Shift or Alarms District
D				Un a			Platoon
Aid Given Or Recei	ved			Controlle Last Unit		14:11	
1 Mutual Aid Recei 2 Auto. Aid Recei 3 Mutual Aid Given 4 Auto. Aid Given 5 Other Aid Giver	eived ved n	r FDID	Their State umber	Cleared			E3 Special Studies L L L ID# Value

F Actions Taken 11-Extinguishment by fire so personnel Primary Action Taken	ervice	G1 Resources Apparatus or Perso Appara Suppression 7 EMS 2 Other 2		G2 Estimated Dollar Losses and Values Losses: Required for all fires if known. Optional for all non-fires. Property: \$ V Contents: \$ V		
		Resource counts in resources.	clude aid received	Pre-Incider Property: \$ Contents: \$	1 1	None マ マ
Completed Modules	Fire Service Civilian H2 Detector Required for Cc	onfined Fires r Alerted Occupants	H3 Hazardous Mate T 1 - Natural Gas T 2 - Propane Ga T 3 - Gasoline T 4 - Kerosene T 5 - Diesel Fuel T 6 - Household T 7 - Motor Oil T 8 - Paint T 0 - Other None	s s /Fuel Oil	Mixed Use Proper Not Mixed 10 - Assembly UF 20 - Education UF 33 - Medical User 40 - Residential F 51 - Row OF Stor 53 - Enclosed MF 58 - Business an Residential F 59 - Office User 60 - Industrial UF 63 - Military User 65 - Farm User 00 - Other Mixer	Jse Jse Use res all d
Property Use None Structures 131 Church, Place of None 162 Restaurant or Caf 162 Bar/Tavern or Nig 213 Elementary School 215 High School, Junic 241 College, Adult Ed 311 Nursing Home 331 Hospital	Vorship eteria htclub ol, Kindegarten or High	341 Clinic, Clinic-Ty 342 Doctor/Dentis 361 Prison or Jail, I 419 1- or 2-Family Iv 429 MultiFamily Dv 439 Rooming/Boar 449 Residential, Bo 464 Dormitory/Bar 519 Food and Beve	t Office Not Juvenile Owelling velling ding House otel or Motel oard and Care racks	571 Gas or Se 579 Motor Ve 599 Business 615 Electric- 629 Laborato 700 Manufacl 819 Livestocl	ehicle/Boat Sales/Rej Office Generating Plant ory/Science Laborato turing Plant k/Poultry Storage (Ba idential Parking Gara	pairs ry arn)
Outside 124 Playground or Par 655 Crops or Orchard 669 Forest (Timberlan 807 Outdoor Storage 919 Dump or Sanitary 931 Open Land or Fiel 936 Vacant Lot	d) Area Landfill	938 Graded/Cared 946 Lake, River, Str 951 Railroad Right 960 Other Street 961 Highway/Divid 962 Residential Str 981 Construction S	ream -of-Way ed Highway reet/Driveway Site	Property Use: Description Look up and enter description only Property Use box	er a Property Use code if you have NOT checke x.	and ed a
K2 Owner Local Option	Person/E	Entity Type	Business Name (if app	olicable) Phone	e Number	
L	First Name J L Prefix	MI L Street or High	Last Nar		LSuffix LSuffix	
Post Office Box L State				City		

Remarks:

E5 on scene to dispatched address. One story wood frame construction. Dark grey smoke visible from approach B, C and D divisions. E5 command called for an additional engine and ambulance.

Assigned E14 water supply. 360 completed and fire attack initiated "A" division 200' 1 3/4". C division four seasoned porch noted. Assigned first in ladder ventilation. Assigned M5 backup line off of E5 300' 1 3/4".

Neighbor stated that home is thought to be unoccupied. Same neighbor handed me a slip of paper with the back door code to gain access to home. Code was not used and forcible entry to front door storm door and main door accomplished with irons.

On entry dark smoke banked to the floor. Left hand hose advancement first floor. No fire located on stretch to the basement. Fire located in basement behind stairs B C corner. Horizontal ventilation assigned and accomplished. Fire under control and knocked down.

Overhaul operations performed and additional hot spots extinguished. Scene ventilated and monitored. Scene left to FIT. E5 returned.

approximately 12 steps to the back of preceding firefighter during hose advancement for fire attack.

A completed 04/27/22. -Crossen

^M Authorization				
fddmc	Crossen, David	Lieutenant	E5	04/27/2022
Officer In Charge ID	Signature	Position or Rank	Assignment	Date
fddmc	Crossen, David	Lieutenant	E5	04/27/2022
Member Making Report ID	Signature	Position or Rank	Assignment	Date

NFIRS-2 Fire

A 13	010	w	04	27	2022		22-155544	0		
FDI	D	State	Month	Day	Year	Station	Number	Exposure		
B Property Details B1 1					d	C On-Site Materials Or Products Storage Use				
	Acres burned (ou			all I acre	-					
D Ignit D1 D2 D3	ion 43-Storage: suppl dead storage Area of Fire Origi Heat Source Item First Ignite Type of Material	d		1 - I 7 2 - U 7 3 - F Source 7 4 - A 1 5 - C 1 U - U Investi	e Act of Nature Cause Under I Cause Undete Gation	ipment or Heat nvestigation ermined After ing to Ignition	ation ation I After I - Asleep I 2 - Possibly impaired by alcohology I After I 3 - Unattended person I 4 - Possibly Mentally Disabled I 5 - Physically Disabled I 6 - Multiple Persons Involved I 7 - Age Was A Factor Estimated Age of Person Involved I Male I Female			
lo. ∐	el	In Ignitio	on	Equipme 3 Equipm 7 1 - Po 7 2 - St	ationary equipment no	rce	one or two	G Fire Suppression Factors		

H1 Mobile Property Involved	H2 Mobile Property Type and Make	Local Use
☐ 1 - Not involved in ignition, but burned ☐ 2 - Involved in ignition, but did not burn ☐ 3 - Involved in ignition and burned ☐ None	Mobile Property Type Mobile Property Make	Pre-Fire Plan Available Arson Report Attached Police Report Attached Coroner Report Attached Other Reports Attached
Mobile Property Model	Year	
State License Plate Number		
State License riate Mulhoel	VIIV	

NFIRS-3 Structure Fire

MIND-D Structure Life							
I1 Structure Type ✓ 1 - Enclosed Building ✓ 2 - Portable/Mobile Structure ✓ 3 - Open Structure ✓ 4 - Air-Supported Structure ✓ 5 - Tent ✓ 6 - Open Platform ✓ 7 - Underground Structure ✓ 8 - Connective Structure ✓ 0 - Other	Building Status 1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U - Undetermined	Building Height 1 Number of Stories At/Above Grade 1 Number of Stories Below Grade	I4 Main Floor Size 1000 Total Square Feet OR BY Length (ft) X Width (ft)				
J1 Fire Origin 0 F Below Grade Story of Fire Origin J2 Fire Spread Confined to Object of Origin 2 - Confined to Room of Origin 3 - Confined to Floor of Origin 4 - Confined to Building of Origin 5 - Beyond Building of Origin	Number of Stories Damaged By Number of Stories w/Minor I Number of Stories w/Signific Number of Stories w/Heavy I Number of Stories w/Extrem *Count the roof as part of the high	Damage (1-24%) ant Damage (25-49%) Damage (50-74%) e Damage (75-100%)	Type of Material Contributing Most to Flame Spread K1 L Item Contributing Most to Flame Spread K2 L Type of Material Contributing Most To Flame Spread				
L1 Presence of Detectors □ N - None Present □ 1 - Present □ U - Undetermined	L3 Detector Power Supply 1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical 7 - Multiple Detectors	Detector Effectivenes 1 - Alerted Occupant 2 - Alerted Occupant 3 - There Were No Of 4 - Failed to Alert Oc U - Undetermined	es, Occupants Responded es, Occupants Failed to Respond ccupants				
L2 Detector Type 1 - Smoke 2 - Heat 3 - Combination of Smoke and Heat 4 - Sprinkler, Water Flow Detection 5 - More Than One Type Present 0 - Other U - Undetermined	& Power Supplies 0 - Other U - Undetermined L4 Detector Operation 1 - Fire Too Small To Activate 2 - Operated 3 - Failed To Operate U - Undetermined	L6 Detector Failure Reason					

M1	МЗ	M5	
Presence of Automatic Extinguishing System	Operation of Automatic Extinguishing System	Reason for Automatic Extinguishing System Failure	
▼ N - None Present	☐ 1 - Operated/Effective☐ 2 - Operated/Not Effective☐ 3 - Fire Too Small To Activate☐ 4 - Failed To Operate☐ 0 - Other☐ U - Undetermined	 ☐ 1 - System Shut Off ☐ 2 - Not Enough Agent Discharged ☐ 3 - Agent Discharged But Did Not Reach Fir ☐ 4 - Wrong Type of System ☐ 5 - Fire Not In Area Protected ☐ 6 - System Components Damaged ☐ 7 - Lack of Maintenance 	
M2 Type of Automatic Extinguishing System	Required if fire was within designed range		
☐ 1 - Wet-Pipe Sprinkler ☐ 2 - Dry-Pipe Sprinkler ☐ 3 - Other Sprinkler System ☐ 4 - Dry Chemical System ☐ 5 - Foam System ☐ 6 - Halogen-Type System ☐ 7 - Carbon Dioxide System ☐ 0 - Other ☐ U - Undetermined Required if fire was within designed range of AES	M4 Number of Sprinkler Heads Operating Mequired if system operated		

NFIRS-9 Apparatus or Resources

A.							
13010	w	04	27	2022	Station #5 (05)	22-155544	0
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparatus/Resource	Dates/Times	Sent	Number of People	Apparatus Use	Actions Taken
ID: C31	Dispatch: 04/27/2022 11:37	▼ Sent	2	Suppression	81-Incident command
Type: 92-Chief officer car	Arrival: 04/27/2022 11:48			F EMS ▼ Other	
	Clear: 04/27/2022 12:26				
ID: E11	Dispatch: 04/27/2022 11:56	▽ Sent	5	▼ Suppression	87-Investigate fire out on arrival
Type: 11-Engine	Arrival: 04/27/2022 12:46			F EMS Other	
	Clear: 04/27/2022 14:11				
ID: E14	Dispatch: 04/27/2022 11:37	▽ Sent	4	✓ Suppression	81-Incident command
Type: 11-Engine	Arrival: 04/27/2022 11:44			EMS Other	92-Standby
	Clear: 04/27/2022 12:48				
ID: E3	Dispatch: 04/27/2022 11:43	▼ Sent	0	✓ Suppression	92-Standby
Type: 11-Engine	Arrival: 04/27/2022 11:51		-	EMS Other	
	Clear: 04/27/2022 12:04				
ID: E5	Dispatch: 04/27/2022 11:37	▼ Sent	4	Suppression	81-Incident command
Type: 11-Engine	Arrival: 04/27/2022 11:42		-	F EMS Other	11-Extinguishment by fire service personnel
	Clear: 04/27/2022 12:57				
ID: E8	Dispatch: 04/27/2022 11:37	▽ Sent	4	Suppression EMS	51-Ventilate
Type: 11-Engine	Arrival: 04/27/2022 11:45			C Other	
	Clear: 04/27/2022 12:07				
ID: F71	Dispatch: 04/27/2022 12:18	ি Sent	0	Suppression EMS	86-Investigate
Type: 92-Chief officer car	Arrival: 04/27/2022 12:18			Other	
	Clear: 04/27/2022 12:50				
ID: L6	Dispatch: 04/27/2022 11:37	▽ Sent	[4]	Suppression EMS	21-Search
Type: 12-Truck or aerial	Arrival: 04/27/2022 11:46			Other	
	Clear: 04/27/2022 12:33				ć
ID: L8	Dispatch: 04/27/2022 11:37	▽ Sent	4	Suppression EMS	51-Ventilate
Type: 12-Truck or aerial	Arrival: 04/27/2022 11:46			Other	
	Clear: 04/27/2022 12:41				
ID: M14	Dispatch: 04/27/2022 11:43	▽ Sent	2	Suppression EMS	72-Assist animal
Type: 76-ALS unit	Arrival: 04/27/2022 11:55			Other	92-Standby
	Clear: 04/27/2022 12:24				
ID: M5	Dispatch: 04/27/2022 11:37	▽ Sent	2	Suppression P EMS	11-Extinguishment by fire service personnel
Type: 76-ALS unit	Arrival: 04/27/2022 11:42		٠	Other	
	Clear: 04/27/2022 12:11				

NFIRS-10 Personnel

	141.11/2.	IO Pels	Omiet	
A				
13010 V	vi 04 27 2	022	Station #5 22-155544 (05)	0
FDID St	ate Month Day Ye		Station Number	Exposure
				. '
B Apparatus/Resource	Dates/Times		umber People Apparatus Use	Actions Taken
ID: C31	Dispatch: 04/27/2022 11:37	▼ Sent 2	Suppression	81-Incident command
Type: 92-Chief officer car	Arrival: 04/27/2022 11:48	<u> </u>	□ F EMS □ Other	
	Clear: 04/27/2022 12:26			,
Personnel ID	Name	Rank Ro	ole Attend	Actions Taken
FDCAS	Stedman, Che	Division	For	
		Chief		
FDBMV	Vogen, Bradley	Apparatus Engineer	Γ.	
ID: E11	Dispatch: 04/27/2022 11:56	▼ Sent 5	Suppression	87-Investigate fire out on arrival
Type: 11-Engine .	Arrival: 04/27/2022 12:46		EMS Other	
The Language of the Language o	Clear: 04/27/2022 14:11			
Personnel ID	Name	Rank Ro	ole Attend	Actions Taken
FDGDJ	Johnson, Jr., Guy	Firefighter	ne Accend	Actions Token
FDDAS	Santana, David	Apparatus		
	•	Engineer		1 1
FDSMS	Smith, Shannon	Firefighter Paramedic	<u> </u>	∐ ·
FDJAV	Vogen, Jeffrey	Lieutenant		
fdkem	McDonald, Kevin	Lieutenant	J. 2	
ID: E14	Dispatch: 04/27/2022 11:37	V Sent 4	✓ Suppression	81-Incident command
Type: 11-Engine	Arrival: 04/27/2022 11:44	L	□ F EMS □ Other	92-Standby
	Clear: 04/27/2022 12:48			
Personnel ID	Name	Rank Ro	ole Attend	Actions Taken
FDPGB	Burns, Patrick	Apparatus	[7"	Ц
FDWWE	Ecker, Wesley	Engineer Lieutenant	· · · · · · · · · · · · · · · · · · ·	
FDJJS	Suttle, Jason	Firefighter	F	
FDPAS	Schecklman, Paul	Firefighter	, , , , , , , , , , , , , , , , , , ,	
		Paramedic 2	,	
ID: E3	Dispatch: 04/27/2022 11:43	I ✓ Sent 0	Suppression	92-Standby
Type: 11-Engine	Arrival: 04/27/2022 11:51		EMS Other	
	Clear: 04/27/2022 12:04			
Personnel ID	Name	Rank Ro	ole Attend	Actions Taken
ID: ES	Dispatch: 04/27/2022 11:37	√ Sent 4	▽ Suppression	81-Incident command

	L		<u></u>		<u> </u>
Type: 11-Engine	Arrival: 04/27/2022 11:42			Other	11-Extinguishment by fire service personnel
	Clear: 04/27/2022 12:57				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
FDDMC	Crossen, David	Lieutenant		N.	Ц
FDJAS2	Schutz, Joseph			TS .	
FDBRS	Suter, Brian	Firefighter		Ja	Ц
FDBLS	Schultz, Brittany	Firefighter		je	Ц
	I II I		1 1		1 1
ID: E8	Dispatch: 04/27/2022 11:37	▽ Sent	4	Suppression EMS	51-Ventilate
Type: 11-Engine	Arrival: 04/27/2022 11:45			Other	
	Clear: 04/27/2022 12:07				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
FDJDA	Ahn, James	Lieutenant	~	्र	
FDDJB2	Belovarac, Daniel	Apparatus Engineer		**	
FDTMD	Donkle, Troy	Firefighter		T ^e	Ц
FDRS	Scott, Richard	Firefighter		M	Ц
1 1	1 11 1		1 1	-	1
ID: F71	Dispatch: 04/27/2022 12:18	Sent	0	Suppression EMS	86-Investigate
Type: 92-Chief officer car	Arrival: 04/27/2022 12:18			V Other	
	Clear: 04/27/2022 12:50				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
ID: L6	Dispatch: 04/27/2022 11:37	▽ Sent	4	□ Suppression	21-Search
	<u> </u>	Jenc Senc	4	Suppression EMS Other	21-3ed CI
Type: 12-Truck or aerial	Arrival: 04/27/2022 11:46			Other	
	Clear: 04/27/2022 12:33				
Personnel ID	Name	Rank ,	Role	Attend .	Actions Taken
FDCMC	Christenson, Cole	Firefighter		1 1	
FDEJM	Mills, Eric	Lieutenant	*	্ৰ	Ц
FDWRB	Boone, William	Firefighter	~~~	N	<u> </u>
FDLDM	Moen, Larry	FireFighter	-	<u> </u>	
ID: L8	Dispatch: 04/27/2022 11:37	▽ Sent	4	▽ Suppression	51-Ventilate
		W Selic	<u> </u>	EMS Other	31-ventuate
Type: 12-Truck or aerial	Arrival: 04/27/2022 11:46			; Other	
	Clear: 04/27/2022 12:41				
Personnel ID	Name	Rank	Role	Attend	Actions Taken
FDETF	Fredrickson, Eric	Apparatus Engineer		e e	
FDCJH	Hesseling, Cory	Firefighter		<u> </u>	
FDMRO	O'Connell, Michael	Firefighter		ja:	
FDRKS	Stebnitz, Ryan	Lieutenant		Ţ.	
r					•

Type: 76-ALS unit	Arrival: 04/27/2022 11:55 Clear: 04/27/2022 12:24		C Other	92-Standby
Personnel ID	Name	Rank Role	Attend	Actions Taken
FDLLB2	Buggs, Leon JR	Firefighter	Г	Ц
FDMVS	Schabert, Matthew	Firefighter paramedic	jar .	
ID: M5 Type: 76-ALS unit	Dispatch: 04/27/2022 11:37 Arrival: 04/27/2022 11:42 Clear: 04/27/2022 12:11	▼ Sent 2	Suppression EMS Other	11-Extinguishment by fire service personnel
Personnel ID	Name	Rank Role	Attend	Actions Taken
FDBCP	Powell, Bryce	FireFighter Paramedic	in .	
FDAMF	Feys, Alexandra	Firefighter Paramedic	Ţ-	Ц

NFIRS-1S Supplemental

A								
	13010	W	04	27	2022	Station #5 (05)	22-155544	0
	FDID	State	Month	Day	Year	Station	Number	Exposure

Primary Narrative:

E5 on scene to dispatched address. One story wood frame construction. Dark grey smoke visible from approach B, C and D divisions. E5 command called for an additional engine and ambulance.

Assigned E14 water supply. 360 completed and fire attack initiated "A" division 200' 1 3/4". C division four seasoned porch noted. Assigned first in ladder ventilation. Assigned M5 backup line off of E5 300' 1 3/4".

Neighbor stated that home is thought to be unoccupied. Same neighbor handed me a slip of paper with the back door code to gain access to home. Code was not used and forcible entry to front door storm door and main door accomplished with irons.

On entry dark smoke banked to the floor. Left hand hose advancement first floor. No fire located on stretch to the basement. Fire located in basement behind stairs B C corner. Horizontal ventilation assigned and accomplished. Fire under control and knocked down.

Overhaul operations performed and additional hot spots extinguished. Scene ventilated and monitored. Scene left to FIT. E5 returned.

approximately 12 steps to the back of preceding firefighter during hose advancement for fire attack.

A completed 04/27/22. -Crossen

Additional Narrative (#1 of 5):

E14 - ECKER

E5 arrived assumed command, self-assigned to interior fire attack. E14 arrived on scene. Assigned by IC to water supply. Laid LDH into E5. E5 assigned 1st in ladder (Ladder 8) to ventilation.

E14 assumed Incident Command. As Command assigned remainder of E14 crew to backup line and to assist with attack line deployment.

E8 arrived , requested staging location. Assigned to hydrant W of incident location.

Ladder 6 arrived. Assigned L6 to S&R.

L8 requested permission to initiate vertical ventilation. Request denied pending location of fire.

E5 advised fire appeared to be in basement via radio.

C31 arrived on location and assumed incident command.

E14 reformed at front door on backup line.

Performed 360. Noted smoke stained cracked basement window on B-division in BC corner. Advised command and E5 of findings via radio.

Post extinguishment, E14 assisted with breakdown of hose.

E14 returned.

Additional Narrative (#2 of 5):

L6 dispatched to the incident address for report of a structure fire.

Upon arrival, L6 was assigned to search by Command.

Primary search of the 1st and 2nd floor were completed, locating only 1 feline who had perished and was removed from the structure and given to its owners.

Once the primary search of the structure had been completed with an all clear and Command notified, L6 assisted E5 in the overhaul and extinguishment of the fire area in the B/C Division corner of the basement level.

Once overhaul was completed, L6 made contact with command who cleared L6 from the incident.

L6 returned.

Lt Mills

Additional Narrative (#3 of 5):

Lt McDonald was added to this report due to . E11 was FIT during this fire. Lt Vogen was Lt of E11 at the time. Lt McDonald came in for the second half of the shift.

. Lt McDonald was added to call in order to complete associated

McDonald was not active on this call during incident. See ePCR. Other paperwork was completed and filed.

Per FF, during fire investigation at Dean Ave FF Smith was climbing through a lot of debris and garbage bags in the basement.

Lt McDonald

Additional Narrative (#4 of 5):

Incident # 22-155544 04/27/2022 Alarm Time 11:36 AM 311 E Dean Ave Madison, WI 53703

INCIDENT SYNOPSIS:

On April 27, 2022 MFD units responded to a structure fire at the above address. Engine 5 arrived on scene and reported smoke showing on arrival. Engine 5 went to fire attack. Ladder companies 6 and 8 performed search and rescue and ventilation operations. Fire was found in the basement and extinguished. Crews performed overhaul and damage was contained to the basement.

A total of 4 Engines, 2 Ladder Trucks, 2 Medic Units, and 1 Command Car, responded for the Suppression of this fire totaling 30 Madison Fire Department personnel under the command of Division Chief Stedman Che. Additionally, the Fire Investigation Team (FIT) responded with Fire investigators utilizing E11 and Car 80 and 2 Occupation Services Unit (OSU) members Responded to assist displaced residents.

MFD FIT (C-Shift) responded to the scene per the request of Incident Commander, Division Chief Stedman Che to conduct an origin and cause fire investigation.

During the course of this investigation, one interviews was performed by FF Doug Johnson along with a fire scene exam performed by AE Santana & FF Smith Shannon to include 63 photographs which were added to the electronic case file. No evidentiary items were collected as a result of this fire.

Damages as a result of this fire are estimated at \$50,000.

After the initial investigation was complete, control and authority of the property was turned over to owner OLIVIA MARCELLINO and ANDREW MARCELLINO, on April 27, 2022 at approximately 1600 hours.

WITNESS STATEMENTS:

See FF Doug Johnson's report for statements

BUILDING CONSTRUCTION:

The fire involved structure is located at 311 E Dean Ave in Madison WI. The structure is a one story single family home approximately 1,152 sq. ft. Built in 1953 valued at \$289,000. It is a 3 bedroom 1 full bathroom and half bathroom. The addressed side of the structure face Dean Ave with the original two car detached garage.

The structure involved is a wood frame construction house, zoned for residential use and built with lightweight wood framing on a concrete foundation. The roof was covered with asphalt shingles. The home had three points of entry through the front door and two on the C side. Sliding Deck door on the C side and one regular door. Engine 5 forced entry on storm door and main house front door. Because there was no one home. Engine 5 pulled the 200 pre-connect line for fire attack.

UTILITIES:

Electric Service – Electrical Service to the structure was located on the Charlie Division of the structure.

AE Santana visually examined and photographed the service panel and circuit breakers for 311 E Dean. Gas Service – The gas meter was mounted on the Charlie Division of the structure.

MGE had been dispatched to the incident scene and secured all utilities for the structure.

EXTERIOR SCENE EXAM:

Investigators approach the one-story ranch structure addressed at 311 East Dean Avenue conducted a 360° walk around exterior. Investigators observed no exterior visual signs of heat or fire damage. There was damage to siding above the B-side basement rear window from smoke damage.

INTERIOR SCENE EXAM:

Entering 311 E. Dean Avenue, investigators walked in the front door into living room area there was no visible smoke, heat or fire damage. Walking past living room to dining room area led to kitchen area where there was some smoke damage. In the kitchen was a door that led to the basement stairs. There was smoke damage in the basement stairway. In the basement there was some smoke and heat damage to game room in basement. In the office room there was smoke, heat and fire damage and in the storage room there was heavy smoke, heat and fire damage. Some of the wall 2 x 4 and floor trusses had severe burn damage. In the laundry room there was smoke heat and fire damage to water heater, PVC drain pipes and PVC water lines from heat and fire. Several breakers were tripped which according to the labels correspond to the area of fire. See photo file for reference.

ROOM/AREA OF ORIGIN:

The storage room on the B and C side of the basement had the most damaged from the fire, heat and smoke. The window in that room had a crack. Possibly from heat. It was noticed from a firefighter doing a 360 around house before windows where broken for ventilation. According to one of the firefighters from engine 14. The floor Joist in the storage room where heavily damaged by the fire. The Wall between the office and the storage room was heavy damage. The top portion of the 2x4 was damaged by the fire. A lot of the plastic containers or plastic fixtures were melted by the heat and fire in the storage room. Some of the drywall was pulled down by the fire fighters to do overhaul. The Floor Joyce had little damage if any because they were protected by the insulation and the drywall when exposed.

See photo file for room/area origin documentation

FIRE CAUSE HYPOTHESIS

Hypothesis 1: Investigators

Santana and Smith notice a fire pattern in the office basement room. The location is where The baby chicks had been housed in a cardboard box. A heat lamp was used to keep them warm. The walls that touched the cardboard box showed a fire pattern on one side and on the other side showed fire damage from the floor to the ceiling. No other area in that room had that type of damage. The owners gave information about how they kept the chicks warm and the location. Owners said in there interview they used a heat lamp to keep chicks warn in a cardboard box. Because of the location of the dead chickens. We determined that what they were telling us was consistent to what we found.

FIRE CAUSE CLASSIFICATION:

Based on the information and evidence available to investigators at this time, to include witness interviews and statements, collection of data, fire dynamics, fire behavior and the examination of the fire scene by MFD fire investigators, it is the opinion of investigators based on a reasonable degree of fire investigative certainty, that this fire resulted due to chicken heat lamp falling or touching something to start the fire. Investigators found evidence of charring to the 2 walls that touched the cardboard box that held the chicks. Furthermore, the fire patterns supported this area, as the area of origin.

Fire Investigator David Santana –FIT Madison Fire Department Fire Investigation Division

Additional Narrative (#5 of 5): WITNESS INTERVIEWS INCIDENT # 22155544 311 E DEAN AVE MADISON, WI 53716 INTERVIEWER: FIRE INV. GUY JOHNSON WITNESSES: OLIVIA MARCELLINO, ANDREW MARCELLINO, AMBER JIRSCHELE, ADAM HANEK, JACOB WELLS OLIVIA MARCELLINO (HOMEOWNER), ANDREW MARCELLINO (HOMEOWNER) , 311 E Dean Ave Madison, WI 53716 , 311 E Dean Ave Madison, WI 53716 (OLIVIA MARCELLINO) Į, (ANDREW MARCELLINO) And their many stated that she, Mr. Marcellino, and their many stated that she meighbor, Amber Jirschele, called her cell phone at 11:39am on the day of the incident to tell her that there was smoke coming from the exterior of their home. Mrs. Marcellino said that she and were given a ride were given a ride were given a ride. back home by a coworker at Rehab Path named Robb Schuler. Mr. Marcellino stated that he took his personal vehicle (RAV-4) and left just before his wife to head back to the home. Mr. Marcellino said that he arrived home at approximately 11:45am and saw grayish smoke coming from the front door and chimney. Mrs. Marcellino says that she arrived home at approximately 12:10pm and saw gray lazy smoke coming from the home. Mr. Marcellino then stated that he thought he know what started the fire. He stated they had six 3-week old baby chickens in the Bravo, Charlie (B, C) corner of the basement. He said they were being kept in a cardboard brooder with wood shavings in the bottom. He also stated that that a heat lamp, that was used to keep the chicks warm, was zip-tied to a level directly above the brooder and that it was always on. In addition to the statements above regarding the incident, Mr. and Mrs. Marcellino answered general questions regarding the home: Mrs. Marcellino stated that she had not made contact with her insurance company at the time of our interview. She stated that she had a mortgage on the home through Fairway Independent Mortgage, with an escrow payment of approximately \$1,400 and that she was current with the payments. She stated that they moved into the home in November of 2018, installed new flooring in December of 2021 and took down a wall in January of 2022. She stated the only electrical issues in the home were the kitchen appliances that would overload the outlet and trip the circuit breakers at times. She stated that they did not have candles or incense in the home. She also stated that no one in the home smoked or vaped. She stated that they owned a grill that is located on the back deck and it was not in use the time of the incident. She stated there were no oily rags in the house. She stated there was a dehumidifier in the basement but was not running or plugged in. Mr. Marcellino said there was a space heater in the basement, in the same area as the chicken brooder, that was purchased new 5 years ago that was plugged in but not running. Mr. Marcellino stated there were two power strips in the basement area near the chicken brooder. He said the heating lamp was plugged into one strip and the computer was plugged into a different strip. , 309 E Dean Ave, Madison, WI 53716 AMBER JIRSCHELE (NEIGHBOR), Ms. Jirschele stated that she was in her bathroom when she heard loud knocking on her neighbor's doors. She came outside of her back door and saw gray smoke coming from a vent near the roof of Mr. and Mrs. Marcellino's home. Next, she noticed a woman on a phone inside a dark SUV in the street. She said that the woman pulled into her, Ms. Jirschele's, driveway. Ms. Jirschele described the woman as older, white, with dark hair. Ms. Jirschele then called Mrs. Marcellino at 11:39am. She then got her cat carrier because she knew the Marcellinos had a cat that may be rescued. She saw Andrew Marcellino arrive between 11:39am and 12:03pm. She then went back inside her home. ADAM HANEK, (WITNESS) 612 ACKER PKWY, DEFOREST, WI 53532 Mr. Hanek is employed with the Madison Forestry Dept. and was working in the area at the time of the incident. He stated that he drove by the address where the fire occurred and saw smoke. He thought maybe someone was burning in the backyard. He then went up to the house to investigate further. He and his coworker Jacob Wells went around the house knocking on windows and doors. Adam then opened a window on the back side of the house and saw the first floor was full of

JACOB WELLS, (WITNESS) , 510 WALKER ST, MAZOMANIE, WI 53560 Mr. Wells is employed the Madison Forestry Dept., and stated that a woman in a silver SUV, who appeared to be in her early 40's with dark hair, drove by them and reported smoke coming from a house. He and Mr. Hanek went to the address and started to bang on windows and doors to see if someone was home. They then went to the back of the house. They opened a back window and could hear a crackling sound in the basement. Mr. Wells then encountered the neighbor, Ms. Jirschele, and that's when he started to hear sirens coming.

smoke. They then told a woman in an SUV to call 911.















