

Sound Management Plan for 610 Junction Road

- Foam sheets have been installed on the exposed decking of the ceiling to minimize sounds impacts.
- The acting restaurant manager will be responsible for monitoring internal and external sound levels.
- The acting restaurant manager and/or property owner may explore installing additional soundproofing measures such as, but not limited to, spray insulation.
- The acting restaurant manager will be responsible for ensuring all exterior doors and any operable windows remain closed during musical performances.