



6675 C01

EXPANSION JOINT STYLE CHANGE

09/28/2011



6675 CO 2 Repair of Bearing Haunch  
CAPITOL SQUARE NORTH GARAGE

Supported  
Slab

← Bearing  
Haunch


09/28/2011



6675 C02

Repair of bearing haunch

09/28/2011








CAPITOL SQUARE NORTH COVERED  
GARAGE: ADDL WORK COVERED  
WILLIAMS CONTRACT

09/28/2011





6675 CO 3 STATE ST. CAPITOL GARAGE  
ADDITIONAL DEPTH FOR CONCRETE REPAIR





6675

CO 3 STATE ST CAPITAL GARAGE

CONCRETE REPAIR