







Commonwealth near SW Path	Speeding; safety of people crossing		1	3	3	<b>8</b>												
Engelhart Dr	Speeding; 800 block Baxter Park path connection; sidewalk gap		1	3	3	<b>8</b>												
Gammon at Harvest Hill Rd	Pedestrian crossing improvements		1	6	0	<b>8</b>												
South High Point at Stratton Way	Pedestrian crossing safety		1	6	0	<b>8</b>												
Acewood at Onyx, Vernon Ave & near Kingston Onyx Park	Pedestrian crossing safety; speeding; request for crosswalks; concerns over unaccessible curb ramps esp at midblock crossing		2	3	1	<b>8</b>												
Darbo Dr from Path to Park	Bike Blvd from path to park; ped crossing safety		2	1	3	<b>8</b>												
Fremont Ave - 1800 block	Speeding; no sidewalk		2	3	1	<b>8</b>												
Lakepoint Dr near Hoboken/Weber	Speeding; safety of children going to neighborhood center		2	3	1	<b>8</b>												
Sherman Ave - 2100 block	Speeding		2	1	3	<b>8</b>												
Anhalt/Hollow Ridge Intersection, near Whitetail Ridge Park	Overall safety but esp pedestrians; One of the highest concern "No Control" intersections on HIN		2	3	0	<b>7</b>												
Carpenter Street - E Washington to path	Speeding, partially unimproved street, sidewalk gap on small section of improved section as well as a small gap on Quincy approaching Carpenter		0	6	1	<b>7</b>												Add to Engineering sidewalk gap list; look issues with slopes, trees for solutions

















