Madiana.

Madison Landmarks Commission

APPLICATION

City of Madison Planning Division

215 Martin Luther King Ir. Blvd. J. Room 11, 100 J. P.O. Box 2985. J. Madison, WI 53701-2985.

ZID Martin Lutrier Milght. Divid. 1 Adolin 11.100 1 P.O.	BOX 2383 1 (Wadd35/1) 14133701 2363
1. <u>Location</u>	
Project Address: 1335 Rutledge St	Aldermanic District:
2. PROJECT	Date Submitted: 12-21-12
Project Title / Description: <u>Installation of Rep</u> i	lacement Windows
This is an application for: (check all that apply)	
☐ Alteration / Addition to a Designated Madison Landmark	
☐ Alteration / Addition to a building adjacent to a Designated	Madison Landmark
☐ Alteration / Addition to a building in a Local Historic District	: (specify):
☐ Mansion Hill	☐ First Settlement
☐ New Construction in a Local Historic District (specify):	
☐ Mansion Hill ☐ Third Lake Ridge☐ University Heights☐ ☐ Marquette Bungalow	☐ First Settlement s
□ Demolition	
☐ Variance from the Landmarks Ordinance	
☐ Referral from Common Council, Plan Commission, or other r	referral
☐ Other (specify):	
	Uindrid Wolls of Milworke of M
SENERAL SUBMITTAL REQUIREMENTS	Silve dendling in 4:20 DM on the Sline dead
welve (12) collated paper copies and electronic (.pdf) files of the following: (Note the Application	
Brief nerrative description of the project	Questions? Please contact the
Scaled plan set reduced to 11" x 17" or smaller pages. Please include:	Historic Preservation Planner: Amy Scanlon
Site plan showing all property lines and structures Building elevations, plans and other drawings as needed to illustrate the project	Phone: 608,266.6552
Photos of existing house/building	Email: ascanlon@cityofmadison.com
Contextual information (such as photos) of surrounding properties	L
Any other information that may be helpful in communicating the details of the project	t and how it complies with the Landmarks
Ordinance, including the impacts on existing structures on the site or on nearby prope	erties.

NOTICE REGARDING LOBBYING ORDINANCE: If you are seeking approval of a development that has over 40,000 square feet of non-residential space, or a residential development of over 10 dwelling units, or if you are seeking assistance from the City with a value of \$10,000 (including grants, loans, TIF or similar assistance), then you likely are subject to Madison's lobbying ordinance (Sec. 2.40, MGO). You are required to register and report your lobbying. Please consult the City Clerk's Office for more information. Failure to comply with the lobbying ordinance may result in fines.

Window World of Milwaukee W188 N10707 Maple Rd. Germantown, WI 53022 (262) 703-9500



Window World of Fond du Lac 235 Morris St. Fond du Lac, WI 54935 (920) 923-4189 "Simply the Best for Less
1-800-Next-Window
www.windowworld.com

Window World of Racine 1500 S. Sylvania Ave. Suite 108 Sturtevant, WI 53177-1274 (262) 886-1800

Window World of Madison 2018 S. Stoughton Rd. Madison, WI 53716 (608) 268-9040

Window World Milwaukee LLC, proposing work at 1335 Rutledge street Madison W.I. 53703

Window World prides itself on providing the best product and service in the industry.

The reason for replacing the windows is on request from the property owner to provide windows that will replace windows that are rotting beyond repair. The replacement windows will enhance fuel efficiency, give the owner little to no maintenance, plus maintain the visual integrity and historic aesthetics of the property. The windows would only replace the inner part of the window. The exterior and interior will remain the same minus the storm windows. The exterior of the window frames on the first, second, and third floor would be re-trimmed with aluminum trim coil in white. By doing this it would only provide a layer of protection for the wood underneath, and maintain the maintenance free properties of this home.

The total number of replacement windows to be replaced is 36. None of the basement windows are to be replaced.

The exterior of the home currently has vinyl siding, aluminum trim around the windows, aluminum soffit and fascia, and aluminum on the porch ceiling. The surrounding homes have vinyl replacement windows, vinyl siding, aluminum trim around the windows, and aluminum soffit and fascia.

The following pictures will show the locations of the windows, and also confirm the above paragraph. Also there are pictures of the surrounding homes in the area. I would put an approximate age of the window as original to the home, early 1900's. The condition of the said windows is as follows. Most of the windows are rotting beyond repair, and have water and air infiltration. On the front of the home there is one window that has leaded glass, which would be replaced with a double hung with clear glass. There are also two windows that are on each side of the home that currently have grids that would be replaced with double hung clear glass. One window in the back of the home is a three lite window. This would remain a three lite window, with the same configuration ½ x ½ x ¼, but would operate as a sliding window instead of a casement window.

We feel that the 4000 series window provides the least amount of change to the windows. The glass lines on the 4000 are slim and provide the most light and replicate the sash profile better than the 6000 series which has a much wider sash profile. On the 6000 series frame, the frame is designed with a much bigger sash profile that cuts the glass size down at least an inch all around.

Thank you.

Window World of Milwaukee W188 N10707 Maple Rd. Germantown, WI 53022 (262) 703-9500



Window World of Fond du Lac 235 Morris St. Fond du Lac, WI 54935 (920) 923-4189 "Simply the Best for Less
1-800-Next-Window
www.windowworld.com

Window World of Racine 1500 S. Sylvania Ave. Suite 108 Sturtevant, WI 53177-1274 (262) 886-1800

Window World of Madison 2018 S. Stoughton Rd. Madison, WI 53716 (608) 268-9040

Picture # 1:

This is a side profile of our 4000 series double hung window. This picture shows the thickness of the mainframe and sash. The 4000 series window better replicates the existing windows at the 1335 Rutledge street address. As you can see on the 6000 series pictures, that the 6000 series mainframe and sashes are much more larger, thus shrinking the glass down a significant amount.

Picture # 2:

This is a top profile of our 4000 series double hung window. This picture shows the thickness of the mainframe and sash.

Picture #3:

This is a bottom profile of our 4000 series double hung window. This picture shows the thickness of the mainframe and sash.

Picture # 4:

This is a side profile of our 6000 series double hung window. This picture shows the thickness of the mainframe and sash.

Picture # 5:

This is a top profile of our 6000 series double hung window. This picture shows the thickness of the mainframe and sash.

Picture # 6:

This is a bottom profile of our 6000 series double hung window. This picture shows the thickness of the mainframe and sash.

Picture #7:

This is a picture of the home at 1335 Rutledge Street. This picture shows the front of the home.

Picture #8:

This is a picture of the home at 1335 Rutledge Street. This picture shows the front of the home, and the side of the home.

Picture #9:

This is a picture of the home at 1335 Rutledge Street. This picture shows the side of the home.

Picture #10:

This is a picture of the home at 1335 Rutledge Street. This picture shows the side of the home, and the back of the home.

Picture #11:

This is a picture of the home at 1335 Rutledge Street. This Picture shows the back of the home.

Picture #12:

This is a picture of the home at 1335 Rutledge Street. This picture shows the side of the home.

Picture #13:

This is a picture of the home at 1335 Rutledge Street. This picture shows the side of the home.

As you can see in all of the pictures of the home at 1335 Rutledge street, there is currently vinyl siding on the home, aluminum trim around all of the windows, and aluminum soffit, fascia, and porch ceiling.

Picture #14:

This is a picture of a surrounding home that has had vinyl siding installed and some of the windows were replaced.

Picture #15:

This is a picture of a surrounding home showing that some of the windows were replaced, and some that were not replaced. From the pictures you can see that the ones that were not replaced still have the burgundy wood storm windows.

Picture #16:

This is a picture of a surrounding home that has had vinyl windows installed, exterior aluminum trim around the windows done, and vinyl siding installed.

Picture #17:

This is just a close up of picture #16.

Picture #18:

This is a picture of a surrounding home that had vinyl windows installed, and exterior aluminum trim around the windows done.

Picture #19:

This is just a close up of picture #18.

Picture #20:

This is a picture of a surrounding home that has had vinyl windows installed, and exterior aluminum trim around the windows done.

Picture #21:

This is just a close up of picture #20.

Picture #22:

This is a picture of a surrounding home that has had vinyl windows installed, and exterior aluminum trim around the windows done.

Picture #23:

This is a picture of a surrounding home that has had vinyl windows installed, and exterior aluminum trim around the windows done.

Picture #24:

This is a picture of a surrounding home that has nothing done. Everything looks original.

Picture #25:

This is a picture of a surrounding home that has had vinyl windows installed, exterior aluminum trim around the windows done, and vinyl siding installed.

Picture #26

This is a newspaper clipping of a Historical restoration project that Window World did in Fond du Lac W.I.

Picture #27:

This is a before picture of a Historical restoration project that Window World did in Fond du lac W.I.

Picture #28:

This is an after picture of a Historical restoration project that Window World did in Fond du Lac W.I.

Picture #29:

This is an after picture of a Historical restoration project that Window World did in Fond du Lac W.I.

Picture #30:

This is an after picture of a Historical restoration project that Window World did in Fond du Lac W.I.

(Picture #1) 4000 SERIES DOUBLE HUNG SIDE PROFILE:





(Picture #3) 4000 SERIES DOUBLE HUNG BOTTOM PROFILE:



(Picture #4) 6000 SERIES DOUBLE HUNG SIDE PROFILE:



(Picture #5) 6000 SERIES DOUBLE HUNG TOP PROFILE:



(Picture #6) 6000 SERIES DOUBLE HUNG BOTTOM PROFILE:



(Picture #7) 1335 RUTLEDGE STREET MADISON W.I. 53703:



(Picture #8) 1335 RUTLEDGE STREET MADISON W.I. 53703:



(Picture #9) 1335 RUTLEDGE STREET MADISON W.I. 53703:







(Picture #11) 1335 RUTLEDGE STREET MADISON W.I. 53703:



(Picture #12) 1335 RUTLEDGE STREET MADISON W.I. 53703:



(Picture #13) 1335 RUTLEDGE STREET MADISON W.I. 53703:



(Picture #14) SURROUNDING PROPERTY:





(Picture #16) SURROUNDING PROPERTY:













(Picture #20) SURROUNDING PROPERTY:











(Picture #23) SURROUNDING PROPERTY:



(Picture #24) SURROUNDING PROPERTY:







(Picture #26) FOND DU LAC NEWS PAPER HISTORICAL HOME WINDOW WORLD WORKED ON:



Window World restoration

ilindow Wordd Inc. of Fond du Lic. owned and operated Inc., of these with replacement windows, ultime, guiters, fairly not one of the second o





(Picture #29) AFTER PICTURE OF HISTORICAL HOME IN FOND DU LAC WINDOW WORLD DID WORK ON:



