
2014 LANDSCAPE RESTORATION KNOWN LOCATIONS



1

Indian Springs:

Repair to include replacing existing bridge with new culvert and stabilize drainage channel with seeding and erosion control matting.



Hickory Hollow: Repair to include seeding and matting areas with exposed soil



North Penito Creek Greenway: Repair to include bank stabilization and erosion control measures

