# PREPARED FOR THE LANDMARKS COMMISSION



Application Type: DEMOLITION REPORT

Legistar File ID # 32607

Prepared By: Amy Scanlon, Preservation Planner

# Summary

## 315 N Carroll St

**DESIGNATED LANDMARK**, constructed in 1896.



Google street view

Applicant: Matt Aro, Aro Eberle Architects

Applicant's Comments: This is a technical demolition to relocate the Steensland House, 315 N. Carroll Street, to a new location on the same block.

Staff findings: The current proposal is to relocate the landmark building to a different site on the same block. This is a technical demolition and will result in relocation.

Legistar File ID # 32607 Demolition Report October 1, 2014 Page 2 of 4

#### 1018 Williamson St

Residential building constructed in 1894.



Google street view

Applicant: Jim Glueck, Glueck Architects

Applicant's Comments: House is in poor condition. Foundation is sandstone, in need of major rebuilding/replacement. There are structural issues with the wood frame: bowing of walls, missing beams and nonfunctional basement posts. The interior has been gutted since before the present owner purchased it in 1992. A certificate of appropriateness for demolition was previously granted in the early 1990's. Lot is 24' wide, making it very difficult to build a new building proposed use after demolition is as greenspace.

Staff findings: The preservation file was created for the review of the demolition request in 1993 and does not provide historic information.

Legistar File ID # 32607 Demolition Report October 1, 2014 Page **3** of **4** 

## **5102 Spring Court**

Residential building, date of construction unknown (circa 1920?)



City of Madison photo of storm damage

Applicant: Randy Weisner, City Engineering

Applicant's Comments: The cottage is located in Merrill Springs Park and was damaged by a large-diameter tree that fell onto the house on August 30, 2014, causing extensive damage. The home was vacant at the time of the incident and is uninhabitable as a result of the damage. It will be razed.

Staff findings: A preservation file does not exist for this property.

# 5775 Tokay Blvd

Commercial structure, date of construction unknown (circa 1970?).



Google aerial view

Legistar File ID # 32607 Demolition Report October 1, 2014 Page 4 of 4



Google street view

Applicant: Jim Triatik, Sullivan Design Build

Applicant's Comments: Building is in southeast portion of site . Labeled 5712 Odana.

Staff findings: A preservation file does not exist for this property.