Official	Pro	iect	Name
----------	-----	------	------

Bascom Pl, Bascom St & Chamberlain Ave Recon. Assm't Dist-2015



Project Engineer

LeAnne Hannan

266-4057

Project Limits

Street

Ald. Shiva Bidar-Sielaff

Van Hise to Chamberlalin, Bascom PI to Forest, Allen to Forest

Existing Proposed

Project Type Reconstruction

Last Surfaced 1983, 1989 (Chamberlain)

Pavement Rating 4 (Bascom PI) 5 (Bascom St) 3 (Chamberlain)

Curb Rating 4 (Bascom PI & ST) 3 (Chamberlain)

Width 28 same
Surface Type Asphalt over concrete, asphalt (Chamb.) Asphaltic
Traffic (Average Vehicles per Day) N/A Same

Sidewalk Existing Proposed

Work Required Replace As Necessary

Storm Sewer	Existing	Proposed
Work Required		none
Design Storm		
Size	12"	TBD
Material	RCP	RCP
Year	1920	2015

Rain Gardens Existing Proposed

Work Required construction of rain gardens is a

voluntary program, but there are areas

within the project that could accommodate rain gardens

Same

Sanitary Sewer	Existing	Proposed
Work Required		Complete Replacement
Size	6 Inch (Substandard)	8 Inch
Material	VP	PVC
Year	1922	2015

Water Main	Existing	Proposed
Work Required		Complete Replacement
Size	6"	8"
Material	SACI UL	ductile iron
Year	1899-1923	2015

Parking	Existing	Proposed	
Darking Conditions	Parking one cide	Como	

\$1,133,432

Street Lighting	Existing	Proposed	
Parking Conditions	Parking one side	Same	

Street Lighting On MG&E wood poles

Cost

City Share

Total Cost	\$1,246,500	street \$505K, storm \$161.5K
Adjacent Property Assessments	\$113,068	sanitary \$310K, water \$270K

Assessment Policy

Street Concrete Items Owner 50% / City 50% Sanitary Sewer Lateral Replacements Owner 25% / City 75%

Assessments payable in one lump sum or over a period of 8 years, with 3.5% interest charged on unpaid balance

Rain Gardens, if installed Owner 25% / City 75% All remaining contract items to be paid for by the City of Madison

Schedule

Start Date mid to late April Length of Project 3.5-4 months

Traffic Calming none

Traffic Detours none

Real Estate Requirements Not Required

Tree Information Forestry has identified 19 trees for removal--most are located on the east

side of Bascom PI, above the wall, and are undesirable species in poor condition. Adjacent homeowners have been notified & support removal.

Large oak tree at 2125 Chamberlailn, on Bascom Place, will be

protected during construction.

Correspondence

Charles Anderson 2114 Bascom St- considered about replacement of 10 yr old apron that was replaced with his lead service replacement.

He was told that we might be able save part of the apron,

but the grade changes will likely require complete removal/replacement.

David Wood 2115 Bascom St

He is working with Corey Stelljes to see if his 3 private storm laterals can

be combined into 1 new private storm connection.

Louis Seiter 2125 Chamberlain Ave

Concerned about saving large oak tree on the Bascom PI side of his lot.

He was told that we will protect the tree.