The building needs to be repainted and about 20- 30 % of the masonry joints need to be re-pointed.