Elvehjem Park Master Plan

1202 Painted Post Dr.

City of Madison Parks Division Madison, WI





Board of Park Commissioners January 8, 2020

Prepared by the City of Madison Parks Division

Eric Knepp, Parks Superintendent Kay Rutledge, Assistant Parks Superintendent

Master Plan Staff Team

Sarah Close, Landscape Architect Ann Freiwald, Park Planning and Development Manager

City of Madison Board of Park Commissioners

Emily R. Gnam Moira Harrington Zachary Henak Madelyn D. Leopold Alan J. Martin Paul E. Skidmore Venus D. Washington

Table of Contents

Introduction	p. 1
History	p. 1
Existing Conditions	p. 2
Current Uses and Maintenance Practices	p. 4
Master Plan	p. 4
Exhibits	p. 7
Exhibit 1: Adjacent Parks Map	
Exhibit 2: Painted Posts Estates Plats 1961, 1963, 1965, 1966	
Exhibit 3: Elvehjem Neighborhood Association Land Use Map	
Exhibit 4: Topography Map	
Exhibit 5: Slope Analysis Map	
Exhibit 6: Existing Vegetation Inventory	
Exhibit 7: Community Design Activity	
Exhibit 8: Community Survey Results	
Exhibit 9: Public Input Meeting Presentations	
Exhibit 10: Planning Document Links	
Exhibit 11: Elvehjem Park Master Plan	

INTRODUCTION

Elvehjem Park is a 5.39-acre park located on the east side of Madison at 1202 Painted Post Road. Classified as a neighborhood park, the service area for Elvehjem is 1/2 mile. The nearest developed parks to this location are Droster Park to the southeast, Acewood Park to the southwest, and Heritage Heights Park to the north. In addition, several conservation parks exist within this service area: Acewood Conservation Park to the south, Elvehjem Sanctuary to the west, and Heritage Prairie to the north. All of these parks fall within or near a 1/2-mile radius from Elvehjem Park (see Adjacent Parks Map, Exhibit 1).




Photo: Location of Elvehjem Park

HISTORY

Elvehjem Park has a long history as a crop production field on agricultural property before becoming parkland. The first parcel was dedicated to the City for use as public parkland in the year 1961 as part of the Painted Post Estates development. Additional parcels followed in 1963, 1965, and 1966 (see Exhibit 2). A portion of the land dedicated in 1963 for park and school purposes was eventually divided into separate park and school parcels in 1964 by City Council resolution.



Photo: Elvehjem Park, circa 1955

Elvehjem Park and the surrounding neighborhood are part of the <u>Elvehjem Neighborhood Association</u> (see Exhibit 3).



Photo: Aerial view of Elvehjem Park, circa 2018.

EXISTING CONDITIONS

Elvehjem Park is an existing developed park, consisting of 5.39 acres of mowed turf, wooded edges, and recreational amenities. The parcel features an overall drop in elevation from the north to the south, in a series of steep slopes, and a large, graded playing field, which can be seen on the topography map (see Exhibit 4). Adjacent to Elvehjem Park is Elvehjem Sanctuary, which features steep slopes falling to the west.

A majority of the park area features slopes less than 5% as shown in the Slope Analysis Map (see Exhibit 5). These slopes are primarily located in the area of the existing community gardens, the playing field, and the tennis courts. The steepest slopes (greater than 20%) occur along the edges of the community garden and playing field and where the existing shelter is built into the side of a hill.



Photo: View of the community gardens at Elvehjem Park.

The dominant soil on site is made land. comprising more than 60% of the park property. During the development of the surrounding neighborhood, fill of unknown origin was placed on site and used to rough grade the topography for park amenities. The Natural Resources Conservation Service (NRCS) lacks a uniform description for made land, as the qualities vary greatly depending on the type of fill and construction methods utilized. However, general assumptions about the composition of made land include: the soils lack horizons, feature mixed and disorganized particle sizes, and vary in their compaction or stability. The community gardens area features the other dominant soil type on site, Ringwood silt loam. Typical of moraine landforms, this soil has gentle slopes of 2-6%, excellent drainage, and is considered prime farmland.

Existing trees on the property were evaluated and identified by a consultant, see the Existing Vegetation Inventory (Exhibit 6). This inventory identified a variety of tree species on-site, predominantly located around the park property boundaries and around an existing pea gravel area (which previously contained play equipment; the play equipment was removed as it could no longer be maintained). The most common tree species include *Quercus rubra* (Red Oak), *Ulmus rubra* (Red Elm), *Celtis occidentalis* (Hackberry), and *Acer negundo* (Box Elder).



Photo: Map of public open spaces in the Elvehjem neighborhood.

The public open space that is Elvehjem Park is part of a larger open space area that includes Elvehjem Sanctuary and Elvehjem Elementary School. Together these three properties provide a variety of recreational opportunities. Elvehjem Sanctuary, a City of Madison conservation park, is forested and provides a multitude of natural surface hiking trails. These trails are greatly valued by the surrounding neighborhood; nine of ten community survey respondents rated them as important to very important. During non-school hours, the amenities at Elvehjem Elementary (which are owned by the Madison Metropolitan School District) are available for use by the general public. This includes basketball courts, play equipment, a fully-accessible play structure, a backstop, soccer fields, and various hopscotch/four square courts.

CURRENT USES AND MAINTENANCE PRACTICES

The primary activities currently occurring in Elvehjem Park include the community garden, shelter reservations, pick-up tennis games, and informal (unreserved) field sport practice. The community garden is a popular amenity, featuring 30 rentable plots (as of 2019) and has a waiting list of interested gardeners for 2020. The other amenities (the shelter, field, and tennis courts) have seen declining reservations in the last five years.

Reservations at the shelter have been declining due, in part, to dissatisfaction with the current facility. A number of improvements are being contemplated to address these issues. The lack of offstreet parking seems to be a deterrent to athletic field reservations, though unreserved field sport practice has been observed on several occasions by Parks staff.

The lack of use seen at the tennis courts could be due to a number of factors, such as the growing popularity for tennis tournaments (which require several courts in use at one time), growing popularity for alternative court sports such as pickleball, and the condition of the existing courts. The existing soils on site (classified as made land) provide insufficient support to maintain a satisfactory sport court playing surface, resulting in excessive cracking and higher maintenance requirements. The courts at Elvehjem Park were not identified as an important amenity during the public engagement process.

Current maintenance practices in the park include turf management, such as mowing and patching, and routine shelter upkeep and cleaning. This property will be maintained in accordance with the <u>City of Madison Adopted Land Management Plan</u>.

MASTER PLAN

The master plan process included two public input meetings, a pop-up booth, and a community survey, which is consistent with the adopted <u>Park Master Plan Policy</u>.

Public Input Process

The first public input meeting was held on June 19, 2019. The public input meeting provided history, background, and context for the site and elicited neighborhood input on the park and potential amenities. The results of the community design activity from this meeting can be seen in Exhibit 7. To gather additional feedback, a community survey was created to gauge the desire for specific amenities that are typically offered within neighborhood parks while also identifying seasonal usage patterns and

demographic information. This survey was mailed to approximately 898 addresses within 1/2 mile of the park and made available online. The results of the survey were then compiled; these results can be seen in Exhibit 8. A pop-up booth was hosted in Elvehjem Park on August 6, 2019, to complement the Neighborhood Association's National Night Out event and gather in-person feedback from park users. Staff present provided information regarding the master planning process and gathered input.

After analyzing the input received at the first public input meeting, the pop-up booth event, and through the community survey, two master plan design concepts were created. These master plans were provided for the community to review and comment on at the second input meeting, held on October 3, 2019. The majority of the public input meeting participants expressed a preference for the final proposed master plan for Elvehjem Park. The presentations provided at all public input meetings can be seen in Exhibit 9.

Proposed Park Amenities

The proposed park master plan takes into consideration the usage patterns, existing park amenities, and public input received by Parks staff. The top desired amenities identified through the master planning process included a nature play area, open space for active/passive recreation, a shelter, and community garden space. The proposed amenities include one additional recreational amenity for a neighborhood park that was not identified in Table 4.2 Typical Park Facilities by Park Classification (2018-2023 Park and Open Space Plan, see Exhibit 10), as it is a newly emerging recreation trend. A bicycle playground and potential pump track are proposed for the southern portion of the park. Parks Division staff continue to research and analyze this innovative recreational facility due to the neighborhood's interest.

All of the proposed amenities included in the master plan are shown on Exhibit 11 and include the following:

Natural Play Area

A play area, containing natural elements such as logs and boulders, is proposed near the existing shelter and in the area of the existing baseball/softball backstop (the backstop will be removed prior to play area construction). As seen in the community survey, a strong majority of respondents rated play equipment as an important or very important amenity for Elvehjem Park.

Bicycle Playground/Pump Track

The master plan includes an area at the southern edge of the park for a bicycle playground and a potential pump track. This would partially encompass the existing tennis court area. The tennis courts may either be removed or repurposed for the pump track feature, and the bicycle playground potentially located on the lawn area to the east of the tennis courts. The idea of a bicycle playground or pump track facility received many positive comments via email, at the second public input meeting, and in the community survey.

Informal Seating Area with Additional Park Entry Sidewalk

To increase access to the park and to the bicycle playground/pump track area, the master plan includes a path on the southern edge of the park (this would require permission from the Madison

Metropolitan School District). The path leads to an informal seating area adjacent to the bike playground/pump track area, providing a location to gather or supervise the activity.

Reservable Shelter

Four out of five community survey respondents rated the presence of a shelter in the park as important or very important. As discussed previously in this report, the Parks Division is considering a series of improvements to the existing shelter.

Open Space for Active/Passive Recreation

The master plan seeks to preserve the existing open space in Elvehjem Park. Seventy percent of community survey respondents rated open space as important or very important to include in the master plan, and twenty-nine percent felt the existing open space is the best aspect of the park.

Community Garden

The master plan includes a proposed expansion of the community garden area. The current number of plots have all been rented for the 2019 season and garden coordinators have requested an increase to accommodate demand. Approximately two thirds of community survey respondents rated the gardens as an important or very important amenity to include in the master plan update. Amending the City's Lease Agreement with Community Groundworks to expand the garden would be the next step in the process.

Exhibits

Exhibit 1: Adjacent Parks Map

Exhibit 2: Painted Posts Estates Plats, 1961, 1963, 1965, 1966

Exhibit 3: Elvehjem Neighborhood Association Land Use Map

Exhibit 4: Topography Map

Exhibit 5: Slope Analysis Map

Exhibit 6: Existing Vegetation Inventory

Exhibit 7: Community Design Activity

Exhibit 8: Community Survey Results

Exhibit 9: Public Input Meeting Presentations

Exhibit 10: Planning Document Links

Exhibit 11: Elvehjem Park Master Plan





Exhibit 1: Adjacent Parks Map


Legend

City of Madison Parks



Ownership Parcels





FIRST ADDITION TO PAINTED POST ESTATES

BEING A SUBDIVISION OF A PART OF THE SOUTHEAST ONE QUARTER OF SECTION 10,

TOWN 7 NORTH,

CITY OF MADISON,

DANE COUNTY,

RANGE IO EAST

WISCONSIN

			BLOC	K CURVE	DATA	
CURVE	RADIUS	ARC	CHORD	CHORD BEARING	CENTRAL ANGLE	DEFLECTION
1-2	561.75	326.20	321.63	N 73°-02'-6.5" W	33°-16'-11"	16°-38'-5.5*
2-3	561,75	336.79	331.76	N 39°-13'-30.5'W	34°-21'-01"	17°-10'-30.5"
1-3	561.75	662.99	625.16	N 55°-51'-36"W	67° 37'-12"	33°-48'-36"
4-5	241.21	140.06	138.10	N 16°-57'-53.5"E	33°-16'-11"	16°-38'-5.5"
6-7	260.56	106.18	105.44	N 11°-20'-37" W	23°-20'-50"	11°-40'-25"
8-9	290.56	106.25	105.66	N10°-08'-45" W	20°-57'-06"	10°-28'-33"
9 - 10	14.95	23.48	21.14	\$44°-40'-12"E	90°~00'-00"	45°-00'-00"
11-12	591.75	356.33	350,97	N 7 2°-25'-10" W	34°-30'-04"	17°-15'-02"
12-13	591.75	15.00'	15.00'	N 54°-26'-34"W	1°-27'-08"	0°-43'-34"
13-14	591.75	327.06	322.91	N 37°-53'-00" W	31°-40'-00"	15°-50'-00"
15-16	531,75	74.25	74.19	N 26°-03'-00" W	8°-00'-00"	4°-00'-00"
15-17	531.75	272.67	269.68	N 36°-44'-22*W	29°-22'-44"	14°-41'-22"
16-17	531.75	198.42	197.26	N 40°-44'-22"W	21°-22'-44"	10°-41'-22*
17-18	15.005	24.65	21.97	\$80°-39-04"W	94°-06'-10"	47°-03'-05"
19-20	211.21	122.64	120.93	N 16°-57'-53.5"E	33°-16'-11"	16°-38'-5.5"
21-22	271.21	157.49	155.28	N 16°-57'-53.5"E	33°-16'-11"	16°-38'-5.5"
23-24	15.005	24.65	21.97	N 13°-27'-06" W	94°-06'-10"	47°-03'-05"
24-25	531.75	262.64	259.97	N 75°-31'-15" W	28°-17'-54"	14°-08'-57"
26-27	15.00	23.51	21.18	N 45°-14'-05"E	89°-48'-34"	44°-54'-17"
27-28	230.56	106.16	105.22	N12°-51'-36"W	26°-22'-48"	13°-11'-24"
28-29	230.56	64.39	64.18	S34°-03'-00"E	16°-00'-00"	8°-00'-00"
27-29	230.56	170.55	166.68	N20°-51'-36" W	42°-22'-48"	21°-11'-24"
11-14	591.75	698.38	658.55	N 55°-51'-36"W	67°-37'-12"	33°-48'-36"

LOT CURVE DATA CENTRAL CHORD DEFLECTION LOT BLOCK RADIUS ARC CHORD BEARING ANGLE ANGLE 531.75 63.84 63.80 N 64°-48'-40"W 6°-52'-44" 3°-26'-22" 2 531.75 78.89 78.81 N 72°-30'-02" W 8°-30'-00" 4°-15-00" 531.75 78.89 3 78.81 N 81°-00'-02" W 8°-30'-00' 4°- 15'-00" 4 531.75 41.01 41.01 N 87°-27-37 W 4°-25'-10' 2°-12'-35 271.21 95.95 95.45 S 23°-27'-53.5"W 20°-16'-11 10-08-05.5 271.21 61.54 7 13°-00'-00' 61.40 | S 6°-49'-48" W | 6°-30'-00" 8 3 211.21 20.28 20.27 | S 3°-04'-48" W 5°-30'-00' 2°-45'-00" 8 211,21 S 19°-42'-53.5 W 102.37 101,37 27°-46'-11" 13°-53'-055' 96.19 N 46°-14'-22" W 8 531.75 96.33 10°-22'-44' 5°-11'-22" 8 531.75 102.09 101.93 N 35°-33'-00" W 2 11°-00'-00' 5°-- 30'- 00" 4 591.75 12.06 12.06 N 89°-05'-10" W 1°-10'-04" 0°-35'-02" 4 9 591.75 68.86 68.81 N 85°-10'-08"W 6°-40'-00" 3°-20'-00" 10 4 591.75 68.86 68.81 N 78°-30'-08"W 6°-40'-00' 3°-20'-00' 591.75 68.86 11 68.81 N 71°-50'-08"W 6°-40'-00" 3°-20'-00" 4 12 591.75 68.81 N 65°-10'-08"W 68.86 6°~40'-00' 3°-20'-00" 4 591.75 68.86 13 68.81 N 58°-30'-08'W 6°-40'-00" 3°-20'-00" 65.38 N 50°-33-00'W 591.75 65.41 6°-20'-00" 3°-10'-00" 591.75 65.41 65.38 N 44°-13'-00"W 6°- 20'-00' 3°-10'-00" 3 591.75 65.41 65.38 N 37°-53'-00"W 6°-20-00 3°- 10'~00" 9 4 591.75 65.41 65.38 N 31°-33-00"W 6°-20'-00" 3°-10'-00" 5 591.75 65.41 65.38 N 25°-13-00"W 6°-20'-00" -3°-- 10'- 00"



VO SURVY

SURVEYOR'S CERTIFICATE

STATE OF WISCONSIN) DANE COUNTY) SS

I, HARRY M. BRIDWELL, REGISTERED LAND SURVEYOR, BEING FIRST DULY SWORN, ON OATH HEREBY DEPOSE AND SAY:

THAT I HAVE SURVEYED, DIVIDED AND MAPPED "FIRST ADDITION TO PAINTED POST ESTATES" BEING A SUBDIVISION OF A PART OF THE SE 1/4 AND SW 1/4 OF THE SE 1/4; SECTION 10, T7N, RIOE, CITY OF MADISON, DANE COUNTY, WISCONSIN, WHICH IS BOUND AND DESCRIBED AS FOLLOWS:

COMMENCING AT THE SOUTHEAST CORNER OF SECTION 10, T7N, R1OE; THENCE S \$9°-58'-02"W, 330.00 FEET ALONG THE SOUTH LINE OF SAID SECTION; THENCE NO⁸-19'-48"E, 484.90 FEET TO THE POINT OF BEGINNING OF THIS DESCRIPTION; THENCE CONTINUING NO⁶-19'-48"E, 527.09 FEET; THENCE N89°-40'-12"W, 524.75 FEET; THENCE SO⁶-19'-48"W, 35.28 FEET; THENCE N89°-40'-12" W, 435.99 FEET; THENCE S59°-57'W, 100.00 FEET; THENCE ALONG THE ARC OF A CURVE TO THE RIGHT RADIUS 531.75 FEET, CHORD BEARING N26°-03'W, 74.19 FEET; THENCE S67°-57'W, 190.00 FEET; THENCE N21°-10'-48"W, 162.75 FEET; THENCE S0°-33'-41"W, 589.65'; THENCE N89°-57'E, 559.75 FEET; THENCE S84°-31'-53"E, 207.96 FEET; THENCE N69°-22'-42"E, 48.53 FEET; THENCE N89°-02'-33" E, 64.82 FEET; THENCE ALONG THE ARC OF A CURVE TO THE LEFT RADIUS 230.56', CHORD BEARING S34°-03'E; 64.18 FEET; THENCE N42°-50'-35"E, 67.26 FEET; THENCE N89°-57'E 359.05 FEET TO THE POINT OF BEGINNING.

THAT I HAVE MADE SUCH SURVEY, LAND DIVISION AND PLAT BY THE DIRECTION OF LOM, INC., OWNER OF SAID LAND.

THAT SUCH PLAT IS A CORRECT REPRESENTATION OF ALL THE EXTERIOR BOUNDARIES OF THE LAND SURVEYED AND THE LAND DIVISION THEREOF MADE.

THAT I HAVE FULLY COMPLIED WITH THE PROVISIONS OF CHAPTER 236 OF THE WISCONSIN STATUTES AND THE SUBDIVISION REGULATION OF THE CITY OF MADISON IN SURVEYING, DIVIDING AND MAPPING THE SAME.

Bridwell m HARRY M. BRIDWELL, REGISTERED LAND SURVEYOR NO. **5-**516

CORPORATE OWNER'S CERTIFICATE OF DEDICATION

LOM, INC., A CORPORATION DULY ORGANIZED AND EXISTING UNDER AND BY VIRTUE OF THE LAWS OF THE STATE OF WISCONSIN, AS OWNER, DOES HEREBY CERTIFY THAT SAID CORPORATION CAUSED THE LAND DESCRIBED ON THE PLAT TO BE SURVEYED, DIVIDED, MAPPED AND DEDICATED AS REPRE-SENTED ON THIS PLAT.

LOM, INC., AS OWNER, DOES FURTHER CERTIFY THAT THIS PLAT IS REQUIRED BY S. 236.10 OR S.236.12 TO BE SUBMITTED TO THE FOLLOWING FOR APPROVAL OR OBJECTION:

(L) THE DIRECTOR, PLANNING DIVISION, DEPARTMENT OF RESOURCE DEVELOPMENT

(2) COMMON COUNCIL OF THE CITY OF MADISON

IN WITNESS WHEREOF, THE SAID LOM, INC., HAS CAUSED THESE PRESENTS TO BE SIGNED BY WILLIAM A. OUWENEEL, ITS PRESIDENT AND COUNTERSIGNED BY PATRICK J. LUCEY ITS SECRETARY-TREASURER AT MADISON, WISCONSIN, AND ITS CORPORATION SEAL TO BE HEREUNTO AFFIXED THIS 77 DAY OF Sectember, 1961.

IN THE PRESENCE OF: LOM INCORPORATED Millouse mo VITNESS TRICK J. AUCEY, SECY TREAS. STATE OF WISCONSIN SS DANE COUNTY

PERSONALLY CAME BEFORE ME THIS 27 DAY OF September 1961, WILLIAM A. OUWENEEL,

CERTIFICATE OF CITY TREASURER

STATE OF WISCONSIN SS DANE COUNTY

I, WALTER G. HUNTER, BEING DULY APPOINTED, QUALIFIED AND ACTING CITY TREASURER OF THE CITY OF MADISON DO HEREBY CERTIFY THAT IN ACCORDANCE WITH THE RECORDS IN MY OFFICE THERE ARE NO UNPAID TAXES OR UNPAID SPECIAL ASSESSMENTS AS OF OCT 3190N ANY OF THE LANDS INCLUDED IN THE PLAT OF "FIRST ADDITION TO PAINTED POST ESTATES."

CITY OF MADISON TREASURER,

034172

VoL

 \sim

رب ا

 Σ

\$ II

 $\frac{1}{\omega}$

4 1 1

CERTIFICATE OF COUNTY TREASURER

STATE OF WISCONSIN) SS

I, WALTER N. SMITHBACK, BEING THE DULY ELECTED, QUALIFUE AND ACTING TREASURER OF THE COUNTY OF DANE DO HEREBY CERTIFY THAT THE RECORDS IN MY OFFICE SHOW NO UNREDEEMED TAX SALES AND NO UNPAID TAXES OR SPECIAL ASSESSMENTS AS OF OCT. 2 /961 AFFECTING THE LANDS INCLUDED IN THE PLAT OF "FIRST ADDITION TO PAINTED ROST ESTATES."

Oct. 2, 1961 DATE

Walter h. mithback WALFER N. SMITHBACK, TREASURER, DANE COUNTY, WISCONSIN

COMMON COUNCIL RESOLUTION

RESOLVED, THAT THE PLAT OF "FIRST ADDITION TO PAINTED POST ESTATES", BEING A SUBDIVISION OF A PART OF THE SE 1/4 OF SECTION 10, T7N, RIOE, IN THE CITY OF MADISON, DANE COUNTY, WIS-CONSIN, HAVING BEEN APPROVED BY THE CITY PLANNING COMMISSION BE AND THE SAME IS HEREBY APPROVED ON THIS Job DAY OF October 1961.



AND I DO FURTHER CERTIFY THAT THIS PLAT WAS FOREWARDED AS REQUIRED BY 5.236.12(2) ON THE ______ DAY OF ______, 1961 AND THAT ALL OBJECTIONS TO THE PLAT HAVE BEEN MET.

10-3-61 DATE

Clup train

W. BARIES, CITY CLERK, CITY OF MADISON

CERTIFICATE OF COUNTY REGISTER OF DEEDS

RECEIVED FOR RECORDING THIS 3 DAY OF C., 1961, AT 23 O'CLOCK MAND RECORDED IN VOLUME 25 OF PLATS ON PAGE 22 any 23

and HAROLD K. HILL, DANE COUNTY REGISTER OF DEEDS


PRESIDENT AND PATRICK J. LUCEY SECRETARY OF THE ABOVE NAMED CORPORATION, TO ME KNOWN TO BE THE PERSONS WHO EXECUTED THE FOREGOING INSTRUMENT AND TO ME KNOWN TO BE SUCH PRESIDENT AND SECRETARY OF SAID CORPORATION, AND ACKNOWLEDGED THAT THEY EXECUTED THE FOREGOING IN-STRUMENT AS SUCH OFFICERS AND AS THE DEED OF SAID CORPORATION BY ITS AUTHORITY.

NOTARY PUBLIC. DANE COUNTY. MY COMMISSION EXPIRES Chill & 1962

THIS INSTRUMENT DRAFTED BY HARRY M. BRIDWELL

This FINAL PLAT is hereby CERTIFIED as complying with ss. 236.15, 236.16, 236.20 and 236.21 (1) & (2) Wis. Stats. day of fiftender 196 / Signed this, Kenn How Henry M. Ford / Deputy Director, Division of Planning dy Department of Resource Development

SHEET 2 OF 2







STATE OF WISCONSIN } SS COUNTY OF DAVE } SS	AS TREASURER OF THE CITY OF MADISON, I DO HEREBY CERTIFY THAT THE RECORDS IN MY OFFICE BHOW NO UNDAID TAXES OF UNMID SOFCIAL ASSASSMENTS AS OF SOFT, 13, 1963 ON ANV OF THE LANDS INCLUDED IN THIS PLAT.		STATE OF WISCONSW 35 COUNTY OF DANE 35	AS TREASURER OF THE COUNTY OF DANE, I DO HEREBY CERTIFY THAT THE RECORDS IN MY OFFICE
		hr		

DAT

0 ω)

ELDON

1082805

Z DDIT A 00H ပ ဟ


SE 1/4 & SW 1/4 SEC. 10, T.7 N., R. 10E., CITY OF MADISON, DANE OF THE PART

APRIL 1962

CORRECT BOUNDAR, HE KEN VISIONS TH WITH TH OF THE R OIVIDING 121/E. 236 PLAT 1. Y COMPL 140 CEETLEY THAT THIS SENTATION OF ALL VE LAND SURVEYED AND I HAVE FULLY C SLONS OF CHAPTER VTES IN SURVEYIN VG OF THE SAME.

SNHO Nau Vi 2 P N (1 er surver, er the dire Y THAT SUCH HS MADE BY

KUMON S. HAMEL VERNON S. HAMEL, REGISTERED LAND SURVEVOR AND PROFESSIONAL ENGINE





E WISCONSIN 35 STATE OF COUNTY OF

NT IN

らそ OWNER. NS CAL 140 , CORPC VDER AND B De Wiscon T SAID 9ED 0 INVESTMENT INC., COR EXISTING, UNDER AND THE STATE OF WISC CERTIFY THAT SAID LAND DESCRIBED ON DIVIDED, AND MADDE REPRESENTED ON T

5. 236. 10 00 21. 10 11 11 50 21. 10 11 11 50 21. 11 05 617 21 746 01 65 25 20 12 55 CORPO. FURTHE AUTO ACCEPTANCE CO. INVESTMENT INC., DO FUR; PLAT 15 REQUIRED BY 5. SUBMITTED TO THE FOL OBVECTION: COMMON COUN COUNTY, WISCONSIN, AND DIVISION, DEPARTMENT OF FOL


たいい

ß XAMIN KY-TREASURER A CORPORATE SEAL 26 DAYOF IN WITNESS WHEREOF, SEPRENTION HAS CAUSE GAVED BY EDWARD E. VO COUNTER SIGNED BY ECRETARY-TREASURER VO IT'S CORPORATE SE VO THIS 200 DAY OF 10 IN CORPORN SIGNED AND COU SECRET

PRESENCE T.46 2

maria

dee J.



ACCEPTA

4050

1456557478 70 BE 51, 7 AND COUN 1, AT 111,14 12 TO BE A THE SAID PRESENTS PRESIDENT SECRETARI Ŋ 113 . 20 Par 05 >

₹

INC. , HAREY GY C

SENCE 1N - T- ME

J. 2

1 xonni iy o

SECR KANN SKY BLFSON, D. W. Spincer

E WISCONSIN 35

101 STATE COUNT

50.88 CANE DERSONALLY

R DO 0 3AID , SECRETARY GED THAT THEY IS SUCH OFF ,1962, ECK, 01, 550EF COR VENT AND KNOWLEDG PRESIDENT AND ACKNOW INSTRUMEN SAID CORP. JONS Are D ACCEPT 155.81 11 TES

IONS, PREGOI

THE ORIT

4 U T H

NOTARY P

WAUKEE, WISCONSIN ES 3/16/66

 $\mathbf{Q}^{\mathbf{a}}$

1411 VS

N

0

N

ίų

SHE

ETGI XI BUNILAIS 10 KNO HLH SIHL ORIJILAIDI LATO

ara no ol 6, 236.2

There al 236.16,

Dire

ent of R

Dèpartme

Dire

There are 236.16, 2: Certified t

Rute 29 Zol.

n n

Ø

LEGEND

' IRON PIPE STAKE Pipe Stake, Minimum Weight 11 11

3.65 LBS./ LIN. FOOT MIN. RON Š ึง SET

CORNER S, OTHER LOT NOTE ο

24" IRON PIPE STAKES AT ALL 1,13 LBS. / LIN. FOOT SET 1" X 24" Weight 1,13

EASEMENT 11 →₽+-||

UTILITY E. Minimum

ALL DIMENSIONS ARE TO THE NEAREST ONE HUNDREDTH OF A FOOT


ORDINATE SYSTEM; MENTED WITH A 4"X NG THE FOLLOWING MONUMENTED 00 HAVING PLANE THE WEST 1/4 CORNER OF SECTION 10 HAS BEEN A CONCRETE MONUMENT APPROXIMATELY 30" LONG, STATE NOTE "A" ON THE WISCONSIN BASED CO-ORDINATES

FEET NORTH 395,905.20 East 2,185, 340, 47


THE WISCONSIN Р THE ЧO ALL BEARINGS ARE REFERRED TO GRID NORT

ANG 2.22 2.22 2.22 2.22 2.22 2.22 2.22 2.		RADIUS	L ON		CENTRAL			SUB CH	ORDS
C. Second Calify and		LENGTH	LENGTH	BEARI	SN.	FROM	2	LENGTH	BEARING
B BAD A			62.40			A	Ă	62.17	Z
B SOOOD GS 23 S 265 25 (2) S 265 25						٩ı	A2	42.08	S.C7.12.01 E.
1 1 2						A3	4	42.08	5.32*20 00 W
B SACOO C.3.3 S.W. W. OO 2.7.7.7.7.2.2. B <t< td=""><td>-</td><td></td><td></td><td></td><td></td><td>Å4</td><td>A</td><td>39.22</td><td>5.80° 18' 37"W</td></t<>	-					Å 4	A	39.22	5.80° 18' 37"W
C 3330000 (44, 27) 5,445 (7) (2015 6,16,14,10,30,34 C 330000 (44, 27) 5,445 (7) (2015 2,2130,000 5,151,40,30,34 C 330000 (24, 35, 5,450 (7005)) 2,2130,000 5,151,40,30,34 C 330000 (24, 35, 5,450 (7005)) 2,1130,000 2,114,12 C 330000 (24, 35, 5,20000) 2,1230,000 2,141,12 C 2,1330,000 2,2230,000 2,141,12 2,141,12 C 2,1231,000 2,2230,000 2,141,12 2,143,143 C 2,1231,000 2,1231,000 2,141,12 2,143,143 C 2,1231,000 2,124,000 2,124,000 2,124,000 C 1,132,000 2,124,000 2,124,000 2,124,000 2,124,000 C	+ +	50.00	69	20. 20. 20.	11				
C J320.00 (44.2.1) (3.47.0)'00'' C (2.2.2.30'00') (3.4.1.30'') C J320.00 (44.2.1) (3.47.0)'00'' C (2.2.2.30'') (2.1.1.4.1'') C J320.00 (44.2.1) (3.47.0)'00'' C (2.2.2.30'') (2.1.1.4.1'') C J320.00 (44.2.1) (3.47.0)'00'' C (2.2.2.30'') (2.1.1.4.1') C J320.00'' C J321'' 00'' C J321'' 00'' C (2.2.2.30'') (2.1.1.4.1') C J320.00'' C J321'' 00'' C J321'' 00'' C J321'' 00'' C J321'' 00'' C C J321'' 00'' C J321'' 00'' C J221'' 00'' C J221'' 00'' C J21''' 10''' C J321'' 00'' C J321'' 00'' C J221'' 00'' C J21''' 10''' J21'''' 10'''' C J321'' 00'' C J321'' 00'' C J321'''''''''' J321''''''''''''''''''''''''''''''''''''						Q	ā	35.45	N. 27*42 28 6
C 3243:000 63:45:1						ã õ	<u>ä</u> 8	40.93 38.94	N. 72-40.04 E
C: 330.000 (44.8.2) 5.44°07'00° E 22.2.30 (2.15.16.04) C: 330.000 (44.8.7) 5.44°07'00° E 22.2.30 (2.15.16.04) C: 5.44°07'00° E 22.2.30 (2.15.16.04) (2.15.16.04) C: 5.44°07'00° E 22.2.30 (2.16.14.44, 4.16) (2.16.14.44, 4.16) C: 5.44°07'00° E 22.2.30 (2.16.14.44, 4.16) (2.16.14.44, 4.16) C: 5.44°07'00° E 22.2.30 (2.16.14, 4.16) (2.16.14.44, 4.16) C: 5.44°07'00° E 22.2.30 (2.16.14.45, 4.16) (2.16.14.45, 4.16) C: 5.44°07'00° E 22.2.30 (2.16.14, 4.16) (2.16.14.45) C: 5.44°07'00° E 22.2.30 (2.16.14, 4.16) (2.16.14.45) C: 5.5000° E 10.117 <td< td=""><td></td><td></td><td></td><td></td><td></td><td>0</td><td>ð</td><td>30.24</td><td>S.14*22'42"E</td></td<>						0	ð	30.24	S.14*22'42"E
C 338.00 148.71 3.4870700 E 2.273000 C 1.41.8 C 338.00 148.71 3.4870700 E 2.273000 C 1.41.8 C 200.00 C 1.01.1 1.00.20 C 1.41.8 C 200.00 C 1.01.1 1.01.1 1.01.1 0.01.2 0.01.2 C 200.00 C 1.01.1 1.01.1 1.01.1 0.01.2 0.01.2 C 1.01.1 1.01.1 1.01.1 1.01.1 1.01.1 0.01.2 0.01.						0	ő	47.05	S. 36 3612 W.
C. 320000 (46.2.7) 5.4600700°C 2.7230000 C. <				A CANADA MANAGAMININA MANAGAMININA MANAGAMININA MANAGAMININA MANAGAMININA MANAGAMININA MANAGAMININA MANAGAMININ		2	D	07.23	N C4 20 10 20
0' 3202 000 [24,34,6] 5449'01'00'' [2,7,30'' 00'' [2,7,5,1] 60,43,1 F' 332933 481''0,100'' 2,2,30''00'' 10,10,1 14,43,0 F' 332933 11704 3,227''30''00'' 10,10,1 3,323'' F' 33333 11704 3,227''30''00'' 10,10,1 13,323'' F' 232333 11704 3,227''30''00'' 10,10,1 13,323'' F' 23233 11,17 N.462''30''C 10,10,1 13,32'' F' 13233 N.464''33''SO'' 44'''''''''''''''''''''''''''''''''''	U	360.00	148.27	8	-30.00				
0 323230 244 01 00 222 30 00 0 <th0< th=""> 0 0 <th0< th=""></th0<></th0<>								14.12	5.58 18 06 E
0 300 300 300 243 45 544° 07100 5 27 30 500 10 0.0 <th0.0< th=""> <th0.0< th=""> 0.0</th0.0<></th0.0<>								60.06	S.43"36'23"E
0' 2202-300 E 440'01'00''.E 22''30'00'' D 0 <t< td=""><td>1</td><td></td><td></td><td></td><td></td><td></td><td></td><td>14.86</td><td>S. 37-59'13"E.</td></t<>	1							14.86	S. 37-59'13"E.
F 232333 Control 232333 Control 232333 Control 232333 F 232333 117041 5.25730005 227350000 1 0	Ō	320.00	124	5					
F 1333 33 3.3 23' 23' 03' E 10, 10 0, 10						٥		32,99	N N
F 233333 53123700* 101.0* 54.6 F 233339 63.76 5.312300* 1 1 F 23333 14.64733 5.25300* 1 1 F 1500 11.71 N.567335 2.27300* 2 1 2 F 1500 11.71 N.567335 2.27300* 2 1 2 2 F 1500 11.71 N.567335 2 2 2 2 2 N 1500 12.21 N.56735 2 2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2						õ		83.76	4
F 33333 6476 337300° 6"574° F	1					2	1	0.66	n
F 2323.35 ITO 4 5.25° 3700°E 27° 30°00° F <t< td=""><td>ш,</td><td>559.95</td><td>68.76</td><td>31*23'09"</td><td>5</td><td></td><td>$\left \right$</td><td></td><td></td></t<>	ш,	559.95	68.76	31*23'09"	5		$\left \right $		
Marcal Marcal<	Ŧ	2000	2021	- 100,0X - 20 - 2					
H' 90:24 58.74 N.G4*23'00'E 22*30'00' F <tr< td=""><td>\mathbf{H}</td><td></td><td></td><td></td><td></td><td>L</td><td>Ē,</td><td>35.38</td><td>S 33"25</td></tr<>	\mathbf{H}					L	Ē,	35.38	S 33"25
G' 150.54 5.8.74 N.G.47.33 OOE 227.30 OO 1 H' 15.00 11.77 N.G.47.33 OOE 227.30 OO 1 F 15.00 11.77 N.G.47.33 OOE 227.30 OO 1 H' 15.00 11.77 N.S.647.33 OOE 227.30 OO 1 H' 15.00 11.77 N.S.67.30 OE 227.30 OO 1 H' 15.00 11.77 N.S.67.30 OE 227.30 OO 1 H' 15.00 11.77 N.S.67.30 OE 227.30 OO 1 1 H' 15.00 11.77 N.S.67.30 OE 227.30 OO 0						ũ	ù	81.54	S.22-10
H 920:54 33.33 Nucer:73 oct 227 30'00' 1 E 15:00 11.71 Nucer:73 oct 227 30'00' 1 E 15:00 11.71 Nucer:73 oct 227 30'00' 1 F 15:00 11.71 Nucer:73 oct 246'11'12' 1 F 15:00 21.21 Nus9'22'00'W 90'00'00'' 1 N 15:00 21.21 Nus9'22'00'W 90'00'00'' 1 N 15:00 21.21 Nus9'22'00'W 90'00'00'' 1 N 300'00'' 14''36''00'' 10''10''' 10''10''''''''''''''''''''''''''''''''	-	50.54		N.64"23'O	Ĩ.	T	+		
H 32.33 N.e47.23 OC 22.3 DOOC 11.17 N.Wer 23 OC 22.5 DOOC 11.17 N.Wer 23 OC 24.6 "11"2" 1 E 15.000 11.17 N.NOTS' 23 OC 44" 34" 00" NI 24.9 " N 15.000 18.971 N.E. Cold CON 76" (11"2") 1 24.9 " N 155.000 18.971 N.E. Cold CON 76" (11"2") 1 24.9 " N 155.000 18.971 N.E. Cold CON 41" 34" 00" 0 0 24.9 " N 155.000 18.971 N.E. Cold CON 41" 34" 00" 0 0 24.9 " N 155.000 18.971 N.SE Cold CON 41" 34" 00" 0 0 1 24.9 " N 150.000 177.24 5.84" 50" 00" 41" 34" 00" 0 0 1 24.9 " N 150.000 177.24 5.84" 50" 00" 0 0 1 24.9 " N 150.000 18.000 18" 24" 24.9 " <td>┢╍╍╋</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	┢╍╍╋								
B 15.00 11.77 N.70*13*36* 446*11*12* 1 F 15.00 11.71 N.3073*25* 446*11*12* 1 F 15.00 11.71 N.3073*25* 446*11*12* 1 N 15.00 11.21 N.827*00* 78*27*14* 1 N 15.00 21.21 N.30*26* 500*00* 41*36*00* 0 0 N 30056* 21.21 N.30*26* 55*4*50*00* 41*36*00* 0 0 10.43*3 N 30056* 212.85 5.5*4*50*00* 41*36*00* 0 0 10.13*43 N 30056* 212.85 5.5*4*50*00* 41*36*00* 0 0 10.13*43 O 24556 777.24 5.5*4*50*00* 41*36*00* 0 0 10.12*43 N 30056 14*36*00* 0 0 0 0 0 0 0 0 0 0 0 0 12*38*27	Ĭ	90.54	1	23 00.	X	1			
E 15.00 11.77 N. 30052.245 4.2"1.12" 1 F 15.00 11.77 N. 30052.245 4.2"1.12" 1 N 15.00 11.21 N. 50022.200 90000000 1 1 N 15.00 21.21 N. 5722.000 9000000 1 1 N 30556 21.21 N. 572 0000 0 0 0 N 305500 21.21 N. 57020 90000 0<	0	15.00	77.11	76.13	46.11,12		╋		
B 15.00 11.71 N.30572 2012 15.20 11.71 N.30572 2014 15.20 11.71 N.30572 2014 15.20 11.51 12.21 N.30752 2014 12.21 N.30752 2014 12.21 N.30752 2014 12.21 N.30752 2012 N.N. 24339 N 15.00 21.21 N.30752 2014 200000000 N.N. 24339 N 302356 213.85 5.54750 0000 41.36000 0.0 N.N. 24339 N 302356 213.85 5.54750 0000 41.36000 0.0 0.00 60.45 N 302356 213.85 5.54750 0000 41.3600 0.0 0.01034243 N 302356 213.85 5.54750 000 41.3600 0.0 0.01034243 N 30256 233.45 323324 5.64760 0.0 0.01034243 N 325334 5.64560 42.0400 0.0 0.01034243 5.6456 N 325334 5.64560 42.0400 0.0 0.010342435 2.4356 N <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>╉</td> <td></td> <td></td>							╉		
E 15.000 18.971 N.65°.000 78°.27'42' 1 N 15.000 21.21 N.52°.22 000' N/N 24.93 N 15.000 21.21 N.30°.36 00' 0 0 0 N 302.56 21.345 5.54°.50<00'W	0	15.00	11.77	30,05	0				
L 15.00 19.27 N.65:00 21.21 N.35:22 000000 N.N. 2439 N 155:00 21.21 N.35'22 0000000 N.N. 2439 N 35:00 21.21 N.35'22 0000 N.N. 2439 N 35:00 21.21 N.35'25 0000 N.N. 2439 N 35:00 21.24 5.54'5000W 41'34'00 0							╈		
L 15.00 21.21 N.55722.00'W 20''00'00' N N 15.00 21.21 N.35722.00'W 20''00'00' N N N 302564 212.81 N.35722.00'W 41'36'00' N N X5433 O 20121 N.35725 554''50'00'W 41'36'00' N N X5433 O 249.56 177.24 5.54''50'00'W 41'36'00' O O U X5434 O 249.56 177.24 5.54''50'00'W 41'36'00' O O U X5434 O 249.56 14'5'W 24'5'W 27''5'W Y X4324 O 225500 163.51 N56''45'W 24''2''5'' Y X4324 C 225500 163.51 N56''51''5''W 24''5''5''5''5''' Y X4324 C 225503 163.51''5''W 24''5''S''5''5''' Y Y X4326 C 225500 163.51''5''S''S''S''5''5''S''5''5'''S'''S		15.00	18.97	8	27		+		
N 15:00 21:3(1 N.30-36 000 N 2439 N 302:56 213:35 5:34'50'000'' N N 2439 N 302:56 213:35 5:34'50'000'' N N 2439 N 302:56 177:24 5:54'50'000'' N N 2439 N 302:56 177:24 5:54'50'000'' 41'36'00'' O 0 N 302:56 177:24 5:54'50'00''' 41'36'00'' O 0 10.43 N 302:56 177:24 5:54'50'00''' 41'36'00'' O 0 10.43 N 302:56 177:24 5:54'50'00''' 41'36'00'' O 0	-	5.00	21.21		1	╈	╈		
N' IS.00 21.21 N.30 ³ 36 OC' N N 2439 N' 302.54 213.85 554"50'00'' N N' 2439 O' 243.54 70.85 554"50'00'' N N' 2439 O' 243.54 5.54"50'00'' 41"36"00' O O N' 70.82 O' 243.54 5.54"50'00'' 41"36"00' O O ID 10.43 O' 243.54 5.54"50'00'' 41"56"00'' O O ID 243.54 D' 243.54 5.54"50'00'' 41"56"00'' D D 243.24 D' 243.54 25.54"50'00'' 41"56"00'' D D 24.32 D' 243.54 245" 245" D 24.25" 24.25 D' 243.54 245" 245" D 24.25" 24.25 D' 243.54 245" 245" 24.25" 24.25" 24.25" <t< td=""><td></td><td></td><td></td><td></td><td>8</td><td>1</td><td></td><td></td><td></td></t<>					8	1			
N 3203.554 213.85 3.54*50'00'W 41*36'00'' NIN 2439 NIN 10, 12,443 C' 243.554 177.24 5.54*50'00'W 41*36'00' C 0 0. 113.43 C' 243.550 133.51 N.58*65' 00'C 0 0. 10. 13.43 C' 243.550 133.51 N.58*65' 00'C 0 0. 10. 13.43 C' 243.55 00 233.45 N.58*65' 00'C 0 0. 10. 13.43 C' 243.55 00 233.45 N.58*65' 00'C 0 0. 10. 13.43 C' 255.00 133.51 N.58*65' 00'C 0 0. 10. 13.43 C' 255.00 133.51 N.58*65' 00'C 0 0. 13.43 C' 13.00 C' 13.00 C		15.00	21.21	N 30 38 00 E	8				
No. 249.5% No. 249.5% No. 249.5% P. 249.5% 177.24 5.54'''50' 00''' 0.	Z	2005	2000			╧	Ť		
NI NI<					<u>}</u>		Ī	24.99	10
N: N:<							R	4.88	1
C 249.5% 171.24 5.54*50.00°W 41*36 00° 0 <th0< th=""> <th0< th=""> 0 0</th0<></th0<>							ź	3.67	<u>5.56.35.39 W.</u>
0. 249 56 171.24 5.54'50'00''' 41*36'00'' 0 0 60.45 P 288.00'' 281.00'' 0 0 60.45 51.07 P 285.00' 232.45 N.38'00'' 00''E 48*05'' 00'' 0 0 10.45 P P P P P 51.07 24.92 P P P P P 14.95 54.92 Q' 225500 193.51 N.28'00'' 00'' 49*'05 0.10'' 13.03 Q' 225500 193.51 N.28'00'' 24.20'' 24.35 Q' 225500 193.51 N.28'0'' 24.20''' 24.35 Q' 225500 193.51 R'''''' 24.35 24.35 Q' 225500 193.51 R'''''''''' 24.35 Q' 225500 193.51 R''''''''''''''''''''''''''''''''''''									
P ZB5.000 Z33.45 M.38*000 OD OD OD OD G0.45 P P P P P P B S4.25 P P P P P P B S4.25 Q Q D D C O C D C	0	249.56		57	36,00		-		
P' 285.000 2372.445 M.SA'CO'OO'E 48° 05' 00' 1 38.25 P1 P1 P1 P1 P1 54.65 P1 P1 P1 P1 P1 54.65 P1 P1 P1 P1 P1 24.93 P1 P1 P1 P1 P1 24.93 P1 P1 </td <td></td> <td></td> <td></td> <td>2</td> <td></td> <td></td> <td></td> <td>61.40</td> <td>W 65 75 75 5</td>				2				61.40	W 65 75 75 5
P ¹ 285.000 237.345 M.587.000 6 P1 P1 P3 85.655 P1 P1 P1 P1 P1 25.657 P1 25.651 P1 P1 P1 P1 P1 P1 25.651 P1 P1 P1 P1 P1 25.651 P1 P1 P1 P1 P1 25.651 P1 P1 P1 P1 P1 P1 P1 P1			2				┢╌╽		
N:35:00 B3:S1 N:35'00 B3:S1 N:35'00 B3:S1 N:35'00 B3:S1 N:35'00 B3:S1 N:35'00 B3:S1 N:35'00 B3:S1 S:4.29 S:4.20 S:4.20<	۵	82.00		N.58°00'00'E	°o	1			
Clipped End End End End End End End End End End End End End End End End End End End End End End End <	1							1012	1 00 X0 X0 V
Q1 Z25500 IB3.51 N58°06 48°005 A9° Z4.23 Q1 Z25500 IB3.51 N58°06 48°05 Q1 24.23 R1 353333 323.24 S.0053145 M. 34°20 30° 49.30 R1 353333 323.24 S.0053145 M. 34°20 30° 49.30 R1 353333 323.24 S.0053145 M. 34°20 30° 49.30 R1 353333 323.24 S.0053145 M. 34°20 30° R. R. 13.21 R1 R1 R1 R1 R. R. 13.23 24.30 14.00 R1 26.845 S.00551 S.145 R. R. 13.21 20° 14.00 S1 15.00 18.18 S.55°45 177°51 21 23.32 U 15.00 18.18 S.5°56 14.00 23.33 23.23 23.23 14.00 V 15.00 18.18 S.5°56 177°51 21 14.00 14.00						6	ł I	56.55	N.57-42' 03' E.
Q' Z25:00 IB3.51 N.SB'06' 00' E 4B' 06' 00' C4.90 Q' Z25:00 IB3.51 N.SB'06' 00' E 4B' 06' 00' Q Q R Z Q Q Q Q Q 13.03 R Z Q Q Q Q Q Q Q Q Q Q 13.03 R Z Q <td></td> <td></td> <td></td> <td></td> <td></td> <td>á</td> <td></td> <td>68.21</td> <td>N. 70"16" 06" E.</td>						á		68.21	N. 70"16" 06" E.
Q' 225.00 IB.3.51 NSª'06.00 48'00.00 90' 13.03 R 323.24 500'31 45" W 54' 20'30' 0 0 03 0' 49.90 R 323.33 323.24 500'31 45" W 54'20'30' R R 13.03 R 323.33 323.24 500'31 45" W 54'20'30' R R 14.86 R 323.33 323.24 500'31 45" W 54'20'30' R R R 12.01 S' 293.33 26.84 45 5.00'51 45" W 54'20'30' S 55'1'1 35'2'1' S' 293.33 26.84 45 5.00'51 45" W 54'20'30' S 63.60' V 15.00 13.18 57'2'5' 53'5'5'5'5' 14.00' V 15.00 13.17'3' 50'5'5'5'5'5'5'5'5'5'5'5'5'5'5'5'5'5'5'						đ	1.1	24.99	N. 79°39' (3" E.
Q. 225.00 183.51 N58*06.00 48*06.00 0 0 12.03 R. 353.93 323.24 506'51 45" W 54*20 30 49.90 R. 353.93 323.24 506'51 45" W 54*20 30 49.90 R. 353.93 323.24 506'51 45" W 54*20 30 49.90 R. 353.93 323.24 506'51 45" W 54*20 30 43.92 S. 293.93 323.24 506'51 45" W 54*20 30 53.16 S. 293.93 226.84 506'51 45*0 30'5 53.16 S. 293.93 226.84 506'51 45*0 50'5 53.16 S. 200 15.00 18.78 54'56 53.5 14.00 V 15.00 18.78 55'55 55'55 14.00 V 15.00 23.33 55'55 55'55 55'55 14.00 V 15.00 11.77 10'52'56 30'55 55'55 14.00 V 150						-	- 1		
R: 333.32.4 S.OX.5! 45" W. 54'20'30' 0.0 0.3 0.43.0 R: 323.32.4 S.OX.5! 45" W. 54'20'30' R.R. R. 3.148 R. 3.25'8 S: 293.93 323.24 S.OX.5! 45" W. 54'20'30' R.R. R. 49.90 S: 293.93 323.24 S.OX.5! 45" W. 54'20'30' R.R. R. 23.29 S: 293.93 26.8.45 S.OX.5! 45" W. 54'20'30' S. 63.60 S: 15.00 18.78 5.30'55 45" W. 102'28'30' S. 1400 V: 15.00 18.78 5.30'55 45" M. 102'28'30' S. 1400 V: 15.00 18.78 5.30'55 45" M. 102'28'30' S. 1400 V: 15.00 18.78 3.5'5 S. 1400 V: 15.00 18.78 5.30'55 5.30'5'5 V: 15.00 18.78 3.5'5 5.3'5'5'5 A 15.00 18.78 17'5'5'5' 5.5'5'5'5'5'5'5'5'5'5'5'5'5'5'5'5'5'5'5	ø	25.00		8	8	-		1	
R 353.53 323.24 5 06'5! 45' W 54'20'30' 49.90 R 353.53 323.24 5 06'5! 45' W 54'20'30' 8'2 6.83 S 293.53 323.24 5 06'5! 45' W 54'20'30' 8'2 6.32 S 293.53 268.45 5 06'5! 45' W 54'20'30' 8'2 6.32 S 15.00 18.78 5 06'5! 45' W 54'20'30' 5'2'3.23 V 15.00 18.78 5 06'5' 45' W 5'2'5' 5'' 740'0' V 15.00 18.78 5 55'5' 5'' 77'5' 740'0' V 15.00 18.78 5 55'5' 5'1'7'5' 5'1'4'0'0' V 15.00 18.78 5 55'5' 5'1'7'5' 5'1'4'0'0' V 15.00 18.78 5 5'5'5'5' 5'1'7'5' 5'1'4'0'0' A 15.00 18.78 5'1'7'5'' 5'1'7'5'' 5'1'4'0'0' A 15.00 18.72'15''W 17'3'3'0'' 5'1'4'0'0' 5'14'0'0'' A 15.00 11.77 N.73'5'''S''' 4'6'1'1'S'''						Τ-		12.02	A 47*24' 35' F
R 333333 323324 S.06' Si 4S' W 34' 20' 30' R I I22 (B S 333333 323324 S.06' Si 4S' W 34' 20' 30' R R I22 (B S 293.93 323.24 S.06' Si 4S' W S4' 20' 30' R R 2.323 S 293.93 268.45 S.06' Si' 4S' W S4' 20' 30' S S 14.00 S 15.00 18.18 S.06' Si' 4S' W S4' 20' 30' S S 14.00 V 15.00 18.18 S.06' Si' 4S' W S4' 20' 30' S 14.00 V 15.00 18.18 S.55' 4S' W 17' 31' 20' S 14.00 V 15.00 23.33 S.35' 5S' 5S' 5S' 5S' 5S' 5S' 5S' 5S' 5S' 5						ő		49.90	N 75 46 02 E.
R: 355.933 323.24 S.06' SI 45" W 54' 20' 30' R: R: 122.18 R:									
R R R2 122.18 S' 293.33 268.45 5.06'Si 45' W 59.78 6.933 S' 293.33 268.45 5.06'Si 45' W 59.78 6.338 S' 293.33 268.45 5.06'Si 45' W 59.78 6.338 S' 293.33 268.45 5.06'Si 45' W 59.123.10 53.51 14.00 V 15.00 18.78 5.55'45' W 102'28'30' 5.35 76.20 V 15.00 18.78 5.55'45' W 102'28'30' 5.35 76.20 V 15.00 18.78 5.35'5'5' W 102'28'30' 5.35 76.20 V 15.00 18.78 102'28'30' 5.12.20'1' 5.3 76.20 V 15.00 18.77 15''W 102'28'30' 5.12.20'1' 76.20 A 15.00 18.727'15''W 177'3'30'' 76.20'' 76.20'' A 15.00 18.727'15''W 177'3''00'' 76''1''1'''' 76''1''''' <td>ά</td> <td>353.93</td> <td>323.24</td> <td>S. 06 51 45"</td> <td>20, 30.</td> <td></td> <td></td> <td></td> <td></td>	ά	353.93	323.24	S. 06 51 45"	20, 30.				
R1 R2 74.86 S' 293.93 268.45 500° 83.84 69.83 S' 293.93 268.45 500° 83.84 63.83 S' 293.93 268.45 500° 5 5 12.3.71 S' 293.93 268.45 500° 51' 45° W 54° 20' 5 5 12.3.71 S' 15.00 18.78 550° 64 15' E, 77° 31' 50' 5 14,00 V 15.00 23.33 N.71° 33' 45' W 17° 31' 30' 5 14,00 V 15.00 18.78 S.1° 30' 5 14,00 V 15.00 18.78 N.71° 33' 45' W 17° 31' 30' 1 14,00 A 15.00 18.78 S.8° 55' 55' 55' 55' 55' 55' 55' 55' 55' 55							. 1	122.18	S. 10° 22' 10° E.
S' 293.93 268.45 5.06' 5! 45' W 54' 20' 30' R3 R4 63.83 S' 293.93 268.45 5.06' 5! 45' W 54' 20' 30' 5 5 12.3.1 S' 293.93 268.45 5.06' 5! 45' W 54' 20' 30' 5 5 12.3.1 U 15.00 18.78 5.53' 50' 15' W 17' 31' 30' 5 12.2.0 V 15.00 18.78 5.53' 55' 55' 55' 55' 55' 55' 55' 55' 55'							1	74.86	S. 05" 36" 24" W.
S' 293-93 268.45 5.06° Si' 4S° W 54° 20° 30° R3 87 3.99 S' 293-93 268.45 5.06° Si' 4S° W 54° 20° 30° 5 5 63.60 S' 293-93 268.45 5.06° Si' 4S° W 54° 20° 30° 5 5 63.60 S' 293-93 268.45 5.06° Si' 4S° W 54° 20° 30° 5 76.20 V 15.00 18.78 5.55° Si' 15° W 17° 31° 30° 5 14.00 V 15.00 18.78 530° SS 4S° W 102° 28° 30° 5 6.3.60 V 15.00 18.78 102° 28° 30° 5 6.46° 11° 12° 1 A 15.00 18.70 N.71° 32′ 45° W 102° 28° 30° 5 6.40° 10° A 15.00 18.70 N.71° 32′ 36° W 102° 28° 30° 5 6.40° 10° A 15.00 18.70 N.71° 32′ 36° W 102° 28° 30° 5 6.40° 00° A 15.00 11.71 N.80° 18° 36° C 4.40° 11′ 12° 1 1 A 15.000 21.21 N.33° 20° 12° 20° E							-	69.83	S.17-22 35 W.
S' 293.93 268.45 5.06*5i 45° M 54° 20° 30° 5 5 5 5 16.3.00 S' 293.93 268.45 5.06*5i 45° M 54° 20° 30° 5 5 16.3.00 S 15.00 18.78 5.55° 64° 15° E 77° 31° 30° 5 5 74.02 V 15.90 23.39 N.71° 32′ 45° M 102° 28° 30° 5 14.00 V 15.900 23.39 N.71° 32′ 45° M 102° 28° 30° 5 14.00 V 15.900 23.39 N.71° 32′ 45° M 102° 28° 30° 5 14.00 V 15.900 18.70 36° 55 46° 11′ 12° 1 1 1 A 15.000 11.77 N.80° 18° 36° E 46° 11′ 12° 1 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>63.82</td><td>3.28.12 54 W</td></t<>								63.82	3.28.12 54 W
S' 293.93 268.45 5.06° SI' 4S' W. 54'20' 30" 5 5: 63.60 S' 293.93 268.45 5.06° SI' 4S' W. 54'20' 30" 5 5: 63.60 S' 15.00 18.78 5.55'04' 15'E, 77' 31' 30" 5: 53.53 76.20 U' 15.00 23.33 N.71' 33' 45' W. 102' 28' 30" 5 14.00 V' 15.00 23.33 N.71' 33' 45' W. 102' 28' 30" 5 14.00 V' 15.00 23.33 N.71' 33' 45' W. 102' 28' 30" 5 14.00 V' 15.00 23.33 N.71' 33' 45' W. 102' 28' 30" 5 14.00 A' 15.00 11.77 N.80'18' 36' E 4.6' 11' 12" 5 A' 15.00 11.77 N.80'18' 36' E 4.6' 11' 12" 5 A' 15.00 21.21 N.30'28' 5E 4.6' 11' 12" 5 A' 15.00 21.21 N.30'28' 5C 50'00'00' 5 5 A' 15.00 21.21 N.30'28' 5C 50'00'00' 5 5 A' 15.00 21.21 N.30'28' 5C 50'00'00' 5 5 A' 15.00 21.21 N.30'28' 5C 50'00'00' 5 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>3.99</td><td>2 23 42 28 W</td></t<>								3.99	2 23 42 28 W
N 15:00 18.78 5:55*04 5:5 5:5 14:00 S 15:00 18.78 5:55*04 15:5 5:5 14:00 V 15:00 23.39 5:30*55 45*W 102*28 30* 14:00 V 15:00 23.39 5:30*55 45*W 102*28 30* 14:00 V 15:00 23.39 N.71*33 45*W 102*28 30* 14:00 V 15:00 23.39 N.71*33 45*W 102*28 30* 14:00 V 15:00 23.39 N.71*33 45*W 102*28 30* 14:00 A 15:00 23.39 N.71*33 45*W 17*31 30* 14:00 A 15:00 23.39 N.71*33 45*W 17*31 30* 14:00 A 15:00 11.77 N.80*18*34* 44*11 12* 15* A 15:00 21.21 N.34*07 24*6 44*11 12* A 15:00 21.21 N.34*07 24*6 <td>īn</td> <td>26.26</td> <td>268 45</td> <td>51.45</td> <td>.</td> <td>T</td> <td>┢</td> <td></td> <td></td>	īn	26.26	268 45	51.45	.	T	┢		
N S1 S1 (23.1) S1 S1 (32.0) S2 S2 (4.0) S1 S1 (3.0) S2 S2 (4.0) S1 S1 (3.0) S2 S2 (4.0) S1 S1 (3.0) S2 S2 (4.0) V IS.00 IB.78 V IS.00 18.78 V IS.00 23.33 V IS.00 23.35 A IS.00 23.30 A IS.00 11.71 N.34*07 24.61 26 A IS.00 21.21 A IS.00 21.21 A IS.00 21.21 A IS.00 21.1 A S								63.60	S 14 05 52 E.
S1 S2 S2 76.20 S1 S2 15.00 18.78 S25°04 15.6 53 14.00 V 15.00 18.78 S55°04 15.6 77°31 50° 14.00 V 15.00 23.39 S.30°55 45° W 102°28 30° 14.00 V 15.00 23.39 S.30°55 45° W 102°28 30° 14.00 K 15.00 18.78 S18°27 15° W 77°31 30° 14.00 A 15.00 11.77 N.80°18 36°5 46°11 12° 1 A 15.00 11.77 N.30°38'00'E 46°11 12° 1 1 A 15.00 21.21 N.30°38'00'E 90°00'00' 1 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>123.71</td><td>5.04"15 41" W.</td></t<>								123.71	5.04"15 41" W.
S 15.00 18.78 5.59°04 15' 50' 5.55°1 U 15.00 18.78 5.59°04 15' 50' 5.55°1 V' 15.00 23.35 5.30°55 45' M. 102' 28' 30' 100' V' 15.00 18.78 5.30°55 45' M. 102' 28' 30' 100' K 15.00 18.78 11''3' 30'' 11''3''30'' A 15.00 11.77 N.34''0''24''5' 44''1''12'' 100'' A 15.000 21.21 N.30''38''0'5' 30''' 10''''' 10''''''''''''''''''''''''''''''''''''								76.20	S. 23 31 24 W
S 15.00 18.78 5.59°04 15.67 77°31 V 15.00 23.39 5.30°55 45° W 102°28 V 15.00 23.39 5.30°55 45° W 102°28 V 15.00 23.39 5.30°55 45° W 102°28 V 15.00 18.78 5.80°55 46°11 A 15.00 11.77 N.80°16 36°05 44°11 A 15.00 11.77 N.34°07 24°61 44°11 A 15.00 21.21 N.30°38 30°60 44°11 A 15.00 21.21 N.30°38 30°60 44°11 A 15.00 21.21 N.30°38 30°60 44°11 A 266.52 54.18 520°12 30°60 40° A 266.52	1							14.00	<u>5.32.40 05 W</u>
U 15.00 23.39 5.30'55 45' W. 102'28' V' 15.00 23.39 N.71'32 45' W. 102'28' R 15.00 18.78 5.18'27'15' W 77'31' A' 15.00 11.77 N.80'16'34''E 46'11' A 15.00 11.77 N.34'07'24''E 46'11' A 15.00 11.77 N.34'07'24''E 46'11' A 15.00 21.21 N.30''36''00''E 30''00' AA' 266'52 54.18 5.20''12''00'E 11'40'	S	15.00	18.78	5.59*04	.16		\top		
U 15.90 23.39 5.30 \$5.50 \$5.45 W 102 \$28 V' 15.00 23.39 N 71*33 45 W 102 \$28 R 15.00 18.78 17*21 A 15.00 11.77 N.80*18 36 \$5 44*11 A 15.00 11.77 N.80*18 36 \$5 44*11 A 15.00 11.77 N.34*07 \$24*6 44*11 A 15.000 21.21 N.30*38 000 90*00 A 15.000 21.21 N.30*38 000 90*00 A 266.52 54.18 5.20*12*00 11*40 A 266.52 54.98 5.20*12*00 11*40						Π			
V' 15.00 23.39 N.71*32'45' W 102*28 R 15.00 18.78 5.18*27'15' W 77*31' A' 15.00 11.77 N.80*18'36'E 46*11' A 15.00 11.77 N.34*07'24'E 46*11' A 15.00 11.77 N.34*07'24'E 46*11' A 15.00 21.21 N.30*38'00'E 90*00 AA 266.52 54.18 5.20*12'00'E 11*40' AB 206.52 41.98 5.20*12'00'E 11*40'	· o	15.00	23	N	• 28.	ĺ			
R 15.00 18.78 5.18*27' 15" W 77*31' A' 15.00 11.77 N.80*18' 36" E 44*11' A 15.00 11.77 N.34*07' 24" E 44*11' A 15.00 11.77 N.34*07' 24" E 44*11' A 15.00 21.21 N.34*07' 24" E 44*11' A 15.00 21.21 N.30*36'00'E 90*00 AA' 266.52 54.18 5.20*12'00'E 11*40' AB' 266.52 54.18 5.20*12'00'E 11*40'	+	15.00		N. 71-32 45	102, 28, 30	\top	+		
R 15:00 18.78 5.18*27' 15" W 77*31' A' 15:00 11.77 N.80*18'36'E 44*11' A 15:00 11.77 N.34*07'24*E 44*11' A 15:00 21.21 N.34*07'24*E 44*11' G 15:00 21.21 N.30*38'00'E 90*00 AN 266.52 54.18 5.20*12'00'E 11*40' BB 206.52 41.98 5.20*12'00'E 11*40'	┢╍╋					Π	H		
A' 15.00 11.77 N. 80° 18' 34' E 446' 11' A 15.00 11.77 N. 34' 07' 24' E 446' 11' G 15.00 21.21 N. 30' 38' 00' E 90' 00' AA' 266.52 54.18 5.20' 12' 00' E 11' 40' BE 206.52 41.98 5.20' 12' 00' E 11' 40'	ď	15.00	19.78	5.18.27	ñ		+		
A 15.00 11.11 N.34.07 24*E1 A 15.00 11.77 N.34*07 24*E 44*11 G 15.00 21.21 N.30*38 00'E 90*00 AA 266.52 54.18 5.20*12 00'E 11*40 BB 206.52 54.18 5.20*12 00'E 11*40		1	75 11	i, a	1.	T	+		
A IS.00 II.77 N.34°07'24°E. 46°11' G IS.00 21.21 N.30°38'00'E 90°00 AA 266.52 54.18 S.20°12'00'E 11°40' BB 206.52 41.98 S.20°12'00'E 11°40'			11.11		1	T	+-		
G 15:00 21.21 N.30 38:00 6 90 00 AA 266.52 54.18 5.20 12:00 6 11 40 BB 206.52 41.98 5.20 12:00 6 11 40	A		11.77	1.1	46-11.12"		Ħ		
A 15.00 21.21 N.30 38.00 5 90'00 AA 266.52 54.18 5.20'12'00'E 11°40' BB 206.52 41.98 5.20'12'00'E 11°40'	_	1		-		T	╈		
AA' 266.52 54.18 5.20°12'00'E 11°40' BB 206.52 41.98 5.20°12'00'E 11°40'		8 8	21.21	38.00	80,00	T	+		
E8 206.52 41.98 5.20°12'00'E 11°40'	Į.	266.52	54.18	12.00	5	Ì	T		
BB 206.52 41.98 5.20°12'00'E 11*									
	BB	206.52		5.20°12'00'	•	T	+		
	ľ	-			_ i.	T	+		والمحافظ والمحافظ والمحافظ والمتعاومة والمحافظ والمحافظ والمحافظ والمحافظ والمحافظ والمحافظ

100







O D A C EVER A BELIA OF THE ABSE LA OF THE ABSE LA OF THE THE ABSE LA OF THE THE ABSE LA OF THE	CEVOOD OF THE SW I/4, SEC. IO, T.7N., R.IOE. ON SIN There are no objections to the sect to Sect. 236.15. 236.16, 236.20 and 236.21 (1) and (2). Statutes.	Certified this for a flat of flat flat in 1944. Walter K. Johnson Director, Planning Division Department of Resource Development	$ \begin{array}{c} \text{Contractions} & \text{Contractions} \\ \text{Contractions} & Co$	RECEIVED FOR RECORD THIS DAY OF WILL. 1964, AT 235 O'CLOCK D. M., AND RECORDED IN VOLUMN 29 OF PLATS ON PAGE 38 and 39. NOLUMN 29 OF PLATS ON PAGE 38 and 39. HARDO R. HIL, DWE COUNT REASTER OF DEED
---	--	---	---	---

PART OF THE NW 1/4 & SW 1/4 OF THE SE 1/4 AND NE 1/4 & SE 1/4

CITY OF MADISON, DANE COUNTY, WISC

WISCONSIN } 55 DF DANE } 55

I, VERNON S. HAMEL, REGISTERED LAND SURVEYOR, O HEREDY CERTIFY THAT I HAVE SURVEYED DIVIDED ND MAPPED PART OF THE NORTHWEST 1/4 AND SOUTHWESS 4 OF THE SOUTHEAST 1/4 AND PART OF THE NORTHEAST 4 AND SOUTHEAST 1/4 OF THE SOUTHWEST 1/4 OF ERTION 10, TOWN 7 NORTH, RANGE 10 EAST, CITY OF 10150N, DAVE COUNTY, WISCONSIN, DESCRIBED AS

"Conneucing AT THE WEST /4 CORVER OF SECTION 10, Town 7 NORTH, RANGE 10 EAST; THENCE N 88°0424", 1551.70 TEET; THENCE 51°10'36"E, 236.35 FEET; THENCE N 87°38'E, 235.89 FEET; THENCE N 88°0424", 1551.70 TEET; THENCE 51°10'36"E, 236.35 FEET; THENCE N 87°38'E, 235.89 FEET; THENCE 559°22'E 487.14 FEET TO THE POINT OF GETY; THENCE 559°22'E THENCE 583°08'E, 353.95 FEET; THENCE N82°10'E, 202.65 FEET; THENCE N57°13'E, 533.45 FEET; THENCE 534°52'E, 19160 FEET; THENCE N82°10'E, 202.65 FEET; THENCE N57°13'E, 533.45 FEET; THENCE 534°52'E, 19160 FEET; THENCE N57°58'W, 202.65 FEET; THENCE N57°13'E, 533.45 FEET; THENCE 534°56'N 570.00 FEET; THENCE N55°58W, 130.00 FEET; THENCE N 13°27'W, 81.40 FEET; THENCE N 30°21'W, 45.47 FEET; THENCE 563°58'W; 135.17 130,00 FEET; THENCE N 13° 27'W, BI, 40 FEET; THENCE
N 30° 21'W, 45.77 FEET; THENCE S 63°58'W; 135.17
FEET; THENCE S 11° 44'W, 39.80 FEET; THENCE
S 49° 02'W, 126.13 FEET; THENCE N 56° 22'W
45.35 FEET; THENCE N 26° 02'W, 232.48 FEET;
718 FECE S THENCE N 569,80 FEET; THENCE N 36°52'W, 173.72 FEET; THENCE N 57° 22'W, 30.00 FEET;
718.72 FEET; THENCE N 57° 22'W, 30.00 FEET;
728.73 FEET; THENCE N 59° 25'W, 30.00 FEET;
728.75 FEET; THENCE N 59° 25'W, 30.00 FEET;
728.75 FEET; THENCE N 55° 55'S

THE COORDINATES OF THE SAID 14 CORNER ARE ON THE WISCONSIN COORDINATE SYSTEM, SOUTH ZONE, 395,905,20 FEET NORTH AND 2,185,340,47 FEET EAST, AND ALL DESCRIPTION BEARINGS ARE REFERED TO SAID COORDINATE GRID.

SURVEY ING, DIVIDING TIFY THAT THIS PLAT IS A CORRECT ATTON OF ALL EXTERIOR BOUNDARIES NO SURVEYED AND DIVISIONS THEREON I HAVE FULLY COMPLIED WITH THE C CHAPTER 236 OF THE REVISED AND WITH THE SUBDIVISION REGULATION TY OF MADISON IN SURVEYING, DIVIDING. CORRECT OF HAUISON THE SAME.

SURVEY, SUBDIVISION, THE DIRECTION OF IC., O WINER OF Y O IFY THAT SUCH SURI WAS MADE BY THE ASSOCIATES, INC.,

NAMME J. HAMEL, REGISTERED VERVON S. HAMEL, REGISTERED LAND SURVEYOR

THE OWNER FURTHER CERTIFIES THAT THE CITY OF MADISON IS RELEASED FROM ANY CLAIMS OF DAMAGE UNDER SECTION 32.18 OF THE WISCONSIN STATUTES BECAUSE OF CHANGES IN STREET GRADES. Νοτε Ά"

STATE OF WISCONSIN STATE OF WISCONSIN

WOODSIDE DEVELOPMENT COMPANY, A LIN DARTNERSHIP BY ITS GENERAL PARTNER MORTGAGE ASSOCIATES, INC., A COR NORTGAGE ASSOCIATES, INC., A COR NIRTUE OF THE LANS OF THA STATE AND VIRTUE OF THE LANS OF THA STATE OF MU AS OWNER, AEREBY CERTIFIES THAT SUDE A SURVERED, DIVIDEO, AND MAPPEO, AND DEDICA SURVEYED, DIVIDEO, AND MAPPEO, AND DEDICA AS ERRESSENED ON THIS PLAT SURVEYED, DIVIDEO, AND MAPPEO, AND DEDICA AS ERRESSENED ON THIS PLAT SURVEYED, DIVIDEO, AND MAPPEO, AND DEDICA AS ERRESSENED ON THIS PLAT SURVEYED, DIVIDEO, AND MAPPEO, AND DEDICA AS ERRESSENED ON THIS PLAT SURVEYED, DIVIDEO, AND MAPPEO, AND DEDICA AS ERRESSENED ON THIS PLAT SURVEYED, DIVIDEO, AND MAPPEO, AND DEDICA SURVEYED, DIVIDEO, AND MAPPEO, AND DEDICA AS ERRESSENED ON THIS PLAT SURVEYED, DIVIDEO, AND MAPPEO, AND DEDICA AS ERRESSENED ON THIS PLAT SURVEYED, DIVIDEO, AND MAPPEO, AND DEDICA AS ERRESSENED ON THIS PLATE SURVEYED, DIVIDEO, AND MAPPEO, AND DEDICA CERTIFY THAT THIS PLATES, INC., DOES FUE SELENUM, FOR ASSOCIATES, INC., DOES FUE FRIEDOWN, FOR ASSOCIATES, INC., DOES FUE FRIEDOWN, FOR ASSOCIATES, INC., DOES FUE SELENUM, AND THE SELENCE, PLANNING DI USSONSIN, AND THE DIFECTOR, PLANNING DI USEDART OF RESOURCE DEVELORMENT,

IN WITNESS WHEREOF, THE SAID MOR ASSOCIATES, INC., HAS CAUSED THESE A TO BE SIGNED BY EARL D. LILLYDAHL, I VICE PRESIDENT AND COUNTERSIGNED BY L B. SWARTWOUT, ITS SECRETARY, AT MICH WISCONSIN, AND ITS CORPORATE JEAL TO HEREOUTD AFFIXED ON THIS JELDAY OF WOODSIDE DEVELOPMEN A LIMITED PARTNE 1964.

IN THE PRESENCE OF

BRAUN CLAIRE

BY GENERAL MORTGAGE

Penera HEREMANN

EARL D.

 \bigcirc

Alidio B. Currenter STATE OF WISCONSIN COUNTY OF MILWAUKEE 55

PERSONALLY CAME BEFORE WE THIS I ON CERSONALLY CAME BEFORE WE THIS I CARLO CHART AND WILL IS B. SWARTWOUT, SECRETARY, ON HORTGAGE ASSOCIATES, INC., TO ME KNOWN BE THE PERSONS WHO EXECUTED THE RESOLUTION AND EXCUTED THE RESOLUTION AND ACCNOWLEDGED THAT THE CORDERTION AND ACCNOWLEDGED THAT THE TARY OF SAID LEDGED THAT T INSTRUMENT A X910 0 FORE GOING LUTED THE FOR H OFFICERS AS -ITS AUTHORITY. CORPORATION Executed Th

NOFARY PUBLIC, MILWAUKEE CO MYY COMMISSION EXPIRES


40


0320

SUCH BY IT









 \geq



BLACK ADDITION TO PAINTED POST ESTATES LOCATED IN THE SE I/4 OF SECTION IO, T7N, RIOE CITY OF MADISON, DANE COUNTY, WISCONSIN

SURVEYOR'S CERTIFICATE

STATE OF WISCONSIN) 88 COUNTY OF DANE

I, Claude L. Carrington, Surveyor, hereby certify that in full compliance with the provisions of Chapter 236, Wisconsin Statutes and the subdivision regulations of the City of Madison, and under the direction of the owners below, I have surveyed, divided and mapped BLACK ADDITION TO PAINTED POST ESTATES, and that such plat correctly represents all exterior boundaries and subdivision of the land surveyed and is located in the SE, NE, SW and NW quarters of SE 1/4 of Section 10, T7N, RIOE, City of Madison, Dane County, Wisconsin more particularly described as follows:

SW and NW quarters of SE 1/4 of Section 10, T7N, RIOE, City of Madison, Dane County, Wisconsin, more particularly described as follows: COMMENCING at the east 1/4 corner of said Section 10; thence S 58° 34' 36" W, 997.94 feet; thence S 0° 50' 43" E, 60.00 feet to the point of beginning; thence S 1° 11' 37" E, 121.71 feet; thence S 5° 56' 25" E, 60.21 feet; thence S 1° 11' 37" E, 445.00 feet; thence N 58° 45' 23" E, 135.00 feet; thence S 51° 43' 53" E, 60.53 feet; thence N 58° 45' 23" E, 135.00 feet; thence S 1° 11' 37" E, 517.50 feet; thence S 58° 45' 23" W, 195.00 feet; thence S 1° 11' 37" E, 11.25 feet; thence S 58° 45' 23" W, 135.00 feet; thence S 1° 11' 37" E, 236.00 feet; thence S 58° 45' 23" W, 330.00 feet; thence N 1° 11' 37" W, 211.62 feet; thence S 58° 45' 23" W, 130.25 feet; thence N 1° 11' 37" W, 26.73 feet; thence S 58° 45' 23" W, 193.55 feet; thence N 0° 43' 25" W, 1160.62; thence N 58° 34' 36" E, 639.64 feet to the point of beginning. point of beginning.

Date: 9/30/'66

Claude L. Carrington

Revised; 10/13/66

Registered Land Surveyor 8-835

OWNER'S CERTIFICATE OF DEDICATION

Lom, Inc., a corporation duly organized and existing under and by virtue of the laws of the State of Wisconsin, as owner, does hereby certify that said corporation caused the land described on this plat to be surveyed, divided, mapped and dedicated as represented on this plat.

Lom, Inc., as owner, does further certify that this plat is required by 8. 236.10 or 8. 236.12 to be submitted to the following for approval or objection:

Director, Planning Division, Department of Resource Development (2) Common Council of the City of Madison

CERTIFICATE OF CITY TREASURER

STATE OF WISCONSIN) SS COUNTY OF DANE

I, Walter G. Hunter, being duly appointed, qualified and acting city treasurer of the City of Madison do hereby certify that in accordance with the records in my office there are no unpaid taxes or unpaid special assessments as of <u>MOVE M6ER 30,1766</u> on any of the lands included in the plat of BLACK ADDITION TO PAINTED POST ESTATES.

Hunter, Cfty Treasurer City of Madison

CERTIFICATE OF COUNTY TREASURER

STATE OF WISCONSIN SS COUNTY OF DANE

I, Martin Gunnulson, being the duly elected, qualified and acting treasurer of the County of Dane do hereby certify that the records in my office show no unredected tax sales and no unpaid taxes or special assessments as of <u>December 1</u> 1966 affective the lands included in the plat of BLACK ADDITION TO PAINTED POST ESTATES.

Martin Gunnulson, Treasurer Dane County, Wisconsin

COMMON COUNCIL RESOLUTION

As owners we hereby restrict all present or future owners from making claims of damages under Section 32.18 of the Wisconsin Statutes against the City of Madison, because of changes in street grade. This restriction constitutes a restriction for the benefit of the public according to Section 236.293, Wisconsin Statutes and shall be enforceable by the City of Madison.

In witness whereof, the said Lom, Inc., has caused these presents to be signed by William A. Ouweneel, its president and countersigned by Patrick J. Lucey its secretarytreasurer at Madison, Fisconsin, and its corporation seal to be hereunto affixed this 10 day of November, 1966.

In the presence of:

Mary A/ Ritchie

1ta/

Patricia Ann Flath

Lon, Inc lurres William A. Ouweneel President

Patrick J. Lucey Becretary-treasurer

STATE OF WISCONSIN) 38 COUNTY OF DANE

Personally came before me this _____ day of ______, 1966, William A. Ouweneel, President and Patrick J. Lucey, Secretary of the above named corporation, to me known to be the persons who executed the foregoing instrument and to me known to be such president and secretary of said corporation, and acknowledged that they executed the foregoing instrument as such officers and as the deed of said corporation by its authority.

Nobary Public, Dane County; Wisconsin Dudley H. Davis Jr.

My Commission Expires 15 PERMANENT

∫i: ∕n: . ບັ


I, Eldon L. Hoel, do hereby certify that I am the duly ephotine of maturied and acting city clerk of the City of Madison and the foregoing is a thus and correct of of a resolution passed and adopted by the City of Madison, Dane County, Vietnain this day of

Eldon L. Hoel, City of Madison

CERTIFICATE OF COUNTY REGISTER OF DEEDS

RECEIVED for recording this 2 day of 2. α . M. and recorded in Volume 32 of plats on page

Register of Deeds




DRAFTED BY BRIDWELL ENGINEERING COMPANY

0

* *****

Elvehjem Neighborhood Profile: Land Use Map



City of Madison Department of Planning and Community & Economic Development, Planning Division 1/25/2019



Legend



Ownership Parcels

2' Contours

Elevation - High












Exhibit 5: Slope Analysis Map

Legend

Elveh	jem	Park

Ownership Parcels

Slope (in %)

0
1-5
6-10
11-20
21-100






Exhibit 6: Existing Vegetation Inventory

Legend




Elvehjem Park


Ownership Parcels

Tree Species

- Basswood- Tilia Americana (2)
 - Black Cherry- Prunus serotina (2)
- Black Walnut (9)
- Box Elder- Acer Negundo (4)
- Hackberry- Celtis occidentalis (4)
- Honey Locust (1)
- Kentucky Coffee (2)
- Mulberry- Morus sp. (1)
- Norway Maple (1)
- Other (1)
- Red Elm- Ulmus rubra (5)
- Red Oak- Quercus rubra (6)
- Shagbark Hickory- Carya ovata (2)
- White Cedar (1)

Inventory completed by Tree Health Management on 6/19/2019.











PUBLIC INFORMATION MEETING 1, 6/19/2019

Q1 How important are public parks and open spaces to your quality of life?



ANSWER CHOICES	AVERAGE NUMBER	TOTAL NUMBER		RESPONSES	
	9		1,447		163
Total Respondents: 163					


Q2 Why do you typically visit parks/outdoor recreation areas?



ANSWER CHOICES RESPONSES 41.14% 72 To walk/hike or view nature 10.29% 18 To play a game or participate in a field sport 29.14% 51 To take my child(ren) to a playground 5.14% 9 To go to an event or festival 14.29% 25 Other (please specify) TOTAL 175

Answered: 175 Skipped: 1

Q3 How often do you visit Elvehjem Park in the below seasons?PLEASE CHECK A BOX FOR EACH SEASON.



Not at all during this season

	DAILY	A FEW TIMES A WEEK	ONCE OR TWICE DURING THIS SEASON	NOT AT ALL DURING THIS SEASON	TOTAL
Summer	10.47% 18	51.74% 89	32.56% 56	5.23% 9	172
Spring	8.24% 14	47.65% 81	40.00% 68	4.12% 7	170
Fall	10.47% 18	44.19% 76	40.70% 70	4.65% 8	172
Winter	4.19% 7	19.76% 33	41.32% 69	34.73% 58	167

Q4 Please write two (2) to three (3) adjectives which describe how you feel when you think about the current condition and availability of amenities in Elvehjem Park. (How do you feel in this space?)

> Answered: 123 Skipped: 53

Of the 123 respondents who answered this question, 60 provided negative answers (using descriptors such as crummy, outdated, or neglected), 17 provided neutral answers (such as meh, sparse, potential), and 38 provided positive answers (for example, peaceful, relaxed, and fun). The remaining 8 answers did not fit the guestion and were not classified.

ELVEHJEM PARK MASTER PLAN SURVEY

Q5 Please write two (2) to three (3) adjectives which describe how you would LIKE to feel when you think about the condition and availability of amenities in Elvehjem Park. (How would you like to feel in this space?)

Answered: 123 Skipped: 53

123 survey respondents provided input on how they would like to feel; these results are summarized below in the form of a word cloud. The most common adjectives are displayed. The size and prominence of the adjective in the graphic is determined by the number of responses received in the survey. If a particular adjective was included in many responses, it will be displayed in a larger font and be positioned more prominently.



Q6 What do you feel is the best aspect of Elvehjem Park?

Answered: 129 Skipped: 47

Of the 129 survey respondents who answered this question, 29% thought the available open space or size of Elvehjem Park was the best aspect, 15% touted the park's convenient location, 13% voted for a specific facility or aspect of the park, and an additional 19 comments were not clear and thus not categorized. Finally, the remaining 21% of responses felt the best aspect of the park was actually neighboring Elvehjem Sanctuary (the woods and hiking trails specifically), which is owned by the City of Madison but not considered a part of Elvehjem Park.


ELVEHJEM PARK MASTER PLAN SURVEY

Q7 What do you feel is the biggest drawback of Elvehjem Park?

Answered: 124 Skipped: 52

Of the 124 responses to this question, approximately 42% were concerned with the condition of the existing amenities in the park. Most of these comments specifically mentioned the shelter. 36% of responses mentioned a current lack of amenities or limited activities available in the park, 4% stated accessibility difficulties, and of the remaining comments 8 had no drawbacks to mention and 5 were unrelated to the question at hand.

Q8 Please select and rank the recreational amenities below on how important you feel it is that they be included in the Elvehjem Park master plan.




Answered: 176 Skipped: 0

Not at all important Slightly important Important Very important

	NOT AT ALL IMPORTANT	SLIGHTLY IMPORTANT	IMPORTANT	VERY IMPORTANT	NO OPINION	TOTAL	WEIGHTED AVERAGE
Baseball/Softball Backstop	25.88% 44	25.88% 44	26.47% 45	14.12% 24	7.65% 13	170	2.52
Basketball Court (Half Court)	24.55% 41	28.74% 48	27.54% 46	13.17% 22	5.99% 10	167	2.47
Basketball Court (Full Court)	30.23% 52	22.09% 38	27.91% 48	12.79% 22	6.98% 12	172	2.44
Tennis/Pickleball Courts	18.24% 31	31.18% 53	27.06% 46	18.82% 32	4.71% 8	170	2.61
Community Gardens	10.71% 18	17.26% 29	31.55% 53	35.71% 60	4.76% 8	168	3.07
Hiking/Walking Paths	2.34% 4	8.19% 14	27.49% 47	59.65% 102	2.34% 4	171	3.51
Open Fields for Soccer, Frisbee, Football, Catch, etc.	7.06% 12	17.65% 30	30.00% 51	40.00% 68	5.29% 9	170	3.19
Play Equipment	5.81% 10	14.53% 25	23.84% 41	52.91% 91	2.91% 5	172	3.33
Sun Shelter	2.94% 5	12.35% 21	34.12% 58	45.88% 78	4.71% 8	170	3.37
GaGa Ball Pit	46.06% 76	16.97% 28	7.27% 12	2.42% 4	27.27% 45	165	2.48
Alternative Adult Fitness Equipment	23.53% 40	27.06% 46	21.18% 36	12.94% 22	15.29% 26	170	2.69
Off-road Pump Track/Bicycle Playground	24.86% 43	17.92% 31	13.87% 24	34.10% 59	9.25% 16	173	2.85

Q9 If you are a parent/guardian, how many children live in your HOUSEHOLD (aged 17 or younger only)?



ANSWER CHOICES	RESPONSES	
None	37.04%	60
1	19.75%	32
2	26.54%	43
3	12.35%	20
4	4.32%	7
More than 4	0.00%	0
TOTAL	1	62

ELVEHJEM PARK MASTER PLAN SURVEY

Q10 Please share any additional comments or concerns regarding the Elvehjem Park master plan development.

Answered: 68 Skipped: 108

1)The community gardens was a good addition to the Park use. - Maybe combined use of the Elvehjem School lands w/ City Park land would work for more options. I'm thinking of the open lands west of the school and north of Academy Dr.

2) Options for hookups (water, electricity) for food carts, events, bands, and other activities would be great at LVM park.

3) My major concern for the park is that the sanctuary portion is not being cared for well enough, specifically managing the invasive plant growth that is choking out the native plants.

4) This park is underutilized and there is poor visibility from the main entrance on Painted Post. Please keep and update the shelter and bathrooms. This park *needs* a playground. A bike playground would be an innovative draw for the neighborhood and surrounding areas; I would love to see one in Madison.

5) None

6) Teen age GANGS don't need another place to hang out! Give your money to the police to fix the jail or to the Parks dept. to help the golfers.

7) I was disappointed that the play structure was removed. My friend worked hard to put that up.

8) We have older/elderly adults with disabilities living in this household so accessiblity and access is important to them.

9) again... well taken care of tennis courts are important. Need a practice area and a tennis ball recycling bin (which is free BTW)

10) There is a drainage on the park by the playground that I twisted my able in

11) I'd like to see dogs officially allowed on leash.

12) It's important to me that the park be dog-friendly. I'd like to see more that would draw in adults as well. Things with an interactive and/or educational component are also good. I wonder if there's a way to collaborate or pull in members of the church across the street. What about an ice rink/sledding hill for winter fun?

13) I think that some of the woods can be removed for equipment and playing fields.

14) While I have no children living with me, my Grandchildren use the park when they visit.

15) Great Neighborhood would draw more people out if the park was better

16) It would be really great to have an asphalt pump track. It is such a unique and fun activity that would draw many families to the park. Its not something that many parks have so it would really add to all the great activities the park provides.

17) Dog park!

18) Dog park. This neighborhood has a lot of dogs and this would be a great addition.

19) Would be GREAT to get bike area~every other park close is for skateboarding!

20) Be the site of the first and only bike pump track in Dane Co. Work with PumptraxUSA.

21) Safety

22) Dogs should be allowed, this is a family space and people bring their dogs if they want to enjoy time with the whole family.

23) Please add a pump track for bikes!! Madison needs one sooo bad. There's a huge demand.

24) It would be so wonderful to build an asphalt pumptrack. The nearest one is in LaCrosse and Madison could build a better one. Even if it was simple and did not look like a butterfly from the sky

25) A bicycle pump track would be amazing. My son participates in bmx and would be a wonderful workout for him

26) The shaded playground that was appropriate for young children was my family's favorite park. We met many neighborhood kids there, and spents hours at a time there. The shade is very important. VERY disappointed playground was removed and not immediately replaced!

27) as a huge biking city, we lack any place for kids to go and ride their bikes. Google "Lebanon Bike Park" in Lebanon, OH - we had the opportunity to visit there recently and it's great. So many families enjoying the space, lots for all to do there!

28) A bike/pump track would extend the life of the park to older kids/teenagers as a fun safe place to go.

29) I would LOVE a pump track or bicycle play ground. There are none in this area and I find myself traveling often to get to them. My family participates at Madtown BMX and there are lots of kids from there thst eould come use this. I think this would be a great addition to our neighborhood.

30) City should follow up on renting private events. If trashed make sure not allowed back. Lots of times i find trash out in front of my home after an event

31) If I were to give a pitch to the Madison Parks Department, I would first tell them to think BIG when it comes to this park master plan. The Elvehjem Neighborhood is the foundation of the East Side, with a neighborhood association that has been going for 50 consecutive years, the longest in all of Madison. This new shelter and park will be used for 10+ neighborhood events, and could be the focal part of our neighborhood. We could host association board meetings there, have our annual 4th of July with over 200+ people ever year, and numerous holiday events.

The neighborhood is slowly turning over to more young families, ready to start a new generation for this neighborhood. A newly renovated shelter along with a grand master plan for Elvehjem Park would help kick start that generation in the right direction. I want to see this park become part of the future our neighborhood.

32) We are really missing a playground when school is in session and cannot play at the school. It would be nice to have a place to picnic under shade. The park is such a beautiful place, but the shelter is outdated and not welcoming.

33) I would appreciate having a LifeTrail fitness trail. I have used these at Middleton parks. They are exercise stations that help you focus on various muscle groups/stretching, etc.

34) I live across the street from the park and use it on an almost daily basis year around. I am also a gardener at the LVM Community Garden. I thoroughly enjoy the park as well as the Elvehjem Conservation area. Here are my thought: 1) the shelter needs to be replaced. The current shelter is dark and does not really invite folks to enjoy the park. It is also a hang out for teens, who are mostly innocent but it can be a surprise to come down the hill and turn the corner to find kids, or anyone hanging out. Kids also climb on the roof of the shelter all the time - its a neighborhood rite of passage. If there is to be play equipment it should be near the shelter. The school has plenty of play equipment on the other side, but far away from the shelter. 2) Dogs should be allowed on leash n the park. Dirty secret is that many people do it and there is never an issue. 3) The conservation area is a wonderful place!...but entirely under used. The nature there is terrific and the walk is serenely wonderful. I do worry however that it's beauty is being lost to invasives (garlic mustard, honeysuckle, buckthorn) and the amount of dead tree branches concerns me as fuel for a fire during a dry spell. The conservation area needs a plan of its own to restore and save it. Also the undergrowth in the conservation area traps so many mosquitoes in the summer that it is inaccessible for all practical purposes except on the most windy or cold days. Of course, I do not expect the area to be mosquito free.

35) We've lived in Elvehjem neighborhood for 41 years. Raised 2 children here (born 1980, 1983). Been caring for our granddaughter for 5+ years in our home now. We know Elvehjem shelter is used by LVM Neighborhood Association (we are members) and we are very grateful for this shelter and park. We also attend MSCR activities at Elvehjem Park.

36) Would love school and city to work together for wheelchair swing and paths

37) Most value the openness and spaciousness of the park. Would like it to maintain it's 1970's open, breezy style. Acewood park changes appear to have more of an urban style (for instance the dark metal fencing). Much prefer the mroe suburban, woodsy style of Elvehjem Park (for instance, the open wood fencing near entrance to Park Shelter and near where there are currently gardens). Would like changes or additions to keep the original look and feel of the park. New tennis courts and basketball court would be good along with new wood benches by the tennis courts. Also better manicured trees and bushes- trimmed, cut back to allow for better visibility, safety surrounding the tennis courts. New fencing around tennis court (some kind as what is there now). New green court with white boundary lines would be a good improvement.

38) Lights for tennis and pickleball.

39) Other than the tennis courts or woods, for running or walking, we don't use the park much (no kids). Our impression is much of Elvehjem Park is just a big, open grass field. While this may be good for kids' sport events, it doesn't really have a "park-like" feel to it. How about more trees around the fields? Though we don't participate, the community garden space is a good feature too.

40) I would really love to see a dog park component in this park, or another local park. 60% or more of our park usage includes our dog and we would like to increase that number.

41) I'd love to see a sand volleyball court put in at Elvehjem. There are already many amenities for those with young kids, but sand volleyball is a big deal for post college-middle aged people in Madison, and would draw people out who otherwise might not make use of Elvehjem Park already.

42) I think of Elvehjem Sanctuary and the school grounds as part of this larger space. Because of the increasing loss of natural spaces, preserving and enhancing the natural spaces we have is very important. The basketball, softball and soccer fields co used with the elementary school is a good plan. I don't think we need more in addition to that, especially with Acewood and Droster Parks in easy walking distance.

43) It would be nice if LVM was dog friendly. The shelter could use a little makeover.

44) Restrooms should be locked overnight to discourage those that might choose to occupy the building overnight! Seems the restrooms could be open to those using the building with a permit, or when there are people using the park for sporting events or general use! (during the day and early evening.(

45) Adding a dog exercise area, or at least making it not against the "rules" to have a dog in the park.

46) There are a lot of dogs in the neighborhood that could benefit from an off leash park. It also gives our neighbors a chance to get together more often which could strengthen neighborhood bonds!

47) I would like to see better lighting in the area.

- 48) I'm just glad it's going to be updated soon.
- 49) Excited that we're discussing it!

50) before adding anything put car parking at top of list. I can"t even get out of my driveway now here on academy dr. on game days or practice or other activities. I can"t have folks over as Academy dr. becomes a parking lot you can"t get near my home. it used to be a lovely neighborhood park, something has to be done about parking, take some that land and make parking, there don"t seem to be any respect for those of us that live here, it has become a dangerous sitituation. so what ever is added to the park concider parking places 1st.

51) Area needs more diverse activities besides open field sports

52) Pickle Ball is one of the fastest growing sports and would like designated courts. Tennis courts are unsafe to use due to the asphalt is extremely cracked and eroded. Paved walking path encircling the park and to the activities. We have lived in the LVM area for 33-years.

53) the shelter is totally wasted right now. keep the rest rooms open.

54) It will be a great improvement around here to have the whole site taken into consideration. Turn it into a place to be enjoyed by all...Thank You.

55) Again, as someone who chose to live in this neighborhood because of the proximity to the park, let me please emphasize the need for lights at night. Lots of illicit activity occurs parked along the street and in the park because it's so dark there at night. It need to have better lighting.

56) It would be awesome to have more family friendly activities available at the park.

57) Park is great, no need to make any drastic changes

58) We take 3 grandchildren to the play area at Elv. School.

59) We were at a wedding in the shelter last summer that was lovely. The couple worked very hard to get it ready for tor people as it was pretty gross. I see teens there a lot smoking and doing other things which makes us leave.

60) Pathways would be nice for accessibility for those with disabilities, as well as some playground equipment for those with disabilities.

61) lack of parking makes using this as a sports field very inconvenient for the neighbors.

62) The school has a softball diamond and half court basketball. What about football or soccer goal posts?

63) We loved the playground in the shade that wasn't part of the school and would love to see it come back. We also would really appreciate access to bathrooms and drinking water.

64) Would love to see playground for small children in a shady area.

65) This space is beautiful and has the opportunity to be a great space to build community in the neighborhood. In its current condition, it doesn't do this and ultimately is underutilized. If better developed I could see it be a heavily used park.


66) Thanks for looking into making some much needed improvements! Even if there is small impact it will be huge!

67) I love it that so many people in the neighborhood use and enjoy this space! It's literally in my backyard (lucky me!), so I see how much use it gets daily. The one thing that's a problem is the East Side Sharks football team. They practice 5 days a week, for 3 hours a night, for 3 months straight. It is excessive. They are loud - lots of yelling (coaches) and constant whistle blowing. This activity is not a good fit for a small space in the middle of a residential area. All the other groups who practice and play there are great -quieter, less frequent, etc. - but not this one. Another thing to consider is that even though a lot of people here have kids, a lot don't. The park shouldn't only be kid centered. I enjoy using it because it's an extremely accessible way to get out in nature, when I don't have time to drive somewhere.

68) The open field might be better off with some trees and paths, maybe a sculpture and landscape features rather than used for large field sports given current underutilization for that purpose.


Q11 OPTIONAL: How do you identify your race?

ELVEHJEM PARK MASTER PLAN SURVEY



ANSWER CHOICES	RESPONSES	
Asian	0.68%	1
American Indian or Alaskan Native	0.68%	1
Black, African or African American	0.68%	1
Hispanic or Latino	1.37%	2
White or Caucasian	83.56%	122
From multiple races	2.05%	3
Other	2.05%	3
Prefer not to answer	8.90%	13
Other	0.00%	0
TOTAL		146


ELVEHJEM PARK MASTER PLAN SURVEY



Q12 OPTIONAL: What is your age?

ANSWER CHOICES	RESPONSES	
10 or younger	0.68%	1
10-18	0.68%	1
19-29	4.05%	6
30-40	32.43%	48
40-59	41.89%	62
60 or older	18.24%	27
Prefer not to answer	2.03%	3
TOTAL		148

Q14 OPTIONAL: How would you most like to receive additional information regarding this project?



ANSWER CHOICES	RESPONSES	
E-mail	49.22%	63
Madison Parks Website	12.50%	16
Mail	14.84%	19
Social Networks (Facebook, Twitter)	21.88%	28
Other (Please Specify)	1.56%	2
TOTAL		128

play MADISON

PARKS

ELVEHJEM PARK MASTER PLAN UPDATE

Public Meeting #1 Elvehjem Elementary 6-19-2019

INTRODUCTION

Sarah Close, City of Madison Parks Division Ann Freiwald, City of Madison Parks Division

WELCOME


Thanks for coming, we're looking forward to working with you to design Elvehjem Park! We want to hear your thoughts and ideas, so to make sure everyone has an equal chance to speak...

- We will take all comments/questions at the end of the presentation.
- Do not interrupt others while they are speaking.
- No disparaging remarks about others' comments.

- If you are not comfortable speaking tonight, please call, email, or take our community survey.

Don't forget to sign in and grab an IClicker!







MASTER PLANNING

What is it?

A master plan:

ols a forum for public input

 Provides a common vision for future management/development of a property through a public consensus building process
 Analyzes site inventory and suitability (What is there now and what can we do with it?)

 Provides programming (aka activities), development, and resource protection recommendations

Questions answered by a master plan: What is going to happen, where-ish, when-ish, and about how much will it cost?

A 10,000 foot view!



A master plan does NOT:

Specify specific materials or finishes

oDesignate exact locations


 $\circ Contain construction drawings (which include information like dimensions, colors, products, quality requirements, etc.)$


Not a blueprint!


Questions NOT answered by a master plan: Who is going to build it, when (exact date), and how much will it really cost?





ZOOMING IN	
Elvehjem Neighborhood Association	
Existing Park & Recreation Opportunities	
Elvehjem Park	





















HISTORY

• First parcel dedicated to the City of Madison in 1965 as part of the Painted Post Estates development

Long history as agricultural property/made land

oNo significant or suspected archaeological artifacts/buildings in park










EXISTING CONDITIONS


- o Aerial
- o Site Photos
- Topography and Slope
- o Soils
- o Vegetation































COMMENTS?



CONTACT US: SARAH CLOSE OFFICE: (608) 263-6850 EMAIL: SCLOSE@CITYOFMADISON.COM

ELVEHJEM PARK MASTER PLAN UPDATE

Public Meeting #2 Elvehjem Elem. Library 10-3-2019

INTRODUCTION

Sarah Close, City of Madison Parks Division Ann Freiwald, City of Madison Parks Division






WELCOME

Thanks for coming, we're looking forward to working with you to design Elvehjem Park! We want to hear your thoughts and ideas, so to make sure everyone has an equal chance to speak...

- We will take all comments/questions at the end of the presentation.
- Do not interrupt others while they are speaking.
- No disparaging remarks about others' comments.
- If you are not comfortable speaking tonight, please call, email, or take our community survey.

Don't forget to sign in and grab an IClicker!



MASTER PLANNING

A master plan does NOT:


oSpecify specific materials or finishes


oDesignate exact locations

Contain construction drawings (which include information like dimensions, colors, products, quality requirements, etc.)

Not a blueprint!

Questions NOT answered by a master plan: Who is going to build it, when (exact date), and how much will it really cost?









HISTORY

 \circ First parcel dedicated to the City of Madison in 1965 as part of the Painted Post Estates development

Long history as agricultural property/made land

oNo significant or suspected archaeological artifacts/buildings in park









EXISTING CONDITIONS


- o Aerial
- Topography and Slope
- o Soils


























COMMON THEMES

✓ IClickers Top Results - Most tacking in local ares? Places to picnic and have gatherings; All of the above. • Why do you typically visit parks? To walk/hike or view nature; To take my children to a playground

✓ Survey • Natural areas • Hiking trails • Seating • Play equipment • Bike Playground/Pump Track

Design Exercise
 Active activities (play equipment, organized sports, ski/sled hill)
 Passive activities (walking access, open space)
 Functionality (shelter renovations)





COMMENTS?



CONTACT US: SARAH CLOSE OFFICE: (608) 263-6850 EMAIL: SCLOSE@CITYOFMADISON.COM City of Madison Park and Open Space Plan

https://www.cityofmadison.com/parks/about/parksopenspaceplan.cfm

City of Madison Comprehensive Plan

https://imaginemadisonwi.com/document/comprehensive-plan-adopted

Dane County Park and Open Space Plan

https://parks-lwrd.countyofdane.com/Information/Planning-Development/Parks-Open-Space-Plan

EXHIBIT 11



 $M:\blue hjem\blue hjem\b$