## Change Order Report for BPW

**Entered Date From:** 10/1/2020 **To:** 10/31/2020

Contract: 8294 Dairy Drive (new street)

Contract Amount: \$970,640

Change Order 2 Additional underdrain and engineered soil in ditch to account for storm pipe P-200 cuttin

**Issue Date:** 10/12/2020 **Amount** \$19,963.89 **Percent:** 2.0568%

**Project(s):** 11865 Dairy Drive (new street)

Reason(s): Missing Bid Item or Additional Bid Item needed.

Underground conflicts (utility revision).

Change Type(s): Street

Sewer-Storm

CO Description: Additional underdrain and engineered soil in ditch to account for storm pipe P-200 cutting off

flow to pond. Tack coat for paving, and inlet protection for terrace inle missed in bid item

quantities.

Notes:

Change Order 3 Repair water main after existing tee cracked

**Issue Date:** 10/12/2020 **Amount** \$475.00 **Percent:** 0.0489%

**Project(s):** 11865 Dairy Drive (new street)

**Reason(s):** Field Decision (Expanded Scope).

Change Type(s): Water

**CO Description:** Repair water main after existing tee cracked

**Notes:** 

Total Previous: Previous Percent: 0.0000%

Total Current: \$20,438.89 Current Percent: 2.1057%

Revised Contract Amount: \$970,640.00 Revised Percent 2.1057%

Contract: 8306 Toepfer, Holly, Euclid and St. Clair Resurfacing w/Utilities

**Contract Amount:** \$4,476,394

Change Order 3 Tonnage overun for 3" clear stone needed for undercut areas at pervious pavement. Need

**Issue Date:** 10/21/2020 **Amount** \$30,405.00 **Percent:** 0.6792%

Project(s): 11744 Toepfer, Holly, Euclid and St. Clair Resurfacing w/Utilities

Reason(s): Actual vs. Estimated Quantities differ.

Missing Bid Item or Additional Bid Item needed.

Design did not adequately anticipate field conditions.

Change Type(s): Sewer-Storm

CO Description: Tonnage overun for 3" clear stone needed for undercut areas at pervious pavement. Needed to

fill gap between curb and gutter and pre-cast pervious panels placed next to the curb and

gutter. Recommended to seal the paver blocks per manfacturer.

Notes:

3.7527% **Previous Percent: Total Previous:** \$167,984.20 **Current Percent:** 0.6792% **Total Current:** \$30,405.00 **Revised Percent** 4.4319% **Revised Contract Amount:** \$4,476,393.77 Contract: 8427 Fire Station No. 14 Training Tower Contract Amount: \$193,300 Change Order 1 Change order request for added gravel base around perimeter of training tower. Add set o \$5,659.64 2.9279% Percent: **Issue Date:** Amount 17451 Fire Station 14 (2018) & Fire Station 14 Training Tower (2019) **Project(s):** Field Decision (Expanded Scope). Reason(s): **Change Type(s): Facilities CO Description:** Change order request for added gravel base around perimeter of training tower. Add set of hinges to training tower gate. Notes: **Total Previous: Previous Percent:** 0.0000% **Total Current: Current Percent:** 0.0000% #Error Revised Percent **Revised Contract Amount:** \$193,300.00 0.0000%Contract: 8430 Government East Ramp Demolition Contract Amount: \$709,300 Change Order 1 COR-01 Revised Demo Plan due to unforeseen condition of exterior wall of Great Dane Issue Date: 11/4/2020 Amount \$25,780.00 **Percent:** 3.6346% Judge Doyle Garage(20017) Government East Ramp Demolition(2019) Project(s): 11471 Other Reason(s): **Change Type(s): Facilities** COR-01 Revised Demo Plan due to unforeseen condition of exterior wall of Great Dane Pub **CO Description: Notes:** Completion date changed from 02/28/2020 to12/18/2020 **Previous Percent:** 0.0000% **Total Previous: Current Percent:** 0.0000% **Total Current:** #Error **Revised Contract Amount:** Revised Percent 0.0000% \$709,300.00 Contract: 8501 Gregory/Cross/Copeland/Western Reconstruction Contract Amount: \$2,674,277 4 Change Order **Issue Date:** Amount \$8,350.00 Percent: 0.3122% 11188 Gregory/Cross/Copeland/Western Reconstruction Project(s): Field Decision (Expanded Scope). Reason(s): **Change Type(s):** Water

Wednesday, November 11, 2020

Notes:

**CO Description:** 

Total Previous: \$6,972.92 Previous Percent: 0.2607%

Total Current: #Error Current Percent: 0.0000%

Revised Contract Amount: \$2,674,276.81 Revised Percent 0.2607%

Contract: 8514 Julia Street & Julia Court Resurfacing

Contract Amount: \$519,118

Change Order 1 Additional work and down time to redesign the sanitary grade, SAS #2 to #3. Additional

**Issue Date:** 11/4/2020 **Amount** \$16,090.00 **Percent:** 3.0995%

Project(s): 12717 Julia Street & Julia Court Resurfacing

**Reason(s):** Differing site conditions.

Design did not adequately anticipate field conditions.

Underground conflicts (utility revision).

Missing Bid Item or Additional Bid Item needed.

Change Type(s): Sewer-Sanitary

Sewer-Storm

**CO Description:** Additional work and down time to redesign the sanitary grade, SAS #2 to #3. Additional

work for depth of storm sewer that needed to be lower due to watermain conflict. Type IV

trench patching - missing item

Notes: An Additional 14 days

Total Previous: Previous Percent: 0.0000%

Total Current : #Error Current Percent: 0.0000%

Revised Contract Amount: \$519,117.75 Revised Percent 0.0000%

Contract: 8538 2020 Playgrounds - Group 2

Contract Amount: \$164,999

Change Order 1 Curb cut by contractor at Brentwood Park for asphalt path connection to Sheridan Dr.

**Issue Date:** 10/12/2020 **Amount** \$500.00 **Percent:** 0.3030%

Project(s): 12678 2020 Playgrounds - Group 2

Reason(s): Other
Change Type(s): Parks

**CO Description:** Curb cut by contractor at Brentwood Park for asphalt path connection to Sheridan Dr.

**Notes:** 

Total Previous: Previous Percent: 0.0000%

Total Current: \$500.00 Current Percent: 0.3030%

Revised Contract Amount: \$164,999.20 Revised Percent 0.3030%

Contract: 8543 RIMROCK INTRCPTR-INDUSTRIAL DR EXT

Contract Amount: \$774,216

Change Order 1 Removed and replaced 2 older SAS's with 2 new 6' SAS's. All other tiems- A temporary r

**Issue Date:** 10/21/2020 **Amount** \$34,957.50 **Percent:** 4.5152%

Project(s): 11446 RIMROCK INTRCPTR-INDUSTRIAL DR EXT

Reason(s): Missing Bid Item or Additional Bid Item needed.

Change Type(s): Street

Sewer-Sanitary

**CO Description:** Removed and replaced 2 older SAS's with 2 new 6' SAS's. All other tiems- A temporary road

was constructed adjacent to the county bike path to obtain access to the project and also limit

damages to the existing bike path.

**Notes:** 

Total Previous: Previous Percent: 0.0000%

**Total Current :** \$34,957.50 **Current Percent:** 4.5152%

Revised Contract Amount: \$774,216.00 Revised Percent 4.5152%

Contract: 8555 Prairie Road/Raymond Road Intersection Improvement

Contract Amount: \$142,853

Change Order 1 Bid items for restoration, seed, matt and topsoil, did not include areas disturbed plaving c

**Issue Date: Amount** \$4,102.50 **Percent:** 2.8718%

Project(s): 12487 Prairie Road/Raymond Road Intersection Improvement

Reason(s): Actual vs. Estimated Quantities differ.

Change Type(s): Electrical

**CO Description:** Bid items for restoration, seed, matt and topsoil, did not include areas disturbed plaving

conduit in the medians

**Notes:** 

Total Previous: Previous Percent: 0.0000%

Total Current: #Error Current Percent: 0.0000%

Revised Contract Amount: \$142,853.00 Revised Percent 0.0000%

Contract: 8849 2020 Playgrounds - Group 1

Contract Amount: \$132,978

Change Order 2

Issue Date: Amount \$900.00 Percent: 0.6768%

Project(s): 12676 2020 Playgrounds - Group 1

Reason(s): Field Decision (Expanded Scope).

Change Type(s): Parks

**CO Description:** 

**Notes:** 

Total Previous: Previous Percent: 0.0000%

Total Current: #Error Current Percent: 0.0000%

**Revised Contract Amount:** \$132,978.20 **Revised Percent** 0.0000%

Contract: 8858 Felland Road Water Main Extension Phase 1

Contract Amount: \$1,078,484

Change Order 3 Additional fittings per the revised plan. Regrading road due to varying cross slope along

Issue Date: 11/4/2020 Amount \$31,010.02 Percent: 2.8753%

Project(s): 12327 Felland Road Water Main Extension Phase 1

Reason(s):
Change Type(s):

**CO Description:** Additional fittings per the revised plan. Regrading road due to varying cross slope along

Felland Road. Mislabled bid item for asphalt. Adjusting quantities for overage on bid items.

**Notes:** 

Total Previous: \$5,164.75 Previous Percent: 0.4789%

Total Current: #Error Current Percent: 0.0000%

Revised Contract Amount: \$1,078,483.75 Revised Percent 0.4789%

Contract: 8885 2020 Parking Garage Maintenanc

Contract Amount: \$421,905

Change Order 1 Adjustment to unit price, additional work to temporarily restrain rotating retaining wall a

**Issue Date:** 10/27/2020 **Amount** \$15,768.00 **Percent:** 3.7373%

**Project(s):** 8214556x 2020 Parking Garage Maintenance

**Reason(s):** Field Decision (Expanded Scope).

Differing site conditiions.

Change Type(s): Traffic Eng

CO Description: Adjustment to unit price, additional work to temporarily restrain rotating retaining wall and

correct drainage at new CSN pour strip, material premium for lane turnover at SSCo per

owner request

**Notes:** Time extension of 14 days

Total Previous:Previous Percent:0.0000%Total Current :\$15,768.00Current Percent:3.7373%Revised Contract Amount:\$421,904.55Revised Percent3.7373%

Contract: 9411 McKenna Boulevard Flood Mitigation

**Contract Amount:** \$5,866,227

Change Order 4 Remove sandbags placed at property owners to help prevent flooding of their homes in h

**Issue Date:** 10/21/2020 **Amount** \$24,405.00 **Percent:** 0.4160%

Project(s): 12011 McKenna Boulevard Flood Mitigation

Reason(s): Field Decision (Expanded Scope).

Other

Change Type(s): Sewer-Storm

**CO Description:** Remove sandbags placed at property owners to help prevent flooding of their homes in heavy

rains. Grouting needed getween new cunette and slope protection to prevent wash out and

replaced existing CMP crossing bike path with RCP

Notes:

Change Order 5 Slope of grade next ot sidewalk at new cunnette was to steep and a retaining wall was nee 1.0134% **Issue Date:** 10/21/2020 \$59,448.86 **Percent: Amount** Project(s): 12011 McKenna Boulevard Flood Mitigation Missing Bid Item or Additional Bid Item needed. Reason(s): Design did not adequately anticipate field conditions. **Change Type(s):** Sewer-Storm **CO Description:** Slope of grade next ot sidewalk at new cunnette was to steep and a retaining wall was needed. Gradation 1 was needed for base course under new cunnette. Bid item was not included in the storm account. completion date July 2, 2020 **Notes: Previous Percent: Total Previous:** 2.4220% \$142,080.00 **Current Percent: Total Current:** 1.4294% \$83,853.86 **Revised Percent** 3.8514% \$5,866,227.25 **Revised Contract Amount:** 

Wednesday, November 11, 2020