# **LANDMARKS COMMISSION APPLICATION**

Complete all sections of this application, making sure to note the requirements on the accompanying checklist (reverse).

If you need an interpreter, translator, materials in alternate formats or other accommodations to access these forms, please call (608) 266-4635

City of Madison Planning Division 215 Martin Luther King Jr Blvd, Ste 017 PO Box 2985 Madison, WI 53701-2985 (608) 266-4635



		• •		"The about the same of the sam
1. <u>LOCATION</u>				
Project Address: 731 State	St., Madison, WI 53703			_Aldermanic District: 8
2. <u>PROJECT</u>				
Project Title/Description: P	res House Masonry Resto	oration		
This is an application for: (cl	heck all that apply)			
New Construction/Alter District or Designated	eration/Addition in a Local Hist Landmark (specify)**:	oric		Legistar #:
☐ Mansion Hill	☐ Third Lake Ridge	☐ First Settlement		DATE STAMP
☐ University Heights	☐ Marquette Bungalows	Landmark		
or to Designated Landn ☐ Mansion Hill ☐ University Heights ☐ Demolition	ation in a Local Historic District nark Site (specify)**:  Third Lake Ridge  Marquette Bungalows  a building adjacent to a Design	☐ First Settlement ☐ Landmark	DPCED USE ONLY	3/25/21 8:16 am
☐ Variance from the Histo	oric Preservation Ordinance (C	hapter 41)		
_	Rescission or Historic District I storic Preservation Planner for spe	•		Preliminary Zoning Review  Zoning Staff Initial:  Date: / /
3. <u>APPLICANT</u>			_	Date: / /
Applicant's Name: Mark Els	sdon	Company: Presbyter	ian Studen	t Center Foundation (Pres House)
Address: 731 State St., M	ladison, WI 53703			
Telephone: 608-216-7312	Street	Email: mark@presh		
Property Owner (if not applic	cant):Presbyterian Student	Center Foundation (Pre	s House	9)
Address: same as above		- Marie - Jan - Ja		A
Property Owner's Signature:	Street Mak	Z	CityDat	e:March 24, 2021

NOTICE REGARDING LOBBYING ORDINANCE: If you are seeking approval of a development that has over 40,000 square feet of non-residential space, or a residential development of over 10 dwelling units, or if you are seeking assistance from the City with a value of \$10,000 (including grants, loans, TIF or similar assistance), then you likely are subject to Madison's lobbying ordinance (Sec. 2.40, MGO). You are required to register and report your lobbying. Please consult the City Clerk's Office for more information. Failure to comply with the lobbying ordinance may result in fines.

#### **4. <u>APPLICATION SUBMISSION REQUIREMENTS</u>** (see checklist on reverse)

All applications must be filed by 12:00 pm on the submission date with the Preservation Planner. Applications submitted after the submission date *or* incomplete applications will be postponed to the next scheduled filing time. Submission deadlines can be viewed here: <a href="https://www.cityofmadison.com/dpced/planning/documents/LC">https://www.cityofmadison.com/dpced/planning/documents/LC</a> Meeting Schedule Dates.pdf



To: The Landmarks Commission

From: Pres House Executive Director and Board of Directors

Date: March 25, 2021

To Whom It May Concern,

It is the intent of the Board of Directors of Pres House to make repairs to the exterior of our 90-year-old facility which is on the National Historic Registry. This letter describes existing conditions, proposed repairs/restoration of select masonry elements, and the routine maintenance on Tower stone/masonry/roof decks proposed.

Age and weathering have caused breakage and weakened the structure of decorative stone features near the top of Pres House Tower. Up to four pieces were professionally removed (and stored) in an emergency measure. (SEE Existing Condition Photos, pages 2-6)

A proposal for Masonry Repair and Restoration has been obtained from Statz Restoration and Engineering Company, Inc. (SEE Statz: Feb 5 2021; page 7-8). Preservation architect of Isthmus Architecture reviewed proposal for compliance with National Park Service guidelines for masonry repairs. Briefly, the following work is slated to be done: Dutchman repair/reset all broken elements, tuckpoint the mortar joints, re-caulk the sills and windows, and re-seal the Tower roof decks.

Materials have been chosen to match all original finishes and are noted in a letter from Statz. Nothing is to be altered in design, color, placement, or appearance in any way. (SEE March 10 Statz Letter and Materials list; pages 9-17)

This project scope is limited to the Tower part of building. While a lift is on site, any masonry features on the adjacent Church Building that appear to pose a safety risk will be brought to attention and, if necessary and feasible, repaired. (SEE Elevations; page 18)

No Architect has been engaged for this maintenance work. Detailed drawings of the original construction are available for reference as needed, however a drawing of the upper tower is included. (SEE Upper Tower Detail; page 19)

We trust that this description along with the following details will provide you with the information needed to allow us to proceed with these repairs. As stated, our goal is to return the Pres House Tower to its original state and the materials to be used will mirror the original as closely as possible. No additions or changes from the original design are proposed or envisioned. Thank you for your consideration of our project and please contact us should you require additional information.

(SEE the following pages for supporting materials as referenced above.)

731 STATE STREET MADISON, WI 53703

608,257,1030 INFO@PRESHOUSE.ORG WWW.PRESHOUSE.ORG

# **Existing Conditions Photos**



Rusted anchor with pediment removed.



Rusted anchor with pediment cracked but still in place.



Three pediments removed and stored on upper roof.



Existing broken pediment.



Recaulk sill joints.



Recaulk sill joints.



Recaulk window perimeters.



Proposed Dutchman repaired pediment showing stone repaired back to original height. Dutchman will be attached to original stone using stainless steel dowel/epoxy. Pediment will then be reinstalled on stone base using stainless steel dowel/epoxy and mortar.



Small pediment with missing top.

Large pediment removed from base stone. Rusted steel dowel will be removed and replaced with stainless steel dowel.



Loose stones at upper parapet. Stones will be removed and reset in mortar.



Deck coating on second exposed level.



Deck coating on third exposed level



Deck coating on roof areas (8 roof locations total).



Loose stones at base of tower wall by sidewalk.

# Statz Feb. 5 Proposal for Repair



February 5, 2021

Pres House – UW Madison 731 State Street Madison, WI 53703

Attn: Rev. Mark Elsdon

Re: Proposal for Masonry Repairs on Tower

Dear Rev. Elsdon,

Based on our recent onsite meeting, we have prepared the following proposal for your review:

#### SCOPE OF WORK

The University Presbyterian Church and Student Center, more commonly known as the Pres House, was constructed during the period 1931 -1935. The building is constructed of stone, brick and concrete. Statz Restoration completed masonry restoration repairs on the building back in 1996. The repairs included tuckpointing of failed mortar, caulking repairs and the installation of waterproof coatings on the four exposed levels of the tower. The tower on the building requires some masonry repairs. The owner would like pricing to repair the masonry on the tower.

Accordingly, we propose to complete the following repairs on the Pres House tower:

- 1. Mobilize and set up. We will use a large boom lift for access and bosun's chair drops off the back side of the tower as necessary.
- 2. Tuckpoint deteriorated mortar joints in the stone and brick masonry as required using type N mortar. Mortar to match original as best possible and as approved by the owner based on test samples.
- 3. Recaulk skyward facing joints in the stone (sills, capstones and joints in the stone lattice) using Tremco Spectrem 3 silicone sealant. We will remove old sealant from joint prior to recaulking.
- 4. Recaulk window and door perimeters using Tremco Spectrem 2 sealant. 5. Stone Pediment Replacement There are eight damaged stone pediments around the parapet at the top of the tower. Each pediment is anchored to the stone below with a steel rod which has rusted. The expanding rust is causing the surrounding stone to crack and spall making the pediment unstable. There are eight pediments and four have already been removed and placed inside the tower. The remaining four are cracked and are a safety concern. We will remove these four stone pediments.

Milwaukee Office Madison Office N57 W13580 Reichert Avenue ◆ Menomonee Falls, WI 53051 1600 Algonquin Drive ◆ Baraboo, WI 53913 (262) 783-7745 ◆ (800) 486-0659 ◆ Fax (262) 783-4941 (608) 356-9080 ◆ Fax (608) 356-8865 office@statzrestoration.com www.statzrestoration.com

The rusted steel rods will be drilled out and removed from the stone. We will cut off the damaged bottom portion of each pediment and attach new stone matching the configuration of the original stone. The Dutchman pieces will be attached using stainless steel dowels and epoxy. All eight pediments will then be reinstalled back onto the base stones using stainless steel dowels, epoxy and mortar.

- 6. Repair one small pediment with missing top. We will have a new stone top fabricated and we will install using stainless dowel and epoxy. Additional damaged stone can be repaired for an additional charge if needed.
- 7. Reset loose masonry parapet pieces on the upper roof deck. These pieces are loose and will be removed and reset in new mortar.
- 8. Resurface deck coated areas. Clean and reapply urethane deck coating to the four landings in the tower and also on the eight roof areas that were coated in 1996. Any cracks in the concrete will be routed and caulked prior to recoating. Coating area will be solvent wipe cleaned. We will then apply one top coat of urethane with silica sand for skid resistance.
- 9. Replace loose stones at the base of the wall where the west stairs meet the sidewalk. 10. As an option, wash the tower exterior using mild detergent and low psi pressure washer. 11. As an option, complete other masonry repairs on the building as required while the boom lift is on site. This work can be completed on a time and material basis.

Please see photos at the end of this proposal.

#### **PRICING**

Statz Restoration & Engineering Company, Inc. will provide all labor, equipment, insurance, and materials for the above-described work for the following prices:

- A. Base bid work items 1-9 above. Price: \$83,600.00
- B. Option for cleaning the tower exterior. Estimated Costs: \$5,000.00 to \$7,500.00
- C. Additional time and material work. Estimated costs: not to exceed \$10,000.00.

Thank you for the opportunity to submit this proposal. Please call with any questions.

Sincerely,		
Richard A. Stupply		
Richard A. Stelpflug		
Project Manager		
Accepted By:	Date:	
(Owner or Authorized Representative)		

Milwaukee Office Madison Office N57 W13580 Reichert Avenue ◆ Menomonee Falls, WI 53051 1600 Algonquin Drive ◆ Baraboo, WI 53913 (262) 783-7745 ◆ (800) 486-0659 ◆ Fax (262) 783-4941 (608) 356-9080 ◆ Fax (608) 356-8865 office@statzrestoration.com www.statzrestoration.com

# Statz: March 10; Proposal for repair materials



March 10, 2021

Pres House – UW Madison 731 State Street Madison, WI 53703

Attn: Rev. Mark Elsdon

Re: Submittals for Masonry Repairs on Tower

Dear Rev. Elsdon,

We propose to compete the masonry repair and cleaning on the Pres House tower using the following materials:

- 1. Metal Frame to Masonry Sealants Tremco Spectrem 2 silicone sealant. Colors to be selected by the owner from Tremco standard color chart. Data sheet is attached.
- 2. Masonry and Stone Sealants Tremco Septtrem 3 silicone sealant. Colors to be selected by the owner from Tremco standard color chart. Data sheet is attached.
- 3. Mortar Mortar Technologies premixed Type N mortar. Mortar to match original as best possible and as approved by the owner based on test samples. Data sheet is attached.
- 4. Stone Dutchman for Pediment Replacement Indiana Limestone in buff color supplied and tooled by Madison Block and Stone. Sandblast finish to match surrounding stone.
- 5. Stone Anchors Stainless dowels and Rapid Set Fast Anchoring and Repair Adhesive structural epoxy. Data sheet is attached.
- 6. Deck Coating Masterseal Traffic 1500 urethane deck coating (top coat only). This is the same product we installed on the concrete landings back in 1996 (it used to be named Sonoguard). Data sheet is attached.
- 7. Traffic Bearing Sealant (for cracks in landing prior to recoating) MasterSeal SL 2 polyurethane sealant. Data sheet is attached.
- 8. Solvent (for deck coating cleaning) Klean Strip Xylol. Data sheet is attached.
- Masonry Cleaner Low psi pressure washer (500 psi) and Prosoco BioWash cleaner. Data sheet is attached.

Please call with any questions.

Richard A. Stulpfly

Sincerely,

Richard A. Stelpflug Project Manage

Milwaukee Office

N57 W13580 Reichert Avenue • Menomonee Falls, WI 53051 (262) 783-7745 • (800) 486-0659 • Fax (262) 783-4941 office@statzrestoration.com

**Madison Office** 

1600 Algonquin Drive ◆ Baraboo, WI 53913 (608) 356-9080 ◆ Fax (608) 356-8865 www.statzrestoration.com

### Materials List: Solvent





GIRLS W.W. Size & Co., Sc. + www.hissoning.com



# MasterSeal® SL 2

Multi-component self-leveling polyurethane sealant

#### **DESCRIPTION**

MasterSeal SL 2 is a multi-component, self-leveling, elastomeric polyurethane sealant that is mixed and poured in place. When cured, it forms a tough, resilient joint seal that resists penetration and abrasion and remains flexible when exposed to weather and aging.

#### **FEATURES**

- Abrasion resistant to help handle pedestrian and vehicular traffic
- Joint movement capability ±25% provides
- excellent flexibility for keeping moving joints
- weathertight
- Weather resistant, producing long-lasting weathertight seals
- Easy to gun and tool, speeding up application and making neater joints
- MasterSeal 905 accelerator available for use in cold climate applications to help speed initial cure
- No primer required for most construction materials, lowering installation costs
- Wide temperature-application range makes MasterSeal SL 2 suitable for all climates
- UL listed; Passes 4-hour, 4-inch, fire and hose stream test when used with Ultra Block or mineral wool
- Suitable for water immersion with documented performance in wet areas
- Chemical cure allows for faster turnaround time
- Bulk packaging results in less waste
- Long pot life offers extended working time
- Formulated to withstand pedestrian and vehicular traffic

#### **SUBSTRATES**

- Concrete
- Metal

#### **APPLICATIONS**

- Horizontal
- Interior and exterior
- Expansion joints
- Control joints
- Pavers
- Plaza decks
- Industrial floors
- Driveways/garages
- Sidewalks
- Decks
- Parking structures
- Pitch pans

#### **PACKAGING**

MasterSeal SL 2 5.67 liters containing Part A and Part B

MasterSeal P 173 473 ml cans

#### **COLOR**

40 standard, stocked colors are available.

Refer to the Popular Palette for Sealants and Waterproofing.

#### **STANDARDS**

- ASTM C 920, Type M, Grade P, Class 25, Use T, NT, M, A, O\* and I
- Federal Specification TT-S-00227E, Type I, Class A
- Corps of Engineers CRD-C-506, Type I, Class A
- Canadian Specification CAN/CGSB 19.24-M90, Classification MCG-1-40-B-L, No. 81031
- CFI accepted
- USDA compliant for use in areas that handle meat and poultry
- \* Refer to substrates in Where to Use.

#### **SHELF LIFE**

Parts A and B: 1 year when properly stored MasterSeal 900 Color Packs: 5.5 years

A brand of MBCC GROUP



# Spectrem® 2

### **High-Performance Silicone Sealant**

#### **Product Description**

Spectrem® 2 is a medium-modulus, one-part, high-performance, neutral-cure silicone sealant ideal for a variety of perimeter caulking and glazing applications.

#### **Basic Uses**

- Two-sided structural glazing
- Perimeter and weather seals
- Cap, heel and toe beads
- · Curtainwall or window joints

Spectrem 2 may be used on substrates such as aluminum, glass, steel, painted metal, plastic, stone, concrete and brick. Spectrem 2 exhibits primerless adhesion to many common building materials.

All structural glazing applications must be reviewed and approved by Tremco Technical Service prior to the application of Spectrem 2.

#### Applicable Standards

Spectrem 2 meets or exceeds the requirements of the following specifications:

 ASTM C920 Type S, Grade NS, Class 50, Use NT, M, G, A and O



- ASTM C1248
- U.S. Federal Specification TT-S-001543A (COM-NBS) Class A
- U.S. Federal Specification TT-S-00230C (COM-NBS) Class A, Type II
- CAN/CGSB 19 13 M87
- Black meets all of AAMA 802.3-92 (Type I and II), 805.2-94 (Group C), and 808.3-92

#### **Packaging**

1/12-gallon (300mL) cartridges, 20-ounce (600mL) sausages, 2-gallon (7.6L) and 4.5-gallon (17L) pails and 55-gallon (208.2L) drums. All colors are not available in all package sizes. Contact Tremco Customer Service for more information.

Property	Test Method	Typical Value
As Supplied:		
Tack-free time	ASTM C679	20-40 minutes
Sag	ASTM D2202	0-0.1mm (0-0.03")
Tooling Time (skin formation)		10-15 minutes
As Cured: After 14 days at 77° F (25° C) and 50% R.H.		
Hardness (Shore A)	ASTM C661	37-40
Tensile strength at maximum elongation	ASTM D412	1.52-1.59 MPa (220-230 psi)
Elongation	ASTM D412	235-260%
Tensile Strength at 100% elongation	ASTM C1135	0.62-0.69 MPa (90-100 psi)
Tear Strength	ASTM D624	6.14-7.02 kN/m (35-40 pli)
Peel Strength Aluminum, Glass	ASTM C794	2.81-3.86 kN/m (16-22 pli)
Staining of Porous Substrates		
White Marble Primed & Unprimed	ASTM C1248	No Stain
Cyclic movement	ASTM C719	±50%
As Cured: After 21 days at 77° F (25° C) and 50% R.H.		
Ultimate Tensile Strength	ASTM C1135	0.85 MPa (123 psi)
Ultimate Elongation	ASTM C1135	261%

www.tremcosealants.com

Page 1 of 2

# FAST ANCHORING & REPAIR ADHESIVE

C Rapid Set

Multi-Purpose Two-Component Structural Epoxy



#### PRODUCT DATASHEET

DESCRIPTION: Rapid Set® FAST ANCHORING & REPAIR ADHESIVE is a two-component, rigid structural epoxy anchoring repair adhesive designed to develop a strong, durable bond to concrete, masonry, and dissimilar building materials. The high-performance mechanical bond strength and pull-out strength make it suitable for use in a wide range of general construction, repair and maintenance projects.

USES: Use FAST ANCHORING & REPAIR ADHESIVE on properly prepared concrete and masonry substrates. It has a high chemical resistance for use in environments such as swimming pools with chlorine or near salt water. It is ideal for anchoring bolts, dowels. rebar, and wall ties to concrete, concrete blocks, stone, and other masonry substrates. Use as a mortar to fill holes, divets, pop-outs, and non-moving joints/cracks on concrete and masonry. This anchor and repair material is not intended for use as a cosmetic or decorative product. The resin may cause staining in certain materials.

SURFACE PREPARATION: Ensure the substrate is clean, sound and free of bond inhibitors, such as grease, oil, mold, coatings and sealers. Do not install anchor in delaminated or weak substrates. Follow the Technical Installation Procedures for Anchoring, at www.CTScement.com. to properly prepare the anchor hole.

APPLICATION: The minimum application temperature is 41°F (5°C) and rising. The maximum application temperature is 104°F (40°C). Cartridge temperature needs to be a minimum of 41°F (5°C); optimal temperature is 68°F (20°C). For best results, place adhesive when the ambient temperature is between 68°F and 86°F (20°C and 30°C). Ensure surface, personnel and equipment are ready before application. Unscrew top and screw on the provided nozzle onto the mouth of the cartridge. Insert the cartridge into a quality extrusion gun with a minimum of 18:1 thrust ratio. Extrude material with three full pumps until an even gray color, without streaks, flows out. Refer to the Technical Installation Procedures for Anchoring to apply resin inside the anchoring hole.

CURING: At 68°F (20°C), working time is 30 minutes and is load bearing ready in 10 hours.

Cartridge Temperature	Gel & Work Time	Cure Time Dry Substrate	Cure Time Wet Substrate
*41°F (5°C)	180 min	50 hours	100 hours
*50°F (10°C)	120 min	24 hours	48 hours
68°F (20°C)	30 min	10 hours	20 hours
86°F (30°C)	20 min	6 hours	12 hours
104°F (40°C)	12 min	4 hours	8 hours

\*For installations in base material temperature between 41°F and 50°F (5°C and 10°C) the cartridge temperature must be conditioned to between 41°F and 68°F (5°C and 20°C).

COLD WEATHER: Installation in low temperatures will extend cure times of the Rapid Set® FAST ANCHORING & REPAIR ADHESIVE. To ease flow and placement in cold conditions, warm the cartridge above 50°F (10°C) for 24 hours prior to installation. Remove dew, frost or ice from the substrate with acetone on a clean cloth, then place adhesive immediately.

#### OVERVIEW

# Highlights:

Superior pull-out strength

Use on cracked or uncracked concrete

High chemical resistance

Can be used for overhead applications

Fill non-moving cracks and joints

Bonds in water filled anchor holes

#### Conforms to:

ASTM C881 Type IV, Grade 3, Class A, B, C

#### MasterFormat® 2016

03 05 07	Adhesives for Concrete
09 05 00	Adhesives – Common Work Results, Finishes
99 00 00	Construction & Industrial Products

CTS Cement Manufacturing Corp. 12442 Knott St. Garden Grove, CA 92841 Tel: 800-929-3030 | Fax: 714-379-8270 Web: www.CTScement.com E-mail: info@CTScement.com



RODUCT CATALOG

& ADHESIVES

◑



# Spectrem® 3

### Non-Staining, Low-Dirt Pick-Up, Low-Modulus Silicone Sealant

#### **Product Description**

Spectrem® 3 is a general-purpose, low-modulus, highperformance, one-part, neutral-cure, non-staining, low dirt pickup, construction-grade silicone sealant.

#### **Basic Uses**

Spectrem 3's patented chemistry has been specifically formulated to seal porous stone, EFIS, metal panels, masonry and pre-cast concrete joints.


#### **Product Features**

- · Low polar attraction to dirt
- Extremely low stain potential
- Low-modulus and low Shore A hardness
- Primerless adhesion to most porous substrates
- Extended tooling time and workability in high temperatures
- No cure inhibition with Spectrem 1, Spectrem 2 or Dymonic® FC when applied "wet-to-wet" Low VOC, zero solvent content
- Matte finish

#### **Applicable Standards**

Spectrem 3 meets or exceeds the requirements of the following specifications:

- ASTM C 920 Type S, Grade NS, Class 50, Use NT, M, G, A and O
- ASTM C 1248
- **ASTM C 1382**



- U.S. Federal Specification TT-S-001543A Class A
- U.S. Federal Specification TT-S-00230 Class A
- CAN/CGSB 19.13-M87
- EIMA Test Method 300,01

#### **Product Benefits**

- · A 20 year non-stain warranty when pre-approved and tested by Tremco in accordance with ASTM C 1248.
- Less chance of EIFS substrate failures when compared to applications with medium-modulus sealants.
- Ease of use reduces the risk of application failure.
- Compatibility with other sealants minimizes the chance of leakage when sealants abut at glazing and other façade intersects.
- · Low VOC satisfies the LEED criteria for Indoor Environmental Criteria.
- Matte finish affords an aesthetically pleasing appearance with EIFS and stone substrates.

TYPICAL PHYSICAL PROPERTIES		
Property	Test Method	Typical Value
As Supplied:		
Tooling Time		40 minutes
Tack Free Time	ASTM C 679	2 hrs
As Cured: After 14 days at 77° F (25°C) and 5	50% R.H.	
Hardness (Shore A)	ASTM C 661	15
After 14 days at 25°C (77°F)		
Tensile Strength at Max Elongation	ASTM D 412	155 psi
100% Modulus		55 psi
50% Modulus		40 psi
25% Modulus		25 psi
Tear Strength (die "C")	ASTM D 624	25-30 pli min.
Peel Strength	ASTM C 794	
Aluminum, Glass, Concrete		25-35 pli min.
Temperature Range		-40°F to +300°F
Staining of Porous Substrates		
White Marble Primed & Unprimed	ASTM C 1248	No Stain
Stain and Color Change	ASTM C 510 (TT-S-001543A)	No Stain
Joint movement capability	ASTM C 719	
Extension Compression		±50%
NOTE: The foregoing information is published as gapproximate values and are not part of the produ		performance characteristics are

www.tremcosealants.com

Page 1 of 2

# Materials List: Polyurethane waterproofing



We create chemistry

Technical Data Guide

07 18 00 Traffic Coatings

# MasterSeal® Traffic 1500

Polyurethane waterproofing, traffic-bearing membrane systems for vehicular and pedestrian areas

FORMERLY SONOGUARD®

#### **PACKAGING**

- MasterSeal P 222:
- 5 gallon (18.93 L) pails MasterSeal P 220:

  - 4 gallon (15.14 L) units in
- 5 gallon pails (18.93 L)
- MasterSeal M 200,
- (self-leveling and slope-grade):
- 5 gallon (18.93 L) pails
- 55 gallon (208 L) drums 55 gallon (208 L) drums MasterSeal M 205:
- 5 gallon (18.93 L) pails
- MasterSeal TC 225: - 5 gallon (18.93 L) pails
- 55 gallon (208 L) drums MasterSeal TC 235:
- 5 gallon (18.93 L) pails
- MasterSeal 914: 1 pint (473 mL) cans
- MasterSeal 915 (for recoat applications):
- 0.5 pint (236 mL) cans MasterSeal 960
- 4" x 75' roll
- 6" x 75' roll

# YIELD

See chart on page 3 COLORS

#### Gray, Charcoal, Tan, Dark Tan

STORAGE

Store in unopened containers in a cool, clean, dry area SHELF LIFE MasterSeal M 200, M 205, TC 225,

and TC 235: 5 gal pails, 1 year when properly stored 55 gal drums, 9 months when

- properly stored MasterSeal 914, pint cans:
- 2 years when properly stored MasterSeal 915:
- 1 year when properly stored
- MasterSeal 960:
- 2 years when properly stored

#### DESCRIPTION

MasterSeal Traffic 1500 waterproofing systems are composed of:

- MasterSeal M 200, a one-component, moisture-curing polyurethane, OR MasterSeal M 205,
- a low VOC, one component, moisture curing polyurethane.
- MasterSeal TC 225, a one-component aliphatic moisture-curing polyurethane, OR MasterSeal TC 235, a low VOC, one component aliphatic, moisture curing polyurethane.
- -MasterSeal TC 225 Tint Base or MasterSeal TC 235

Note: MasterSeal TC 225 Tint Base and TC 235 Tint Base are intended for pedestrian use only and are not suitable for vehicular traffic.

For projects requiring primer, two choices are available:

- MasterSeal P 222, a one-component solvent-based primer and sealer,
- MasterSeal P 220, a two-component waterborne epoxy primer and sealer.

#### PRODUCT HIGHLIGHTS

- Primer coat not typically required which helps to
   MasterSeal M 200: reduce labor and material costs
- Waterproof which helps to protect concrete from freeze/thaw damage; protects occupied areas below from water damage
- Excellent chloride resistance provides protection against chloride intrusion; extends the life of reinforcing steel
- Seamless elastomeric membrane offers excellent durability and superior abrasion resistance, has • MasterSeal TC 235: 95 g/L less water and no seams that may result in leaks
- Provides skid resistance to increase safety and offers excellent durability and superior abrasion resistance
- Multiple systems available, making MasterSeal Traffic 1500 ideal for various vehicular or pedestrian traffic solutions
- · Repairable and recoatable to extend the useful life of the system
- · Four standard colors: gray, charcoal gray, tan and dark tan

#### VOC CONTENT

- - -Self-leveling grade:
  - 196 g/L less water and exempt solvents
  - -Flash/slope grade: 71.0 g/L less water and exempt solvents
- · MasterSeal M 205: 98 g/L less water and exempt solvents
- . MasterSeal TC 225: 209 g/L less water and exempt solvents.
- exempt solvents

Master Builders Solutions by BASF www.master-builders-solutions.basf.us



٧

### Materials List: Mortar



# Mortar Technologies

#### CERTIFICATION

DATE:

2/20/15

PROJECT NAME:

Various

MASONRY CONTRACTOR:

Statz Restoration

GENERAL CONTRACTOR:

Various

PRODUCT:

N PL (Pro), Type N, Portland/Lime mortar by proportion.

1:1:6 volume proportion

To Whom It May Concern:

Mortar Technologies certifies the above referenced mortar is manufactured to comply with ASTM C270 using aggregate meeting ASTM C144, Portland Cement meeting ASTM C150 (Type I) and hydrated lime meeting ASTM C207.

Please note ASTM C270 is not a specification to determine mortar strengths in the field (per section 3) but only to ensure compliance with property specification requirements under laboratory testing. Field testing should be performed according to ASTM C780 procedures.

Sincerely,

Mortar Technologies

4980 Wildlife Road, Hartford, WI 53027 Toll Free: 877-599-5090 Fax: 262-644-4011

A Part of Lycon Inc.



# **BioWash®**

biological soiling remover for monuments & gravestones

#### **OVERVIEW**

Enviro Klean® BioWash removes mold and mildew staining and atmospheric staining that disfigures and degrades many types of construction materials. BioWash® is a highly efficient alternative to aggressive cleaners traditionally used on interior and exterior masonry, stone and tile surfaces.

BioWash® can also be applied safely to non masonry substrates such as wood, painted surfaces, metal, plastic and glass. Simply dilute with clean water as directed, and apply BioWash® to the surface. A short contact time, gentle scrubbing and a water rinse are normally enough to remove light-to-moderate soiling and staining typically encountered on building surfaces and monuments.

#### **SPECIFICATIONS**

For all PROSOCO product specifications visit www.prosoco.com and click on "SpecBuilder" or "Solution Finder."

#### **ADVANTAGES**

- Safe for landscape plantings and grass.
- Safe for interior use in occupied buildings.
- Effective on all types of stone, concrete and brick masonry.
- Non-fuming, low-odor formulation.
- Needs no substrate neutralization.
- Minimal precautions required for handling and storage.
- Easy to apply with brush, roller or coarse spray.
- Biodegradable.
- Concentrated for economy.
- Safe and effective on wood, painted surfaces, metal, glass and plastic.

#### Limitations

 For removal of heavy biological or atmospheric soiling, consult your PROSOCO representative, or call Customer Care - technical support, toll-free at (800) 255-4255.

# REGULATORY COMPLIANCE

#### **VOC Compliance**


Enviro Klean® BioWash® is compliant with all national, state and district regulations

### TYPICAL TECHNICAL DATA

FORM	Clear, low-odor liquid. Slight amber color
SPECIFIC GRAVITY	1.00
рН	5.5-6.5
WT/GAL	8.34 lbs
ACTIVE CONTENT	Not applicable
TOTAL SOLIDS	Not applicable
VOC CONTENT	Not applicable
FLASH POINT	Not applicable
FREEZE POINT	32°C (0°C)
SHELF LIFE	3 years in tightly sealed, unopened container
SOLUBILITY IN Water	Complete

Product Data Sheet • Page 1 of 4 • Item #41055 • EKBW - 031612 • ©2012 PROSOCO • www.prosoco.com

# Elevations





Upper Tower Detail

