



Legislation Text

File #: 52419, **Version:** 1

Title

215 Martin Luther King Jr Blvd C-07-60-2018

Randall Jacobs of MEP Associates, LLC appealing IMC Section 608.3.3.2.1.

The rule requires that a smoke detector be installed within five feet of damper. There are two different situations. The Madison Fire Department supports the variance for a distance greater than five feet.

Alder District 4