


STORMWATER IMPROVEMENTS  
GLENWOOD CHILDREN'S  
PARK

# LOCATION




# EXISTING LIMESTONE RAILROAD ARCH SUMMER 2017





# EXISTING LIMESTONE RAILROAD ARCH SPRING 2018





# EROSION DOWNSTREAM OF EXISTING INLET



APRIL 2018



JULY 2018





# EROSION AT THE UPSTREAM STORM SEWER CAUSED BY FAILURE OF THE DIVERSION WALL








# PROPOSED IMPROVEMENTS



# PROPOSED IMPROVEMENTS




CROSS SECTION



FRONT VIEW




# DESIGN EXAMPLES



STEPPED  
OVERFLOW



TYPICAL PIPE WITH NO  
SURFACE TREATMENTS



FORM LINERS

STONE VENEER

