

## Pre-Demolition Building & Site Photographs

Former Georgeson Farm – 7317 Cottage Grove Road, Madison, WI




1 – North side of former residential structure. The former home was used by MPD for training exercises. Pre-demolition abatement work was completed in 2021.



2 – Northwest side of residential structure.



3 – South side of the residential building. An adjacent storage shed is located on the left side of the photo.



4 – Photo of the basement of the former residence.



5 – Photo of the main living room of the former residence.



6 – Photo of the kitchen of the former residence.

## Pre-Demolition Building & Site Photographs

Former Georgeson Farm – 7317 Cottage Grove Road, Madison, WI



7 – Photo of the main level of the former residence.



8 – Photo of the main level of the former residence.



9 – Photo of the storage garage adjacent to former residence.



10 – Photo of the storage shed interior.



11 – Photo of the east side of former barn structure and silos located to the west of the former residence.



12 – Photo of the south side of the northern-most barn buildings on the property.

## Pre-Demolition Building & Site Photographs

Former Georgeson Farm – 7317 Cottage Grove Road, Madison, WI



13 – Photo of an entry point to a barn structure located southwest of the former residence.



14 – Photo of additional barn structures on the property. Pre-demolition abatement work was completed for all the barn structures in 2021.



15 – Lower-level access point to the barn structures west of the former residence.



16 – Close-up of lower-level access point to the barn structures west of the former residence.



17 – Primary access to the milking parlor area of the primary barn structure west of the former residence.



18 – Interior view of the former milking parlor.

## Pre-Demolition Building & Site Photographs

Former Georgeson Farm – 7317 Cottage Grove Road, Madison, WI



19 – Photo of the roof of the deteriorated roof area of the western barn structure.



20 – Interior view of barn structure.



21 – Photo of the southern storage/barn structure.



22 – Additional photo of the interior of the southern storage/barn structure.



23 – Small storage structure to the south of the garage and former residence.



24 – Interior photo of the small storage structure to the south of the garage and former residence.